

CENTRIFUGAL PUMP P-102 ROUTINE INSPECTION REPORT (JANUARY 2026)

1.0 Equipment Identification

Asset ID: P-102
Equipment Description: Centrifugal Crude Charge Pump
Unit: Unit 101 — Crude Distillation
Inspection Date: 2026-01-15
Lead Reliability Engineer: R. Sharma

2.0 Measured Operating Parameters

Pump P-102 baseline condition post-overhaul:

- Overall Vibration Velocity (RMS): 2.1 mm/s (Acceptable, baseline normal)
- Drive End Bearing Temperature: 68°C
- Non-Drive End Bearing Temperature: 65°C
- Discharge Pressure: 14.2 bar
- Suction Pressure: 2.1 bar

3.0 Findings & Status

Pump P-102 — Vibration: 2.1 mm/s. Temperature: 68°C. Status: Normal. Operating well within manufacturer baseline.