DEMO TEST FILE FOR GHAT WATCH - NOT AN OFFICIAL MPPCB DOCUMENT

Durga Idol Immersion -2026

Water Quality Monitoring Report

R.O. Bhopal

Location- Murti-visarjan ghat at Shahpura lake, Bhopal.

S. No.	Parameter	Pre Immersion	During Immersion	After one week
1	pH	7.53	7.48	7.55
2	Total Solids	577	614	635
3	Dissolved Solids	491	541	553
4	D.Oxygen	4.6	4.1	5.4
5	BOD	8.0	9.8	9.9
6	COD	51.9	65.8	61.6
7	Turbidity	21.7	26.4	25.0
8	Conductivity	743.6	792.6	799.5
9	Chromium	BDL	BDL	BDL
10	Lead	BDL	0.105	BDL
11	Zinc	0.328	0.197	0.334
12	Copper	0.033	0.069	0.050

Note: the 2026 table is synthetic test data. Each value is the mean of the three earlier Durga readings at this ghat for the same phase; metals are BDL where two of the three readings were BDL. Sources: MPPCB reports of 2023 (p. 60), 2024 (p. 26) and 2025 (p. 65). Not a measurement.

DEMO DATA

DEMO TEST FILE FOR GHAT WATCH - NOT AN OFFICIAL MPPCB DOCUMENT

Ganesh Idol Immersion -2023

Water Quality Monitoring Report

R.O. Bhopal

Location- Murti-visarjan ghat at Shahpura lake, Bhopal.

S. No.	Parameter	Pre Immersion	During Immersion	After one week
1	pH	7.32	7.36	7.76
2	Total Solids	432	480	604
3	Dissolved Solids	394	428	528
4	Suspended Solids	38	52	76
5	D.Oxygen	5.9	5.2	5
6	BOD	6.4	8.4	10.4
7	COD	40	59.28	68.6
8	Turbidity	10.2	12.1	20.3
9	Conductivity	622.1	647.8	813.6
10	Chromium	BDL	BDL	BDL
11	Lead	BDL	BDL	BDL
12	Zinc	0.009	0.021	0.025
13	Copper	BDL	BDL	0.078

Reproduced for testing from the MPPCB Idol Immersion Report 2023 (CPCB format), page 28, values as printed.
Uploading these pages should show them as already in the official pack (ignored, not double-counted).

DEMO TEST FILE FOR GHAT WATCH - NOT AN OFFICIAL MPPCB DOCUMENT

Durga Idol Immersion -2023

Water Quality Monitoring Report

R.O. Bhopal

Location- Murti-visarjan ghat at Shahpura lake, Bhopal.

S. No.	Parameter	Pre Immersion	During Immersion	After one week
1	pH	7.35	7.73	7.76
2	Total Solids	554	570	732
3	Dissolved Solids	478	498	648
4	D.Oxygen	4.5	4	5
5	BOD	6.4	6.8	7.8
6	COD	40	50	39.2
7	Turbidity	19.4	24	27.2
8	Conductivity	779.3	800	881.5
9	Chromium	BDL	BDL	BDL
10	Lead	BDL	0.14	BDL
11	Zinc	0.056	0.363	0.068
12	Copper	0.047	0.121	0.081

Reproduced for testing from the MPPCB Idol Immersion Report 2023 (CPCB format), page 60, values as printed.
Uploading these pages should show them as already in the official pack (ignored, not double-counted).

DEMO TEST FILE FOR GHAT WATCH - NOT AN OFFICIAL MPPCB DOCUMENT

Ganesh Idol Immersion -2024

Water Quality Monitoring Report

R.O. Bhopal

Location- Murti-visarjan ghat at Shahpura lake, Bhopal.

S. No.	Parameter	Pre Immersion	During Immersion	After one week
1	pH	7.88	7.61	7.92
2	Total Solids	384	448	616
3	Dissolved Solids	342	392	438
4	Suspended Solids	42	56	178
5	D.Oxygen	7.4	6.8	6.3
6	BOD	5.8	10	6.8
7	COD	28.56	40.32	39.52
8	Turbidity	71	81	98.4
9	Conductivity	475.8	587.3	629.4
10	Chromium	0.077	0.164	0.359
11	Lead	BDL	0.282	0.413
12	Zinc	0.358	0.612	1.323
13	Copper	0.061	0.752	1.638

Reproduced for testing from the MPPCB Ganesh and Durga Visarjan Report 2024, page 72, values as printed.
Uploading these pages should show them as already in the official pack (ignored, not double-counted).

DEMO TEST FILE FOR GHAT WATCH - NOT AN OFFICIAL MPPCB DOCUMENT

Durga Idol Immersion -2024

Water Quality Monitoring Report

R.O. Bhopal

Location- Murti-visarjan ghat at Shahpura lake, Bhopal.

S. No.	Parameter	Pre Immersion	During Immersion	After one week
1	pH	7.36	7.35	7.53
2	Total Solids	600	654	700
3	Dissolved Solids	544	578	598
4	Suspended Solids	56	76	102
5	D.Oxygen	6.8	5.4	3.8
6	BOD	10.8	11.2	11.6
7	COD	77.4	77.4	78.4
8	Turbidity	14.3	25	28.4
9	Conductivity	795.8	794	860.8
10	Chromium	BDL	BDL	BDL
11	Lead	BDL	BDL	BDL
12	Zinc	BDL	BDL	BDL
13	Copper	BDL	BDL	BDL

Reproduced for testing from the MPPCB Ganesh and Durga Visarjan Report 2024, page 26, values as printed.
Uploading these pages should show them as already in the official pack (ignored, not double-counted).

DEMO TEST FILE FOR GHAT WATCH - NOT AN OFFICIAL MPPCB DOCUMENT

Ganesh Idol Immersion -2025

Water Quality Monitoring Report

R.O. Bhopal

Location- Murti-visarjan ghat at Shahpura lake, Bhopal.

S. No.	Parameter	Pre Immersion	During Immersion	After one week
1	pH	7.7	7.82	7.84
2	Total Solids	432	470	480
3	Dissolved Solids	364	348	378
4	Suspended Solids	68	122	102
5	D.Oxygen	7	6	6.5
6	BOD	4.2	5	4.8
7	COD	29.4	38.4	39.2
8	Turbidity	12.5	19.5	20.1
9	Conductivity	553.1	590.4	601
10	Chromium	0.03	0.03	0.03
11	Lead	0.031	0.031	0.031
12	Zinc	0.091	0.085	0.07
13	Copper	0.137	0.013	0.13

Reproduced for testing from the MPPCB Ganesh and Durga Visarjan Report 2025, page 30, values as printed.
Uploading these pages should show them as already in the official pack (ignored, not double-counted).

DEMO TEST FILE FOR GHAT WATCH - NOT AN OFFICIAL MPPCB DOCUMENT

Durga Idol Immersion -2025

Water Quality Monitoring Report

R.O. Bhopal

Location- Murti-visarjan ghat at Shahpura lake, Bhopal.

S. No.	Parameter	Pre Immersion	During Immersion	After one week
1	pH	7.88	7.36	7.35
2	Total Solids	578	618	472
3	Dissolved Solids	450	546	414
4	D.Oxygen	2.5	2.8	7.4
5	BOD	6.8	11.4	10.4
6	COD	38.4	70	67.2
7	Turbidity	31.4	30.2	19.4
8	Conductivity	655.6	783.9	656.3
9	Chromium	0.03	0.03	0.03
10	Lead	0.06	0.07	0.06
11	Zinc	0.6	0.03	0.6
12	Copper	0.018	0.018	0.018

Reproduced for testing from the MPPCB Ganesh and Durga Visarjan Report 2025, page 65, values as printed.
Uploading these pages should show them as already in the official pack (ignored, not double-counted).