

Three phase short circuit at 1s at bus 380 kV BE-Busbar_1. Short Curcuit is cleared at 1.15 s, no elements are tripped.

