

Status: Closed**Severity: High****Category: Fire Safety**

1. PROJECT & OBSERVATION DETAILS

Project / Organisation

Hilltop court

Date & Time Raised

4/20/2026, 11:08:51 AM

Location on Site

Rear azis

Close-out Timeframe

Immediate

Reported By

Franklin Chibuike Njoku

Responsible Person

Jack manuel

2. DESCRIPTION OF NON-CONFORMANCE

Gas leakage close to the power house



Observation Photo Evidence

3. REQUIRED CORRECTIVE ACTION

Cease supply until issue has been rectified

4. CLOSE-OUT & VERIFICATION

Close-out Action Taken

gas supply ceased, leaking hose replaced

Close-out Date

20/04/2026

5. ACKNOWLEDGEMENT & SIGNATURES

Raised By:

Franklin Chibuike Njoku

Signature: _____

Responsible Person / Dept:

Jack manuel

Signature: _____