

UUT Report

Station ID: STELLA-SMALL
Test Socket Index: 0
Serial Number: 38335915-008-62020047
Date: Friday, September 25, 2026
Time: 2:13:59 PM
Operator: Administrator
Execution Time: 93.1243201 seconds
Number of Results: 198
UUT Result: Failed
Part Number: Single-MID
Failure Chain:

Step	Sequence	Sequence File
2.52 Read T1 torque value	Section 2	EOL_CHMB1_Single.seq
Section 2: System Voltages, Write Calibrations, Check Temperature and Torque Position Signals	MainSequence	EOL_CHMB1_Single.seq

Begin Sequence: MainSequence
(C:\UTP\source\ProductSequences\EOL_CHMB1_Single.seq)

Section 1: Power Up and System Setup	
Status:	Passed
Module Time:	1.5913401

Begin Sequence: Section 1
(C:\UTP\source\ProductSequences\EOL_CHMB1_Single.seq)

1.09 Discharge Capacitance	
Status:	Passed
Module Time:	1.4916611

1.10 Place controller in fixture	
Status:	Passed
1.12 Close fixture	
Status:	Passed
1.14 Perform function tester initialization and checks	
Status:	Passed
1.16 Autoscan Barcode	
Status:	Passed
SerialNumber:	"
1.18 Set DC Supply to Level 3	
Status:	Skipped
1.20 Set Torque inputs to Level 1	
Status:	Passed

1.22 Motor Sense Magnet speed = 0 RPM	
Status:	Passed

End Sequence: Section 1

Section 2: System Voltages, Write Calibrations, Check Temperature and Torque Position Signals	
Status:	Failed
Module Time:	25.9535536

Begin Sequence: Section 2

(C:\UTP\source\ProductSequences\EOL_CHMB1_Single.seq)

2.22.0 Measure funtion test stand voltage DC Supply +	
Status:	Passed
Measurement:	18
Units:	V
Limits:	
Low:	17.7
High:	18.3
Comparison Type:	GELE (>= <=)
Module Time:	1.0607365

2.28.0 Measure DC Supply Current	
Status:	Skipped
2.30.0. Measure CAN H	
Status:	Passed
Measurement:	2.592
Units:	V
Limits:	
Low:	2.4
High:	2.6
Comparison Type:	GELE (>= <=)
Module Time:	1.0431124

2.30.1. Measure CAN L	
Status:	Passed
Measurement:	2.421
Units:	V
Limits:	
Low:	2.4
High:	2.6
Comparison Type:	GELE (>= <=)
Module Time:	0.5341614

2.27. Nexteer Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996

MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2779495
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
2.35 Set NMV Access Defeat	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	1
DATA_3_:	254
DATA_4_:	238
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	1
DATA_3_:	254
DATA_4_:	238
DATA_5_:	0
DATA_6_:	0

DATA_7_:	0
Module Time:	0.2759801
2.36 Write Polarity	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	7
DATA_1_:	46
DATA_2_:	253
DATA_3_:	3
DATA_4_:	1
DATA_5_:	24
DATA_6_:	16
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	3
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2669606
2.37 Write Single Inverter Hardware value	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	46
DATA_2_:	254
DATA_3_:	223
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	254
DATA_3_:	

DATA_3_:	223
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2694823
2.38 Write Motor BEMF	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	5
DATA_1_:	46
DATA_2_:	253
DATA_3_:	192
DATA_4_:	9
DATA_5_:	252
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	192
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2711872
2.40.01 Write Torque Scale Sensor T1	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	7
DATA_1_:	46
DATA_2_:	253
DATA_3_:	182
DATA_4_:	62
DATA_5_:	81
DATA_6_:	235
DATA_7_:	133
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0

LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	182
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2793463

2.40.02 Write Torque Scale Sensor T2

Status:	Passed
---------	--------

Communication [Out]:

Communication [Out][0]:

ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	7
DATA_1_:	46
DATA_2_:	253
DATA_3_:	183
DATA_4_:	62
DATA_5_:	81
DATA_6_:	235
DATA_7_:	133

Communication [Out][1]:

ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	183
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0

Module Time:	0.2724498
--------------	-----------

2.42.01 Trim HW Torque sensor T1

Status:	Passed
---------	--------

Communication [Out]:

Communication [Out][0]:

ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	1
DATA_3_:	253
DATA_4_:	164
DATA_5_:	0
DATA_6_:	0

DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	1
DATA_3_:	253
DATA_4_:	164
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2713554
2.42.02 Trim HW Torque sensor T2	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	1
DATA_3_:	253
DATA_4_:	165
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	1
DATA_3_:	253
DATA_4_:	165
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2769991
2.44.01 Verify HW Torque trim performed T1	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253

DATA_3_:	188
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	188
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2693101
2.44.02 Verify HW Torque trim performed T2	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	189
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	189
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2793883
2.45. XCP Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0

LEN:	8
DATA_0_:	255
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	8
DATA_0_:	255
DATA_1_:	5
DATA_2_:	192
DATA_3_:	64
DATA_4_:	64
DATA_5_:	0
DATA_6_:	1
DATA_7_:	1
Module Time:	0.2726708
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
2.46 Read T1 torque value	
Status:	Passed
Measurement:	2.512665987015
Units:	V
Limits:	
Low:	2.325
High:	2.675
Comparison Type:	GELE (>= <=)
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	96
DATA_5_:	195
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	133

DATA_2_:	207
DATA_3_:	32
DATA_4_:	64
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Correct answer [Out]:	True
Module Time:	0.2786729
2.48 Read T2 torque value	
Status:	Passed
Measurement:	2.529323101044
Units:	V
Limits:	
Low:	2.325
High:	2.675
Comparison Type:	GELE (>= <=)
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	100
DATA_5_:	195
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	110
DATA_2_:	224
DATA_3_:	33
DATA_4_:	64
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Correct answer [Out]:	True
Module Time:	0.2785604
2.45. XCP Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	255
DATA_1_:	0

DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	8
DATA_0_:	255
DATA_1_:	5
DATA_2_:	192
DATA_3_:	64
DATA_4_:	64
DATA_5_:	0
DATA_6_:	1
DATA_7_:	1
Module Time:	0.2708888
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
2.52 Read T1 torque value	
Status:	Failed
Measurement:	2.304977941513
Units:	V
Limits:	
Low:	1.85
High:	2.25
Comparison Type:	GELE (>= <=)
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	96
DATA_5_:	195
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	143
DATA_2_:	81
DATA_3_:	32
DATA_4_:	64

DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Correct answer [Out]:	True
Module Time:	0.2748118
2.53 Read T2 torque value	
Status:	Failed
Measurement:	2.320353794098
Units:	V
Limits:	
Low:	1.85
High:	2.25
Comparison Type:	GELE (>= <=)
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	100
DATA_5_:	195
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	122
DATA_2_:	77
DATA_3_:	33
DATA_4_:	64
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Correct answer [Out]:	True
Module Time:	0.2737754
2.45. XCP Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	255
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0

DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	8
DATA_0_:	255
DATA_1_:	5
DATA_2_:	192
DATA_3_:	64
DATA_4_:	64
DATA_5_:	0
DATA_6_:	1
DATA_7_:	1
Module Time:	0.2743861
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
2.54 Read T1 torque value	
Status:	Failed
Measurement:	2.720353794098
Units:	V
Limits:	
Low:	2.75
High:	3.15
Comparison Type:	GELE (>= <=)
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	96
DATA_5_:	195
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	122
DATA_2_:	77
DATA_3_:	33
DATA_4_:	64
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0

Correct answer [Out]:	True
Module Time:	0.2773339
2.55 Read T2 torque value	
Status:	Failed
Measurement:	2.737010908127
Units:	V
Limits:	
Low:	2.75
High:	3.15
Comparison Type:	GELE (>= <=)
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	100
DATA_5_:	195
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	99
DATA_2_:	94
DATA_3_:	34
DATA_4_:	64
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Correct answer [Out]:	True
Module Time:	0.2720345
2.27. Nexteer Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0

Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2710579
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
2.27. Nexteer Connect	
Status:	Passed
2.58 Write EOL Offset values to defaults	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	55
DATA_2_:	46
DATA_3_:	253
DATA_4_:	245
DATA_5_:	72
DATA_6_:	244
DATA_7_:	36
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0

DATA_2_:	189
DATA_3_:	76
DATA_4_:	204
DATA_5_:	205
DATA_6_:	189
DATA_7_:	76
Communication [Out][3]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	204
DATA_2_:	205
DATA_3_:	189
DATA_4_:	76
DATA_5_:	204
DATA_6_:	205
DATA_7_:	0
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	36
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	63
DATA_6_:	192
DATA_7_:	0
Communication [Out][6]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	37
DATA_1_:	0
DATA_2_:	63
DATA_3_:	192
DATA_4_:	0
DATA_5_:	0
DATA_6_:	63

DATA_7_:	192
Communication [Out][7]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	38
DATA_1_:	0
DATA_2_:	0
DATA_3_:	63
DATA_4_:	192
DATA_5_:	0
DATA_6_:	0
DATA_7_:	63
Communication [Out][8]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	39
DATA_1_:	192
DATA_2_:	0
DATA_3_:	0
DATA_4_:	63
DATA_5_:	192
DATA_6_:	0
DATA_7_:	0
Communication [Out][9]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	245
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.8308521
2.60 Write EOLGain values to defaults	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	27
DATA_2_:	46
DATA_3_:	253
DATA_4_:	244
DATA_5_:	67
DATA_6_:	0
DATA_7_:	179

Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	51
DATA_2_:	67
DATA_3_:	0
DATA_4_:	179
DATA_5_:	51
DATA_6_:	67
DATA_7_:	0
Communication [Out][3]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	179
DATA_2_:	51
DATA_3_:	67
DATA_4_:	5
DATA_5_:	76
DATA_6_:	205
DATA_7_:	67
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	5
DATA_2_:	76
DATA_3_:	205
DATA_4_:	67
DATA_5_:	5
DATA_6_:	76
DATA_7_:	205
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3

DATA_1_:	110
DATA_2_:	253
DATA_3_:	244
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.8993459
2.64 Write Controller Serial Number Scanned in Section 1	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	23
DATA_2_:	46
DATA_3_:	253
DATA_4_:	48
DATA_5_:	54
DATA_6_:	50
DATA_7_:	48
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	50
DATA_2_:	48
DATA_3_:	48
DATA_4_:	52
DATA_5_:	55
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	0

DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	48
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.6294336
2.57 Nexteer connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126

DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2747587
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
2.65 Read Controller Serial Number	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	48
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	23
DATA_2_:	98
DATA_3_:	253
DATA_4_:	48
DATA_5_:	54
DATA_6_:	50
DATA_7_:	48
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8

DATA_0_:	33
DATA_1_:	50
DATA_2_:	48
DATA_3_:	48
DATA_4_:	52
DATA_5_:	55
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.5449796
2.65.01 Check Controller Serial Number	
Status:	Passed
Measurement:	62020047
Units:	SN
Limits:	
Low:	62020047
Comparison Type:	EQ (==)
2.66 Write HW Part Number to controller	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	23
DATA_2_:	46
DATA_3_:	253
DATA_4_:	50

DATA_5_:	50
DATA_6_:	56
DATA_7_:	51
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	49
DATA_2_:	54
DATA_3_:	52
DATA_4_:	56
DATA_5_:	57
DATA_6_:	45
DATA_7_:	48
Communication [Out][3]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	48
DATA_2_:	57
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997

MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	50
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.7712201

2.67 Read HW Part Number

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	50
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	23
DATA_2_:	98
DATA_3_:	253
DATA_4_:	50
DATA_5_:	50
DATA_6_:	56
DATA_7_:	51
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0

LEN:	8
DATA_0_:	33
DATA_1_:	49
DATA_2_:	54
DATA_3_:	52
DATA_4_:	56
DATA_5_:	57
DATA_6_:	45
DATA_7_:	48
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	48
DATA_2_:	57
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.5316261
2.67.01 Check HW Part number	
Status:	Passed
Measurement:	28316489
Units:	PN
Limits:	
Low:	28316489
Comparison Type:	EQ (==)
2.67.02 Check HW Part revision	
Status:	Passed
Measurement:	9
Units:	PN
Limits:	
Low:	9
Comparison Type:	EQ (==)
2.68 Write EPS Serial Number with null	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	

ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	23
DATA_2_:	46
DATA_3_:	253
DATA_4_:	49
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0

DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	49
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.6380511
2.70 Read MES Counter	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	2
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	2
DATA_4_:	252
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2721417
2.71 Check MES Counter	
Status:	Passed
Measurement:	252
Units:	counter
Limits:	

Low:	40
High:	254
Comparison Type:	GELE (>= <=)
2.72 MCU Reset	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	17
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	127
DATA_2_:	17
DATA_3_:	120
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	17
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	81
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0

DATA_7_:	0
Module Time:	1.0318779
2.76 Read MES Counter	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	2
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	2
DATA_4_:	251
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.3520288
2.77 Check MES Counter	
Status:	Passed
Measurement:	251
Units:	counter
Limits:	
Low:	251
High:	251
Comparison Type:	GELE (>= <=)
2.78 Set Vehicle Speed Override	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	47
DATA_3_:	253
DATA_4_:	66
DATA_5_:	3
DATA_6_:	0

DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	111
DATA_3_:	253
DATA_4_:	66
DATA_5_:	3
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8

DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.7879575
2.82 Read First Motor Position	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	242
DATA_3_:	63
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	7
DATA_1_:	98
DATA_2_:	242
DATA_3_:	63
DATA_4_:	0
DATA_5_:	14
DATA_6_:	252
DATA_7_:	64
Module Time:	0.2746925
2.83 Check First Motor Position	
Status:	Passed
Measurement:	119.8828125
Units:	degrees
Limits:	
Low:	-360
High:	360
Comparison Type:	GELE (>= <=)

End Sequence: Section 2

Section 3: Current Calibration Procedure	
Status:	Failed
Module Time:	25.200641

Begin Sequence: Section 3**(C:\UTP\source\ProductSequences\EOL_CHMB1_Single.seq)**

2.57 Nexteer connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2634344
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
3.10 Set Manufacturing Diagnostic Defeat	
Status:	Passed
Module Time:	0.278561
3.11 Set Motor Torque to 0Nm	
Status:	Passed
Module Time:	0.7870651
3.13 Set NMV Access Defeat	
Status:	Passed
Module Time:	0.2762284
3.14 Perform Current Calibration Offset	
Status:	Passed
Module Time:	0.2761057
Clear	
Status:	Passed
Module Time:	0.2704861

Enable	
Status:	Passed
Module Time:	0.2673792
3.18 Read Current Offset Status 02	
Status:	Passed
3.19 Check Current Offset Status 02	
Status:	Passed
Measurement:	2
Units:	State
Limits:	
Low:	2
Comparison Type:	EQ (==)
2.57 Nexteer connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2724921
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
3.22 Enable Engine Run	
Status:	Passed
Module Time:	0.2728546
3.24.1 Read System State	
Status:	Passed
3.24.2 Verify System State in RUN (02)	
Status:	Passed

Measurement:	2
Units:	State
Limits:	
Low:	2
Comparison Type:	EQ (==)
System State:	0
3.30.01 Measure Total Phase Current ABC	
Status:	Passed
Measurement:	45
Units:	A
Limits:	
Low:	44.82
High:	45.18
Comparison Type:	GELE (>= <=)
Module Time:	0.0703176

2.57 Nexteer connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.263606
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
3.32 Perform Current Gain	
Status:	Passed
Module Time:	0.2735442
3.36.1 Read Gain Status	

Status:	Passed
3.36.2 Test Gain Status 02	
Status:	Passed
Measurement:	2
Units:	Status
Limits:	
Low:	2
Comparison Type:	EQ (==)
2.57 Nexteer connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2779267
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
3.42 Disable Torque Ramp Down	
Status:	Passed
Module Time:	0.2681961
3.44 Disable Engine Run	
Status:	Passed
Module Time:	0.2692495
3.45 Read MES Counter	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996

MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	2
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	2
DATA_4_:	251
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2776161
3.46 Check MES Counter	
Status:	Passed
Measurement:	251
Units:	counter
Limits:	
Low:	40
High:	254
Comparison Type:	GELE (>= <=)
3.48 MCU Reset	
Status:	Passed
Module Time:	1.0284041
3.54 Measure DC Supply current	
Status:	Skipped
3.67 Nexteer Connect	
Status:	Passed
Module Time:	0.2912479
3.67 Nexteer Connect	
Status:	Passed
Module Time:	0.2692182
3.68 Read MEC counter	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34

DATA_2_:	253
DATA_3_:	2
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	2
DATA_4_:	250
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2773627
3.69 Check MES Counter	
Status:	Passed
Measurement:	250
Units:	counter
Limits:	
Low:	250
High:	250
Comparison Type:	GELE (>= <=)
3.70 Set Vehicle Speed Override	
Status:	Passed
Module Time:	0.7856366
3.72 Enable Engine Run	
Status:	Passed
Module Time:	0.4210168
3.74 Read System State - RUN(2)	
Status:	Passed
3.74.2 Verify System State in RUN (02)	
Status:	Passed
Measurement:	2
Units:	Status
Limits:	
Low:	2
Comparison Type:	EQ (==)
System State:	0
3.76 Read Current Calibration Offset	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3

DATA_1_:	34
DATA_2_:	253
DATA_3_:	245
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	55
DATA_2_:	98
DATA_3_:	253
DATA_4_:	245
DATA_5_:	73
DATA_6_:	20
DATA_7_:	155
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	235
DATA_2_:	189
DATA_3_:	218
DATA_4_:	180
DATA_5_:	96
DATA_6_:	189
DATA_7_:	188
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	241
DATA_2_:	208
DATA_3_:	189
DATA_4_:	168
DATA_5_:	123

DATA_6_:	176
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][6]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	36
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	63
DATA_6_:	191
DATA_7_:	134
Communication [Out][7]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	37
DATA_1_:	30
DATA_2_:	63
DATA_3_:	192
DATA_4_:	160
DATA_5_:	81
DATA_6_:	63
DATA_7_:	192
Communication [Out][8]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	38
DATA_1_:	80
DATA_2_:	113
DATA_3_:	63
DATA_4_:	192
DATA_5_:	0
DATA_6_:	0
DATA_7_:	63
Communication [Out][9]:	
ID:	1997
MSGTYPE:	0

LEN:	8
DATA_0_:	39
DATA_1_:	192
DATA_2_:	0
DATA_3_:	0
DATA_4_:	63
DATA_5_:	192
DATA_6_:	0
DATA_7_:	0
Module Time:	0.5690074
3.76.03 Verify Offsetf A	
Status:	Passed
Measurement:	1.496280431747
Units:	V
Limits:	
Low:	1.4
High:	1.6
Comparison Type:	GELE (>= <=)
3.76.04 Verify Offset B	
Status:	Passed
Measurement:	1.504892468452
Units:	V
Limits:	
Low:	1.4
High:	1.6
Comparison Type:	GELE (>= <=)
3.76.05 Verify Offset C	
Status:	Passed
Measurement:	1.5024548769
Units:	V
Limits:	
Low:	1.4
High:	1.6
Comparison Type:	GELE (>= <=)
3.78.1 Calculate absolute difference between offset1	
Status:	Passed
Measurement:	0.008612036705017
Units:	V
Limits:	
Low:	0
High:	0.15
Comparison Type:	GELE (>= <=)
3.78.2 Calculate absolute difference between offset2	
Status:	Passed
Measurement:	0.002437591552734
Units:	V
Limits:	
Low:	0
High:	0.15
Comparison Type:	GELE (>= <=)
3.78.3 Calculate absolute difference between offset3	

Status:	Passed
Measurement:	0.006174445152283
Units:	V
Limits:	
Low:	0
High:	0.15
Comparison Type:	GELE (>= <=)
3.80.01 Verify Diff Volt A	
Status:	Skipped
3.80.02 Verify Diff Volt B	
Status:	Skipped
3.80.03 Verify Diff Volt C	
Status:	Skipped
3.67 Nexteer Connect	
Status:	Passed
Module Time:	0.5557458
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
3.82.01 Read Gain Values	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	244
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	27
DATA_2_:	98
DATA_3_:	253
DATA_4_:	244
DATA_5_:	67
DATA_6_:	3
DATA_7_:	246
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8

DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	152
DATA_2_:	67
DATA_3_:	3
DATA_4_:	166
DATA_5_:	26
DATA_6_:	67
DATA_7_:	3
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	250
DATA_2_:	138
DATA_3_:	67
DATA_4_:	5
DATA_5_:	84
DATA_6_:	123
DATA_7_:	67
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	5
DATA_2_:	84
DATA_3_:	123
DATA_4_:	67
DATA_5_:	5
DATA_6_:	84
DATA_7_:	123
Module Time:	0.5447477
3.82.02 Verify Gain A	
Status:	Passed
Measurement:	131.9632568359
Units:	Gain
Limits:	
Low:	129
High:	143
Comparison Type:	GELE (>= <=)

3.82.03 Verify Gain B	
Status:	Passed
Measurement:	131.6488342285
Units:	Gain
Limits:	
Low:	129
High:	143
Comparison Type:	GELE (>= <=)
3.82.04 Verify Gain C	
Status:	Passed
Measurement:	131.9786682129
Units:	Gain
Limits:	
Low:	129
High:	143
Comparison Type:	GELE (>= <=)
3.67 Nexteer Connect	
Status:	Passed
Module Time:	0.3719923
3.84 Clear Nexteer NTCs	
Status:	Passed
Module Time:	0.2698297
3.67 Nexteer Connect	
Status:	Passed
Module Time:	0.2704663
3.86 Read Second Motor Position	
Status:	Passed
Module Time:	0.2722495
3.86 Check Second Motor Position	
Status:	Passed
Measurement:	7470.571289062
Units:	degrees
Limits:	
Low:	-360
High:	10000
Comparison Type:	GELE (>= <=)
3.88 Check difference between first and second motor positions	
Status:	Failed
Measurement:	7350.688476562
Units:	degrees
Limits:	
Low:	800
High:	2000
Comparison Type:	GELE (>= <=)

End Sequence: Section 3

Section 4: Verify SW and Cal Version Procedure	
Status:	Passed
Module Time:	3.0596403

Begin Sequence: Section 4**(C:\UTP\source\ProductSequences\EOL_CHMB1_Single.seq)**

4.10 Read Software ID	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	241
DATA_3_:	148
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	19
DATA_2_:	98
DATA_3_:	241
DATA_4_:	148
DATA_5_:	83
DATA_6_:	105
DATA_7_:	110
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	103
DATA_2_:	108
DATA_3_:	80
DATA_4_:	101

DATA_5_:	112
DATA_6_:	115
DATA_7_:	72
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	119
DATA_2_:	48
DATA_3_:	48
DATA_4_:	49
DATA_5_:	66
DATA_6_:	0
DATA_7_:	0
String test data [Out]:	SinglPepsHw001
Module Time:	0.535069
4.11 Verify Software ID	
Status:	Passed
4.12 Read Software Version	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	241
DATA_3_:	149
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	19
DATA_2_:	98
DATA_3_:	241
DATA_4_:	149
DATA_5_:	49
DATA_6_:	50
DATA_7_:	46
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8

DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	48
DATA_2_:	56
DATA_3_:	46
DATA_4_:	48
DATA_5_:	49
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
String test data [Out]:	12.08.01
Module Time:	0.6442435
4.13 Verify Software Version	
Status:	Passed
4.14 Read Bootloader ID	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	241
DATA_3_:	240
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0

LEN:	8
DATA_0_:	16
DATA_1_:	19
DATA_2_:	98
DATA_3_:	241
DATA_4_:	240
DATA_5_:	83
DATA_6_:	84
DATA_7_:	76
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	65
DATA_2_:	115
DATA_3_:	95
DATA_4_:	69
DATA_5_:	80
DATA_6_:	83
DATA_7_:	65
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	70
DATA_2_:	66
DATA_3_:	76
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
String test data [Out]:	STLAs_EPSAFBL
Module Time:	0.5388435
4.15 Verify Bootloader ID	
Status:	Passed
4.16 Read Bootloader Version	
Status:	Passed
Communication [Out]:	

Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	241
DATA_3_:	241
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	19
DATA_2_:	98
DATA_3_:	241
DATA_4_:	241
DATA_5_:	48
DATA_6_:	49
DATA_7_:	32
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	48
DATA_2_:	49
DATA_3_:	32
DATA_4_:	48
DATA_5_:	48
DATA_6_:	32
DATA_7_:	32
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34

DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
String test data [Out]:	01 01 00
Module Time:	0.5355287
4.17 Verify Bootloader Version	
Status:	Passed
4.18 Calibration Number 0	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	241
DATA_3_:	242
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	98
DATA_3_:	241
DATA_4_:	242
DATA_5_:	0
DATA_6_:	0
DATA_7_:	140
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997

MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	221
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
String test data [Out]:	36061
Module Time:	0.5317493
4.19 Verify Calibration Number 0	
Status:	Passed

End Sequence: Section 4

Section 5: Function Test Procedure	
Status:	Passed
Module Time:	17.1159689

Begin Sequence: Section 5

(C:\UTP\source\ProductSequences\EOL_CHMB1_Single.seq)

5.09 XCP Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	255
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	8
DATA_0_:	255
DATA_1_:	5
DATA_2_:	192
DATA_3_:	64
DATA_4_:	64
DATA_5_:	0
DATA_6_:	1
DATA_7_:	1

Module Time:	0.2760302
5.10 Read Temperature	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	12
DATA_5_:	197
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	111
DATA_2_:	46
DATA_3_:	184
DATA_4_:	65
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2711624
5.11 Verify LimitsTemperature	
Status:	Passed
Measurement:	23.0226726532
Units:	Degrees C
Limits:	
Low:	19
High:	44
Comparison Type:	GELE (>= <=)
5.12 Read Battery Voltage	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	32
DATA_5_:	196
DATA_6_:	190
DATA_7_:	254

Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	16
DATA_2_:	211
DATA_3_:	93
DATA_4_:	65
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2730354
5.13 Verify Limits Battery Voltage	
Status:	Passed
Measurement:	13.86402893066
Units:	V
Limits:	
Low:	13.4
High:	14.1
Comparison Type:	GELE (>= <=)
5.15 Nexteer Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2712067
5.16.1 Read Motor Angle 0	
Status:	Passed
Communication [Out]:	

Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	242
DATA_3_:	48
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	5
DATA_1_:	98
DATA_2_:	242
DATA_3_:	48
DATA_4_:	192
DATA_5_:	115
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2777095
5.16.2 First Angle 0	
Status:	Passed
Measurement:	270.1041564941
Units:	degree
Limits:	
Low:	-360
High:	360
Comparison Type:	GELE (>= <=)
5.16.3 Read Motor Angle 1	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	242
DATA_3_:	49
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8

DATA_0_:	5
DATA_1_:	98
DATA_2_:	242
DATA_3_:	49
DATA_4_:	107
DATA_5_:	32
DATA_6_:	0
DATA_7_:	0
Module Time:	0.273494

5.16.4 First Angle 1

Status:	Passed
Measurement:	150.3508758545
Units:	degree
Limits:	
Low:	-360
High:	360
Comparison Type:	GELE (>= <=)

5.18.1 Read Motor Angle 0

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	242
DATA_3_:	48
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	5
DATA_1_:	98
DATA_2_:	242
DATA_3_:	48
DATA_4_:	64
DATA_5_:	179
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2727458

5.18.2 Second Angle 0

Status:	Passed
Measurement:	90.80592346191
Units:	degree
Limits:	
Low:	-360
High:	360

Comparison Type:	GELE (>= <=)
5.18.2 Read Motor Angle 1	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	242
DATA_3_:	49
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	5
DATA_1_:	98
DATA_2_:	242
DATA_3_:	49
DATA_4_:	235
DATA_5_:	96
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2726068
5.18.4 Second Angle 1	
Status:	Passed
Measurement:	330.3508911133
Units:	degree
Limits:	
Low:	-360
High:	360
Comparison Type:	GELE (>= <=)
5.20.1 Angle difference Sensor 0	
Status:	Passed
Measurement:	179.2982330322
Units:	degrees
Limits:	
Low:	170
High:	190
Comparison Type:	GELE (>= <=)
5.20.2 Angle difference Sensor 1	
Status:	Passed
Measurement:	180.0000152588
Units:	degrees
Limits:	
Low:	170
High:	190

Comparison Type:	GELE (>= <=)
5.23 XCP Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	255
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	8
DATA_0_:	255
DATA_1_:	5
DATA_2_:	192
DATA_3_:	64
DATA_4_:	64
DATA_5_:	0
DATA_6_:	1
DATA_7_:	1
Module Time:	0.2803862
5.24 Read Motor Speed	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	224
DATA_5_:	195
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	49
DATA_2_:	249
DATA_3_:	252

DATA_4_:	66
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2703278
5.25 Verify Limits Motor Speed	
Status:	Passed
Measurement:	126.4867019653
Units:	rad/sec
Limits:	
Low:	120.43
High:	130.9
Comparison Type:	GELE (>= <=)
Motor Speed:	126.4867019653
5.15 Nexter Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2742931
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
5.28 Start Motor Torque 0Nm	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0

LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	47
DATA_3_:	253
DATA_4_:	64
DATA_5_:	3
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	111
DATA_3_:	253
DATA_4_:	64
DATA_5_:	3
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0

DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.781841
5.32 Measure DC Supply Current	
Status:	Passed
Measurement:	0.1409
Units:	mA
Limits:	
Low:	0.12
High:	0.2
Comparison Type:	GELE (>= <=)
Module Time:	1.0696068

5.15 Nexteer Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244

DATA_7_:	0
Module Time:	0.2803822
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
5.34 Start Motor Torque -3Nm	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	47
DATA_3_:	253
DATA_4_:	64
DATA_5_:	3
DATA_6_:	192
DATA_7_:	64
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	111
DATA_3_:	253

DATA_4_:	64
DATA_5_:	3
DATA_6_:	192
DATA_7_:	64
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.7892035
5.23 XCP Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	255
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	8
DATA_0_:	255
DATA_1_:	5
DATA_2_:	192
DATA_3_:	64
DATA_4_:	64

DATA_5_:	0
DATA_6_:	1
DATA_7_:	1
Module Time:	0.2753056
5.38 Read Motor Current	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	168
DATA_5_:	195
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	157
DATA_2_:	83
DATA_3_:	163
DATA_4_:	66
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2717167
5.39 Check Motor Current	
Status:	Passed
Measurement:	81.66330718994
Units:	A
Limits:	
Low:	80
High:	100
Comparison Type:	GELE (>= <=)
5.40 Measure DC Supply Current	
Status:	Passed
Measurement:	25.959
Units:	A
Limits:	
Low:	15
High:	30
Comparison Type:	GELE (>= <=)
Module Time:	0.0584096
5.53 Nexteer Connect	
Status:	Passed
Communication [Out]:	

Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2890983
5.54 Stop Motor Torque	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	47
DATA_3_:	253
DATA_4_:	64
DATA_5_:	3
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	

ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	111
DATA_3_:	253
DATA_4_:	64
DATA_5_:	3
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.7901665
5.58 Read System Status	
Status:	Passed

End Sequence: Section 5

Section 6: End of Line Writes, Verify Data	
Status:	Passed
Module Time:	15.0533346

Begin Sequence: Section 6
(C:\UTP\source\ProductSequences\EOL_CHMB1_Single.seq)

5.53 Nexteer Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2664796
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
6.10 Read NTC Storage Array	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	96
DATA_4_:	0
DATA_5_:	0

DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	103
DATA_2_:	98
DATA_3_:	253
DATA_4_:	96
DATA_5_:	0
DATA_6_:	6
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	11
DATA_2_:	56
DATA_3_:	0
DATA_4_:	176
DATA_5_:	0
DATA_6_:	10
DATA_7_:	1
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	1
DATA_2_:	36
DATA_3_:	0
DATA_4_:	11
DATA_5_:	0
DATA_6_:	1
DATA_7_:	37
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0

LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	11
DATA_3_:	0
DATA_4_:	1
DATA_5_:	64
DATA_6_:	0
DATA_7_:	11
Communication [Out][6]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	36
DATA_1_:	0
DATA_2_:	1
DATA_3_:	68
DATA_4_:	0
DATA_5_:	11
DATA_6_:	0
DATA_7_:	1
Communication [Out][7]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	37
DATA_1_:	73
DATA_2_:	0
DATA_3_:	11
DATA_4_:	0
DATA_5_:	1
DATA_6_:	80
DATA_7_:	0
Communication [Out][8]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	38
DATA_1_:	11
DATA_2_:	0
DATA_3_:	1
DATA_4_:	86
DATA_5_:	0
DATA_6_:	11
DATA_7_:	0
Communication [Out][9]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	39
DATA_1_:	1
DATA_2_:	89
DATA_3_:	0

DATA_4_:	11
DATA_5_:	0
DATA_6_:	1
DATA_7_:	96
Communication [Out][10]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	40
DATA_1_:	0
DATA_2_:	11
DATA_3_:	0
DATA_4_:	1
DATA_5_:	104
DATA_6_:	0
DATA_7_:	11
Communication [Out][11]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	41
DATA_1_:	0
DATA_2_:	1
DATA_3_:	105
DATA_4_:	0
DATA_5_:	11
DATA_6_:	0
DATA_7_:	1
Communication [Out][12]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	42
DATA_1_:	114
DATA_2_:	0
DATA_3_:	11
DATA_4_:	0
DATA_5_:	1
DATA_6_:	115
DATA_7_:	0
Communication [Out][13]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	43
DATA_1_:	11
DATA_2_:	0
DATA_3_:	1
DATA_4_:	144
DATA_5_:	0
DATA_6_:	11
DATA_7_:	24
Communication [Out][14]:	

ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	44
DATA_1_:	1
DATA_2_:	146
DATA_3_:	0
DATA_4_:	11
DATA_5_:	1
DATA_6_:	0
DATA_7_:	0
Communication [Out][15]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	45
DATA_1_:	255
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	255
DATA_7_:	0
Communication [Out][16]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	46
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	255
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.598077
6.12 Disable Torque Ramp Down	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	1
DATA_3_:	241
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997

MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	1
DATA_3_:	241
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.6101543

6.14 Disable Engine Run

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	2
DATA_3_:	241
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	2
DATA_3_:	241
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2763224

6.16 MCU Reset

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	17
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0

DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	127
DATA_2_:	17
DATA_3_:	120
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	17
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	81
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	1.031423
6.31 Nexteer Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0

DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2733116
6.31 Nexteer Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2706717
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
6.32 Read MEC counter	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0

LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	2
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	2
DATA_4_:	249
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2649565
6.34 Enable Engine Run	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	1
DATA_3_:	241
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	1
DATA_3_:	241
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2755447
6.36 Read System State	
Status:	Passed

6.38 Read Serial Number	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	48
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	23
DATA_2_:	98
DATA_3_:	253
DATA_4_:	48
DATA_5_:	54
DATA_6_:	50
DATA_7_:	48
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	50
DATA_2_:	48
DATA_3_:	48
DATA_4_:	52
DATA_5_:	55
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1997

MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.5383691
6.39 Check Controller Serial Number	
Status:	Passed
Measurement:	62020047
Units:	SN
Limits:	
Low:	62020047
Comparison Type:	EQ (==)
6.40 Read HW part number	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	50
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	23
DATA_2_:	98

DATA_3_:	253
DATA_4_:	50
DATA_5_:	50
DATA_6_:	56
DATA_7_:	51
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	49
DATA_2_:	54
DATA_3_:	52
DATA_4_:	56
DATA_5_:	57
DATA_6_:	45
DATA_7_:	48
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	48
DATA_2_:	57
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0

Module Time:	0.6714167
6.40.01 Check HW Part number	
Status:	Passed
Measurement:	28316489
Units:	PN
Limits:	
Low:	28316489
Comparison Type:	EQ (==)
6.40.02 Check HW Part revision	
Status:	Passed
Measurement:	9
Units:	PN
Limits:	
Low:	9
Comparison Type:	EQ (==)
6.41 Read Single Inverter Hardware value	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	254
DATA_3_:	223
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	254
DATA_3_:	223
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2716439
6.41.01 Check Single Inverter Hardware value	
Status:	Passed
Measurement:	1
Units:	State
Limits:	
Low:	1
Comparison Type:	EQ (==)
6.42 Read Offset values	

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	245
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	55
DATA_2_:	98
DATA_3_:	253
DATA_4_:	245
DATA_5_:	73
DATA_6_:	20
DATA_7_:	155
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	235
DATA_2_:	189
DATA_3_:	218
DATA_4_:	180
DATA_5_:	96
DATA_6_:	189
DATA_7_:	188
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0

LEN:	8
DATA_0_:	34
DATA_1_:	241
DATA_2_:	208
DATA_3_:	189
DATA_4_:	168
DATA_5_:	123
DATA_6_:	176
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][6]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	36
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	63
DATA_6_:	191
DATA_7_:	134
Communication [Out][7]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	37
DATA_1_:	30
DATA_2_:	63
DATA_3_:	192
DATA_4_:	160
DATA_5_:	81
DATA_6_:	63
DATA_7_:	192
Communication [Out][8]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	38
DATA_1_:	80
DATA_2_:	113
DATA_3_:	63

DATA_4_:	192
DATA_5_:	0
DATA_6_:	0
DATA_7_:	63
Communication [Out][9]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	39
DATA_1_:	192
DATA_2_:	0
DATA_3_:	0
DATA_4_:	63
DATA_5_:	192
DATA_6_:	0
DATA_7_:	0
Module Time:	0.5655806
6.42.01 Verify Offsetf A	
Status:	Passed
Measurement:	1.496280431747
Units:	V
Limits:	
Low:	1.496280431747
Comparison Type:	EQ (==)
6.42.02 Verify Offset B	
Status:	Passed
Measurement:	1.504892468452
Units:	V
Limits:	
Low:	1.504892468452
Comparison Type:	EQ (==)
6.42.03 Verify Offset C	
Status:	Passed
Measurement:	1.5024548769
Units:	V
Limits:	
Low:	1.5024548769
Comparison Type:	EQ (==)
6.44.01 Verify Diff Volt A	
Status:	Passed
Measurement:	0.01453125476837
Units:	V
Limits:	
Low:	0.01453125476837
Comparison Type:	EQ (==)
6.44.02 Verify Diff Volt B	
Status:	Passed
Measurement:	0.009990930557251
Units:	V
Limits:	
Low:	0.009990930557251

Comparison Type:	EQ (==)
6.44.03 Verify Diff Volt C	
Status:	Passed
Measurement:	0.02452218532562
Units:	V
Limits:	
Low:	0.02452218532562
Comparison Type:	EQ (==)
6.46.00 Read Gain Values	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	244
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	27
DATA_2_:	98
DATA_3_:	253
DATA_4_:	244
DATA_5_:	67
DATA_6_:	3
DATA_7_:	246
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33

DATA_1_:	152
DATA_2_:	67
DATA_3_:	3
DATA_4_:	166
DATA_5_:	26
DATA_6_:	67
DATA_7_:	3
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	250
DATA_2_:	138
DATA_3_:	67
DATA_4_:	5
DATA_5_:	84
DATA_6_:	123
DATA_7_:	67
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	5
DATA_2_:	84
DATA_3_:	123
DATA_4_:	67
DATA_5_:	5
DATA_6_:	84
DATA_7_:	123
Module Time:	0.8095965
6.46.01 Verify Gain A	
Status:	Passed
Measurement:	131.9632568359
Units:	gain
Limits:	
Low:	131.9632568359
Comparison Type:	EQ (==)
6.46.02 Verify Gain B	
Status:	Passed
Measurement:	131.6488342285
Units:	gain
Limits:	
Low:	131.6488342285
Comparison Type:	EQ (==)
6.46.03 Verify Gain C	
Status:	Passed
Measurement:	131.9786682129
Units:	gain
Limits:	
Low:	131.9786682129

Comparison Type:	EQ (==)
6.48 Read Polarity	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	3
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	7
DATA_1_:	98
DATA_2_:	253
DATA_3_:	3
DATA_4_:	1
DATA_5_:	24
DATA_6_:	16
DATA_7_:	0
Module Time:	0.2751051
6.49 Verify Polarity	
Status:	Passed
Measurement:	1181000
Units:	Polarity
Limits:	
Low:	1181000
Comparison Type:	EQ (==)
6.50 Read NTC	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	96
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	

ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	103
DATA_2_:	98
DATA_3_:	253
DATA_4_:	96
DATA_5_:	0
DATA_6_:	6
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	11
DATA_2_:	56
DATA_3_:	1
DATA_4_:	36
DATA_5_:	0
DATA_6_:	11
DATA_7_:	0
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	1
DATA_2_:	37
DATA_3_:	0
DATA_4_:	11
DATA_5_:	0
DATA_6_:	1
DATA_7_:	64
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0

DATA_2_:	11
DATA_3_:	0
DATA_4_:	1
DATA_5_:	68
DATA_6_:	0
DATA_7_:	11
Communication [Out][6]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	36
DATA_1_:	0
DATA_2_:	1
DATA_3_:	73
DATA_4_:	0
DATA_5_:	11
DATA_6_:	0
DATA_7_:	1
Communication [Out][7]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	37
DATA_1_:	80
DATA_2_:	0
DATA_3_:	11
DATA_4_:	0
DATA_5_:	1
DATA_6_:	86
DATA_7_:	0
Communication [Out][8]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	38
DATA_1_:	11
DATA_2_:	0
DATA_3_:	1
DATA_4_:	89
DATA_5_:	0
DATA_6_:	11
DATA_7_:	0
Communication [Out][9]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	39
DATA_1_:	1
DATA_2_:	104
DATA_3_:	0
DATA_4_:	11
DATA_5_:	0
DATA_6_:	1

DATA_7_:	105
Communication [Out][10]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	40
DATA_1_:	0
DATA_2_:	11
DATA_3_:	0
DATA_4_:	1
DATA_5_:	114
DATA_6_:	0
DATA_7_:	11
Communication [Out][11]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	41
DATA_1_:	0
DATA_2_:	1
DATA_3_:	115
DATA_4_:	0
DATA_5_:	11
DATA_6_:	0
DATA_7_:	1
Communication [Out][12]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	42
DATA_1_:	144
DATA_2_:	0
DATA_3_:	11
DATA_4_:	24
DATA_5_:	1
DATA_6_:	146
DATA_7_:	0
Communication [Out][13]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	43
DATA_1_:	11
DATA_2_:	1
DATA_3_:	0
DATA_4_:	176
DATA_5_:	1
DATA_6_:	8
DATA_7_:	0
Communication [Out][14]:	
ID:	1997
MSGTYPE:	0
LEN:	8

DATA_0_:	44
DATA_1_:	1
DATA_2_:	96
DATA_3_:	1
DATA_4_:	73
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][15]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	45
DATA_1_:	255
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	255
DATA_7_:	0
Communication [Out][16]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	46
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	255
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.6046135
6.52 Clear Nexteer NTCs	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	1
DATA_3_:	253
DATA_4_:	112
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4

DATA_1_:	113
DATA_2_:	1
DATA_3_:	253
DATA_4_:	112
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2638543

6.54 Write MEC Counter FE

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	46
DATA_2_:	253
DATA_3_:	2
DATA_4_:	254
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	2
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2757249

6.55 Read MEC Counter FE

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	2
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	

ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	2
DATA_4_:	254
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2784812
6.55 Check MEC Counter FE	
Status:	Passed
Measurement:	254
Units:	Counter
Limits:	
Low:	254
Comparison Type:	EQ (==)
6.31 Nexteer Connect	
Status:	Skipped
6.56 Write Toque Trim T1	
Status:	Skipped
6.57 Write Toque Trim T2	
Status:	Skipped
6.58 Disable Torque Ramp Down	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	1
DATA_3_:	241
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	1
DATA_3_:	241
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0

DATA_7_:	0
Module Time:	0.2729525
6.60 Diabie Engine Run	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	2
DATA_3_:	241
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	2
DATA_3_:	241
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2650775
6.64 MCU Reset	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	17
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	127
DATA_2_:	17

DATA_3_:	120
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	17
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	81
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	1.0250688
6.70 Measure voltage across Rq for Ignition Off current measurement	
Status:	Skipped

End Sequence: Section 6

Failure Procedure	
Status:	Skipped
Test Cleanup	
Status:	Passed
Module Time:	4.2708543

End Sequence: MainSequence

End UUT Report
