

UUT Report

Station ID: STELLA-SMALL
Test Socket Index: 0
Serial Number: 38335915-008-62020047
Date: Friday, September 25, 2026
Time: 3:30:38 PM
Operator: Administrator
Execution Time: 88.5674752 seconds
Number of Results: 197
UUT Result: Failed
Part Number: Single-MID
Failure Chain:

Step	Sequence	Sequence File
2.28.0 Measure DC Supply Current	Section 2	EOL_CHMB1_Single.seq
Section 2: System Voltages, Write Calibrations, Check Temperature and Torque Position Signals	MainSequence	EOL_CHMB1_Single.seq

Begin Sequence: MainSequence
(C:\UTP\source\ProductSequences\EOL_CHMB1_Single.seq)

Section 1: Power Up and System Setup	
Status:	Passed
Module Time:	1.5682984

Begin Sequence: Section 1
(C:\UTP\source\ProductSequences\EOL_CHMB1_Single.seq)

1.09 Discharge Capacitance	
Status:	Passed
Module Time:	1.4633414
1.10 Place controller in fixture	
Status:	Passed
1.12 Close fixture	
Status:	Passed
1.14 Perform function tester initialization and checks	
Status:	Passed
1.16 Autoscan Barcode	
Status:	Passed
SerialNumber:	"
1.18 Set DC Supply to Level 3	
Status:	Skipped
1.20 Set Torque inputs to Level 1	

Status:	Passed
1.22 Motor Sense Magnet speed = 0 RPM	
Status:	Passed

End Sequence: Section 1

Section 2: System Voltages, Write Calibrations, Check Temperature and Torque Position Signals	
Status:	Failed
Module Time:	21.7939684

Begin Sequence: Section 2

(C:\UTP\source\ProductSequences\EOL_CHMB1_Single.seq)

2.22.0 Measure funtion test stand voltage DC Supply +	
Status:	Passed
Measurement:	18
Units:	V
Limits:	
Low:	17.7
High:	18.3
Comparison Type:	GELE (>= <=)
Module Time:	1.0683612

2.28.0 Measure DC Supply Current	
Status:	Failed
Measurement:	18
Units:	A
Limits:	
Low:	0.08
High:	0.2
Comparison Type:	GELE (>= <=)
Module Time:	2.9003038

2.30.0. Measure CAN H	
Status:	Passed
Measurement:	2.591
Units:	V
Limits:	
Low:	2.4
High:	2.6
Comparison Type:	GELE (>= <=)
Module Time:	1.0431049

2.30.1. Measure CAN L	
Status:	Passed
Measurement:	2.421
Units:	V
Limits:	
Low:	2.4
High:	2.6

Comparison Type:	GELE (>= <=)
Module Time:	0.5371902

2.27 Nexteer Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2758423
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
2.35 Set NMV Access Defeat	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	1
DATA_3_:	254
DATA_4_:	238
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0

LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	1
DATA_3_:	254
DATA_4_:	238
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2769152

2.36 Write Polarity

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	7
DATA_1_:	46
DATA_2_:	253
DATA_3_:	3
DATA_4_:	1
DATA_5_:	24
DATA_6_:	16
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	3
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2730108

2.37 Write Single Inverter Hardware value

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	46
DATA_2_:	254
DATA_3_:	223
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0

DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	254
DATA_3_:	223
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2716486
2.38 Write Motor BEMF	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	5
DATA_1_:	46
DATA_2_:	253
DATA_3_:	192
DATA_4_:	9
DATA_5_:	252
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	192
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2783269
2.40.01 Write Torque Scale Sensor T1	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	7
DATA_1_:	46
DATA_2_:	253

DATA_3_:	182
DATA_4_:	62
DATA_5_:	81
DATA_6_:	235
DATA_7_:	133
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	182
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2738654
2.40.02 Write Torque Scale Sensor T2	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	7
DATA_1_:	46
DATA_2_:	253
DATA_3_:	183
DATA_4_:	62
DATA_5_:	81
DATA_6_:	235
DATA_7_:	133
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	183
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2716837
2.42.01 Trim HW Torque sensor T1	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0

LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	1
DATA_3_:	253
DATA_4_:	164
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	1
DATA_3_:	253
DATA_4_:	164
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2706969
2.42.02 Trim HW Torque sensor T2	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	1
DATA_3_:	253
DATA_4_:	165
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	1
DATA_3_:	253
DATA_4_:	165
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2779446
2.44.01 Verify HW Torque trim performed T1	
Status:	Passed

Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	188
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	188
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2717234
2.44.02 Verify HW Torque trim performed T2	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	189
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	189
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0

Module Time:	0.273481
2.45 XCP Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	255
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	8
DATA_0_:	255
DATA_1_:	5
DATA_2_:	192
DATA_3_:	64
DATA_4_:	64
DATA_5_:	0
DATA_6_:	1
DATA_7_:	1
Module Time:	0.2711693
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
2.46 Read T1 torque value	
Status:	Passed
Measurement:	2.515228748322
Units:	V
Limits:	
Low:	2.325
High:	2.675
Comparison Type:	GELE (>= <=)
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	96
DATA_5_:	195

DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	130
DATA_2_:	249
DATA_3_:	32
DATA_4_:	64
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Correct answer [Out]:	True
Module Time:	0.278161
2.48 Read T2 torque value	
Status:	Passed
Measurement:	2.529323101044
Units:	V
Limits:	
Low:	2.325
High:	2.675
Comparison Type:	GELE (>= <=)
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	100
DATA_5_:	195
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	110
DATA_2_:	224
DATA_3_:	33
DATA_4_:	64
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Correct answer [Out]:	True
Module Time:	0.2753724
2.51 XCP Connect	

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	255
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	8
DATA_0_:	255
DATA_1_:	5
DATA_2_:	192
DATA_3_:	64
DATA_4_:	64
DATA_5_:	0
DATA_6_:	1
DATA_7_:	1
Module Time:	0.2772823
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
2.52 Read T1 torque value	
Status:	Passed
Measurement:	2.073059368134
Units:	V
Limits:	
Low:	1.85
High:	2.25
Comparison Type:	GELE (>= <=)
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	96
DATA_5_:	195
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	

ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	206
DATA_2_:	121
DATA_3_:	17
DATA_4_:	64
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Correct answer [Out]:	True
Module Time:	0.2745039
2.53 Read T2 torque value	
Status:	Passed
Measurement:	2.0615275383
Units:	V
Limits:	
Low:	1.85
High:	2.25
Comparison Type:	GELE (>= <=)
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	100
DATA_5_:	195
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	222
DATA_2_:	188
DATA_3_:	16
DATA_4_:	64
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Correct answer [Out]:	True
Module Time:	0.2749375
2.53. XCP Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	

ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	255
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	8
DATA_0_:	255
DATA_1_:	5
DATA_2_:	192
DATA_3_:	64
DATA_4_:	64
DATA_5_:	0
DATA_6_:	1
DATA_7_:	1
Module Time:	0.275613
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
2.54 Read T1 torque value	
Status:	Passed
Measurement:	2.948428583145
Units:	V
Limits:	
Low:	2.75
High:	3.15
Comparison Type:	GELE (>= <=)
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	96
DATA_5_:	195
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5

DATA_0_:	255
DATA_1_:	65
DATA_2_:	230
DATA_3_:	47
DATA_4_:	64
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Correct answer [Out]:	True
Module Time:	0.2735579

2.55 Read T2 torque value

Status:	Passed
Measurement:	2.988149356842
Units:	V
Limits:	
Low:	2.75
High:	3.15
Comparison Type:	GELE (>= <=)
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	100
DATA_5_:	195
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	10
DATA_2_:	113
DATA_3_:	50
DATA_4_:	64
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Correct answer [Out]:	True
Module Time:	0.2843721

2.27. Nexteer Connect

Status:	Passed
---------	--------

2.58 Write EOL Offset values to defaults

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996

MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	55
DATA_2_:	46
DATA_3_:	253
DATA_4_:	245
DATA_5_:	72
DATA_6_:	244
DATA_7_:	36
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	189
DATA_3_:	76
DATA_4_:	204
DATA_5_:	205
DATA_6_:	189
DATA_7_:	76
Communication [Out][3]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	204
DATA_2_:	205
DATA_3_:	189
DATA_4_:	76
DATA_5_:	204
DATA_6_:	205
DATA_7_:	0
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0

DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	36
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	63
DATA_6_:	192
DATA_7_:	0
Communication [Out][6]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	37
DATA_1_:	0
DATA_2_:	63
DATA_3_:	192
DATA_4_:	0
DATA_5_:	0
DATA_6_:	63
DATA_7_:	192
Communication [Out][7]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	38
DATA_1_:	0
DATA_2_:	0
DATA_3_:	63
DATA_4_:	192
DATA_5_:	0
DATA_6_:	0
DATA_7_:	63
Communication [Out][8]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	39
DATA_1_:	192
DATA_2_:	0
DATA_3_:	0
DATA_4_:	63
DATA_5_:	192
DATA_6_:	0
DATA_7_:	0

Communication [Out][9]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	245
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.837274
2.60 Write EOLGain values to defaults	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	27
DATA_2_:	46
DATA_3_:	253
DATA_4_:	244
DATA_5_:	67
DATA_6_:	0
DATA_7_:	179
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	51
DATA_2_:	67
DATA_3_:	0
DATA_4_:	179
DATA_5_:	51
DATA_6_:	67
DATA_7_:	0
Communication [Out][3]:	

ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	179
DATA_2_:	51
DATA_3_:	67
DATA_4_:	5
DATA_5_:	76
DATA_6_:	205
DATA_7_:	67
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	5
DATA_2_:	76
DATA_3_:	205
DATA_4_:	67
DATA_5_:	5
DATA_6_:	76
DATA_7_:	205
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	244
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.8913809
2.64 Write Controller Serial Number Scanned in Section 1	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	23
DATA_2_:	46
DATA_3_:	253
DATA_4_:	48
DATA_5_:	54
DATA_6_:	50
DATA_7_:	48
Communication [Out][1]:	
ID:	1997

MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	50
DATA_2_:	48
DATA_3_:	48
DATA_4_:	52
DATA_5_:	55
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253

DATA_3_:	48
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.6284895
2.65 Read Controller Serial Number	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	48
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	23
DATA_2_:	98
DATA_3_:	253
DATA_4_:	48
DATA_5_:	54
DATA_6_:	50
DATA_7_:	48
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	50
DATA_2_:	48
DATA_3_:	48

DATA_4_:	52
DATA_5_:	55
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.5395438
2.65.01 Check Controller Serial Number	
Status:	Passed
Measurement:	62020047
Units:	SN
Limits:	
Low:	62020047
Comparison Type:	EQ (==)
2.66 Write HW Part Number to controller	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	23
DATA_2_:	46
DATA_3_:	253
DATA_4_:	50
DATA_5_:	50
DATA_6_:	56
DATA_7_:	51
Communication [Out][1]:	

ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	49
DATA_2_:	54
DATA_3_:	52
DATA_4_:	56
DATA_5_:	57
DATA_6_:	45
DATA_7_:	48
Communication [Out][3]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	48
DATA_2_:	57
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110

DATA_2_:	253
DATA_3_:	50
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.624497
2.67 Read HW Part Number	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	50
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	23
DATA_2_:	98
DATA_3_:	253
DATA_4_:	50
DATA_5_:	50
DATA_6_:	56
DATA_7_:	51
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	49
DATA_2_:	54

DATA_3_:	52
DATA_4_:	56
DATA_5_:	57
DATA_6_:	45
DATA_7_:	48
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	48
DATA_2_:	57
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.5374447
2.67.01 Check HW Part number	
Status:	Passed
Measurement:	28316489
Units:	PN
Limits:	
Low:	28316489
Comparison Type:	EQ (==)
2.67.02 Check HW Part revision	
Status:	Passed
Measurement:	9
Units:	PN
Limits:	
Low:	9
Comparison Type:	EQ (==)
2.68 Write EPS Serial Number with null	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	16

DATA_1_:	23
DATA_2_:	46
DATA_3_:	253
DATA_4_:	49
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0

DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	49
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.6363888
2.70 Read MES Counter	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	2
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	2
DATA_4_:	253
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2694542
2.71 Check MES Counter	
Status:	Passed
Measurement:	253
Units:	counter
Limits:	
Low:	40
High:	254
Comparison Type:	GELE (>= <=)
2.72 MCU Reset	

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	17
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	127
DATA_2_:	17
DATA_3_:	120
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	17
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	81
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	1.0387902
2.76 Read MES Counter	
Status:	Passed

Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	2
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	2
DATA_4_:	252
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.3519396
2.77 Check MES Counter	
Status:	Passed
Measurement:	252
Units:	counter
Limits:	
Low:	252
High:	252
Comparison Type:	GELE (>= <=)
2.78 Set Vehicle Speed Override	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	47
DATA_3_:	253
DATA_4_:	66
DATA_5_:	3
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0

LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	111
DATA_3_:	253
DATA_4_:	66
DATA_5_:	3
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0

DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.7875495
2.80 Read System State - Warm init (03)	
Status:	Passed
2.80.02 System state - Warm init (03)	
Status:	Passed
Measurement:	3
Units:	State
Limits:	
Low:	3
Comparison Type:	EQ (==)
System State:	0
2.82 Read First Motor Position	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	242
DATA_3_:	63
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	7
DATA_1_:	98
DATA_2_:	242
DATA_3_:	63
DATA_4_:	0
DATA_5_:	11
DATA_6_:	99
DATA_7_:	40
Module Time:	0.2658769
2.83 Check First Motor Position	
Status:	Passed
Measurement:	91.0986328125
Units:	degrees
Limits:	
Low:	-360
High:	360
Comparison Type:	GELE (>= <=)

End Sequence: Section 2

Section 3: Current Calibration Procedure	
Status:	Failed
Module Time:	24.3267211

Begin Sequence: Section 3**(C:\UTP\source\ProductSequences\EOL_CHMB1_Single.seq)**

3.09 Nexteer connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2643014
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
3.10 Set Manufacturing Diagnostic Defeat	
Status:	Passed
Module Time:	0.2794664
3.11 Set Motor Torque to 0Nm	
Status:	Passed
Module Time:	0.7851348
3.13 Set NMV Access Defeat	
Status:	Passed
Module Time:	0.2729954
3.14 Perform Current Calibration Offset	

Status:	Passed
Module Time:	0.2776871
X.X1 Clear NTCs	
Status:	Passed
Module Time:	0.2702681
X.X2 Enable Engine Run	
Status:	Passed
Module Time:	0.2663379
3.18 Read Current Offset Status 02	
Status:	Passed
3.19 Check Current Offset Status 02	
Status:	Passed
Measurement:	2
Units:	State
Limits:	
Low:	2
Comparison Type:	EQ (==)
2.57 Nexteer connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2747359
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
3.22 Enable Engine Run	
Status:	Passed

Module Time:	0.2742865
3.24.1 Read System State	
Status:	Passed
3.24.2 Verify System State in RUN (02)	
Status:	Passed
Measurement:	2
Units:	State
Limits:	
Low:	2
Comparison Type:	EQ (==)
System State:	0
3.30.01 Measure Total Phase Current ABC	
Status:	Passed
Measurement:	45
Units:	A
Limits:	
Low:	44.82
High:	45.18
Comparison Type:	GELE (>= <=)
Module Time:	0.0756538

2.57 Nexteer connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2671557
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0

Final Loop Index:	1
3.32 Perform Current Gain	
Status:	Passed
Module Time:	0.2785388
3.36.1 Read Gain Status	
Status:	Passed
3.36.2 Test Gain Status 02	
Status:	Passed
Measurement:	2
Units:	Status
Limits:	
Low:	2
Comparison Type:	EQ (==)
2.57 Nexteer connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2787424
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
3.42 Disable Torque Ramp Down	
Status:	Passed
Module Time:	0.2744095
3.44 Disable Engine Run	
Status:	Passed
Module Time:	0.268443

3.45 Read MES Counter	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	2
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	2
DATA_4_:	252
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2758068
3.46 Check MES Counter	
Status:	Passed
Measurement:	252
Units:	counter
Limits:	
Low:	40
High:	254
Comparison Type:	GELE (>= <=)
3.48 MCU Reset	
Status:	Passed
Module Time:	1.0330936
3.54 Measure DC Supply current	
Status:	Skipped
3.67 Nexteer Connect	
Status:	Passed
Module Time:	0.2700632
3.68 Read MEC counter	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8

DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	2
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	2
DATA_4_:	251
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2799245
3.69 Check MES Counter	
Status:	Passed
Measurement:	251
Units:	counter
Limits:	
Low:	251
High:	251
Comparison Type:	GELE (>= <=)
3.70 Set Vehicle Speed Override	
Status:	Passed
Module Time:	0.7858976
3.72 Enable Engine Run	
Status:	Passed
Module Time:	0.4223283
3.74 Read System State - RUN(2)	
Status:	Passed
3.74.2 Verify System State in RUN (02)	
Status:	Passed
Measurement:	2
Units:	Status
Limits:	
Low:	2
Comparison Type:	EQ (==)
System State:	0
3.76 Read Current Calibration Offset	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0

LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	245
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	55
DATA_2_:	98
DATA_3_:	253
DATA_4_:	245
DATA_5_:	73
DATA_6_:	20
DATA_7_:	155
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	234
DATA_2_:	189
DATA_3_:	218
DATA_4_:	131
DATA_5_:	128
DATA_6_:	189
DATA_7_:	188
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	212
DATA_2_:	176
DATA_3_:	189

DATA_4_:	168
DATA_5_:	126
DATA_6_:	160
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][6]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	36
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	63
DATA_6_:	191
DATA_7_:	132
Communication [Out][7]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	37
DATA_1_:	121
DATA_2_:	63
DATA_3_:	192
DATA_4_:	159
DATA_5_:	190
DATA_6_:	63
DATA_7_:	192
Communication [Out][8]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	38
DATA_1_:	79
DATA_2_:	190
DATA_3_:	63
DATA_4_:	192
DATA_5_:	0
DATA_6_:	0
DATA_7_:	63
Communication [Out][9]:	

ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	39
DATA_1_:	192
DATA_2_:	0
DATA_3_:	0
DATA_4_:	63
DATA_5_:	192
DATA_6_:	0
DATA_7_:	0
Module Time:	0.5663623
3.76.03 Verify Offset A	
Status:	Passed
Measurement:	1.496230244637
Units:	V
Limits:	
Low:	1.4
High:	1.6
Comparison Type:	GELE (>= <=)
3.76.04 Verify Offset B	
Status:	Passed
Measurement:	1.504874944687
Units:	V
Limits:	
Low:	1.4
High:	1.6
Comparison Type:	GELE (>= <=)
3.76.05 Verify Offset C	
Status:	Passed
Measurement:	1.502433538437
Units:	V
Limits:	
Low:	1.4
High:	1.6
Comparison Type:	GELE (>= <=)
3.78.1 Calculate absolute difference between offset1	
Status:	Passed
Measurement:	0.008644700050354
Units:	V
Limits:	
Low:	0
High:	0.15
Comparison Type:	GELE (>= <=)
3.78.2 Calculate absolute difference between offset2	
Status:	Passed
Measurement:	0.00244140625
Units:	V
Limits:	
Low:	0
High:	0.15
Comparison Type:	GELE (>= <=)

3.78.3 Calculate absolute difference between offset3	
Status:	Passed
Measurement:	0.006203293800354
Units:	V
Limits:	
Low:	0
High:	0.15
Comparison Type:	GELE (>= <=)
3.80.01 Verify Diff Volt A	
Status:	Skipped
3.80.02 Verify Diff Volt B	
Status:	Skipped
3.80.03 Verify Diff Volt C	
Status:	Skipped
3.67 Nexteer Connect	
Status:	Skipped
3.82.01 Read Gain Values	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	244
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	27
DATA_2_:	98
DATA_3_:	253
DATA_4_:	244
DATA_5_:	67
DATA_6_:	3
DATA_7_:	233
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0

DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	77
DATA_2_:	67
DATA_3_:	3
DATA_4_:	188
DATA_5_:	136
DATA_6_:	67
DATA_7_:	3
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	243
DATA_2_:	143
DATA_3_:	67
DATA_4_:	5
DATA_5_:	84
DATA_6_:	123
DATA_7_:	67
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	5
DATA_2_:	84
DATA_3_:	123
DATA_4_:	67
DATA_5_:	5
DATA_6_:	84
DATA_7_:	123
Module Time:	0.8179819
3.82.02 Verify Gain A	
Status:	Passed
Measurement:	131.9113311768
Units:	Gain
Limits:	
Low:	129
High:	143
Comparison Type:	GELE (>= <=)
3.82.03 Verify Gain B	
Status:	Passed
Measurement:	131.7364501953

Units:	Gain
Limits:	
Low:	129
High:	143
Comparison Type:	GELE (>= <=)
3.82.04 Verify Gain C	
Status:	Passed
Measurement:	131.9514007568
Units:	Gain
Limits:	
Low:	129
High:	143
Comparison Type:	GELE (>= <=)
3.67 Nexteer Connect	
Status:	Skipped
3.84 Clear Nexteer NTCs	
Status:	Passed
Module Time:	0.2692096
3.67 Nexteer Connect	
Status:	Skipped
3.86 Read Second Motor Position	
Status:	Passed
Module Time:	0.2766941
3.86 Check Second Motor Position	
Status:	Passed
Measurement:	7454.223632812
Units:	degrees
Limits:	
Low:	-360
High:	10000
Comparison Type:	GELE (>= <=)
3.88 Check difference between first and second motor positions	
Status:	Skipped

End Sequence: Section 3

Section 4: Verify SW and Cal Version Procedure	
Status:	Passed
Module Time:	3.0114969

Begin Sequence: Section 4

(C:\UTP\source\ProductSequences\EOL_CHMB1_Single.seq)

4.10 Read Software ID	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0

LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	241
DATA_3_:	148
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	19
DATA_2_:	98
DATA_3_:	241
DATA_4_:	148
DATA_5_:	83
DATA_6_:	105
DATA_7_:	110
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	103
DATA_2_:	108
DATA_3_:	80
DATA_4_:	101
DATA_5_:	112
DATA_6_:	115
DATA_7_:	72
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	119
DATA_2_:	48
DATA_3_:	48

DATA_4_:	49
DATA_5_:	66
DATA_6_:	0
DATA_7_:	0
String test data [Out]:	SinglPepsHw001
Module Time:	0.5363739
4.11 Verify Software ID	
Status:	Passed
4.12 Read Software Version	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	241
DATA_3_:	149
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	19
DATA_2_:	98
DATA_3_:	241
DATA_4_:	149
DATA_5_:	49
DATA_6_:	50
DATA_7_:	46
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33

DATA_1_:	48
DATA_2_:	56
DATA_3_:	46
DATA_4_:	48
DATA_5_:	49
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
String test data [Out]:	12.08.01
Module Time:	0.6016233
4.13 Verify Software Version	
Status:	Passed
4.14 Read Bootloader ID	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	241
DATA_3_:	240
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	19
DATA_2_:	98
DATA_3_:	241
DATA_4_:	240
DATA_5_:	83
DATA_6_:	84
DATA_7_:	76
Communication [Out][2]:	
ID:	1996

MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	65
DATA_2_:	115
DATA_3_:	95
DATA_4_:	69
DATA_5_:	80
DATA_6_:	83
DATA_7_:	65
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	70
DATA_2_:	66
DATA_3_:	76
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
String test data [Out]:	STLAs_EPSAFBL
Module Time:	0.5364414
4.15 Verify Bootloader ID	
Status:	Passed
4.16 Read Bootloader Version	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	241
DATA_3_:	241
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0

DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	19
DATA_2_:	98
DATA_3_:	241
DATA_4_:	241
DATA_5_:	48
DATA_6_:	49
DATA_7_:	32
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	48
DATA_2_:	49
DATA_3_:	32
DATA_4_:	48
DATA_5_:	48
DATA_6_:	32
DATA_7_:	32
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
String test data [Out]:	01 01 00
Module Time:	0.5382582
4.17 Verify Bootloader Version	
Status:	Passed

4.18 Calibration Number 0	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	241
DATA_3_:	242
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	98
DATA_3_:	241
DATA_4_:	242
DATA_5_:	0
DATA_6_:	0
DATA_7_:	140
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	221
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
String test data [Out]:	36061
Module Time:	0.522367

4.19 Verify Calibration Number 0	
Status:	Passed

End Sequence: Section 4

Section 5: Function Test Procedure	
Status:	Failed
Module Time:	16.7697227

Begin Sequence: Section 5 (C:\UTP\source\ProductSequences\EOL_CHMB1_Single.seq)

5.09 XCP Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	255
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	8
DATA_0_:	255
DATA_1_:	5
DATA_2_:	192
DATA_3_:	64
DATA_4_:	64
DATA_5_:	0
DATA_6_:	1
DATA_7_:	1
Module Time:	0.2765542
5.10 Read Temperature	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0

DATA_4_:	12
DATA_5_:	197
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	118
DATA_2_:	50
DATA_3_:	181
DATA_4_:	65
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2721089
5.11 Verify LimitsTemperature	
Status:	Passed
Measurement:	22.64963912964
Units:	Degrees C
Limits:	
Low:	19
High:	44
Comparison Type:	GELE (>= <=)
5.12 Read Battery Voltage	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	32
DATA_5_:	196
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	95
DATA_2_:	247
DATA_3_:	93
DATA_4_:	65
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0

Module Time:	0.2723547
5.13 Verify Limits Battery Voltage	
Status:	Passed
Measurement:	13.87289333344
Units:	V
Limits:	
Low:	13.4
High:	14.1
Comparison Type:	GELE (>= <=)
5.15 Nexteer Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2723326
5.16.1 Read Motor Angle 0	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	242
DATA_3_:	48
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0

Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	5
DATA_1_:	98
DATA_2_:	242
DATA_3_:	48
DATA_4_:	180
DATA_5_:	223
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2736231
5.16.2 Angle 0 First Position	
Status:	Passed
Measurement:	253.8541717529
Units:	degree
Limits:	
Low:	-360
High:	360
Comparison Type:	GELE (>= <=)
5.16.3 Read Motor Angle 1	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	242
DATA_3_:	49
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	5
DATA_1_:	98
DATA_2_:	242
DATA_3_:	49
DATA_4_:	116
DATA_5_:	16
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2741421
5.16.4 Angle 1 First Position	
Status:	Passed
Measurement:	162.8947296143

Units:	degree
Limits:	
Low:	-360
High:	360
Comparison Type:	GELE (>= <=)
5.18.1 Read Motor Angle 0	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	242
DATA_3_:	48
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	5
DATA_1_:	98
DATA_2_:	242
DATA_3_:	48
DATA_4_:	53
DATA_5_:	47
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2733638
5.18.2 Angle 0 Second Position	
Status:	Passed
Measurement:	74.64363861084
Units:	degree
Limits:	
Low:	-360
High:	360
Comparison Type:	GELE (>= <=)
5.18.2 Read Motor Angle 1	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	242
DATA_3_:	49

DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	5
DATA_1_:	98
DATA_2_:	242
DATA_3_:	49
DATA_4_:	244
DATA_5_:	112
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2715321
5.18.4 Angle 1 Second Position	
Status:	Passed
Measurement:	343.0701904297
Units:	degree
Limits:	
Low:	-360
High:	360
Comparison Type:	GELE (>= <=)
5.20.1 Angle difference Sensor 0	
Status:	Passed
Measurement:	179.2105331421
Units:	degrees
Limits:	
Low:	170
High:	190
Comparison Type:	GELE (>= <=)
5.20.2 Angle difference Sensor 1	
Status:	Passed
Measurement:	180.1754608154
Units:	degrees
Limits:	
Low:	170
High:	190
Comparison Type:	GELE (>= <=)
5.23 XCP Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	255
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0

DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	8
DATA_0_:	255
DATA_1_:	5
DATA_2_:	192
DATA_3_:	64
DATA_4_:	64
DATA_5_:	0
DATA_6_:	1
DATA_7_:	1
Module Time:	0.2739529
5.24 Read Motor Speed	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	224
DATA_5_:	195
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	111
DATA_2_:	191
DATA_3_:	226
DATA_4_:	66
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2779621
5.25 Verify Limits Motor Speed	
Status:	Failed
Measurement:	113.3738937378
Units:	rad/sec
Limits:	
Low:	120.43
High:	130.9

Comparison Type:	GELE (>= <=)
Motor Speed:	113.3738937378
5.15 Nexteer Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2713671
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
5.28 Start Motor Torque 0Nm	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	47
DATA_3_:	253
DATA_4_:	64
DATA_5_:	3
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0

LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	111
DATA_3_:	253
DATA_4_:	64
DATA_5_:	3
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0

DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.7885221
5.32 Measure DC Supply Current	
Status:	Passed
Measurement:	0.1413
Units:	mA
Limits:	
Low:	0.12
High:	0.2
Comparison Type:	GELE (>= <=)
Module Time:	1.0469262

5.15 Nexteer Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2742617
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
5.34 Start Motor Torque -3Nm	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996

MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	47
DATA_3_:	253
DATA_4_:	64
DATA_5_:	3
DATA_6_:	192
DATA_7_:	64
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	111
DATA_3_:	253
DATA_4_:	64
DATA_5_:	3
DATA_6_:	192
DATA_7_:	64
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	0

DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.7918654
5.23 XCP Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0
LEN:	8
DATA_0_:	255
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	8
DATA_0_:	255
DATA_1_:	5
DATA_2_:	192
DATA_3_:	64
DATA_4_:	64
DATA_5_:	0
DATA_6_:	1
DATA_7_:	1
Module Time:	0.2727148
5.38 Read Motor Current	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1966
MSGTYPE:	0

LEN:	8
DATA_0_:	244
DATA_1_:	4
DATA_2_:	0
DATA_3_:	0
DATA_4_:	168
DATA_5_:	195
DATA_6_:	190
DATA_7_:	254
Communication [Out][1]:	
ID:	1968
MSGTYPE:	12
LEN:	5
DATA_0_:	255
DATA_1_:	243
DATA_2_:	145
DATA_3_:	162
DATA_4_:	66
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2746163
5.39 Check Motor Current	
Status:	Passed
Measurement:	81.28505706787
Units:	A
Limits:	
Low:	80
High:	100
Comparison Type:	GELE (>= <=)
5.40 Measure DC Supply Current	
Status:	Passed
Measurement:	26.398
Units:	A
Limits:	
Low:	15
High:	30
Comparison Type:	GELE (>= <=)
Module Time:	0.0549045
5.53 Nexteer Connect	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0

DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2896177

5.54 Stop Motor Torque

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	47
DATA_3_:	253
DATA_4_:	64
DATA_5_:	3
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0

DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	8
DATA_2_:	111
DATA_3_:	253
DATA_4_:	64
DATA_5_:	3
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.7885338
5.58 Read System Status	
Status:	Passed

End Sequence: Section 5

Section 6: End of Line Writes, Verify Data	
Status:	Passed
Module Time:	15.9010305

Begin Sequence: Section 6
(C:\UTP\source\ProductSequences\EOL_CHMB1_Single.seq)

5.53 Nexteer Connect	

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	16
DATA_2_:	126
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	6
DATA_1_:	80
DATA_2_:	126
DATA_3_:	0
DATA_4_:	50
DATA_5_:	1
DATA_6_:	244
DATA_7_:	0
Module Time:	0.2651102
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
6.10 Read NTC Storage Array	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	96
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	103
DATA_2_:	98

DATA_3_:	253
DATA_4_:	96
DATA_5_:	0
DATA_6_:	6
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	11
DATA_2_:	56
DATA_3_:	0
DATA_4_:	176
DATA_5_:	0
DATA_6_:	10
DATA_7_:	1
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	1
DATA_2_:	36
DATA_3_:	0
DATA_4_:	11
DATA_5_:	0
DATA_6_:	1
DATA_7_:	37
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	11
DATA_3_:	0
DATA_4_:	1
DATA_5_:	64
DATA_6_:	0
DATA_7_:	11

Communication [Out][6]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	36
DATA_1_:	0
DATA_2_:	1
DATA_3_:	68
DATA_4_:	0
DATA_5_:	11
DATA_6_:	0
DATA_7_:	1
Communication [Out][7]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	37
DATA_1_:	73
DATA_2_:	0
DATA_3_:	11
DATA_4_:	0
DATA_5_:	1
DATA_6_:	80
DATA_7_:	0
Communication [Out][8]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	38
DATA_1_:	11
DATA_2_:	0
DATA_3_:	1
DATA_4_:	86
DATA_5_:	0
DATA_6_:	11
DATA_7_:	0
Communication [Out][9]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	39
DATA_1_:	1
DATA_2_:	89
DATA_3_:	0
DATA_4_:	11
DATA_5_:	0
DATA_6_:	1
DATA_7_:	96
Communication [Out][10]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	40

DATA_1_:	0
DATA_2_:	11
DATA_3_:	0
DATA_4_:	1
DATA_5_:	104
DATA_6_:	0
DATA_7_:	11
Communication [Out][11]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	41
DATA_1_:	0
DATA_2_:	1
DATA_3_:	105
DATA_4_:	0
DATA_5_:	11
DATA_6_:	0
DATA_7_:	1
Communication [Out][12]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	42
DATA_1_:	114
DATA_2_:	0
DATA_3_:	11
DATA_4_:	0
DATA_5_:	1
DATA_6_:	115
DATA_7_:	0
Communication [Out][13]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	43
DATA_1_:	11
DATA_2_:	0
DATA_3_:	1
DATA_4_:	144
DATA_5_:	0
DATA_6_:	11
DATA_7_:	24
Communication [Out][14]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	44
DATA_1_:	1
DATA_2_:	146
DATA_3_:	0
DATA_4_:	11
DATA_5_:	1

DATA_6_:	0
DATA_7_:	0
Communication [Out][15]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	45
DATA_1_:	255
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	255
DATA_7_:	0
Communication [Out][16]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	46
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	255
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.6047527
6.12 Disable Torque Ramp Down	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	1
DATA_3_:	241
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	1
DATA_3_:	241
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0

DATA_7_:	0
Module Time:	0.5111629
6.14 Disable Engine Run	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	2
DATA_3_:	241
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	2
DATA_3_:	241
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2768952
6.16 MCU Reset	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	17
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	127
DATA_2_:	17

DATA_3_:	120
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	17
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	81
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	1.0374135
6.31 Nexteer Connect	
Status:	Passed
Number of Loops:	1
Number of Passes:	1
Number of Failures:	0
Final Loop Index:	1
6.32 Read MEC counter	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	2
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	

ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	2
DATA_4_:	250
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2714842

6.34 Enable Engine Run

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	1
DATA_3_:	241
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	1
DATA_3_:	241
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2778702

6.36 Read System State

Status:	Passed
---------	--------

6.38 Read Serial Number

Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253

DATA_3_:	48
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	23
DATA_2_:	98
DATA_3_:	253
DATA_4_:	48
DATA_5_:	54
DATA_6_:	50
DATA_7_:	48
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	50
DATA_2_:	48
DATA_3_:	48
DATA_4_:	52
DATA_5_:	55
DATA_6_:	0
DATA_7_:	0
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0

Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.537239
6.39 Check Controller Serial Number	
Status:	Passed
Measurement:	62020047
Units:	SN
Limits:	
Low:	62020047
Comparison Type:	EQ (==)
6.40 Read HW part number	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	50
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	23
DATA_2_:	98
DATA_3_:	253
DATA_4_:	50
DATA_5_:	50
DATA_6_:	56
DATA_7_:	51
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48

DATA_1_:	0
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	49
DATA_2_:	54
DATA_3_:	52
DATA_4_:	56
DATA_5_:	57
DATA_6_:	45
DATA_7_:	48
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	48
DATA_2_:	57
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.6954891
6.40.01 Check HW Part number	
Status:	Passed
Measurement:	28316489
Units:	PN
Limits:	
Low:	28316489
Comparison Type:	EQ (==)
6.40.02 Check HW Part revision	

Status:	Passed
Measurement:	9
Units:	PN
Limits:	
Low:	9
Comparison Type:	EQ (==)
6.41 Read Single Inverter Hardware value	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	254
DATA_3_:	223
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	254
DATA_3_:	223
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2723709
6.41.01 Check Single Inverter Hardware value	
Status:	Passed
Measurement:	1
Units:	State
Limits:	
Low:	1
Comparison Type:	EQ (==)
6.42 Read Offset values	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	245

DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	55
DATA_2_:	98
DATA_3_:	253
DATA_4_:	245
DATA_5_:	73
DATA_6_:	20
DATA_7_:	155
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	234
DATA_2_:	189
DATA_3_:	218
DATA_4_:	131
DATA_5_:	128
DATA_6_:	189
DATA_7_:	188
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	212
DATA_2_:	176
DATA_3_:	189
DATA_4_:	168
DATA_5_:	126
DATA_6_:	160
DATA_7_:	0
Communication [Out][5]:	

ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][6]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	36
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	63
DATA_6_:	191
DATA_7_:	132
Communication [Out][7]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	37
DATA_1_:	121
DATA_2_:	63
DATA_3_:	192
DATA_4_:	159
DATA_5_:	190
DATA_6_:	63
DATA_7_:	192
Communication [Out][8]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	38
DATA_1_:	79
DATA_2_:	190
DATA_3_:	63
DATA_4_:	192
DATA_5_:	0
DATA_6_:	0
DATA_7_:	63
Communication [Out][9]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	39
DATA_1_:	192

DATA_2_:	0
DATA_3_:	0
DATA_4_:	63
DATA_5_:	192
DATA_6_:	0
DATA_7_:	0
Module Time:	0.5680981
6.42.01 Verify Offset A	
Status:	Passed
Measurement:	1.496230244637
Units:	V
Limits:	
Low:	1.496230244637
Comparison Type:	EQ (==)
6.42.02 Verify Offset B	
Status:	Passed
Measurement:	1.504874944687
Units:	V
Limits:	
Low:	1.504874944687
Comparison Type:	EQ (==)
6.42.03 Verify Offset C	
Status:	Passed
Measurement:	1.502433538437
Units:	V
Limits:	
Low:	1.502433538437
Comparison Type:	EQ (==)
6.44.01 Verify Diff Volt A	
Status:	Passed
Measurement:	0.01449358463287
Units:	V
Limits:	
Low:	0.01449358463287
Comparison Type:	EQ (==)
6.44.02 Verify Diff Volt B	
Status:	Passed
Measurement:	0.009929776191711
Units:	V
Limits:	
Low:	0.009929776191711
Comparison Type:	EQ (==)
6.44.03 Verify Diff Volt C	
Status:	Passed
Measurement:	0.02442336082458
Units:	V
Limits:	
Low:	0.02442336082458
Comparison Type:	EQ (==)
6.46.00 Read Gain Values	
Status:	Passed

Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	244
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	27
DATA_2_:	98
DATA_3_:	253
DATA_4_:	244
DATA_5_:	67
DATA_6_:	3
DATA_7_:	233
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	8
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	77
DATA_2_:	67
DATA_3_:	3
DATA_4_:	188
DATA_5_:	136
DATA_6_:	67
DATA_7_:	3
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8

DATA_0_:	34
DATA_1_:	243
DATA_2_:	143
DATA_3_:	67
DATA_4_:	5
DATA_5_:	84
DATA_6_:	123
DATA_7_:	67
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	5
DATA_2_:	84
DATA_3_:	123
DATA_4_:	67
DATA_5_:	5
DATA_6_:	84
DATA_7_:	123
Module Time:	0.8521223
6.46.01 Verify Gain A	
Status:	Passed
Measurement:	131.9113311768
Units:	gain
Limits:	
Low:	131.9113311768
Comparison Type:	EQ (==)
6.46.02 Verify Gain B	
Status:	Passed
Measurement:	131.7364501953
Units:	gain
Limits:	
Low:	131.7364501953
Comparison Type:	EQ (==)
6.46.03 Verify Gain C	
Status:	Passed
Measurement:	131.9514007568
Units:	gain
Limits:	
Low:	131.9514007568
Comparison Type:	EQ (==)
6.48 Read Polarity	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253

DATA_3_:	3
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	7
DATA_1_:	98
DATA_2_:	253
DATA_3_:	3
DATA_4_:	1
DATA_5_:	24
DATA_6_:	16
DATA_7_:	0
Module Time:	0.2729587
6.49 Verify Polarity	
Status:	Passed
Measurement:	1181000
Units:	Polarity
Limits:	
Low:	1181000
Comparison Type:	EQ (==)
6.50 Read NTC	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	96
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	16
DATA_1_:	103
DATA_2_:	98
DATA_3_:	253
DATA_4_:	96
DATA_5_:	0
DATA_6_:	6
DATA_7_:	0

Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	48
DATA_1_:	0
DATA_2_:	10
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	33
DATA_1_:	11
DATA_2_:	56
DATA_3_:	1
DATA_4_:	36
DATA_5_:	0
DATA_6_:	11
DATA_7_:	0
Communication [Out][4]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	34
DATA_1_:	1
DATA_2_:	37
DATA_3_:	0
DATA_4_:	11
DATA_5_:	0
DATA_6_:	1
DATA_7_:	64
Communication [Out][5]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	35
DATA_1_:	0
DATA_2_:	11
DATA_3_:	0
DATA_4_:	1
DATA_5_:	68
DATA_6_:	0
DATA_7_:	11
Communication [Out][6]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	36

DATA_1_:	0
DATA_2_:	1
DATA_3_:	73
DATA_4_:	0
DATA_5_:	11
DATA_6_:	0
DATA_7_:	1
Communication [Out][7]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	37
DATA_1_:	80
DATA_2_:	0
DATA_3_:	11
DATA_4_:	0
DATA_5_:	1
DATA_6_:	86
DATA_7_:	0
Communication [Out][8]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	38
DATA_1_:	11
DATA_2_:	0
DATA_3_:	1
DATA_4_:	89
DATA_5_:	0
DATA_6_:	11
DATA_7_:	0
Communication [Out][9]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	39
DATA_1_:	1
DATA_2_:	104
DATA_3_:	0
DATA_4_:	11
DATA_5_:	0
DATA_6_:	1
DATA_7_:	105
Communication [Out][10]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	40
DATA_1_:	0
DATA_2_:	11
DATA_3_:	0
DATA_4_:	1
DATA_5_:	114

DATA_6_:	0
DATA_7_:	11
Communication [Out][11]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	41
DATA_1_:	0
DATA_2_:	1
DATA_3_:	115
DATA_4_:	0
DATA_5_:	11
DATA_6_:	0
DATA_7_:	1
Communication [Out][12]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	42
DATA_1_:	144
DATA_2_:	0
DATA_3_:	11
DATA_4_:	24
DATA_5_:	1
DATA_6_:	146
DATA_7_:	0
Communication [Out][13]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	43
DATA_1_:	11
DATA_2_:	1
DATA_3_:	0
DATA_4_:	176
DATA_5_:	1
DATA_6_:	8
DATA_7_:	0
Communication [Out][14]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	44
DATA_1_:	1
DATA_2_:	96
DATA_3_:	1
DATA_4_:	73
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][15]:	
ID:	1997
MSGTYPE:	0

LEN:	8
DATA_0_:	45
DATA_1_:	255
DATA_2_:	0
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	255
DATA_7_:	0
Communication [Out][16]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	46
DATA_1_:	0
DATA_2_:	0
DATA_3_:	0
DATA_4_:	255
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.6025343
6.52 Clear Nexteer NTCs	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	1
DATA_3_:	253
DATA_4_:	112
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	1
DATA_3_:	253
DATA_4_:	112
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2623605
6.54 Write MEC Counter FE	
Status:	Passed

Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	46
DATA_2_:	253
DATA_3_:	2
DATA_4_:	254
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	110
DATA_2_:	253
DATA_3_:	2
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2816143
6.55 Read MEC Counter FE	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	34
DATA_2_:	253
DATA_3_:	2
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	98
DATA_2_:	253
DATA_3_:	2
DATA_4_:	254
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0

Module Time:	0.2699055
6.55 Check MEC Counter FE	
Status:	Passed
Measurement:	254
Units:	Counter
Limits:	
Low:	254
Comparison Type:	EQ (==)
6.31 Nexteer Connect	
Status:	Skipped
6.56 Write Toque Trim T1	
Status:	Skipped
6.57 Write Toque Trim T2	
Status:	Skipped
6.58 Disable Torque Ramp Down	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49
DATA_2_:	1
DATA_3_:	241
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	1
DATA_3_:	241
DATA_4_:	1
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2752817
6.60 Diable Engine Run	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	49

DATA_2_:	2
DATA_3_:	241
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	4
DATA_1_:	113
DATA_2_:	2
DATA_3_:	241
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	0.2708546
6.64 MCU Reset	
Status:	Passed
Communication [Out]:	
Communication [Out][0]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	17
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][1]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	3
DATA_1_:	127
DATA_2_:	17
DATA_3_:	120
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][2]:	
ID:	1996
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	17
DATA_2_:	96

DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Communication [Out][3]:	
ID:	1997
MSGTYPE:	0
LEN:	8
DATA_0_:	2
DATA_1_:	81
DATA_2_:	96
DATA_3_:	0
DATA_4_:	0
DATA_5_:	0
DATA_6_:	0
DATA_7_:	0
Module Time:	1.0367434
6.70 Measure voltage across Rq for Ignition Off current measurement	
Status:	Skipped
6.88 Measure voltage across DC Supply + and - terminals	
Status:	Passed
Measurement:	0.729
Units:	V
Limits:	
Low:	0.001
High:	3
Comparison Type:	GELE (>= <=)
Module Time:	1.0383205

End Sequence: Section 6

Failure Procedure	
Status:	Skipped
Test Cleanup	
Status:	Passed
Module Time:	4.2675741

End Sequence: MainSequence

End UUT Report
