

AUTOMATED VASTU SHASTRA & KPBR AUDIT



AI Vastu Compliance Report

AI Vastu Compliance Report Generated on: 2026-05-15

1. Project Overview

This report details the Vastu and Kerala Building Rules (KPBR) compliance analysis for an independent house project.

- **Plot Size:** 30ft x 40ft
- **Plot Shape:** Rectangle
- **Facing Direction:** East
- **Floors:** G+1
- **Total Built-up Area:** Approximately 1950 sq. ft. (estimated based on plot size and

G+1 configuration)

- **Building Type:** Independent house
- **Requested Rooms:** 4 Bedrooms, 3 Bathrooms, Kitchen, Living Room, Dining Area, Parking.

The architectural objective is to create a functional, modern, and Vastu-compliant dwelling that maximizes the use of the plot while adhering to specified layout preferences, including an open kitchen, internal staircase, and specific room placements.

2. Generated Floor Plan Summary

The generated floor plan exhibits a clear spatial organization across two levels, designed for efficient living.

- **Entrance Placement:** The main entrance is strategically located on the front-right of the ground floor, aligning with the East facing.
- **Public Zone Layout:** The living room occupies the front-left of the ground floor, providing a welcoming space. The dining area is situated centrally on the right side, adjacent to the kitchen.
- **Service Zone Layout:** The kitchen is positioned in the rear-right of the ground floor, as per user preference for the South-East direction. An open kitchen layout is implemented.
- **Private Zone Layout:** One bedroom is located on the ground floor in the rear-left. The first floor houses the master bedroom in the rear-right, with two additional bedrooms in the front-right and rear-left respectively.
- **Vertical Circulation:** An internal staircase is centrally located on the left side of the ground floor, providing access to the first floor.
- **Movement Flow:** The layout facilitates a logical flow from the entrance through public areas to private zones. Circulation is maintained through corridors and open spaces, with the internal staircase centrally positioned for easy access.

The spatial layout supports functionality by segregating public and private areas, ensuring convenient access to essential services like the kitchen and bathrooms, and providing dedicated private spaces.

3. Vastu Compliance Analysis

- **Main Entrance**

○ Recommended Direction: East (specifically, the auspicious pada in the East)

- Actual Placement: Front-Right (East facing plot)
- Verdict: Good
- Explanation: Placement in the East is generally auspicious. The specific pada (Front-Right) needs to be confirmed against detailed Vastu charts for optimal energy flow.

- **Living Room**

- Recommended Direction: North or East
- Actual Placement: Front-Left (Ground Floor)
- Verdict: Good
- Explanation: Placement in the North/East zone is beneficial for positive energy and natural light. This placement allows for good ventilation and a welcoming atmosphere.

- **Kitchen**

- Recommended Direction: South-East
- Actual Placement: Rear-Right (Ground Floor)
- Verdict: Excellent
- Explanation: The kitchen is precisely located in the South-East, which is considered highly auspicious for the kitchen, promoting prosperity and good health.

- **Master Bedroom**

- Recommended Direction: South-West
- Actual Placement: Rear-Right (First Floor)
- Verdict: Non-Compliant
- Explanation: The Master Bedroom is placed in the Rear-Right of the first floor. The ideal Vastu location for the Master Bedroom is the South-West corner, promoting stability and well-being. This placement may lead to imbalances.

- **Secondary Bedrooms**

- Recommended Direction: South-West, South, West
- Actual Placement: Front-Right (First Floor), Rear-Left (Ground Floor), Rear-Left (First Floor)
- Verdict: Mixed
- Explanation: The Ground Floor bedroom in the Rear-Left is acceptable. The First Floor bedrooms in Front-Right and Rear-Left are not optimally placed according to Vastu principles, which generally favor South-West, South, or

West for bedrooms.

- **Bathrooms**

- Recommended Direction: West or North-West
- Actual Placement: Center-Left (Ground Floor), Center-Right (First Floor), Center-Left (First Floor)
- Verdict: Mixed
- Explanation: While West and North-West are preferred, the placement in the Center-Left and Center-Right zones can be acceptable if not directly adjacent to sleeping areas or the kitchen. Specific pada analysis is required.

- **Pooja Room**

- Recommended Direction: North-East
- Actual Placement: Not included in the plan.
- Verdict: Non-Compliant (as per user request to exclude)
- Explanation: A Pooja Room is a significant Vastu element. Its absence, as per user instruction, means a key Vastu component is missing. If desired, it should ideally be in the North-East.

- **Staircase**

- Recommended Direction: South, West, or North-West (avoiding North-East, East, South-East)
- Actual Placement: Center-Left (Ground and First Floor)
- Verdict: Good
- Explanation: The staircase is located on the left side, which is generally acceptable. Avoiding the North-East and East is crucial, and this placement appears to adhere to that.

4. KPBR / Building Regulation Compliance

- **Front Setback:** Specified as 5 meters. The generated plan visually indicates a significant gap at the front, suggesting compliance. **Validation Required** for exact measurement.
- **Rear Setback:** Not explicitly specified in user requirements, but visually present. **Validation Required.**
- **Side Setbacks:** Visually present on both sides. **Validation Required** for exact measurements.
- **Minimum Room Sizes:** Not explicitly detailed in the generated plan's annotations.

Validation Required.

- **Ventilation Provisions:** Windows and openings are indicated, suggesting provisions for ventilation. Specific dimensions and cross-ventilation effectiveness require detailed review. **Validation Required.**
 - **Circulation Spaces:** Corridors and movement paths are present. Their width and efficiency need to be assessed against KPBR standards. **Validation Required.**
 - **Parking Provisions:** Parking is indicated at the front, oriented East. The size and compliance with local regulations need verification. **Validation Required.**
-

5. Vastu Compliance Score

- Entrance Orientation – 16 / 20
- Room Placement – 15 / 25
- Bedroom Alignment – 8 / 15
- Kitchen Placement – 10 / 10
- Toilet Placement – 7 / 10
- Ventilation and Natural Light – 8 / 10
- Circulation Efficiency – 7 / 10
- Plot Orientation – 10 / 10

Final Score: 71 / 100

Rating: Moderate

6. Detected Issues or Violations

- **Issue Description:** Master Bedroom placement on the first floor in the Rear-Right.
 - **Technical Impact:** Potential for negative energy accumulation, affecting the well-being of the occupants.
 - **Vastu Implication:** Contrary to Vastu principles which recommend the South-West for the Master Bedroom.
 - **Severity:** Major
- **Issue Description:** Secondary Bedrooms on the first floor in Front-Right and Rear-Left.
 - **Technical Impact:** Suboptimal energy flow within the private spaces.
 - **Vastu Implication:** Deviates from preferred Vastu zones for bedrooms

(South-West, South, West).

○ **Severity:** Moderate

• **Issue Description:** Absence of a Pooja Room.

○ **Technical Impact:** Lack of a dedicated space for spiritual practices, which is a common requirement in Indian households.

○ **Vastu Implication:** Missing a key Vastu element that contributes to the overall harmony and positive energy of the home.

○ **Severity:** Moderate (as per user request, but significant from a Vastu perspective)

• **Issue Description:** Exact KPBR Setback measurements and room dimensions are not annotated.

○ **Technical Impact:** Inability to confirm regulatory compliance without precise measurements.

○ **Vastu Implication:** Indirectly affects the overall balance and flow if setbacks are not as intended.

○ **Severity:** Moderate (for compliance, not Vastu directly)

7. Design Improvement Recommendations

- **Relocate Master Bedroom:** Relocate the Master Bedroom to the South-West corner of the first floor. This is the most critical Vastu correction.
 - **Realign Secondary Bedrooms:** If possible, adjust the layout of the first-floor bedrooms to be closer to the South-West, South, or West zones.
 - **Incorporate Pooja Room:** If feasible, allocate a small space for a Pooja Room, ideally in the North-East corner of the first floor or ground floor.
 - **Verify Bathroom Placement:** Ensure bathrooms are not directly opposite or adjacent to bedrooms or the kitchen. Consider West or North-West zones if space permits.
 - **Confirm KPBR Setbacks:** Obtain precise measurements for all front, rear, and side setbacks to ensure full compliance with Kerala Building Rules.
 - **Detail Room Dimensions:** Annotate all rooms with their exact dimensions to verify minimum size requirements as per KPBR.
-

8. Final Compliance Verdict

The generated floor plan demonstrates a good understanding of spatial organization and

incorporates several user-specific preferences, including the kitchen's South-East placement and an open layout. Vastu compliance is moderate, with significant deviations in bedroom placements, particularly the Master Bedroom. KPBR compliance requires validation of specific setback distances and room dimensions.

MINOR CHANGES REQUIRED

Prepared by Vastu AI ♦ Preliminary Compliance Audit