



05/12/2020

NYC Department of Buildings 280 Broadway New York, NY 10007

Attn: Elevator Division

RE: 310 West 75th Street

Category One Test Device #: 1P29777

ToWhom It May Concern:

Please be advised that all the necessary work has been completed in accordance with the Category One Test as follows:

2019 CAT1 1P29777

S.No	REMEDY	CONDITION	PART	NOTES
1	02-Clean	O-Dirty	39-Car Top	Car top cleaned
2	02-Clean	O-Dirty	34- Hoistway	Hoistway cleaned
3	07-Provide	M-Missing	52-Hoistway Cables	Data tag
4	07-Provide	M-Missing	53-Governor Ropes	Data tag
5	07-Provide	M-Missing	26-Top Emergency Cover	Safety chain

Please find atatched the ELV-29 form properly filled out, signed and notarized. Should further information be required, please contact us.

Sincerely,

Richard T. L'Esperance

Director Lic: 249-018 Agency: 055779

State of New York, County of Queens
Sworn to or affirmed under penalty of perjury, before me this _______, 20_____

Notary Public Signature

CAN 110