

1 Highlights

2 **Soil-geomorphic impact on berm structural condition and vegetation response in the** 3 **US Southwest**

- 4 • Across the US Southwest, water spreader and contour berms were originally constructed to

5 capture hillslope runoff and increase infiltration upslope
- 6 • Remote sensing and soil survey data are used to quantify soil-geomorphic impacts on berms

7 and vegetation responses in the Altar Valley, southern Arizona
- 8 • Landform, parent material, and soil development interact to influence berm structural condi-

9 tion and impact on surrounding vegetation

10 Soil-geomorphic impact on berm structural condition and vegetation
11 response in the US Southwest

12 **Abstract**

13 Earthen berms are commonly used on rangelands in the southwestern United States to control water
14 runoff, increase soil moisture, and reduce soil erosion. *legacy berms, ubiquitous. Their impact on sur-*
15 *rounding vegetation, stability, and ecohydrologic impact is highly variable.* However, the effectiveness
16 and stability of these berms are influenced by various environmental factors, including geomorphic
17 position, soil properties, and vegetation. This study investigates the structural condition (intact,
18 breached, or flanked) and impact on surrounding vegetation greenness (measured by a SAVI-derived
19 vegetation index) of 550 water spreader berms across the Altar Valley, southern Arizona. We exam-
20 ine how berm structural condition and vegetation greenness relate to landscape features, including
21 landform, parent material, soil development, and berm and surface morphology. Our results suggest
22 that berms on fan terraces exhibit greater stability and enhanced upslope vegetation greenness. In
23 contrast, berms on flood plains exhibit a higher failure incidence and smaller upslope–downslope
24 differences in vegetation greenness. Berms on stream terraces exhibit intermediate characteristics,
25 reflecting their transitional geomorphic and soil development status between fan terraces and flood-
26 plains. Furthermore, factors such as parent material, surface slope, and berm length significantly
27 affect berm structural condition and vegetation response. These findings highlight the importance of
28 incorporating site-specific landscape features when planning and managing berms for erosion control
29 and vegetation restoration in semi-arid regions.

*The ave and intended purpose of these structures is often unknown. Questions – soil development,
landform stability.*

30 **Keywords:** Water spreader and contour berms, fan terrace–stream terrace–floodplain catena, berm
31 upslope–downslope vegetation patterns, landscape management

Plain language summary

Earthworks such as berms are used across rangelands in the southwestern United States to help control water runoff and prevent soil erosion. In particular, water spreader berms work by slowing down rainwater, allowing it to soak into the ground, which helps improve soil moisture and supports vegetation growth. However, over time, berms can degrade, potentially reducing their effectiveness. In this study, we looked at how different environmental factors, such soil type, slope, and landform, affect how berms function and whether they remain intact (and how they impact vegetation in their vicinity).

We studied 550 berms in the Altar Valley, Arizona, and measured their impact on nearby vegetation using a satellite-based method called the Soil Adjusted Vegetation Index (SAVI). We found that berms built on fan terraces and in areas with stronger, more developed soils were more likely to stay intact and led to increased vegetation growth upslope of the berms. In contrast, berms on floodplains, where soils are less developed and more prone to erosion, were more likely to fail and showed little difference in berm upslope-downslope vegetation. Stream terraces showed intermediate results, acting like a transition zone.

Other factors, like the type of parent material, the steepness of the slope, and the length of the berm, also played a role in how likely a berm was to fail and how much it helped vegetation.

This study helps us understand which conditions make berms more effective and long-lasting. It also shows that considering the specific characteristics of the landscape can help land managers make better decisions about where to place and maintain berms for erosion control and vegetation growth in dryland areas.

1. Introduction

Include more historic context here.

Earthworks, including water spreader berms, contour berms, and erosion control berms, are ubiquitous across southwestern US rangelands. Historically, these structures were built to control surface runoff and eroding soil. Because most surface runoff in this region is generated in response to high intensity rainfall, flash floods are common. Earthen berms constructed perpendicular to the flow

direction reduce flow velocities allowing time for runoff to infiltrate and increase soil moisture, which is critical for supporting vegetation. In addition, earthen berms can capture sediment and prevent runoff from causing gully erosion. Because of their influence on water distribution and sediment movement, earthworks were often integral components of efforts to restore degraded rangelands.

Earthen berms are subject to failure over time. Many rangeland berms have been breached (a break through a berm) or flanked (concentrated runoff around the end of a berm). Recent research has focused on the impacts of rangeland berms on geomorphic evolution (Nichols et al., 2022) and the ecological impact of berms on vegetation patterns (Crompton et al. 2025, demonstrated impacts of berms on vegetation). There has been little attention in the literature on the relation of berm condition and vegetation impacts influenced by watershed physical properties such as geomorphic position, soils, and local topography.

To address outstanding gaps in knowledge, this work examines the condition of water and erosion control structures and their impact on vegetation in their vicinity. Specifically, the study focuses on the prediction of berm structural condition (intact, breached, or flanked) and vegetation response as a function of landform, parent material, and soil information, LiDAR-derived surface morphology, and other land use/land cover and berm features. Vegetation response is characterized using the Soil Adjusted Vegetation Index (SAVI), a vegetation index similar to NDVI adjusted for bright soils typical of desert environments. In particular, we use the difference in SAVI between the areas immediately upslope and downslope of berms, within 60 m, normalized by background conditions (ΔS). (difference between upslope and downslope vegetation greenness) The ability to predict berm structural condition and vegetation response as a function of site-specific physical properties will allow land managers to understand the likely evolution of vegetation patterns and identify those locations where berms are at higher risk for failure.

2. Methods

We examine how berm structural condition (e.g., intact, breach, flank) and vegetation response vary depending on landform, parent material, soil properties, berm length, and LiDAR-derived surface slope.

2.1. Site description: Altar Valley

In this study, we focus on water spreader berms that were originally constructed to capture hillslope runoff and increase infiltration upslope from these structures. We use an inventory of mapped berm locations ($n = 550$) in the Altar Valley, a semi-arid, 247,000 ha watershed in southern Arizona, USA [1] (see Figure 1). This dataset classifies berms as intact, breached, or flanked, using a combination of Google Earth Imagery and aerial LiDAR data (2011 and 2016; Pima County Regional Flood Control District) [2].

Berm structural condition was obtained from Nichols and Degginger [1]. Nichols and Degginger [1] includes berm type, structural condition (intact/degraded), and berm length.

TODO design specifications – flood plain berms typically constructed for flood control, not water spreading. Consider berms adjacent to and far from channel network (delineated by...).

2.2. Data

Topography

Two 1/3 arc-second USGS National Map DEM GeoTIFF tiles were downloaded from the USGS National Map Downloader and processed in ArcGIS Pro 3.3.1. The tiles were mosaicked into a single elevation raster (Mosaic to New Raster) and clipped to the dissolved boundary of the Brawley Wash and Río de la Concepción HUC8 watersheds (Clip Raster). To generate flow accumulation, the clipped DEM was hydrologically conditioned using the Fill tool (Spatial Analyst) to remove sinks. Flow direction was then computed from the filled DEM using the D8 algorithm (Flow Direction). Finally, Flow Accumulation was calculated from the D8 flow-direction raster (output data type: Float; input flow direction type: D8) and exported as a GeoTIFF.

NCRS soils data

Landform, parent material, and soil development at each berm location were obtained / for the stud area – were obtained from USDA Natural Resources Conservation Service (NRCS) soil survey data – provide inputs for understanding berm structural condition and vegetation patterns. Landform information provides insights into the topographical and geomorphological context of a site, influencing water flow, erosion potential, and sediment deposition, all of which directly affect berm stability and surrounding vegetation. Parent material, representing the geological substrate,

determining the physical and chemical properties of the soil, including texture, drainage capacity, and susceptibility to erosion—factors that impact berm integrity over time. Soil development reflects the degree of soil maturity and horizon differentiation, and captures processes like organic matter accumulation, nutrient cycling, and structural stability, further influencing berm efficacy in retaining water and mitigating sediment loss. Citations needed...

Includes soil texture, profile, soil organic carbon, landform. Something about accuracy.

Parent material was categorized into three types: (1) moderately fine textured alluvium, moderately coarse textured alluvium; (2) mixed alluvium; and (3) alluvium derived from granite and/or schist, mixed alluvium.

For purpose of interpretation/hypothesis testing... Landform simplified to three categories (flood plains, stream terraces, fan terraces). Parent material grouped into three categories: moderately fine/coarse textured alluvium, mixed alluvium, or alluvium derived from granite and/or schist, mixed alluvium.

Berm locations occurring on three landform types: flood plains, stream terraces, and fan terraces, hills. *Many landform types in the Altar Valley. we grouped these into three broader categories aligned with most common landform types.*

To intro – We hypothesize that berm structural condition and vegetation response to berms are related to/depend on watershed physical features. Local (soil texture), landscape scale (geomorphology, landform, flow accumulation)

Berm structural condition is described as 1 of 3 categories (*intact, breached, or flanked*). Breached and flanked combined, intact or degraded.

2.3. Vegetation response

Sentinel-2 data products (10 m resolution; 2016-2024; [3]) were used to compute Soil Adjusted Vegetation Index (SAVI), derived metrics of berm impact on surrounding vegetation. First, SAVI was computed as:

$$S = \frac{(NIR - RED)}{(NIR + RED + L)} \times (1 + L) \quad (1)$$

where S represents SAVI, NIR is the near-infrared reflectance, RED is the red reflectance, and L

Table 1: Variable categories and corresponding number of berms (N).

Variable	Category	N
<i>Response variables</i>		
Berm structural condition	Intact	291
	Breached	88
	Flanked	155
Berm ΔS	$\leq 10\%$	290
	$> 10\%$	244
<i>Predictor variables</i>		
Landform	Flood plains	172
	Stream terraces	137
	Fan terraces, hills	158
Parent material	Moderately fine textured alluvium,	116
	Moderately coarse textured alluvium	
	Mixed alluvium	229
	Alluvium derived from granite and/or schist, Mixed alluvium	122
Clay content	$\leq 25\%$	305
	$> 25\%$	229
Sand content	$\leq 50\%$	247
	$> 50\%$	287
Typical profile	Weak soil development	296
	Strong soil development	171
Berm length	≤ 50 m	210
	> 50 m	324
Slope	$\leq 2\%$	271
	$> 2\%$	263

is the soil brightness correction factor (typically set to 0.5) (add citation). Following the approach outlined in Crompton et al., 2025, we quantified the difference in vegetation activity between the areas immediately upslope (15–60 m) and downslope (15–60 m) of berms (compared to areas without berms). *Summarize findings in Crompton et al., namely, distance of greatest effect size over ~ 15 -60 m, within 60 m of berm, and impact is greatest in August/September.*

To evaluate the differences between upslope and downslope areas, we calculated the percent change in SAVI as follows:

$$\Delta S(UD_{L,m,j}) = \frac{S(U_{L,m,j}) - S(D_{L,m,j})}{S(B_{m,j})} \times 100 \quad (2)$$

where $\Delta S(UD_{L,m,j})$ is the percent difference in SAVI, $S(U_{L,m,j})$ represents the SAVI value in the upslope area, $S(D_{L,m,j})$ denotes the SAVI value in the downslope area, and $S(B_{m,j})$ is the SAVI value of a background area without berms. For each berm, we computed the monthly median SAVI for Augusts and Septembers across 2016-2024, yielding: $S(U_{L,m,j})$, $S(D_{L,m,j})$, and $S(B_{m,j})$, where

151 L represents the assessment length, m the month, and j the berm location. For example, $S(U_{45,m,j})$
152 is the monthly median SAVI 15–60 m upslope over Augusts and Septembers of 2016-2024 for the
153 j th berm. To simplify interpretation, we use percent difference since typical SAVI values are small
154 and range from 0.05 to 0.2 in the Altar Valley (Crompton et al., 2024).

155 *Models*

156 Fit random forest and logistics regression... other approaches. Model selection by CV-AUC –
157 explain –

158 Models fit with all variables, and for interpretability, subset of best three predictors (difference
159 in performance is minimal).

160 *Simplifications/hypothesis testing*

161 For each berm, local clay content, sand content, status of soil profile development, berm length,
162 and local topographic slope were binarized, as summarized in Table 1. Justification, how variables
163 were binarized, sensitivity analyses.

164 Pairwise χ^2 tests were performed between all categorical pairs to explore relationships. A Bon-
165 ferroni correction was applied to adjust p -values for multiple comparisons (add citation).

166 *2.4. Landscape variables*

167 Soil development was defined as ‘weak if the typical soil profile consisted of an A-C horizon,
168 reflecting limited horizon differentiation and minimal soil-forming processes. In contrast, soil de-
169 velopment was categorized as ‘strong if the typical profile contained a Bt or Bk horizon, indicating
170 illuvial accumulation of silicate clays (‘t) and/or pedogenic carbonate (‘k). These distinctions reflect
171 variations in soil structure, nutrient retention, and water infiltration, which may influence surround-
172 ing vegetation and berm structural condition. In addition, surface clay and sand content (Hengl,
173 2018), berm length [1], and surface slope provide ancillary information as predictor variables.

3. Results

3.1. Controls on berm structural condition

A balanced comparison of berm structural condition between stable and unstable landforms, stratified by parent material composition and cohesion, showed marked differences in the performance of berms. For stable landforms (fan terraces and stream terraces), 13% of berms were breached, 37% were flanked, and 49% remained intact. In contrast, unstable landforms (flood plains) exhibited higher breach rates, with 24% of berms breached, 20% flanked, and 56% intact. The difference between stable and unstable landforms was statistically significant, with a chi-square value of $\chi^2 = 14.23$ and a p-value of 0.0008, highlighting the impact of landform stability on berm structural condition.

When examining berm structural condition by parent material composition and cohesion, further contrasts were observed. For homogeneous/weakly cohesive parent materials, berms on stable landforms (fan terraces and stream terraces) had 15% breaches, 47% flanks, and 38% intact, while berms on unstable landforms (flood plains) had 28% breaches, 14% flanks, and 58% intact. The difference in performance between stable and unstable landforms was highly significant, with a chi-square value of $\chi^2 = 31.31$ and a p-value of < 0.0001 , indicating that landform stability plays a major role in berm structural condition when using homogeneous/weakly cohesive materials (Table ??).

For heterogeneous/strongly cohesive parent materials, berms on stable landforms had 11% breaches, 16% flanks, and 73% intact, while berms on unstable landforms had 14% breaches, 34% flanks, and 52% intact. The difference between stable and unstable landforms in this category was not statistically significant, as evidenced by a chi-square value of $\chi^2 = 5.91$ and a p-value of 0.0520, suggesting a weaker impact of landform stability on berm structural condition when cohesive materials are used (Table ??).

Slope class also played a significant role in berm structural condition. For shallow slopes ($\leq 2\%$), berms on stable fan terraces and stream terraces exhibited 11% breaches, 23% flanks, and 65% intact, while unstable flood plains on shallow slopes showed a higher proportion of breached berms at 27%, with 19% flanked and 54% intact. A chi-square test yielded a value of $\chi^2 = 11.14$ and a p-value of 0.0038, indicating that berms on shallow slopes on stable landforms perform significantly better than

those on unstable landforms. On steep slopes ($> 2\%$), the performance of berms was less distinct, with stable landforms exhibiting 16% breaches, 40% flanks, and 44% intact, while unstable flood plains had 12% breaches, 26% flanks, and 63% intact. The difference in berm structural condition on steep slopes was not statistically significant, with a chi-square value of $\chi^2 = 3.01$ and a p-value of 0.2220 (Table ??).

The comparison of berm structural condition between parent material cohesion classes stratified by slope class again revealed distinct differences in performance. On shallow slopes, berms constructed on homogeneous/weakly cohesive materials showed 29% breaches, 16% flanks, and 55% intact, while berms on heterogeneous/strongly cohesive materials had 12% breaches, 23% flanks, and 64% intact. A chi-square value of $\chi^2 = 9.67$ and a p-value of 0.0080 confirmed that berms on heterogeneous/strongly cohesive materials performed significantly better than those on homogeneous/weakly cohesive materials. On steep slopes, berm structural condition was also distinct, with berms on homogeneous/weakly cohesive materials showing 8% breaches, 47% flanks, and 46% intact, while those on heterogeneous/strongly cohesive materials exhibited 14% breaches, 27% flanks, and 59% intact. The chi-square test for steep slopes produced a value of $\chi^2 = 7.34$ and a p-value of 0.0254, further suggesting the impact of cohesive material in stabilizing berms in steeper terrains (Table ??).

Finally, when stratified by soil development class, berm structural condition continued to show differences based on the composition and cohesiveness of the parent material. On weak soil development sites, berms on homogeneous/weakly cohesive materials exhibited 28% breaches, 14% flanks, and 58% intact, while berms on heterogeneous/strongly cohesive materials showed 9% breaches, 25% flanks, and 66% intact. A chi-square value of $\chi^2 = 15.32$ and a p-value of 0.0005 indicated that berms on heterogeneous/strongly cohesive materials performed significantly better on weakly developed soils. In contrast, on strong soil development sites, berms on homogeneous/weakly cohesive materials had 16% breaches, 43% flanks, and 41% intact, while those on heterogeneous/strongly cohesive materials had 10% breaches, 33% flanks, and 57% intact. The chi-square test for strong soil development sites produced a value of $\chi^2 = 2.70$ and a p-value of 0.2591, suggesting no significant difference between material types on strongly developed soils.

Strategic placement of berms on heterogeneous and cohesive, well-developed soils on stable, gently

sloping landforms can significantly reduce the likelihood of breaching and flanking and enhance long-term performance.

3.2. Controls on vegetation response

4. Discussion

Table 2: Deviations from ideal conditions for berm structural stability, and associated berm structural outcomes

Category	Ideal condition	Change	Structural outcome
Landform	Stable surface (e.g., older fan terrace or older stream terrace)	To flood plain	More breaching, due to pooling, saturation slumping, and/or rill and gully formation on the berm slope
		To steep fan terrace	More flanking, due to lateral flow
Parent material	Heterogeneous/cohesive (e.g., mixed alluvium)	To unconsolidated fine textured alluvium or granite-schist alluvium	More breaching and flanking, due to more homogeneous and less cohesive material
Soil development	Well-developed profile (e.g., Bt and/or Bk horizons)	To weakly developed soils (e.g., A-C profiles)	More breaching and flanking, due to a less stable surface and more easily erodible soils
Berm length	Shorter berms (≤ 50 m)	Increase berm length	More breaching and flanking, due to greater stress and flow concentration
Slope	Shallow slope ($\leq 2\%$)	Increase slope	More breaching and flanking, due to higher runoff energy

This study demonstrates that berm structural condition and vegetation response are shaped by a range of site-specific geomorphic and environmental factors, but these two outcomes are not always directly aligned. While berms in certain settings remain structurally intact, they do not always yield strong vegetation responses, and vice versa. This decoupling underscores the importance of evaluating both structural and ecological performance when assessing the effectiveness of rangeland berms.

Several variables—including landform, parent material, soil development, berm length, and slope—significantly influenced berm condition. Berms were more frequently intact in areas with strongly developed soils and lower slopes, especially on stable landforms such as fan terraces and older stream terraces. In contrast, berms located on steeper slopes and constructed from less cohesive parent materials (e.g., granite- and schist-derived alluvium) were more prone to breaching

246 and flanking. Berm length also emerged as a key factor: longer berms (>50 m) showed higher rates
247 of failure, likely due to greater structural stress and increased opportunities for concentrated flow
248 paths to develop around or through the berm.

249 Stream terraces exhibited intermediate behavior, reinforcing their role as a transitional land-
250 form. While fan terraces were generally associated with greater berm stability and floodplains with
251 higher rates of failure, stream terraces reflected characteristics of both. This suggests that landform
252 classification alone may not be sufficient to predict berm outcomes; rather, it must be interpreted
253 in conjunction with factors such as soil development, slope, and parent material. Soil development
254 was a strong cross-cutting control. Berms located in soils with well-developed profiles (e.g., presence
255 of Bt or Bk horizons) were more likely to be intact and also associated with greater vegetation
256 response. These soils likely provide improved structural integrity and hydrologic properties—such
257 as higher infiltration and water retention—that promote both berm persistence and plant growth.
258 In contrast, weakly developed soils corresponded to higher failure rates and lower ΔS , reflecting less
259 favorable conditions for both stability and vegetation establishment.

260 Vegetation response, as measured by the ΔS index, was significantly influenced by landform,
261 soil development, slope, and parent material. Similar to berm condition, stronger soil development
262 and more cohesive parent materials (e.g., mixed alluvium) supported greater vegetation greenness
263 upslope of berms. However, berm structural condition itself was not significantly associated with
264 ΔS , suggesting that intactness does not guarantee vegetation success. This may reflect time lags in
265 vegetation response, legacy effects from previous disturbance, or other site-level hydrologic processes
266 not fully captured by structural condition alone.

267 Slope played a nuanced role. Berms on steeper slopes were more likely to fail structurally but
268 exhibited higher vegetation response. This may indicate that while steeper slopes enhance the
269 potential for runoff redistribution—benefiting upslope vegetation—they also increase erosive forces
270 that compromise berm stability. These contrasting effects highlight the tradeoffs involved in placing
271 berms on steep terrain.

272 Sand content also influenced vegetation response: berms in sandier soils (>50% sand) were asso-
273 ciated with lower ΔS , possibly due to limited water-holding capacity. In contrast, clay content did
274 not significantly affect berm performance, reinforcing the importance of considering soil development

and overall structure rather than texture alone.

Taken together, these results suggest that berm effectiveness is shaped by a complex interplay of structural and environmental controls. Strategic berm placement in areas with stronger soils, lower slopes, and cohesive substrates can enhance both structural longevity and ecological benefit. In addition, recognizing the transitional nature of stream terraces and the limits of structural condition as a sole indicator of function may help refine conservation planning. Future restoration and monitoring efforts should continue to integrate soil-geomorphic, hydrologic, and ecological data to optimize berm performance in semi-arid rangelands.

5. Conclusion

This study demonstrates that integrating geomorphic and soil information is essential for understanding and predicting the performance of water and erosion control berms in semi-arid rangelands. We found that berms situated on more stable landforms, particularly fan terraces and older stream terraces, and underlain by strongly developed soils, were more likely to remain intact. These structurally stable berms also tended to support greater vegetation greenness upslope, as indicated by higher values of ΔS . In contrast, berms on floodplains, steeper slopes, or in areas with weak soil development and less cohesive parent material were more susceptible to breaching and flanking, reducing their effectiveness in runoff retention and vegetation restoration.

Importantly, berm structural condition did not consistently predict vegetation response, highlighting the need to assess both physical integrity and ecological function independently. Some landforms, such as stream terraces, exhibited intermediate characteristics, underscoring the importance of evaluating site-specific combinations of slope, soil development, and parent material in berm planning.

By combining terrain, soil, and vegetation data, land managers can better anticipate berm performance and prioritize maintenance or restoration efforts in areas at higher risk of failure. The use of satellite-derived vegetation indices like SAVI offers a scalable and effective approach for monitoring berm impact on rangeland vegetation over time. Collectively, these findings support a more nuanced, landscape-informed approach to the design, evaluation, and management of earthworks aimed at improving water retention and vegetation outcomes in dryland ecosystems.

303 Future research should continue to refine predictive models by integrating additional environ-
304 mental variables, long-term monitoring, and hydrologic data to strengthen decision-support tools
305 for rangeland restoration and conservation planning.

306 **Funding**

307 **Disclosure of interest**

308 There are no relevant financial or non-financial competing interests to report.

309 **References**

- 310 1. Nichols M, Degginger T. The landscape impact of unmaintained rangeland water control struc-
311 tures in southern Arizona, USA. *Catena* 2021;201:105201.
- 312 2. Nichols MH, Magirl C, Sayre NF, Shaw JR. The geomorphic legacy of water and erosion con-
313 trol structures in a semiarid rangeland watershed. *Earth Surface Processes and Landforms*
314 2018;43(4):909–18.
- 315 3. Drusch M, Del Bello U, Carlier S, Colin O, Fernandez V, Gascon F, Hoersch B, Isola C, Laberinti
316 P, Martimort P, et al. Sentinel-2: Esa’s optical high-resolution mission for gmes operational
317 services. *Remote sensing of Environment* 2012;120:25–36.