

4-Point Inspection Report

Insured / Applicant Chris Patel

Application / Policy # HO3-4481207

Address Inspected 77 Palm Court


Tampa, FL 33602

Actual Year Built 2004

Date Inspected 09/29/2026

Name of Inspector Jeremy K. Heath

License # FL-HI9921



Electrical System

Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.

Main Panel

Type: ☒ Circuit breaker ☐ Fuse

Total amps: 200

Is amperage sufficient for current usage?: ☒ Yes ☐ No (explain)

Second Panel

Type: ☐ Circuit breaker ☐ Fuse

Total amps: _____

Is amperage sufficient for current usage?: ☐ Yes ☐ No (explain)

Indicate presence of any of the following

Present: ☐ Cloth wiring ☐ Active knob and tube ☐ Branch circuit aluminum wiring

If aluminum wiring is present, describe the usage of all aluminum wiring: _____

Single strand (aluminum branch) wiring remediation: ☐ Connections repaired via COPALUM crimp ☐ Connections repaired via AlumiConn

Hazards Present

Hazards: ☐ Blowing fuses ☐ Tripping breakers ☐ Empty sockets ☐ Loose wiring ☐ Improper grounding ☐ Corrosion ☐ Over fusing ☒ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)

General condition of the electrical system: ☐ Satisfactory ☒ Unsatisfactory (explain)

Supplemental Information

Main panel — panel age: _____

Main panel — year last updated: _____

Main panel — brand / model: _____

Second panel — panel age: _____

Second panel — year last updated: _____

Second panel — brand / model: _____

Wiring type: ☒ Copper ☐ NM, BX or Conduit

HVAC System

Central AC: ☐ Yes ☐ No

Central heat: ☐ Yes ☐ No

If not central heat, indicate primary heat source and fuel type: _____

Are the heating, ventilation and air conditioning systems in good working order?: ☐ Yes ☐ No (explain)

Date of last HVAC servicing / inspection: _____

Hazards Present

Wood-burning stove or central gas fireplace not professionally installed?: ☐ Yes ☐ No

Space heater used as primary heat source?: ☐ Yes ☐ No

Is the source portable?: ☐ Yes ☐ No

Does the air handler / condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?: ☐ Yes

☐ No

Supplemental Information

Age of system: _____

Year last updated: _____

Plumbing System

Is there a temperature pressure relief valve on the water heater?: ☐ Yes ☐ No

Is there any indication of an active leak?: ☐ Yes ☐ No

Is there any indication of a prior leak?: ☐ Yes ☐ No

Water heater location: _____

General condition of plumbing fixtures and connections to appliances

Dishwasher: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

Refrigerator: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

Washing machine: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

Water heater: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

Showers / Tubs: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

Toilets: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

Sinks: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

Sump pump: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

Main shut off valve: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

All other visible: ☐ Satisfactory ☐ Unsatisfactory ☐ N/A

If unsatisfactory, provide comments / details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.): _____

Supplemental Information

Age of piping system: ☐ Original to home ☐ Completely re-piped ☐ Partially re-piped

Year and extent of renovation: _____

Type of pipes (check all that apply): ☐ Copper ☐ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)

**Roof****Predominant Roof**Covering material: **Asphalt shingle**Roof age (years): **8**

Remaining useful life (years): _____

Date of last roofing permit: _____

Date of last update: _____

If updated: ☒ **Full replacement** ☐ Partial replacement

% of replacement: _____

Overall condition: ☒ **Satisfactory** ☐ Unsatisfactory (explain below)Any visible signs of damage / deterioration?: ☐ Cracking ☐ Cupping/
curling ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed felt☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking ☐

Visible hail damage

Any visible signs of leaks?: ☐ Yes ☐ NoAttic / underside of decking: ☐ Yes ☐ NoInterior ceilings: ☐ Yes ☐ No**Secondary Roof**

Covering material: _____

Roof age (years): _____

Remaining useful life (years): _____

Date of last roofing permit: _____

Date of last update: _____

If updated: ☐ Full replacement ☐ Partial replacement

% of replacement: _____

Overall condition: ☐ Satisfactory ☐ Unsatisfactory (explain below)Any visible signs of damage / deterioration?: ☐ Cracking ☐ Cupping/
curling ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed felt☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking ☐

Visible hail damage

Any visible signs of leaks?: ☐ Yes ☐ NoAttic / underside of decking: ☐ Yes ☐ NoInterior ceilings: ☐ Yes ☐ No**Additional Comments / Observations**

Wter heater replaced 2021.a

*I certify that the above statements are true and correct.***Jeremy K. Heath**

Inspector Signature

Home Inspector

Title

FL-HI9921

License Number

09/29/2026

Date

Vision Property Inspections

Company Name

Home Inspector

License Type

Work Phone

 Pictures



Dwelling — front



Dwelling — left side



Dwelling — right side