

Oil Type	TOTAL RUBIA WORKS 4000	Oil Grade	15W40
Compartment	ENGINE PRIMARY - DIESEL	Compart Serial	
Job No		Meter	49485
Lab No	23562815	Sample Date	09-Aug-2026
Eval	C	Sample Site	Blackwater Mine

DETAILS											
Lab No	Eval	Date Sampled	Date Received	Label	Actioned	Meter Read	Comp. Hours	Fluid Hours	Fluid Added	Fluid Changed	Filter Changed
23562815	C	09-Aug-2026	13-Aug-2026		N	49485	49448	604		N	N
23473125	A	17-Jul-2026	22-Jul-2026		N	49115	49078	234		N	N
23397705	A	30-Jun-2026	03-Jul-2026		N	52529	52492	1127		Y	Y
23323728	A	13-Jun-2026	17-Jun-2026		N	52254	52217	8216			

ELEMENT TESTS																																										
Lab No	Eval	S	Cu	Fe	Cr	Pb	Al	Si	Sn	Ni	Na	K	Mo	Ca	Mg	P	Zn	V40	V100	VI	F	WAT	UST	UOXI	USUL	SUL	UNIT	PQ	DEP	Ti	Sb	V	B	Ag	Mn	Cd	Ba	Li	In	Bi		
23562815	C	3666	349	7	<1	2	1	5	<1	<1	2	2	<1	2172	8	818	924	97	13.4	137	2.2	<0.1	4	10	18		<1	1	L-FB	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1
23473125	A	3476	15	2	<1	<1	<1	3	<1	<1	<1	<1	<1	1967	6	744	846	104	14.1	137	<2.0	<0.1	2	9	16		<1	4	N--B	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1
23397705	A	3585	<1	1	<1	<1	<1	4	<1	<1	2	<1	<1	1947	5	785	852	114	14.7	133	<2.0	<0.1	<1	8	15		<1	1	N--B	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1
23323728	A	4086	<1	2	<1	<1	<1	8	<1	<1	2	1	<1	1958	7	772	860	105	14.2	137	<2.0	<0.1	2	10	18		<1	2	N--B	<1	<1	<1	1	<1	<1	<1	<1	<1	<1	<1	<1	<1

COMMENTS		
Lab No	Eval	Comment
23562815	C	Viscosity acceptable for oil grade indicated. Copper is high. Suggested action: Investigate & Evaluate Compartment. Inspect the used oil filters for abnormal debris. Microscopy Filtergram analysis will establish whether the copper result relates to mechanical wear, or chemical leaching. Resample following assessment to confirm normal conditions. Sample Note : service interval: 1000
23473125	A	All Test Results appear to be Normal. Continue Sampling at the Recommended Interval.
23397705	A	All Test Results appear to be Normal. Continue Sampling at the Recommended Interval.
23323728	A	All Test Results appear to be Normal. Continue Sampling at the Recommended Interval.

Could you please check that your phone number is correctly entered in your user preferences in case we need to alert you of alarming results.
Should you have any further questions, you can contact Hastings Deering Laboratory Services directlly on 1300 827 139.*

NOTICE:This message is for the named person's use only. It may contain confidential, proprietary or legally privileged information. BUMA Australia does not waive any confidentiality, copyright or legally privileged information by any transmission. If you receive this message in error, please immediately delete it and all copies of it from your system, destroy any hard copies of it and notify the sender. You must not, directly or indirectly, use, disclose, distribute, print, or copy any part of this message if you are not the intended recipient. BUMA Australia reserves the right to monitor all e-mail communications through its networks. Any views expressed in this message are those of the individual sender, except where the message states otherwise and the sender is authorized to state them to be the views of any such entity.