

District Name: Bagerhat

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	chitalmari	Chitalmari Upazilla Health Complex	1 xlsx	
2	fakirhat	50 Bed Fakirhat Upazila Health Complex	1 xlsx	
3	kachua	kachua Upazilla Health Complex	1 xlsx	
4	mollahat	50 Bed Mollahat Upazila Health Complex	1 xlsx	
5	mongla	Mongla Upazila Health Complex, Bagerhat.	1 xlsx	
6	morrelganj	Morelgonj Upazila Health Complex	No file	
7	rampal	Rampal Upazila Health Complex, Bagerhat.	No file	
8	sarankhola	Sharonkhola Upazila Health Complex, Bagerhat.	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	chitalmari	Chitalmari Upazilla Health Complex	2012	HED	21630 sft area (if pond is filled up)	31	1 dwg	No file	1 pdf	1 pdf	8601	8601.8256, 4110	1 dwg	No file	4 jpegs	H.F+1'	
2	fakirhat	50 Bed Fakirhat Upazila Health Complex	2012	HED	Available	50	1 dwg	No file	1 pdf	1 pdf	8601	8601, 8256,6390	1 dwg	No file	3 jpegs	H.F=G.L+1	Land Area:7.23 acre
3	kachua	kachua Upazilla Health Complex	2005	HED	Available	19	1 dwg	No file	1 pdf	1 pdf	8601	8601, 8256	1 dwg	No file	1 jpeg	3' above	
4	mollahat	50 Bed Mollahat Upazila Health Complex	2012	HED	Available	50	1 dwg	No file	1 pdf	1 pdf	8601	8601, 8256,6390	1 dwg	No file	3 jpegs	H.F=G.L+2	Land Area: 4.05 acre
5	mongla	Mongla Upazila Health Complex, Bagerhat.	2010	HED	Available	50	1 dwg	No file	No file	1 pdf		6000	No file	1 jpeg	1 jpeg	3'-6" above	31 শয্যা হাসপাতাল টি ০১/০৭/২০২৫ তারিখে পরিত্যক্ত ঘোষণা করা হয়েছে। ৯ শয্যা বিশিষ্ট ৩য় তলা ভবনে চিকিৎসা কার্যক্রম চলমান আছে।
6	morrelganj	Morelgonj Upazila Health Complex	1962	Other	Available	19	1 dwg	No file	No file	1 pdf		7750	No file	No file	1 jpeg	3'-6"	বর্তমানে ১৯ শয্যা বিশিষ্ট ৩য় তলা ভবনে চিকিৎসা কার্যক্রম চলমান আছে। ২০১২ সালে ৫০ শয্যা বিশিষ্ট হাসপাতাল উন্নীতকরন করা হয় এবং ৩১ শয্যা বিশিষ্ট হাসপাতাল ভবন HED কতৃক নির্মানাধীন রয়েছে।
7	rampal	Rampal Upazila Health Complex, Bagerhat.	2022	HED	Available	50	1 dwg	No file	No file	1 pdf		6500	No file	1 jpeg	1 jpeg	3'-6"	৬ তলা ফাউন্ডেশন বিশিষ্ট ৩য় তলায় ৩১ বেডের কার্যক্রম চলমান রয়েছে। পাশেই ২০০৯ সালে নির্মিত ১৯ শয্যার হাসপাতাল চলমান আছে।

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
8	sarankhola	Sharonkhola Upazila Health Complex, Bagerhat.	1985	HED	Available	50	1 dwg	No file	No file	1 pdf		9200	No file	No file	1 jpeg	4'-0"	বর্তমানে ১৯ শয্যা বিশিষ্ট ৩য় তলা ভবনে চিকিৎসা কার্যক্রম চলমান আছে। ৩১ শয্যা বিশিষ্ট ২য় তলা ভবনটি ২৮/১০/২০২৫ তারিখে HED পরিত্যক্ত ঘোষণা করে। কিন্তু স্বাস্থ্য সেবা চালিয়া রাখার জন্য পরিত্যক্ত ভবনটি বুকি নিয়ে ব্যবহার করা হচ্ছে।

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	chitalmari	Chitalmari Upazila Health Complex	30	1.5	3	Footing	3	RCC	Structural condition of main hospital building is at a moderate level. Structural defects have become visible in some areas of the building's column, beam & slab.	No file	Not Possible	Regular civil (plaster, paint sanitary work) & electrical maintenance works have been undertaken.	
2	fakirhat	50 Bed Fakirhat Upazila Health Complex	30	2.5	3	Deep	4	RCC	Coloum Size =21"836" ,21"*18",21*13" Span =18'	No file	Not Possible		1.Construction of new boundary wall 2. in crease of Internal Road hight 3.Provision of safe drinking Water facilities (3)old building :Bed 19,Office ,imergency,Lab section , X ray, Store,4 ward (4) New Building :OPD,Farmecy,I centre, Dengu Ward ,Room, cabin
3	kachua	kachua Upazila Health Complex	22	1.66	2	Footing	3	RCC		No file	Not Possible		In 1980, the facility had a total of 31 beds. Over time, due to natural causes, this number gradually decreased. Several beds became unusable because of deterioration, and some were rendered non-functional. As a result, the facility could no longer maintain the original capacity of 31 beds. In 2005, an additional 19 beds were added. These newly added beds were also incorporated into the national database. Among the 50 beds listed in the national database, 19 were newly added, while the remaining 31 had gradually become unusable over the years due to natural causes. Among the 19 newly added beds, 3 were designated for female patients. These 3 beds were included in the national database in alignment with the government's initiative to ensure dedicated facilities for women. Necessary government support and facilities were also allocated for these beds.
4	mollahat	50 Bed Mollahat Upazila Health Complex	30	2.5	3	Deep	4	RCC	Coloum Size =21"836" ,21"*18",21*13" Span =18'	No file	Not Possible		*১টি পরিত্যক্ত ভবন কোন কার্যক্রম নাই * নতুন বিডিং এ জলছাদ আছে * ১টি গভীর নলকুল আছে, + submersible *অন্য কোন পানির উৎস নাই *পৌরসভা, ওয়টার পানির লাইন নাই * পানি নিষ্কাশনের ব্যবস্থা নাই,
5	mongla	Mongla Upazila Health Complex, Bagerhat.	42	2.5	3	Footing	3	RCC	Good/New	No file	Not Possible	NA	১৯ শয্যা বিশিষ্ট ৩য় তলা ভবন এর তথ্য। পরিত্যক্ত ভবনটি উপেক্ষা করা হয়েছে।
6	morrelganj	Morelgonj Upazila Health Complex	42	2.5	3	Footing	3	RCC	Good	No file	Not Possible	NA	
7	rampal	Rampal Upazila Health Complex, Bagerhat.	42	2.5	3	Footing	6	RCC	Good	No file	Possible	NA	31 শয্যা হাসপাতাল এর তথ্য
8	sarankhola	Sharonkhola Upazila Health Complex, Bagerhat.	42	3	3	Footing	3	RCC	Good/New	No file	Not Possible	NA	১৯ শয্যা বিশিষ্ট ৩য় তলা ভবন এর তথ্য। পরিত্যক্ত ভবনটি উপেক্ষা করা হয়েছে।

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	chitalmari	Chitalmari Upazilla Health Complex	30000	1	pond	Septic Tank		No		Apron is provided around the building and surface drain is available along the boundary. This appear to be adequate for proper drainage of rainwater and surface runoff.		At a abandoned area situated approximately 40 feet from the building.	
2	fakirhat	50 Bed Fakirhat Upazila Health Complex	0	1		Septic Tank		No	0	around only main building	Required forTotal project area		1. Water supply system improvement 2.Waste management facilities
3	kachua	kachua Upazilla Health Complex	0	0	Water is taken from the campus pond, purified through a filter system, and then used in the hospital	Septic Tank	10000	No	0	The surface drain is dilapidated and does not provide proper drainage. Due to the inability to drain rainwater, waterlogging occurs	The construction of both the surface drain and the master drain is urgently required.		
4	mollahat	50 Bed Mollahat Upazila Health Complex	0	1		Septic Tank	0	No	0	around only main building	Required forTotal project area		
5	mongla	Mongla Upazila Health Complex, Bagerhat.		0	Rain water	Septic Tank		Yes	20000	poor	RCC Drain		কোষ্টাল এরিয়া হওয়ায় ডীপ-টিউবওয়েল এর লেয়ার পাওয়া যায় না।
6	morrelganj	Morelgonj Upazila Health Complex		0	Rain water	Septic Tank		Yes	20000	poor		NA	
7	rampal	Rampal Upazila Health Complex, Bagerhat.		0	Rain water	Septic Tank		No	0	poor	RCC Drain		
8	sarankhola	Sharonkhola Upazila Health Complex, Bagerhat.	0	0	Rain water	Septic Tank		No	20000	poor	RCC Drain	NA	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	chitalmari	Chitalmari Upazilla Health Complex		1703			12	Internal road is constructed of RCC with a width of 15.5 feet. The current condition of the road is quite good.	Yes	Yes	
2	fakirhat	50 Bed Fakirhat Upazila Health Complex		1719		100	20	10' road	Yes	Yes	
3	kachua	kachua Upazilla Health Complex	0	2099			10	RCC	Yes	Yes	
4	mollahat	50 Bed Mollahat Upazila Health Complex		1719		100	20	10' road	Yes	Yes	
5	mongla	Mongla Upazila Health Complex, Bagerhat.		1800	0	2000	15	good	Yes	Yes	
6	morrelganj	Morelgonj Upazila Health Complex	0	2200	300	1900	18	poor	Yes	Yes	

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
7	rampal	Rampal Upazila Health Complex, Bagerhat.		2050		2200	20	very good	Yes	Yes	
8	sarankhola	Sharonkhola Upazila Health Complex, Bagerhat.	1850	0	315	1535	12	poor	Yes	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional Info (Capacity, Demand etc)
1	chitalmari	Chitalmari Upazila Health complex	0	0	0	10	20		no	0	1	1 nos 10 hp and 2 nos 2 hp Centifugal pum motor required	Not Present	no
2	kachua	Kachua Upazila Health complex	0	0		8	20		no	0	4	2 nos 10 hp and 2 nos 1 hp Centifugal pum motor required	Not Present	
3	mongla	Mongla Upazila Health Complex, Bagerhat.	0	0		30	100	Repair & Maintenance Needed	15 Nos Fire Extinguisher is Available & 40 Nos is Required	0	2	2 HP Centrifugal Or JET Pump - 2 Nos is Required	Incinerator Type	1 No Incineration Type Needed
4	morrelganj	Morelgonj Upazila Health Complex	0	0		9.5	20		no		7.5	1 nos 10 hp and 2 nos 2 hp Centifugal pum motor required	Not Present	
5	rampal	Rampal Upazila Health Complex, Bagerhat.	0	0	Lift Core Available	30	30	Repair & Maintenance Needed	0	2	0	Needed , 2 HP Submersible - 2 Nos, 2 HP Centrifugal Or JET Pump - 2 Nos.	Not Present	1 No Incineration Type Needed
6	sarankhola	Sharonkhola Upazila Health Complex, Bagerhat.	0	0										

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	chitalmari	Chitalmari Upazila Health complex	REB	Yes		0		no	10	50			15rm wap ,20 meter,	Dilapidated	Dilapidated and almos wasted
2	kachua	Kachua Upazila Health complex	REB	Yes	0			no	10	50			25rm wap ,15 meter,	Dilapidated	Dilapidated and almos wasted
3	mongla	Mongla Upazila Health Complex, Bagerhat.	WZPDCL	Yes	70	150	300	Not in Good Situation, Maintenance and Service is Needed.	10	15	2	0	HT Cable - 3C X 50 Sqmm, LT Cable - 4 X 25 sqmm, 25 meter(Approximate)	Concealed Wiring	Dilapidated and almost wasted
4	morrelganj	Morelgonj Upazila Health Complex	REB	Yes		0	0	no	10	50		0	20rm wap ,12 meter,	Dilapidated	Dilapidated and almos wasted
5	rampal	Rampal Upazila Health Complex, Bagerhat.	REB	Yes	70	150	300	Good	5.5	20	0	0	HT Cable - 3C X 50 Sqmm, LT Cable - 4 X 25 sqmm, 25 meter(Approximate)	Concealed Wiring	

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
6	sarankhola	Sharonkhola Upazila Health Complex, Bagerhat.													

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	chitalmari	Chitalmari Upazila Health complex	No		16	There is only oxygen supply for 16 beds	No	No	No	No	Yes	1		
2	kachua	Kachua Upazila Health complex	No		10	There is only oxygen supply for 10 beds	No	No	No	No	Yes	1		
3	mongla	Mongla Upazila Health Complex, Bagerhat.	Yes	0	10	10 Nos Oxygen Cylinder is Available Only	Yes	Yes	Yes	No		1	Needed a Full Functional Incineration Type Medical Gas Plant, Addressable Sound System, PABX System and 3 Nos 16 Chanel CCTV System	
4	morrelganj	Morelgonj Upazila Health Complex	No		0		No	No	No	No	Yes	2		
5	rampal	Rampal Upazila Health Complex, Bagerhat.	Yes	0	30	30 Nos Oxygen Cylinder is Available Only	Yes	Yes	Yes	No	Yes	1	Needed a Full Functional Incineration Type Medical Gas Plant, Addressable Sound System, PABX System and 3 Nos 16 Chanel CCTV System	
6	sarankhola	Sharonkhola Upazila Health Complex, Bagerhat.												

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	chitalmari	Chitalmari Upazilla Health Complex	admin building	1	1998	2	11240	22480	minar cracks were visible in some portions of the walls. Overall, the current condition of the building is satisfactory	No file	1 mp4	
2	fakirhat	50 Bed Fakirhat Upazila Health Complex	OPD Block		1965	2	7012.46	11732.46		No file	No file	Old damaged unserviceable Building
3	kachua	kachua Upazilla Health Complex	UHFPO		1985	1	1242	1242		No file	No file	
4	kachua	kachua Upazilla Health Complex	4TH CLASS QUARTER		1984	1	4312	4312		No file	No file	
5	kachua	kachua Upazilla Health Complex	3RD CLASS QUARTER		1983	2	2905	5810		No file	No file	
6	kachua	kachua Upazilla Health Complex	NURSE QUARTER		1982	1	1550	1550		No file	No file	
7	kachua	kachua Upazilla Health Complex	DOCTORS QUARTER 2		1981	1	1947	1947		No file	No file	
8	kachua	kachua Upazilla Health Complex	DOCTORS QUARTER		1980	1	1947	1947		No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
9	kachua	kachua Upazilla Health Complex	HALL ROOM		2005	1	1104	1		No file	No file	
10	kachua	kachua Upazilla Health Complex	Oxyzen Room		2005	1	264	264		No file	No file	
11	mollahat	50 Bed Mollahat Upazila Health Complex	OPD Block		1965	2	7012.46	11732.46	Old damaged unserviceable Building	1 pdf	No file	
12	mongla	Mongla Upazila Health Complex, Bagerhat.	Mosque		2010	1	5600			No file	1 jpeg	
13	mongla	Mongla Upazila Health Complex, Bagerhat.	Staff Quarter		1998	1	2500	2500	Use	No file	1 jpeg	
14	mongla	Mongla Upazila Health Complex, Bagerhat.	Nurses Quarter		1998	2	2700	5400	Condemned	No file	1 jpeg	
15	mongla	Mongla Upazila Health Complex, Bagerhat.	Dormitory		2010	2	1000	2000	Use	No file	1 jpeg	
16	mongla	Mongla Upazila Health Complex, Bagerhat.	Nurses Quarter		1998	2	1200	4800	Condemned	No file	1 jpeg	ঝুঁকি নিয়ে নার্সরা বসবাস করছে।
17	mongla	Mongla Upazila Health Complex, Bagerhat.	Nurses Quarter		1998	2	1600	6400	Use	No file	1 jpeg	
18	mongla	Mongla Upazila Health Complex, Bagerhat.	Doctors Quarter		1998	2	3000	6000	Running	No file	1 jpeg	
19	morrelganj	Mongla Upazila Health Complex, Bagerhat.	Staff Quarter		1962	1	2000	2000	Condemned	No file	1 jpeg	
20	morrelganj	Morelgonj Upazila Health Complex	Dormitory			2	1150	2300	Running/Repair (on going)	No file	1 jpeg	
21	morrelganj	Morelgonj Upazila Health Complex	Staff Quarter			2	1600	6400	Unuse	No file	No file	
22	morrelganj	Morelgonj Upazila Health Complex	Staff Quarter			2	1700	3400	Unuse	No file	1 jpeg	
23	morrelganj	Morelgonj Upazila Health Complex	Doctors Quarter		2020	2	2200	4400	Running	No file	1 jpeg	
24	sarankhola	Sharonkhola Upazila Health Complex, Bagerhat.	Mosque			1				No file	1 jpeg	
25	sarankhola	Sharonkhola Upazila Health Complex, Bagerhat.	Staff Quarter		1976	1			Condemned	No file	1 jpeg	
26	sarankhola	Sharonkhola Upazila Health Complex, Bagerhat.	Staff Quarter		1976		2800	5600	Running	No file	1 jpeg	
27	sarankhola	Sharonkhola Upazila Health Complex, Bagerhat.	Auditorium		2001	2	1350	2700	Running	No file	1 jpeg	
28	sarankhola	Sharonkhola Upazila Health Complex, Bagerhat.	Nurses Quarter		1976	2	2600	5200	Running	No file	1 jpeg	
29	sarankhola	Sharonkhola Upazila Health Complex, Bagerhat.	Nurses Quarter		2001	2	1300	2600	Running	No file	1 jpeg	
30	sarankhola	Sharonkhola Upazila Health Complex, Bagerhat.	Doctors Quarter		2001	2	3600	7200	Running	No file	1 jpeg	

District Name: Bandarban

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	ali_kadam	Alikadam Upazila Health Complex	No file	
2	lama	Upazila Health Complex, Lama, Bandarban Hill District	No file	
3	naikhongchhari	Naikhongchhari Upazila Health Complex	No file	
4	rowangchhari	Rowanchari Upazila Health Complex	No file	
5	thanchi	Thanchi Upazila Health Complex	No file	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	ali_kadam	Alikadam Upazila Health Complex		HED		50	No file	No file	No file	1 pdf			No file	No file	No file		
2	lama	Lama Upazila Health Complex				50	1 dwg	No file	1 dwg	No file			No file	No file	No file		
3	naikhongchhari	Naikhongchari Upazila Health Complex					No file	No file	No file	1 pdf			1 pdf	No file	No file		
4	rowangchhari	Rowanchari Upazila Health Complex		PWD		10	1 pdf	No file	No file	1 pdf			1 pdf	No file	No file		
5	thanchi	Thanchi Upazila Health Complex					1 pdf	No file	No file	1 pdf			1 pdf	No file	No file		

District Name: Barguna

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	amtali	Amtoli Upazila Health Complex.	No file	1 Nos 3 Storied Building, 1 Nos 2 Storied Building.
2	bamna	Bamna Upazila Health Complex.	No file	1 Nos 3 Storied Building, 1 Nos 2 Storied Building.
3	betagi	Betagi Upazila Health Complex.	No file	1 Nos 2 Storied existing main building, 1 Nos 4 Storied building under construction.
4	patharghata	Patharghata Upazila Health Complex.	No file	1 Nos 3 Storied building, 1 Nos 1 Storied building.
5	taltali	Taltoli Upazila Health Complex.	No file	1 Nos 3 Storied Building.

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	amtali	Amtoli Upazila Health Complex.	1994		yes	50	1 dwg	1 jpeg	No file	1 dwg	12321.39	24642.78	1 dwg	No file	1 jpeg		1 Nos 2 Storied Building.
2	bamna	Bamna Upazila Health Complex. (New)	2008		yes	31	1 dwg	1 pdf	No file	1 dwg	7655.35	22966.05	1 dwg	No file	1 jpeg		1 Nos 3 Storied Building.
3	bamna	Bamna Upazila Health Complex. (Old)	1984		yes	19	1 dwg	1 pdf	No file	1 dwg	10867.37	21734.74	1 dwg	No file	1 jpeg		1 Nos 2 Storied Building.
4	betagi	Betagi Upazila Health Complex. (New)		HED	yes		1 dwg	1 jpeg	No file	1 dwg	8419.42	33677.68	1 dwg	No file	1 jpeg		4 storied new hospital building under construction.
5	betagi	Betagi Upazila Health Complex. (Old)	2008		yes	31	1 dwg	1 jpeg	No file	1 dwg	6591.71	13183.42	1 dwg	No file	1 jpeg		1 Nos 2 Storied building.
6	patharghata	Patharghata Upazila Health Complex. (New)	2008		yes	31	1 dwg	1 jpeg	No file	1 dwg	9403.78	28211.34	1 dwg	No file	1 jpeg		1 Nos 3 Storied Building.
7	patharghata	Patharghata Upazila Health Complex. (Old)	1984		yes	19	1 dwg	1 jpeg	No file	1 dwg	7271.55	7271.55	1 dwg	No file	1 jpeg		1 Nos 1 Storied building.
8	taltali	Taltoli Upazila Health Complex.	2008		yes	50	1 dwg	1 pdf	No file	1 dwg	8952.27	26856.81	1 dwg	No file	1 jpeg		1 Nos 3 Storied Building.

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	amtali	Amtoli Upazila Health Complex.	20.5	1.5	2	Footing		RCC	well	No file	info not available		1 Nos 2 Storied Building.
2	bamna	Bamna Upazila Health Complex. (New)	30.5	1.5	3	Footing		RCC	well	No file	info not available		1 Nos 3 Storied Building.
3	bamna	Bamna Upazila Health Complex. (Old)	20.5	1.5	2	Footing		RCC	well	No file	info not available		1 Nos 2 Storied Building.

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
4	betagi	Betagi Upazila Health Complex. (New)	40.5	2	4	Footing		RCC	Under Construction	No file	info not available		4 Storied new building under construction.
5	betagi	Betagi Upazila Health Complex. (Old)	22	1.5	2	Footing		RCC	well	No file	info not available		1 Nos 2 Storied building.
6	patharghata	Patharghata Upazila Health Complex. (New)	30.5	1.5	3	Footing		RCC	well	No file	info not available		1 Nos 3 Storied Building.
7	patharghata	Patharghata Upazila Health Complex. (Old)	10.5	1.5	1	Footing		RCC	well	No file	info not available		1 Nos 1 Storied building.
8	taltali	Taltoli Upazila Health Complex.	30.5	1.5	3	Footing		RCC	well	No file	info not available		1 Nos 3 Storied Building.

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	amtali	Amtoli Upazila Health Complex.	10000	1	Water supply from Pouroshova	Septic Tank	474.33	No				Local Drain	
2	bamna	Bamna Upazila Health Complex.	10000	1	Water supply from Pouroshova	Septic Tank	474.33	No				Local Drain	
3	betagi	Betagi Upazila Health Complex.	10000	1	Water supply from Pouroshova	Septic Tank	474.33	No				Local Drain	
4	patharghata	Patharghata Upazila Health Complex.	10000	0	Water supply from Pouroshova	Septic Tank	474.33	No				Local Drain	
5	taltali	Taltoli Upazila Health Complex.	10000	1	Water supply from Pouroshova	Septic Tank	474.33	No				Local Drain	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	betagi	Betagi Upazila Health Complex.		2143.54			18		No		
2	patharghata	Patharghata Upazila Health Complex.	0	1945.37			18		No		

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	patharghata	Patharghata Upazila Health Complex.	0			4				0	2		Not Present	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	patharghata	Patharghata Upazila Health Complex.	REB	Yes		0	0		80	120	0				

District Name: Barishal

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	agailjhara	Agailjhara Upazilla Health Complex	No file	
2	babuganj	Babuganj Upazilla Health Complex	No file	
3	bakerganj	Bakerganj Upazilla Health Complex	No file	
4	banaripara	Banarapara Upazilla Health Complex	1 xlsx	
5	gournadi	Gournadi Upazilla Health Complex	No file	
6	hizla	Hizla Upazilla Health Complex	No file	
7	mehendiganj	Mehendiganj Upazilla Health Complex	No file	
8	muladi	Muladi Upazilla Health Complex	No file	
9	wazirpur	Wazirpur	No file	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	agailjhara	Agailjhara Upazilla Health Complex (19 Bed Building)	2006	HED	Yes	19	1 dwg	No file	No file	No file	5881	5881	1 dwg	No file	1 jpeg	1 ft	Building Condition is good but need to rapair
2	agailjhara	Agailjhara Upazilla Health Complex (31 Bed Building)	1974	PWD	Yes	31	1 dwg	No file	No file	No file	9148	9148	1 dwg	No file	1 jpeg	1 ft	Building Condition is not good
3	babuganj	Babuganj Upazilla Health Complex (19 Bed Building)	2017	HED	Yes	19	1 dwg	No file	No file	No file	7843	7843	1 dwg	No file	1 jpg	1 ft	
4	babuganj	Babuganj Upazilla Health Complex (31 Bed Bulding)	1963	PWD	Yes	31	1 dwg	No file	No file	No file	5275	5275	1 dwg	No file	1 jpeg	1 ft	
5	bakerganj	Bakerganj Upazilla Health Complex (31 Bed Building)	2018	HED		19	1 dwg	No file	No file	No file	8098	8098	1 dwg	No file	1 jpeg	1 ft	Building Condition is good.
6	bakerganj	Bakerganj Upazilla Health Complex (31 Bed Building)	1970	PWD	Yes	31	1 dwg	No file	No file	No file	11113		1 dwg	No file	1 jpeg	1 ft	Building Condition is not good. Concrete spalling out found. Cracks in beams, columns and slab found.
7	banaripara	Banarapara Upazilla Health Complex (19 Bed Building)	2007	HED	Yes	19	1 dwg, 1 pdf	No file	No file	No file	5394	5394	1 dwg, 1 pdf	No file	1 jpeg	1 ft	Building Condition is not good enough.
8	banaripara	Banaripara Upazilla Health Complex (31 Bed Building)	1974	PWD	Yes	31	1 dwg, 1 pdf	No file	No file	No file	10490	10490	1 dwg, 1 pdf	No file	1 jpeg	1 ft	Building Condition is not good. Concrete spalling out found.
9	gournadi	Gournadi Upazilla Health Complex	2006	HED	Yes	19	1 dwg	No file	No file	No file	6475	6475	1 dwg	No file	1 jpeg	1 ft	

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
		(19 Bed Building)															
10	gournadi	Gournadi Upazilla Health Complex (31 Bed Building)	1989	PWD	Yes	31	1 dwg	No file	No file	No file	12475	12475	1 dwg	No file	1 jpeg	1 ft	
11	hizla	Hizla Upazilla Health Complex (19 Bed Building)	2018	HED	Yes	19	1 dwg	No file	No file	No file	6641	6641	1 dwg	No file	2 jpegs	1 ft	Building Condition is not good. Concrete spalling out found. Cracks in slab found.
12	hizla	Hizla Upazilla Health Complex (31 Bed Building)		PWD	Yes	31	1 dwg	No file	No file	No file	11330	11330	1 dwg	No file	1 jpeg	1 ft	Building Condition is not good. Concrete spalling out found. Cracks in beams, columns and slab found.
13	mehendiganj	Mehendiganj Upazilla Health Complex (19 Bed Building)	2018	HED	Yes	19	1 dwg	No file	No file	No file	9443	9443	1 dwg	No file	1 jpeg	1 ft	
14	mehendiganj	Mehendiganj Upazilla Health Complex (31 Bed)	1980	PWD	Yes	31	1 dwg	No file	No file	No file	7395	7395	1 dwg	No file	2 jpegs	1 ft	
15	muladi	Muladi Upazilla Health Complex (19 Bed Building)	2017	HED	Yes	19	1 dwg	No file	No file	No file	7519	7519	1 dwg	No file	1 jpeg	1.5 ft	Building Condition is good.
16	muladi	Muladi Upazilla Health Complex (31 Bed Building)	0	HED			1 dwg	No file	No file	No file	6910	6910	1 dwg	No file	1 jpeg	1.5 ft	Building was under construction. Upto short column has been completed. The construction work has been stopped for 2 years. Column reinforcement Corrosion found.
17	wazirpur	Wazirpur Upazilla Health Complex (50 Bed Building)	2010	HED	Yes	50	1 dwg	No file	No file	No file	7440	7440	1 dwg	No file	2 jpegs	1.5 ft	Building Condition is good

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	agailjhara	Agailjhara Upazilla Health Complex (19 Bed Building)	20.5	2	2			RCC	Structural condition is good. Repair & rennovation is required.	No file	info not available	Unknown	
2	agailjhara	Agailjhara Upazilla Health Complex (31 Bed Building)	21	2	2	Footing	2	Load Bearing Brick	Soncrete spalled out found and plaster stripped of.	No file	Not Possible	Unknown	
3	babuganj	Babuganj Upazilla Health Complex	36	2	3		4	RCC	Structural condition is good. No structural damage has been found. found.	No file	Possible		
4	bakerganj	Bakerganj Upazilla Health Complex (19 Bed Building)	36	2.5	3			RCC	Structural condition is good. No structural damage has been found.	No file	info not available	Unknown	
5	bakerganj	Bakerganj Upazilla Health Complex (31 Bed Building)	24	2	2			Load Bearing Brick	Soncrete spalled out, reinforcement corrosion found and plaster stripped of.	No file	Not Possible		

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
6	banaripara	Banarapara Upazilla Health Complex (19 Bed Building)	33	2	3	Deep		RCC	Structural condition is good. No structural damage has been found.	No file	info not available	Unknown	
7	banaripara	Banarapara Upazilla Health Complex (31 Bed Building)	22	2	2	Footing	2	Load Bearing Brick	Structural condition is not good. Structural damage has been found.	No file	Not Possible	Unknown	
8	gournadi	Gournadi Upazilla Health Complex (19 Bed Building)	21.5	2	2			RCC	Structural condition is good. No structural damage has been found.	No file	info not available	Unknown	
9	gournadi	Gournadi Upazilla Health Complex (31 Bed Building)	22	2	2			RCC	Concrete spalled out found and plaster stripped off.	No file	info not available	Unknown	
10	hizla	Hizla Upazilla Health Complex (19 Bed Building)	36	2.5	3			RCC	Structural condition is not good. Structural damage has been found.	No file	Not Possible	Unknown	
11	hizla	Hizla Upazilla Health Complex (31 Bed Building)	22	2	2	Footing		RCC	Structural condition is not good. Structural damage, cracks in beams and columns has been found.	No file	Not Possible	Unknown	
12	mehendiganj	Mehendiganj Upazilla Health Complex (19 Bed Building)	25	2.5	2			RCC	Structural condition is not good. Structural damage has been found.	No file	Not Possible	Unknown	
13	mehendiganj	Mehendiganj Upazilla Health Complex (31 Bed Building)	35.5	2.5	3			RCC	Structural condition is not good. Structural damage has been found.	No file	Not Possible	Unknown	
14	muladi	Muladi Upazilla Health Complex (19 Bed Building)	0	0	0	Deep		RCC	Building is under construction. Upto short column has been completed. Construction work has been stopped for 2 years.	No file	info not available	N/A	
15	muladi	Muladi Upazilla Health Complex (31 Bed Building)	35	2	3			RCC	Structural condition is not good.	No file	info not available	Unknown	
16	wazirpur	Wazirpur Upazilla Health Complex (50 Bed Building)	44	1.5	4		5	RCC	Structural condition is good. No structural damage has been found.	No file	Not Possible	1 year ago	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	agailjhara	Agailjhara Upazilla Health Complex		1	No	Septic Tank		No		Surface drain available	Surface drain and master drain required	Nearby canal	
2	babuganj	Babuganj Upazilla Health Complex	0	1	No	Septic Tank		No		Surface drain available	Master drain required	Nearby river	
3	bakerganj	Bakerganj Upazilla Health Complex	0	1	No	Septic Tank		No		Surface drain available	Surface drain and master drain required	Nearby river	
4	banaripara	Banarapara Upazilla Health Complex		1	No	Septic Tank		No		Surface drain available	Surface drain and master drain required	Nearby canal	
5	gournadi	Gournadi Upazilla Health Complex	0	1	No	Septic Tank		No	0	Surface drain available	Surface drain and master drain required	Nearby canal (500 ft away)	

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
6	hizla	Hizla Upazilla Health Complex		1	No	Septic Tank		No		Surface drain available	Surface drain and master drain required	Nearby canal	
7	mehendiganj	Mehendiganj Upazilla Health Complex	0	2	No	Septic Tank		No	0	Surface drain available	Surface drain and master drain required	Nearby canal (200 ft away)	
8	muladi	Muladi Upazilla Health Complex	0	1	No	Septic Tank		No		Surface drain available	Surface drain and master drain required	Nearby river	
9	wazirpur	Wazirpur Upazilla Health Complex	0	1	No	Septic Tank		No	0	Surface drain available	Master drain required	Nearby canal (360 ft away)	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	agailjhara	Agailjhara Upazilla Health Complex		2600	1000		24	8 ft, 12 ft and 10 ft width rcc road.	Yes	Yes	Bounadary wall repair required.
2	babuganj	Babuganj Upazilla Health Complex	262	2368	262		20	10 ft width rcc road.	Yes	Yes	Bounadary wall repair required.
3	bakerganj	Bakerganj Upazilla Health Complex (31 Bed Building)		1560	500		12	9 ft width rcc road.	Yes	Yes	Bounadary wall repair required.
4	banaripara	Banaripara Upazilla Health Complex		2200	200		12	10 ft width rcc road.	Yes	Yes	Bounadary wall repair required.
5	gournadi	Gournadi Upazilla Health Complex	0	1700			16	8 ft, 12 ft and 10 ft width rcc road.	Yes	Yes	Boundary wall height is not sufficient. Vertical extension required.
6	hizla	Hizla Upazilla Health Complex		1817	160		18	10 & 12 ft RCC road	Yes	Yes	Bounadary wall repair required.
7	mehendiganj	Mehendiganj Upazilla Health Complex		2115	1000		16	10 ft width rcc road.	Yes	Yes	Bounadary wall repair required.
8	muladi	Muladi Upazilla Health Complex	0	2345	750	250	14	8 ft width rcc road.	No	Yes	Bounadary wall repair required.
9	wazirpur	Wazirpur Upazilla Health Complex	0	1998	320	0	13	13 ft width rcc road.	No	Yes	Bounadary wall repair required.

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (If present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional Info (Capacity, Demand etc)
1	agailjhara	Upazila Health Complex,Agailjhara	0	0	N/A	7.5	16	N/A	Fire Extinguisher-3 Nos	3	0	N/A	Not Present	Minimum 20kg/hr capacity needed
2	babuganj	Upazila Health Complex,Babuganj	0	0	N/A	7.5	14	N/A	Fire Extinguisher-2 Nos	1	0	3 HP Needed	Not Present	Minimum 20kg/hr capacity needed
3	bakerganj	Upzila Health Complex , Bakergang	0	0		7.5	14		N/A	3	0		Not Present	
4	banaripara	Upazila Health Complex,Banaripara	0	0	N/A	13	16	N/A	Fire Extinguisher-10 Nos	5.49	0	N/A	Not Present	Minimum 20kg/hr capacity needed

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional Info (Capacity, Demand etc)
5	gournadi	Upazila Health Complex,Gournadi	0	0	N/A	18	10	N/A	Fire Extinguisher-10 Nos	5.5	0	N/A	Not Present	Minimum 20kg/hr capacity needed
6	hizla	Upzila Health Complex , Hijla	0	0		6	16		Fire Extinguisher	4	0		Not Present	
7	mehendiganj	Upzila Health Complex , Mehendigang	0	0		8	14		Fire Extinguisher	3	0		Not Present	
8	muladi	Upzila Health Complex , Muladi	0	0		10.5	10		Fire Extinguisher	3	0		Not Present	Minimum 20 kg/hr capacity needed.
9	wazirpur	Upazila Health Complex,Wazirpur	0	0	N/A	7.5	16	N/A	Fire Extinguisher-2 Nos	3		N/A	Not Present	Minimum 20kg/hr capacity needed

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	agailjhara	Upazila Health Complex,Agailjhara	REB	Yes	56	0	0	Only MDB	30	30	0	0	1c-4*35Sqmm(NYY)		
2	babuganj	Upazila Health Complex,Babugonj	REB	Yes	56	100	44	Only MDB	0	60	0	0	1c-4*35Sqmm(NYY)		
3	bakerganj	Upzila Health Complex , Bakergang	REB	Yes	50	0	0	MDB	30	30	0	0	1c-4*35Sqmm(NYY)		
4	banaripara	Upazila Health Complex,Banaripara	REB	Yes	56	100		Only MDB	0	60	0	0	1c-4*35Sqmm(NYY)		
5	gournadi	Upazila Health Complex,Gournadi	REB	Yes	56	100	44	Only MDB	0	60	0	0	1c-4*35Sqmm(NYY)		
6	hizla	Upzila Health Complex , Hijla	REB	Yes	50	0	0	MDB	30	30	0	0	1c-4*35Sqmm(NYY)		
7	mehendiganj	Upzila Health Complex , Mehendigang	REB	Yes	50	0	0	MDB	30	30	0	0	1c-4*35Sqmm(NYY)		
8	muladi	Upzila Health Complex , Muladi	REB	Yes	50	0	0	MDB	30	30	0	0	1c-4*35Sqmm(NYY)		
9	wazirpur	Upazila Health Complex,Wazirpur	REB	Yes	56	0		Only MDB	0	60	0	0	1c-4*35Sqmm(NYY)		

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	agailjhara	Upazila Health Complex,Agailjhara	No	0	30	Cylinder O2-15 Nos	Yes	No	No	No	Yes	0		
2	babuganj	Upazila Health Complex,Babugonj	No	0	30	Cylinder O2-25 Nos	Yes	No	No	No	Yes	0	N/A	
3	bakerganj	Upzila Health Complex , Bakergang	Yes	0	50		Yes	No	No	No	No	0		

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
4	banaripara	Upazila Health Complex,Banaripara	No	0	30	Cylinder O2-15 Nos	Yes	No	No	No	No	0	N/A	
5	gournadi	Upazila Health Complex,Gournadi	No	0	30	Cylinder O2-12 Nos	Yes	No	No	No	No	0	N/A	
6	hizla	Upzila Health Complex , Hizla	Yes	0	50		Yes	No	No	No	No	0		
7	mehendiganj	Upzila Health Complex , Mehendiganj	Yes	0	50		Yes	No	No	No	No	0		
8	muladi	Upzila Health Complex , Muladi	Yes	0	50		Yes	No	No	No	No	0		
9	wazirpur	Upazila Health Complex,Wazirpur	No	0	30	Cylinder O2-16 Nos	Yes	No	No	No	Yes	0	N/A	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	agailjhara	Agailjhara Upazilla Health Complex	RTC Hostel Building			4	3786	15144	Good.	No file	No file	
2	agailjhara	Agailjhara Upazilla Health Complex	RTC Academic Building			2	3162	6324	Good	No file	No file	
3	agailjhara	Agailjhara Upazilla Health Complex	Pump House			1	160	160	Abandoned	No file	No file	
4	agailjhara	Agailjhara Upazilla Health Complex	Garrage			1	1480	1480	Should be demolished	No file	No file	
5	agailjhara	Agailjhara Upazilla Health Complex	Mosque			1	2560	2560	Good.	No file	No file	
6	agailjhara	Agailjhara Upazilla Health Complex	EPI Centre			1	700	700	Usable but need to be repaired.	No file	No file	
7	agailjhara	Agailjhara Upazilla Health Complex	Training Centre		2000	1	1485	1485	Usable but need to be repaired.	No file	No file	
8	agailjhara	Agailjhara Upazilla Health Complex	Family Planning Building		2020	2	1911	3822	Good.	No file	No file	
9	agailjhara	Agailjhara Upazilla Health Complex	4th Class Quarter		1974	1	1250	1250	Abandoned. Need be condemned and demolished.	No file	No file	
10	agailjhara	Agailjhara Upazilla Health Complex	3rd class quarter		1974	2	2503	5006	Abandoned. Need be condemned and demolished.	No file	No file	
11	agailjhara	Agailjhara Upazilla Health Complex	Nurses Dormitory		1974	1	1858	1858	Abandoned. Need be condemned and demolished.	No file	No file	
12	agailjhara	Agailjhara Upazilla Health Complex	2nd Class Quarter		2000	2	1216	2432	Usable but need to be repaired.	No file	No file	
13	agailjhara	Agailjhara Upazilla Health Complex	Doctors Quarter		1974	2	2800	5600	Abandoned. Need be condemned and demolished.	No file	No file	
14	agailjhara	Agailjhara Upazilla Health Complex	Doctors dormitory		2000	1	2365	2365	Usable but need to be repaired.	No file	No file	
15	babuganj	Babuganj Upazilla Health Complex	Family Planning Building		2017	2	1989	3802	Good.	No file	No file	
16	babuganj	Babuganj Upazilla Health Complex	UHFPO Quarter		1963	1	2107	2107	Repairable.	No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
17	babuganj	Babuganj Upazilla Health Complex	RMO Quarter		1963	1	1545	1545	Repairable.	No file	No file	
18	babuganj	Babuganj Upazilla Health Complex	Doctors Quarter		1963	4	2360	9440	Should be condemned and demolished	No file	No file	
19	babuganj	Babuganj Upazilla Health Complex	Unknown		1963	1	1491	1491	Repairable.	No file	No file	
20	babuganj	Babuganj Upazilla Health Complex	3rd class quarter (6 unit)		1963	1	2796	2796	Should be condemned and demolished	No file	No file	
21	babuganj	Babuganj Upazilla Health Complex	3rd class quarter		1963	1	1524	1524	Should be demolished	No file	No file	
22	babuganj	Babuganj Upazilla Health Complex	Damaged Building		1963	1	255	255	Should be demolished	No file	No file	
23	babuganj	Babuganj Upazilla Health Complex	Unknown	2	1963	1	2198	2198	Repairable.	No file	No file	
24	babuganj	Babuganj Upazilla Health Complex	EPI Store		1963	1	650	650	Repairable.	No file	No file	
25	babuganj	Babuganj Upazilla Health Complex	Unknown		1963	1	525	525	Should be repaired	No file	No file	
26	babuganj	Babuganj Upazilla Health Complex	Kitchen Building		1963	1	607	607	Should be repaired	No file	No file	
27	babuganj	Babuganj Upazilla Health Complex	4th class employee quarter		1963	2	1219	2438	Should be repaired	No file	No file	
28	babuganj	Babuganj Upazilla Health Complex	Pump House		1963	1	361	1	Should be repaired	No file	No file	
29	babuganj	Babuganj Upazilla Health Complex	Damaged Building-2		1963	1	252	252	Should be condemned and demolished	No file	No file	
30	babuganj	Babuganj Upazilla Health Complex	Damaged Building		1963	1	2013	2013	Should be condemned and demolished	No file	No file	
31	babuganj	Babuganj Upazilla Health Complex	Conference Building		1963	1	2182	2182	Should be condemned and demolished	No file	No file	
32	babuganj	Babuganj Upazilla Health Complex	Garrage-2		1963	1	266	266	Should be demolished	No file	No file	
33	babuganj	Babuganj Upazilla Health Complex	Nurses Quarter		1963	3	832	2496	Should be demolished	No file	No file	
34	babuganj	Babuganj Upazilla Health Complex	Garrage		1963	1	443	443	Should be demolished	No file	No file	
35	bakerganj	Bakerganj Upazilla Health Complex	Doctors Quarter	2		2	1795	3590	Usable but need to be repaired.	No file	No file	
36	bakerganj	Bakerganj Upazilla Health Complex	Family Planning Building			2	1681	3362	Good.	No file	No file	
37	bakerganj	Bakerganj Upazilla Health Complex)	Doctors Quarter			2	1809	3618	Usable but need to be repaired.	No file	No file	
38	gournadi	Gournadi Upazilla Health Complex	Pump House			1	180	180	Need to be condemned and demolished	No file	1 jpeg	
39	gournadi	Gournadi Upazilla Health Complex	Garrage				850	850	Repairable.	No file	No file	
40	gournadi	Gournadi Upazilla Health Complex	Mosque			1	875	875	Repairable.	No file	No file	
41	gournadi	Gournadi Upazilla Health Complex	EPI Centre			1	660	660	Repairable.	No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
42	gournadi	Gournadi Upazilla Health Complex	Training Centre		1990	1	1880	1880	Need to be condemned and demolished	No file	1 jpeg	
43	gournadi	Gournadi Upazilla Health Complex	Family Planning Building		2009	2	1575	3150	Good.	No file	No file	
44	gournadi	Gournadi Upazilla Health Complex	4th class employee quarter		1989	2	1170	2340	Need to be condemned and demolished	No file	1 jpeg	
45	gournadi	Gournadi Upazilla Health Complex	3rd class quarter		1989	4	1520	6080	Repairable.	No file	No file	
46	gournadi	Gournadi Upazilla Health Complex	Nurses Dormitory		1989	1	815	815	Abandoned	No file	1 jpeg	
47	gournadi	Gournadi Upazilla Health Complex	2nd class quarter		2006	2	1780	3560	Good.	No file	1 jpeg	
48	gournadi	Gournadi Upazilla Health Complex	1st class doctor's quarter		1989	3	2400	7200	Repairable.	No file	No file	
49	gournadi	Gournadi Upazilla Health Complex	Doctors dormitory		1989	1	2100	2100	Need be condemned and demolished	No file	1 jpeg	
50	gournadi	Gournadi Upazilla Health Complex	UHFPO Quarter		1989	1	1100	1100	abandoned	No file	1 jpeg	Abandoned
51	hizla	Hizla Upazilla Health Complex	Family Planning Building			2	1606	3212	Good.	No file	No file	
52	hizla	Hizla Upazilla Health Complex	3rd class quarter			2	1865	3730	Need be condemned and demolished	No file	No file	
53	hizla	Hizla Upazilla Health Complex	4th class employee quarter	3		2	2924	5848	Should be condemned and demolished	No file	No file	
54	hizla	Hizla Upazilla Health Complex	4th class employee quarter	2		2	1519	3038	Need be condemned and demolished	No file	No file	
55	hizla	Hizla Upazilla Health Complex	4th class employee quarter			2	1329	2658	Need be condemned and demolished	No file	No file	
56	hizla	Hizla Upazilla Health Complex	Nurses Dormitory			2	1989	3978	Usable but need to be repaired.	No file	No file	
57	hizla	Hizla Upazilla Health Complex	Doctors Quarter	2		3	2301	6903	Should be condemned and demolished.	No file	No file	
58	hizla	Hizla Upazilla Health Complex	Doctors Quarter			2	2441	4882	Usable but need to be repaired.	No file	No file	
59	hizla	Hizla Upazilla Health Complex	Mosque			1	1966	1966	Good.	No file	No file	
60	mehendiganj	Mehendiganj Upazilla Health Complex	4th class quarter			2	2552	5104	Need be condemned and demolished	No file	No file	
61	mehendiganj	Mehendiganj Upazilla Health Complex	2nd class quarter			2	1921	3842	Good.	No file	No file	
62	mehendiganj	Mehendiganj Upazilla Health Complex	Nurses Quarter			2	1995	3990	Need be condemned and demolished	No file	No file	
63	mehendiganj	Mehendiganj Upazilla Health Complex	Doctors Quarter	2		2	2412	4824	Need be condemned and demolished	No file	No file	
64	mehendiganj	Mehendiganj Upazilla Health Complex	Doctors Quarter			3	2824	8472	Need be condemned and demolished	No file	No file	
65	muladi	Muladi Upazilla Health Complex	UHFPO Quarter			1	1122	1122	Need be condemned and demolished	No file	No file	
66	muladi	Muladi Upazilla Health Complex	Doctors Quarter			2	2381	4762	Usable but need to be repaired.	No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
67	muladi	Muladi Upazilla Health Complex	3rd and 4th class employee quarter			2	1330	2660	usable but need to be repaired.	No file	No file	
68	muladi	Muladi Upazilla Health Complex	4th class employee quarter			2	1541	3082	usable but need to be repaired.	No file	No file	
69	muladi	Muladi Upazilla Health Complex	Night Guard Quarter			1	345	345	Not good. Regular maintenance is required.	No file	No file	
70	muladi	Muladi Upazilla Health Complex	Damaged Building			1	3156	3156	Need be condemned and demolished	No file	No file	
71	muladi	Muladi Upazilla Health Complex	EPI Building			1	598	598	Not good. Regular maintenance is required.	No file	No file	
72	muladi	Muladi Upazilla Health Complex	Nurses Dormitory			1	1146	1146	Not good. Regular maintenance is required.	No file	No file	
73	muladi	Muladi Upazilla Health Complex	Mosque			1	738	738	Regular maintenance is required.	No file	No file	
74	wazirpur	Wazirpur Upazilla Health Complex	3rd class quarter			2	1282	2564	Good.	No file	No file	
75	wazirpur	Wazirpur Upazilla Health Complex	2nd class Quarter			2	1376	2752	Good and repairable	No file	No file	
76	wazirpur	Wazirpur Upazilla Health Complex	2nd Class Quarter			2	1779	3558	Good.	No file	No file	
77	wazirpur	Wazirpur Upazilla Health Complex	Doctor's Quarter			2	2382	4764	Good.	No file	No file	
78	wazirpur	Wazirpur Upazilla Health Complex	Family Planning Building			3	1600	4800	Good.	No file	No file	
79	wazirpur	Wazirpur Upazilla Health Complex	Nurses Dormitory			1	1450	1450	Good.	No file	No file	
80	wazirpur	Wazirpur Upazilla Health Complex	Sadar Clinic			2	947	1894	Good.	No file	No file	
81	wazirpur	Wazirpur Upazilla Health Complex	Auditorium			1	2108	2108	Need to demolish	No file	No file	
82	wazirpur	Wazirpur Upazilla Health Complex	EPI Building			4	662	2650	Repairable.	No file	No file	

District Name: Bhola

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	burhanuddin	Borhanuddin Upazila Health complex	1 xlsx	
2	char_fasson	Upazila Health Complex, Charfashion, Bhola	1 xlsx	
3	daulatkhon	Upazila Health Complex, Daulatkhan, Bhola	1 xlsx	
4	lalmohan	lalmohon health complex	1 xlsx	
5	manpura	Upazila Health Complex, Manpura, Bhola	1 xlsx	
6	tazumuddin	Upazila Health Complex, Tazumuddin, Bhola	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	burhanuddin	Borhanuddin Upazila Health complex		HED		19	1 pdf	No file	No file	No file	7645	3600	No file	No file	1 jpeg		
2	char_fasson	Char_fasson Upazila Health complex	2023	HED		100	1 pdf	No file	No file	No file	20640	8250	No file	No file	1 jpeg		
3	daulatkhon	Daulatkhan Upazila Health complex	1968	PWD		50	1 pdf	No file	No file	No file	4450	2000	No file	No file	1 jpeg		
4	lalmohan	Lalmohan Health Complex	2011	HED	NO	50	1 pdf	No file	No file	No file	7373	3050	1 pdf	No file	1 jpeg		
5	manpura	Upazila Health Complex, Manpura, Bhola	2014	HED	N/A	50	1 pdf	No file	No file	No file			No file	No file	1 jpeg		
6	tazumuddin	Upazila Health Complex, Tajumuddin	2014	HED		50	1 pdf	No file	No file	No file	7696	3700	No file	No file	1 jpeg		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	burhanuddin	Borhanuddin Upazila Health complex	20	22	2	Footing		RCC		No file	info not available	No	
2	char_fasson	Char_fasson Upazila Health complex	20	22	2	Footing		RCC		No file	info not available	No	
3	daulatkhon	Daulatkhan Upazila Health complex	20	22	2	Footing		RCC		No file	info not available	No	
4	lalmohan	Lalmohan Health Complex	21	24	2	Footing		RCC	Structural Integrity: There are no visible cracks on Column, beam , Deformation & Distress: There is no tilting and other deformation.	No file	info not available	There is no previous renovation history	
5	manpura	Manpura health Complex	20	22	2	Footing		RCC		No file	info not available	No	

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
6	tazumuddin	Upazila Health Complex, Tajumuddin	20	22	2	Footing		RCC		No file	info not available	No	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	burhanuddin	Borhanuddin Upazila Health complex		4	NO	Septic Tank		No					
2	char_fasson	Char_fasson Upazila health complex		6		Septic Tank		No		Low depth drainage system			
3	daulatkhon	Daulatkhan Upazila Health complex		4		Septic Tank		No					
4	lalmohan	Lalmohan Health Complex	2000	6	There are no additional water supply facilities available in this hospital	Septic Tank	5500	No			High quality drainage facilities are required	Waste water transfers direct to nearest canal	
5	manpura	Manpura health Complex		3	NO	Septic Tank		No					
6	tazumuddin	Upazila Health Complex, Tajumuddin		4	NO	Septic Tank		No					

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	burhanuddin	Upazila Health Complex, Burhanuddin, Bhola		1933		450	16	Internal Road of the hospital prepared with rigid pavement. The condition of the road is not so vulnerable but further repair is necessary	No	Yes	
2	char_fasson	Upazila Health Complex, Charfashion, Bhola	500	1250		400	15	The Existing Internal is Bad condition	Yes	Yes	
3	daulatkhon	Upazila Health Complex, Daulatkhan, Bhola	250	1260		500	15	The Existing Internal is Bad condition	Yes	Yes	
4	lalmohan	Lalmohan Health Complex		2500	400	400	16	Internal Road of the hospital prepared with rigid pavement. The condition of the road is not so vulnerable but further repair is necessary	Yes	Yes	
5	manpura	Upazila Health Complex, Manpura, Bhola		11210		450	15	The Existing Internal is Bad condition	No	Yes	
6	tazumuddin	Upazila Health Complex, Tajumuddin		1500			20	Link road needed	Yes	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	burhanuddin	Borhanuddin Health Complex	0	0	need lift	15	10	AC needed	Expired	5	2	Pump motor needed	Not Present	urgently needed.
2	char_fasson	Charfession Health Complex	0	0	need lift	17	10	AC needed	non functional	10	15	demand 12hp, existing pump repair needed.	Not Present	urgently needed.
3	daulatkhon	Daulatkhan Health Complex	0	0	need lift	10	10	AC needed	Expired	5	2	demand 10hp, existing pump repair needed.	Not Present	urgently needed.
4	lalmohan	lalmohon health complex	0	0	na	10	20	na	non functional	10	7.5	demand 10hp, existing pump repair needed.	Not Present	urgently needed.
5	manpura	Manpura Health Complex	0	0	na	0	0	10	Expired	3	1	Pump motor needed	Not Present	urgently needed.
6	tazumuddin	Tazumuddin Health Complex	0	0	need lift	15.5	20	AC needed	Expired	7.5	15	demand 12hp, existing pump repair needed.	Not Present	urgently needed.

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	burhanuddin	Borhanuddin Health Complex	REB	Yes	200	200	180	pole mounted	5	20	15	4	35, nyy,10,6,4,2.5,1.5. bym,bya.	cables need to change/replace. 10,6,4,2.5,1.5 rm cable are existing.	na
2	char_fasson	Charfession Health Complex	REB	Yes	250	250	100	need servicing and maintenance	20	50	20	6	70 rm, 50 metr length.	cables need to change/replace. 10,6,4,2.5,1.5 rm cable are existing.	na
3	daulatkhon	Daulatkhan Health Complex	REB	No	250	150	100	need servicing and maintenance	10	20	20	3	35, nyy,10,6,4,2.5,1.5. bym,bya.	cables need to change/replace. 10,6,4,2.5,1.5 rm cable are existing.	na
4	lalmohan	lalmohon health complex	REB	Yes	150	250	50	need servicing and maintenance	20	50	20	4	70 rm, 50 metr length	cables need to change/replace. 10,6,4,2.5,1.5 rm cable are existing.	na
5	manpura	Manpura Health Complex	WZPDCL	No	100	100	50	na	10	50	10	2	na	cables need to change/replace. 10,6,4,2.5,1.5 rm cable are existing.	na
6	tazumuddin	Tazumuddin Health Complex	REB	Yes	250	100	100	pole mounted	5	20	20	4	35, nyy,10,6,4,2.5,1.5. bym,bya.	cables need to change/replace. 10,6,4,2.5,1.5 rm cable are existing.	na

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	burhanuddin	Borhanuddin Health Complex	Yes	1	1	only oxygen,malfunctioned.	Yes	No	No	No	Yes	1	yes	na
2	char_fasson	Charfession Health Complex	Yes	50	80	except oxygen, others malfunctioned.	Yes	No	No	No	Yes	2	yes	na
3	daulatkhon	Daulatkhan Health Complex	No	0	0	0	Yes	No	No	No	Yes	1	yes	na
4	lalmohan	lalmohon health complex					No	No	No	No	No	1	yes	na
5	manpura	Manpura Health Complex	No	10	10	0	No	No	No	No	Yes	1	yes	na
6	tazumuddin	Tazumuddin Health Complex	Yes	50	50	only oxygen,malfunctioned.	Yes	No	No	No	Yes	1	yes	na

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	burhanuddin	Upazila Health Complex, Burhanuddin, Bhola	Old Hospital Building	1		2				No file	1 jpeg	
2	lalmohan	Lalmohan Health Complex	Old Hospital Building	1	1984	2	12650	10750	Currently used as the main hospital building	No file	1 jpeg	

District Name: Bogura

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	adamdighi	Adamdighi Upazila Health Complex, Adamdighi, Bogura	1 xlsx	
2	dhunat	Dhunat Upazilla Health Complex	1 xlsx	
3	dhupchanchia	Dupchanchia Upazila Health Complex	1 xlsx	
4	gabtali	Gabtali Upazilla Health Complex, Bogura	1 xlsx	
5	kahaloo	Kahaloo Upazila Health Complex	1 xlsx	
6	nandigram	Nandigram Upazilla Health Complex	1 xlsx	
7	sariakandi	Sariakandi Upazilla Health Complex	1 xlsx	
8	shajahanpur	Shajahanpur Upazilla Health Complex	1 xlsx	
9	sherpur	Sherpur Upazilla Health Complex	1 xlsx	
10	shibganj	Shibganj Upazila Health Complex	1 xlsx	
11	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	adamdighi	Adamdighi Upazila Health Complex, Adamdighi, Bogura	1981	PWD		50	1 dwg	No file	2 pdfs	No file	9950	18200	1 dwg	No file	7 jpegs	arbitrary RL of main road=10.48m, Highest Flood Level= 10.18m (approx)	
2	dhunat	Dhunat Upazilla Health Complex	1964	Other	Yes	50	1 dwg, 1 pdf	1 pdf	No file	No file			No file	No file	8 jpgs		
3	dhupchanchia	Dupchanchia Upazila Health Complex	1981	PWD	Additional unused 77,000 sft land available on the compound for further extension	50	1 dwg	No file	2 pdfs	1 dwg, 2 pdfs	9900	18200	1 dwg	No file	6 jpegs	arbitrary RL of connecting road to main road= 9.40m, Highest flood level = 9.095m (approx)	Old building is in bad condition. OPD has poor condition. All quarter bldgs look good.
4	gabtali	Gabtoli Upazilla Health Complex	1964	Other	Yes	50	1 dwg, 1 pdf	2 pdfs	No file	1 pdf	14218		No file	No file	7 jpgs	NA	
5	kahaloo	Kahaloo Upazila Health Complex	1981	PWD	Additional unused 94070 sft land available for further extension	50	2 dwgs	1 pdf	4 pdfs	2 dwgs	18173	9992	2 dwgs	2 jpegs	10 jpegs		2 storied old hospital building was built in 1980. Old 2 storied hospital Building was built in 2002. 1st floor of the old building is unofficially abandoned and not being used. Activities of the first floor is shifted to 1st class quarter.
6	nandigram	Nandigram Upazilla Health Complex	1964	PWD	Yes	50	1 dwg, 1 pdf	1 pdf	No file	No file			No file	No file	8 jpgs		
7	sariakandi	Sariakandi Upazilla Health Complex	1964	HED	Yes	50	1 dwg, 1 pdf	1 pdf	No file	No file	14674	GF-14674, 1st	No file	No file	10 jpgs	NA	

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
												Floor-2336, 2nd Floor-2336					
8	shajahanpur	Shajahanpur Upazilla Health Complex	2009	HED	Yes	50	1 dwg, 1 pdf	1 pdf	1 pdf	No file			No file	No file	9 jpgs		
9	sherpur	Sherpur Upazilla Health Complex	1964	Other	NA	50	1 dwg, 1 pdf	1 pdf	No file	No file			No file	No file	9 jpgs		
10	shibganj	Shibganj Upazila Health Complex	1981	PWD	Additional unused 40000 sft land (Banana Garden) available for further extension	50	1 dwg	2 pdfs	1 dwg, 4 pdfs	1 dwg	9992	18173	1 dwg	1 pdf	6 jpegs	Arbitrary 30m (TBM and Finish Level of 2 Storied OPD building)	
11	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	1992	HED	Additional 82 decimal land situated outside of the UHC, Sonatala completely open for further extension. And 40,000 sft land available on the UHC compound further extension.	50	1 dwg, 1 pdf	No file	1 dwg	1 dwg	10240	18514	No file	No file	4 jpegs	Flood Level= RL of Front main Road- 2'	

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	adamdighi	Adamdighi Upazila Health Complex, Adamdighi, Bogura	23	1.5	3	Footing	3	Load Bearing Brick	হাসপাতালের প্রধান ভবনটি ১৯৮৩ সালে নির্মিত। ভবনটি বর্তমানে অত্যন্ত পুরাতন ও জরাজীর্ণ অবস্থায় রয়েছে। অধিকাংশ ছাদ দিয়ে বৃষ্টির পানি চুইয়ে পড়ে	No file	Not Possible	ভবনটি নির্মাণের পর থেকে এ পর্যন্ত কোনো বড় ধরনের সংস্কার কাজ করা হয়নি	
2	dhunat	Dhunat Upazilla Health Complex	22	1.5	2	Footing	2	Load Bearing Brick	poor	No file	Not Possible	NA	NA
3	dhupchanchia	Dupchanchia Upazila Health Complex	23	1.5	2	Footing	2	Load Bearing Brick	হাসপাতালের প্রধান ভবনটি ১৯৮৩ সালে নির্মিত। ভবনটি বর্তমানে অত্যন্ত পুরাতন ও জরাজীর্ণ অবস্থায় রয়েছে। অধিকাংশ ছাদ দিয়ে বৃষ্টির পানি চুইয়ে পড়ে	No file	Not Possible	ভবনটি নির্মাণের পর থেকে এ পর্যন্ত কোনো বড় ধরনের সংস্কার কাজ করা হয়নি।	
4	gabtali	Gabtali Upazilla Health Complex	22	1.5	2	Footing	2	RCC	poor	No file	Not Possible	NA	NA
5	kahaloo	Kahaloo Upazila Health Complex	23	1.5	2	Footing	2	Load Bearing Brick	poor	No file	Not Possible	unknown	হাসপাতালের প্রধান ভবনটি ১৯৮৩ সালে নির্মিত। ভবনটি বর্তমানে অত্যন্ত পুরাতন ও জরাজীর্ণ অবস্থায় রয়েছে। অধিকাংশ ছাদ দিয়ে বৃষ্টির পানি চুইয়ে পড়ে। ভবনটির ২য় তলা ব্যবহার উপযোগী না হওয়ার ২য় তলাটি আর ব্যবহৃত হচ্ছে না।
6	nandigram	Nandigram Upazilla Health Complex	44	1.5	4	Footing	2	RCC	good	No file	info not available	NA	NA

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
7	sariakandi	Sariakandi Upazilla Health Complex	22	1.5	2	Footing	2	RCC	moderate	No file	info not available	NA	NA
8	shajahanpur	Shajahanpur Upazilla Health Complex	44	1.5	4	Footing	4	RCC	good	No file	info not available	NA	NA
9	sherpur	Sherpur Upazilla Health Complex	22	1.5	2	Footing	2	Load Bearing Brick	poor	No file	Not Possible	NA	NA
10	shibganj	Shibganj Upazila Health Complex	23	2	2	Footing	2	Load Bearing Brick	Structural condition of the main building is bad . OPD building is good.	No file	Not Possible	2017	
11	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	23	1.5	2	Footing	2	Load Bearing Brick	Good	4 jpegs	Not Possible	2023	old building built in 1993 and building condition looks good.

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	adamdighi	Adamdighi Upazila Health Complex, Adamdighi, Bogura	0	2	0	Septic Tank	2000	No	0	Insufficient surface drain available. No master drain found. Waste water is disposed to nearby low land.	Master Drain and well planned surface drain required.	Solid Waste is accumulated on the UHC campus and collected by Pourashava. Waste water is disposed to the nearby low land.	
2	dhunat	Dhunat Upazilla Health Complex	0	2	Not Available		0		0	Surface drain and master drain is existed in the compound, but is in poor condition.	New surface and master drain with proper design and leveling required.	Waste is accumulated in UHC compound using Waste Management system and also collected by Pourashava from UHC's compound. Waste water is disposed to nearby ditches/pond.	NA
3	dhupchanchia	Dupchanchia Upazila Health Complex	0	2	Not available	Septic Tank	1500	No	0	Surface drain available but in poor condition.	New surface and master drain with proper design and leveling required.	Solid Waste is accumulated on the UHC campus and collected by Pourashava. Waste water is disposed to the nearby low land.	
4	gabtali	Gabtali Upazilla Health Complex	0	1	Not Available		0		0	Surface drain and master drain is existed in the compound, but is in poor condition.	New surface and master drain with proper design and leveling is required.	Waste is accumulated in UHC compound using Waste Management system and also collected by Pourashava from UHC's compound. Waste water is disposed to nearby ditches/pond.	NA
5	kahaloo	Kahaloo Upazila Health Complex	0	1	0	Septic Tank	2500	No	0	Drainage condition is good.	some connecting surface drain will be needed.	Solid Waste is accumulated on the UHC campus and collected by Pourashava. Waste water is disposed to the nearby low land.	
6	nandigram	Nandigram Upazilla Health Complex	0	1	Not Available		0		0	Surface drain is existed in the compound, but is in poor condition.	New surface and master drain with proper design and leveling required.	Waste is accumulated in UHC compound using Waste Management system and also collected by Pourashava from UHC's compound. Waste water is disposed to nearby ditches/pond.	NA
7	sariakandi	Sariakandi Upazilla Health Complex	0	1	Not Available		0		0	Surface drain and master drain is existed in the compound, but is in poor condition.	New surface and master drain with proper design and leveling required.	Waste is accumulated in UHC compound using Waste Management system and also collected by Pourashava from UHC's compound.	NA

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
												Waste water is disposed to nearby ditches/pond.	
8	shajahanpur	Shajahanpur Upazilla Health Complex	0	1	Not Available		0		0	Surface drain and master drain is existed in the compound, but is in poor condition.	Renovation of surface and master drain with proper design and leveling required.	Waste is accumulated in UHC compound using Waste Management system and also collected by Pourashava from UHC's compound. Waste water is disposed to nearby ditches/pond.	NA
9	sherpur	Sherpur Upazilla Health Complex	0	4	Not Available		0		0	Surface drain and master drain is existed in the compound, but is in moderate condition.	Renovation of surface and master drain with proper design and leveling required.	Waste is accumulated in UHC compound using Waste Management system and also collected by Pourashava from UHC's compound. Waste water is disposed to nearby ditches/pond.	NA
10	shibganj	Shibganj Upazilla Health Complex	0	1	Not available	Septic Tank	3000	No	0	Surface drain and master drain available but in poor condition. New surface and master drain with proper design and leveling required.	Surface drain and master drain available but in poor condition. New surface and master drain with proper design and leveling required.	Waste is incinerated in UHC compound using Waste Management system and also collected by Pourashava from UHC's compound. Waste water is disposed to nearby river.	
11	sonatala	Sonatala Upazilla Health Complex, Sonatala, Bogura	0	3	Not available	Septic Tank	6000	No	0	Insufficient surface drain available. No master drain found. Waste water is disposed to nearby low land.	Master Drain and well planned surface drain required.	Solid Waste is accumulated on the UHC campus and collected by Pourashava. Waste water is disposed to the nearby low land.	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	adamdighi	Adamdighi Upazilla Health Complex, Adamdighi, Bogura	0	2122	0	0	35	পরিদর্শনকালে হাসপাতালের অভ্যন্তরীণ সড়কের প্রস্থ ১০ (দশ) ফুট দেখা যায়। সড়কটির বর্তমান অবস্থা সন্তোষজনক নয় এবং বিভিন্ন স্থানে ক্ষতিগ্রস্ত হওয়ায় প্রয়োজনীয় মেরামত কাজ করা আবশ্যিক।	Yes	Yes	অতিরিক্ত সীমানা প্রাচীর নির্মাণের প্রয়োজন নেই। তবে নিরাপত্তার স্বার্থে বিদ্যমান সীমানা প্রাচীরের সম্পূর্ণ অংশ উল্লম্বভাবে (উচ্চতায়) সম্প্রসারণ করা প্রয়োজন। হাসপাতাল এলাকার প্রধান সড়কের তুলনায় নিচু হওয়ায় অতিবৃষ্টির সময় পানি জমে জলাবদ্ধতার সৃষ্টি হয়।
2	dhunat	Dhunat Upazilla Health Complex	0	1941.31	0	0	20	Internal CC Road with guide wall is existed, but need to improve and rennovate.	No	Yes	
3	dhupchanchia	Dupchanchia Upazilla Health Complex	0	2062.83	0	0	35	পরিদর্শনকালে হাসপাতালের অভ্যন্তরীণ সড়কের প্রস্থ ১০ (দশ) ফুট দেখা যায়। সড়কটির বর্তমান অবস্থা সন্তোষজনক নয় এবং বিভিন্ন স্থানে ক্ষতিগ্রস্ত হওয়ায় প্রয়োজনীয় মেরামত কাজ করা আবশ্যিক।	Yes	Yes	হাসপাতাল এলাকার প্রধান সড়কের তুলনায় নিচু হওয়ায় অতিবৃষ্টির সময় পানি জমে জলাবদ্ধতার সৃষ্টি হয়।
4	gabтали	Gabтали Upazilla Health Complex	0	1668.45	0	0	20	Internal CC Road with guide wall is existed, but need to improve and rennovate.	No	Yes	
5	kahaloo	Kahaloo Upazilla Health Complex	0	1987.31	450	0	15	Good	Yes	Yes	Boundary wall is of low height and vertical extension of boundary wall will not be feasible.
6	nandigram	Nandigram Upazilla Health Complex	0	1873.22	0	0	20	Internal CC Road with guide wall is existed, but need to improve and rennovate.	No	Yes	
7	sariakandi	Sariakandi Upazilla Health Complex	0	2500	0	0	20	Internal CC Road with guide wall is existed, but need to improve and	No	Yes	

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
								rennovate.			
8	shajahanpur	Shajahanpur Upazilla Health Complex	0	1867.23	0	0	20	Internal CC Road with guide wall is existed, but need to improve and rennovate.	No	Yes	
9	sherpur	Sherpur Upazilla Health Complex	0	2007.15	0	0	20	Internal CC Road with guide wall is existed, but need to improve and rennovate.	No	Yes	
10	shibganj	Shibganj Upazila Health Complex	0	2121	300	1821	25	Internal road scenario is in poor condition because damaged carpeting.	Yes	Yes	Existing 2121' boundary is of low height and poor condition. 300 ft new boundary with retaining wall required along the nearby river.
11	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	0	1631.17	0	400	14	Internal road scenario is in poor condition because damaged carpeting.	Yes	Yes	OPD bldg is constructed beside the old hospital building. Old hospital building and OPD building are connected by corridor. Vertical extension of existing 1631.17' is required.

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	adamdighi	Adamdighi Upazila Health Complex, Adamdighi, Bogura	0	0	N/A	12	18	no	no	5.5	0	standby pump required	Not Present	not present
2	dhupchanchia	Dupchanchia Upazila Health Complex	0	0	N/A	8	10		no	5.5	0	10 HP stand by needed	Not Present	required
3	kahaloo	Sonatala Upazila Health Complex, Sonatala, Bogura	0	0	N/A	9			Not available	15	0		Not Present	Medical Waste Management system will be required.
4	shibganj	Shibganj Upazila Health Complex	0	0	N/A	12	18	Central AC required	Not available	5.5	5.5	2 Nos 5.5 HP pump required for UHC and residential area.	Incinerator Type	Not required
5	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	0	0	N/A	9	15		Not available	15	0		Not Present	Medical Waste Management system will be required.

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	adamdighi	Adamdighi Upazila Health Complex, Adamdighi, Bogura	NESCO	No	110	0	250	poor	30	60	0	0	25 rm, 80m distance LT	poor	
2	dhupchanchia	Dupchanchia Upazila Health Complex	NESCO	No	100	0	250	poor	30	60	0	0	25 rm, 100 meter	poor	
3	shibganj	Shibganj Upazila Health Complex	NESCO	No	120	0	0	poor	5	30	0	0	25 rm, 100 meter	poor	

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
4	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	REB	Yes	50	50	250	Pole mounted transformer and MDB	15	60	0	0	1C-4x25 sqmm Armoured cables	1C-4x25 sqmm Armoured cables	

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	adamdighi	Adamdighi Upazila Health Complex, Adamdighi, Bogura	No	0	0	0	Yes	No	No	No	Yes	0	Solar, PABX, Overhead Line, Medical gas Plant, Computer network needed	
2	dhupchanchia	Dupchanchia Upazila Health Complex	No	0	0	0	Yes	No	No	No	Yes	0	sufficient CCTV, Compound Light, Fire protection system etc. needed	
3	dhupchanchia	Dupchanchia Upazila Health Complex	No	0	0	required	Yes	No	No	No	Yes	0	CCTV, PABX, PA system, Security light, overhead line etc. required	
4	shibganj	Shibganj Upazila Health Complex	No				Yes	No	Yes	No	Yes	0	Medical gas system for 101 bed hospital will be required.	
5	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	No	0	0	0	Yes	No	No	No	Yes	0	Medical gas plant,sufficient CCTV, Compound Light, Fire protection system etc. needed	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	adamdighi	Adamdighi Upazila Health Complex, Adamdighi, Bogura	OPD building (New Hospital Building)	N/A	2002	3	7455.74	2200	Good	1 dwg	5 jpegs	
2	dhupchanchia	Dupchanchia Upazila Health Complex	OPD building (New Hospital Building)	N/A	2002	2	7534	14896	Good	2 pdfs	2 jpgs	
3	kahaloo	Kahaloo Upazila Health Complex	2nd Class Quarter		1982	3	2500	7000	abandoned	No file	1 mp4	
4	kahaloo	Kahaloo Upazila Health Complex	1st Class Quarter (Old)		1982	2	2500	4800	abandoned	No file	1 mp4	
5	kahaloo	Kahaloo Upazila Health Complex	1st Class Quarter (new)		2002	2	3350	6200	Good	No file	2 jpegs	GF of this building used as hospital's female ward and FF is being used as administrative block.
6	kahaloo	Kahaloo Upazila Health Complex, Bogura	OPD building (New Hospital Building)		2002	2	6778	13556	Good	2 dwgs	2 jpegs	OPD building is connected with the old hospital building by corridor.
7	shibganj	Shibganj Upazila Health Complex	Shibganj Health Complex New Building (OPD)	N/A	2004	2	6778	13556	Poor	2 pdfs	1 jpeg	being used
8	shibganj	Shibganj Upazila Health Complex	Garrage cum driver shed	N/A	2024	2	670	1340	Good	1 pdf	1 jpeg	being used
9	shibganj	Shibganj Upazila Health Complex	4th class quarter	N/A	2004	2	1600	3200	poor	1 pdf	1 jpeg	Building is being used
10	shibganj	Shibganj Upazila Health Complex	Nurse's Quarter-1		2002	3	3280	7900	Poor	1 pdf	1 jpeg	the building is being used

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
11	shibganj	Shibganj Upazila Health Complex	Nurse's Quarter-2		2002	3	3280	7900	Poor	1 pdf	1 jpeg	the building is being used
12	shibganj	Shibganj Upazila Health Complex	1st Class Quarter	NA	2004	3	3280	7900	Poor	1 pdf	3 jpegs	the building is being used
13	shibganj	Shibganj Upazila Health Complex	Doctors Quarter	N/A	2004	3	2700	6700	Poor	1 pdf	1 jpeg	Building is being used
14	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	Nurses' Dormitory		2003	1	1200	1100	Good	No file	1 jpeg	
15	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	Junior Consultant's dormitory		2003	1	1024	900	abandoned	No file	1 jpeg	
16	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	TFPO quarter		1992	1	1050	1000	Good	No file	1 jpeg	
17	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	4th class quarter 2		2003	2	1209.36	2300	Good	No file	1 jpeg	
18	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	4th class quarter-1		1992	2	1405	2600	Good	No file	1 jpeg	
19	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	3rd Class Quarter		1992	4	1431.34	5200	Good	No file	1 jpeg	
20	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	2nd Class Quarter		2003	2	2152.6	4000	Poor	No file	2 jpegs	
21	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	1st Class Quarter		1992	4	2260	8000	Good	No file	2 jpegs	Reparable
22	sonatala	Sonatala Upazila Health Complex, Sonatala, Bogura	OPD building		2003	2	5650	10000	Poor	1 dwg	2 jpegs	Stakeholders claimed poor condition of this OPD building. They experience shaking even in minor earth-quake.

District Name: Brahmanbaria

General Information

Sl No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	bancharampur	Bancharampur Upazilla Health Complex		HED	avaiable	50	1 dwg	No file	No file	No file			No file	No file	No file		

District Name: Chandpur

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	faridganj	Faridganj 50 bedded health complex, Faridganj					1 dwg	No file	No file	No file			No file	No file	No file		
2	haimchar	Haimchar 50 bedded health complex, Haimchar					1 dwg	No file	No file	No file			No file	No file	No file		
3	hajiganj	Hajiganj 50 bedded health complex, Hajiganj					1 dwg	No file	No file	No file			No file	No file	No file		
4	kachua	KACHUA 50 BEDDED HEALTH COMPLEX, KACHUA				50	1 dwg	No file	No file	No file			No file	No file	No file		
5	matlab_north	Matlab 50 bedded health complex, Matlab					1 dwg	No file	No file	No file			No file	No file	No file		
6	shahrasti	Shahrasti 50 bedded health complex, Shahrasti					1 dwg	No file	No file	No file			No file	No file	No file		

District Name: Chapai Nawabganj

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	bholahat	50 Beded UHC, Bholahat	No file	
2	gomastapur	50 Beded UHC, Gomostapur	No file	
3	nachole	50 Beded UHC, Nachole	No file	
4	shibganj	50 Beded UHC, Shibganj	No file	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	bholahat	50 Beded UHC, Bholahat	1982	Other			1 dwg, 1 pdf	1 pdf	1 pdf	1 dwg	6850	20550	1 dwg	No file	1 jpeg		one old Building 2 storied Brick structure Plinth area 10710sft, Total floor area 21710(construction year 1982)sft, new building cons. year 2010
2	gomastapur	50 Beded UHC, Gomostapur	2010	HED		50	1 dwg, 1 pdf	1 pdf	No file	1 dwg	9059	33195	1 dwg	No file	1 jpeg		one old Building 3 storied RCC structure Plinth area 6850 sft, Total floor area 20550(construction year 2006)sft, New building Cons. year 2023
3	nachole	50 Beded UHC, Nachole	1982	Other		50	1 dwg, 1 pdf	1 pdf	1 pdf	1 dwg	9059	33195	1 pdf	No file	1 jpeg		one old Building 3 storied RCC structure Plinth area 6850 sft, Total floor area 20550(construction year 2006)sft, new building cons. year 2023
4	shibganj	50 Beded UHC, Shibganj	1982	Other		50	1 dwg, 1 pdf	1 pdf	1 pdf	No file	6850	20550	1 dwg	No file	1 jpeg		one old Building 2 storied Brick structure Plinth area 8000 sft, Total floor area 13600(construction year 1982)sft. New building cons. year 2010.

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	bholahat	Bholahat Upazila Health Complex, Chapai Nawabganj	10	2.5	3	Footing	4	RCC		No file	Not Possible		
2	gomastapur	Gomastapur Upazila Health Complex, Chapai Nawabganjj	10	2.5	3	Mat	6	RCC		No file	Not Possible		
3	nachole	Nachol Upazila Health Complex, Chapai Nawabganj	10	2.5	3	Mat	6	RCC		No file	Not Possible		
4	shibganj	Shibganj Upazila Health Complex, Chapai Nawabganj	10	2.5	3	Footing	4	RCC		No file	Not Possible		

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	bholahat	Bholahat Upazila Health Complex, Chapai Nawabganj		2		Septic Tank	5280	No		Not Good	Master Drain required		
2	gomastapur	Gomastapur Upazila Health Complex, Chapai Nawabganj	25000	2		Septic Tank	3960	No		Not Good	Master Drain required		
3	nachole	Nachol Upazila Health Complex, Chapai Nawabganj	25000	2		Septic Tank	3960	No		Not Good	Master Drain required		
4	shibganj	Shibganj Upazila Health Complex, Chapai Nawabganj		2		Septic Tank	5280	No		Not Good	Master Drain required		

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	bholahat	Bholahat Upazila Health Complex, Chapai Nawabganj		2470	0	0	16.5	RCC	Yes	Yes	
2	gomastapur	Gomastapur Upazila Health Complex, Chapai Nawabganj		2264	0	0	19	RCC	No	Yes	
3	nachole	Nachol Upazila Health Complex, Chapai Nawabganj		2250	0	0	21	RCC & HBB	Yes	Yes	
4	shibganj	Shibganj Upazila Health Complex, Chapai Nawabganj		1909	0	0	20	RCC	Yes	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	bholahat	50 bedded Upazila Health Complex, Bholahat	0	0		20	50		N/A	9	0	NEW PUMP 10 HP with boring	Not Present	needed
2	gomastapur	50 bedded Upazila Health Complex, Gomastapur	0	0		20	50		N/A	9	0	NEW PUMP 10 HP with boring	Not Present	needed
3	nachole	50 bedded Upazila Health Complex, Nachole	0	0		20	50		N/A	9	0	NEW PUMP 10 HP with boring	Not Present	needed
4	shibganj	50 bedded Upazila Health Complex, Shibganj	0	0		20	50		N/A	11	0	NEW PUMP 10 HP with boring	Not Present	needed

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	bholahat	50 bedded Upazila Health Complex, Bholahat	REB	No	80	100	20	Pole Mounted (No LT, HT, PFI, MDB)	10	50	0	0	35 RM, LT= 20ft	FDB 10 RM, 30m. MDB 25 RM, 45m. ELT 6RM, 20m.	No L/A
2	gomastapur	50 bedded Upazila Health Complex, Gomastapur	NESCO	No	80	100	20	Pole Mounted (No LT, HT, PFI, MDB)	10	50	0	0	35 RM, LT= 20ft	FDB 10 RM, 35m. MDB 25 RM, 40m. ELT 6RM, 20m.	
3	nachole	50 bedded Upazila Health Complex, Nachole	NESCO	No	80	100	20	Pole Mounted (No LT, HT, PFI, MDB)	10	50	0	0	35 RM, LT= 20ft	FDB 10 RM, 35m. MDB 25 RM, 40m. ELT 6RM, 20m.	No L/A
4	shibganj	50 bedded Upazila Health Complex, Shibganj	NESCO	No	80	100	20	Pole Mounted (No LT, HT, PFI, MDB)	10	50	0	0	35 RM, LT= 20ft	FDB 10 RM, 30m. MDB 25 RM, 50m. ELT 6RM, 20m.	No L/A

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	bholahat	50 bedded Upazila Health Complex, Bholahat	No	0	0		Yes	No	Yes	No	Yes	0	Medical gas system, PA system, PABX system needed	
2	gomastapur	50 bedded Upazila Health Complex, Gomastapur	No	0	0		Yes	No	Yes	No	Yes	0	Medical gas system, PA system, PABX system needed	
3	nachole	50 bedded Upazila Health Complex, Nachole	No	0	0		Yes	No	Yes	No	Yes	0	Medical gas system, PA system, PABX system needed	
4	shibganj	50 bedded Upazila Health Complex, Shibganj	No	0	0		Yes	No	Yes	No	Yes	0	Medical gas system, PA system, PABX system needed	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	bholahat	Bholahat Upazila Health Complex, Chapai Nawabganj	50 Bed Hospital Buiding (Old))		1982	2	10710	21710		No file	No file	
2	bholahat	Bholahat Upazila Health Complex, Chapai Nawabganj	50 Bed Hospital Buiding(New)		2010	3	6850	20550		No file	No file	
3	gomastapur	Gomastapur Upazila Health Complex, Chapai Nawabganj	50 Bed Hospital Buiding (Old))		2006	3	6850	20550		No file	No file	
4	gomastapur	Gomastapur Upazila Health Complex, Chapai Nawabganj	50 Bed Hospital Buiding(New)		2023	4	9059.59	33195.18		No file	No file	
5	nachole	Nachol Upazila Health Complex, Chapai Nawabganj	51 Bed Hospital Buiding (Old))		2006	3	6850	20550		No file	No file	
6	nachole	Nachol Upazila Health Complex, Chapai Nawabganj	50 Bed Hospital Buiding(New)		2023	4	9059.59	33195.18		No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
7	shibganj	Shibganj Upazila Health Complex, Chapai Nawabganj	50 Bed Hospital Buiding (Old))		1982	2	8000	13600		No file	No file	
8	shibganj	Shibganj Upazila Health Complex, Chapai Nawabganj	50 Bed Hospital Buiding(New)		2010	3	6850	20550		No file	No file	

District Name: Chattogram

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	anwara	Upazila Health Complex, Anowara, Chattogram	1 xlsx	The attached form is filled up with the help of the medical officer of Upazila Health Complex, Anwara, hattogram
2	banshkhali	Banshkhali Upazila Health Complex	No file	
3	boalkhali	Boalkhali Upazila Health Complex	1 xlsx	
4	chandanaish	Chandanaish Upazila Health Complex	No file	
5	fatikchhari	Upazila Health Complex, Fatikchhari, Chattogram	No file	
6	hathazari	Upazila Health Complex Hathazari	No file	
7	karnaphuli	Upazila Health Complex, Karnaphuli, Chattogram	No file	The building is yet to be constructed
8	lohagara	Lohagara Upazila Health Complex	No file	
9	mirsharai	Mirsharai Upazila Health Complex	1 xlsx	ok
10	patiya	Patiya Upazila Health Complex	No file	
11	rangunia	Upazila Health Complex, Rangunia, Chattogram	1 xlsx	
12	raozan	Upazila Health Complex, Raozan, Chattogram	1 xlsx	The attached form is filled up with the help of Medical Officer of Upazila Health Complex, Raozan, Chattogram
13	satkania	Satkania Upazila Health Complex	No file	
14	sitakunda	Sitakunda Upazila Health Complex	1 xlsx	Information collected from UHFPO Sitakunda

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	anwara	Upazila Health Complex, Anowara, Chattogram (Indoor Building)	1988	Other	Shown in the digital survey map	31	1 dwg, 1 pdf	No file	1 dwg	1 dwg	15400.92	15400sft (each Floor)	1 dwg	No file	8 jpegs		The Indoor building is in unstable condition
2	anwara	Upazila Health Complex, Anowara, Chattogram (Outdoor Building)	2006	HED	Shown in the digital survey map	19	1 dwg, 1 pdf	No file	1 dwg	1 dwg	15400.92	15400sft (each Floor)	1 dwg	No file	10 jpegs		The Outdoor Building is in fairly good condition
3	banshkhali	Banshkhali Upazila Health Complex	1965	PWD		50	No file	No file	No file	No file			No file	No file	No file		
4	boalkhali	Boalkhali Upazila Health Complex	1965	PWD		50	1 pdf	No file	No file	No file			No file	No file	7 jpegs		
5	chandanaish	Chandanaish Upazila Health Complex	1965	PWD		50	No file	No file	No file	No file			No file	No file	No file		
6	fatikchhari	Upazila Health Complex, Fatikchhari, Chattogram (Indoor Building)	1965	PWD	Shown in the digital survey report	50	1 dwg	No file	1 dwg	No file	7223.16		1 dwg	No file	3 jpegs, 1 mp4		
7	fatikchhari	Upazila Health Complex, Fatikchhari, Chattogram (Outdoor Building)	2006	HED	Shown in the digital survey report	0	1 dwg, 1 pdf	No file	1 dwg	1 dwg	5087	5087sft (each floor)	1 dwg	No file	4 jpegs, 1 mp4		

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
8	hathazari	Upazila Health Complex, Hathazari, Chattogram(Indoor Building)	1975	PWD	Some lands are exist in hospital compound on the East side which are shown in the survey report	50	2 dwgs, 1 pdf	No file	1 dwg, 2 pdfs	2 dwgs, 1 pdf	7223.16	North Indoor building ground & 1st floor(each)=3264.87 sft(each floor), Middle Indoor building ground & 1st floor(each)=1093.10 sft(each floor), South Indoor Building ground & 1st floor(each)=2865.19 sft(each floor)	1 pdf	No file	2 jpegs, 1 mp4		Bench mark=4.7 m above mean sea level(MSL)
9	hathazari	Upazila Health Complex, Hathazari, Chattogram (Outdoor Building))	2005	PWD		0	2 dwgs, 1 pdf	No file	1 dwg, 2 pdfs	1 dwg	5087	Outdoor building ground & 1st floor(each)=5087sft(each floor)	2 dwgs	No file	1 jpeg, 1 mp4		
10	karnaphuli	Upazila Health Complex, Karnaphuli, Chattogram	0		N/A	0	1 dwg, 1 pdf	No file	1 dwg	No file	0	0	1 dwg	No file	No file		Building has not been constructed yet
11	lohagara	Lohagara Upazila Health Complex	1965	PWD		50	No file	No file	No file	No file			No file	No file	No file		
12	mirsharai	Mirsharai Upazila Health Complex	1965	HED		50	1 dwg	No file	No file	No file			1 pdf	No file	1 jpeg		
13	patiya	Patiya Upazila Health Complex	1965	PWD		50	1 pdf	No file	No file	No file			No file	No file	No file		
14	rangunia	Upazila Health Complex, Rangunia, Chattogram (Indoor Building)	1965	PWD		50	1 dwg, 1 pdf	No file	1 dwg	No file	7223.16	1st Indoor building ground & 1st floor(each)=3264.87 sft(each floor), 2nd Indoor building ground & 1st floor(each)=1093.10 sft(each floor), 3rd Indoor Building ground & 1st floor(each)=2865.19 sft(each floor)	1 dwg	No file	5 jpegs, 1 mp4		The hospital activities in the Indoor Building are currently closed, the building has been declared abandoned
15	rangunia	Upazila Health Complex, Rangunia, Chattogram (Outdoor Building)	2006	HED	Shown in the digital survey map	0	1 dwg, 1 pdf	No file	1 dwg	1 dwg	5087	Outdoor building ground, 1st floor,2nd floor & 3rd floor(each)=5087sft(each floor)	1 dwg	No file	2 jpegs, 1 mp4		The Outdoor Building is in fairly good condition
16	raozan	Upazila Health Complex, Raozan, Chattogram (New Building)	2006	HED	Shown in the digital survey map	19	1 dwg, 1 pdf	No file	1 dwg	1 dwg	28416.99	28416.99	1 dwg	No file	6 jpegs		Necessary rooms including doctor's chambers, separate gynecological wards, breastfeeding rooms for women, separate children's wards, etc must be provided.
17	raozan	Upazila Health Complex, Raozan, Chattogram (Old Building)	1980	Other	Shown in the digital survey map	31	1 dwg, 1 pdf	No file	1 dwg	1 dwg	28416.99	28416.99	1 dwg	No file	10 jpegs		The roof condition is critical & dangerous. Necessary rooms including doctor's chambers, separate gynecological wards, breastfeeding rooms for women, separate children's wards, etc must be provided.
18	satkania	Satkania Upazila Health Complex	1965	PWD		50	No file	No file	No file	No file			No file	No file	No file		

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
19	sitakunda	Sitakunda Upazila Health Complex	1976	Other		50	1 dwg	No file	No file	No file	15467	7733.5	1 pdf	1 pdf	1 jpeg		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	anwara	Upazila Health Complex, Anwara, Chattogram (Indoor Building)	20	1.33	2	Footing	2	Load Bearing Brick	Not satisfactory	No file	Not Possible		The Indoor building is in unstable condition
2	anwara	Upazila Health Complex, Anwara, Chattogram (Outdoor Building)	20	1.33	2	Deep	4	RCC	Satisfactory	No file	Possible		The Outdoor Building is in fairly good condition
3	banshkhali	Banshkhali Upazila Health Complex	20	1	2	Footing	2	RCC	Visible cracks in beam & roof	No file	Not Possible		
4	boalkhali	Boalkhali Upazila Health Complex	20	1	2	Footing	2	RCC	Visible cracks and concrete spalling in beam, wall & roof	No file	Not Possible		
5	chandanaish	Chandanaish Upazila Health Complex	20	1	2	Footing	2	RCC	Visible cracks and concrete spalling in beam, wall & roof	No file	Not Possible		
6	fatikchhari	Upazila Health Complex, Fatikchhari, Chattogram (Indoor Building)	22	2	2	Footing	2	RCC	Not satisfactory	No file	Not Possible		Indoor Building - The current structural condition of the Building is not very good. It was built around 1965. Moreover, plaster is falling off the roof in several places of the building
7	fatikchhari	Upazila Health Complex, Fatikchhari, Chattogram (Outdoor Building)	44	2	4	Deep	4	RCC	Satisfactory	No file	Not Possible		Outdoor Building -The Building is in fairly good condition
8	hathazari	Upazila Health Complex, Hathazari, Chattogram (Indoor Building)	20	2	2	Footing	2	RCC		No file	Not Possible	N/A	The Building condition is not so good
9	hathazari	Upazila Health Complex, Hathazari, Chattogram (Outdoor Building)	20	2	2	Deep	4	RCC	Satisfactory	No file	Possible		
10	karnaphuli	Upazila Health Complex, Karnaphuli, Chattogram	0	0	0		0			No file			The building has not been constructed yet
11	lohagara	Lohagara Upazila Health Complex	20	1	2	Footing	2	RCC	Visible cracks and concrete spalling in beam, wall & roof	No file	Not Possible		
12	patiya	Patiya Upazila Health Complex	20	1	2	Footing	2	RCC	Visible cracks and concrete spalling in beam, wall & roof	No file	Not Possible		

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
13	rangunia	Upazila Health Complex, Rangunia, Chattogram (Indoor Building)	22	2	2	Footing	2	RCC	Not satisfactory	No file	Not Possible		Indoor Building - The hospital activities in this building are currently closed, the building has been declared abandoned
14	rangunia	Upazila Health Complex, Rangunia, Chattogram (Outdoor Building)	44	2	4	Deep	4	RCC	Satisfactory	No file			The Outdoor Building is in fairly good condition
15	raozan	Upazila Health Complex, Raozan, Chattogram (New Building)	10.5	2	1	Footing	1	Load Bearing Brick	Not satisfactory	No file	Not Possible		Necessary rooms including doctor's chambers, separate gynecological wards, breastfeeding rooms for women, separate children's wards, etc must be provided.
16	raozan	Upazila Health Complex, Raozan, Chattogram (Old Building)	10.5	2	1	Footing	1	Load Bearing Brick	Not satisfactory	No file	Not Possible		The roof condition is critical & dangerous. Necessary rooms including doctor's chambers, separate gynecological wards, breastfeeding rooms for women, separate children's wards, etc must be provided.
17	satkania	Satkania Upazila Health Complex	20	1	2	Footing	2	RCC	Visible cracks and concrete spalling in beam, wall & roof	No file	Not Possible		
18	sitakunda	Sitakunda Upazila Health Complex	22	2.5	2	Footing	2	RCC	Old Building(2 storied building 2 storied foundation) seems structurally vulnerable and new one (2 storied building with 4 storied foundation) is an RCC Building (casted with brick chips) which seems structurally sound.	No file	Not Possible	Not found	New building being used as part of whole Hospital. This building has extended false column but the length of reinforcement in these column is between 2ft to 2.5 ft.

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	anwara	Upazila Health Complex, Anwara, Chattogram	0	1		Others		No		Drainage facility exist			Deep Drainage system is required for the compound
2	banskhali	Banskhali Upazila Health Complex	4000	1	NO	Septic Tank	2000	No		No drainage system	Yes		
3	boalkhali	Boalkhali Upazila Health Complex	5000	1	No	Septic Tank	2000	No		No drainage system	Yes		
4	chandanaish	Chandanaish Upazila Health Complex	4000	1	NO	Septic Tank	1500	No		No drainage system	Yes		
5	fatikchhari	Upazila Health Complex, Fatikchhari, Chattogram	0	1		Septic Tank		No		Shown in Digital survey (The current campus drains are shallow and water occasionally rises, so they need to be built deeper)	The upazila road in front of the compound and the surrounding roads have been raised in a timely manner, which has resulted in waterlogging on the compound at various times. So deep drainage system must be needed	N/A	Deep Drainage system is required for the compound
6	hathazari	Upazila Health Complex, Hathazari, Chattogram	0	1	7 nos of 2000L water tanks are available	Septic Tank		No		Drainage facility exist		No place is available for this purpose	There is no UGWR facilities.
7	karnaphuli	Upazila Health Complex,	0	0								N/A	The building has not been

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
		Karnaphuli, Chattogram											constructed yet
8	Iohagara	Lohagara Upazila Health Complex	4000	1	NO	Septic Tank	2000	No		No drainage system	Yes		
9	patiya	Patiya Upazila Health Complex	4500	1	No	Septic Tank	2000	No		No drainage system	Yes		
10	rangunia	Upazila Health Complex, Rangunia, Chattogram	0	1		Septic Tank		No		Shown in Digital survey (The current campus drains are shallow and water occasionally rises, so they need to be built deeper)	Shown in Digital survey (The current campus drains are shallow and water occasionally rises, so they need to be built deeper)	N/A	Deep Drainage system is required for the compound
11	raozan	Upazila Health Complex, Raozan, Chattogram	0	3		Others		No				N/A	One Deep Tube well among 3 Deep Tube Well is non-functional
12	satkania	Satkania Upazila Health Complex	5000	1	No	Septic Tank	1500	No		No drainage system	Yes		
13	sitakunda	Sitakunda Upazila Health Complex	0	0	Existing OHWT is in the UHC Campus but not in use due vulnerability.	Septic Tank	0		0	Surface Drain	Master Drain	Sitakunda Purasava about 2 Km away	Shallow tubewell is being used for water supply in the hospital.

Ancillary Civil Items

Sl No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	anwara	Upazila Health Complex, Anowara, Chattogram		1895.81			12.18		No	Yes	
2	banshkhali	Banshkhali Upazila Health Complex									
3	boalkhali	Boalkhali Upazila Health Complex									
4	chandanaish	Chandanaish Upazila Health Complex							No	Yes	
5	fatikchhari	Upazila Health Complex, Fatikchhari, Chattogram	159	1486.5	455	935	20		Yes	Yes	The upazila road in front of the compound and the surrounding roads have been raised in a timely manner, which has resulted in waterlogging on the compound at various times.
6	hathazari	Upazila Health Complex, Hathazari, Chattogram		1543.15			28.42	described in digital survey report	Yes	Yes	
7	karnaphuli	Upazila Health Complex, Karnaphuli, Chattogram	0	0							The building has not been constructed yet
8	lohagara	Lohagara Upazila Health Complex							No	Yes	
9	patiya	Patiya Upazila Health Complex							No	Yes	

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
10	rangunia	Upazila Health Complex, Rangunia, Chattogram	0	1495.5	439	1056.5	20		Yes	Yes	Site Development is required
11	raozan	Upazila Health Complex, Raozan, Chattogram		3214.39					No	Yes	Site Development is required
12	satkania	Satkania Upazila Health Complex							No	Yes	
13	sitakunda	Sitakunda Upazila Health Complex		2257					Yes		

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	banshkhali	Upazilla Health Complex, Banshkhali, Chattogram	0	0		18			Fire Extinguisher	14	0	2 nos 5.5 HP pumps are damaged	Not Present	
2	boalkhali	Upazilla Health Complex, Boalkhali, Chattogram	0	0		18			Fire Extinguisher	11	0	1 nos 10 HP and 1 nos 1 HP	Not Present	
3	chandanaish	Upazilla Health Complex, Chandanaish	0	0	0	20	4	All are spilt type	Not present. Only 25 Nos Fire extinguishers present	5	0	Present 5 Hp x 2 nos centrifugal pump are unserviceable, need replace	Not Present	
4	fatikchhari	Upazilla Health Complex, Fatikchhari, Chattogram	0	0		12			Fire Extinguisher	5.5	1		Not Present	
5	hathazari	Upazilla Health Complex, Hathazari, Chattogram	0	0		20			Fire Extinguisher	11	2	centrifugal pump repair needed	Not Present	
6	lohagara	Upazilla Health Complex, Lohagara, Chattogram	0	0		26	8	All are spilt AC	only 10 Nos Fire extinguisher presents, Need Refill, 8 Nos new required	1	5	existing pump should be replaced	Not Present	
7	patiya	Upazilla Health Complex, Patia, Chattogram	0			18	6		18 Nos Fire Extinguisher present	2	5		Not Present	
8	rangunia	Upazilla Health Complex, Rangunia, Chattogram	0	0		16	10	All are split type ac	Only 20 Nos Fire extinguisher present, need 10 Nos extinguisher	2	5		Not Present	
9	raozan	Upazilla Health Complex, Raozan, Chattogram	0	0	0	16	12	all are split type ac, 2 Nos 2 Ton Compressor Need to replace	Only 8 Nos Fire Extinguisher Present, Need additional 10 Nos	2	5	Existing 2 nos pump should be replaced	Not Present	
10	satkania	Upazilla Health complex Satkania, Chattogram	0	0	0	24	10	10	Not Present	2	5	Existing Pump Set need replace & Standby Centrifugal Pump 5 HP required	Not Present	

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	banshkali	Upazilla Health Complex, Banshkali, Chattogram	No			Only oxygen gas available by central cylinder	Yes	No	No	No	Yes	0	CCTV system need to be enhanced	
2	boalkhali	Upazilla Health Complex, Boalkhali, Chattogram	No			Only oxygen gas available by central cylinder	Yes	No	No	No	Yes	1	CCTV system need to be enhanced	
3	chandanaish	Upazilla Health Complex, Chandanaish	No				Yes	No	No	No	Yes	0	5 Nos security light need replace	
4	fatikchhari	Upazilla Health Complex, Fatikchhari, Chattogram	No				Yes	No	No	No	Yes		CCTV system need to be enhanced	
5	hathazari	Upazilla Health Complex, Hathazari, Chattogram	No			Only oxygen gas available by central cylinder	Yes	No	No	Yes	Yes	1	CCTV system need to be enhanced	PABX available only for Doctor's room
6	lohagara	Upazilla Health Complex, Lohagara, Chattogram	No				Yes	No	No	No	Yes	0	5 Nos Security Light & 4 Nos pole required	16 Nos CCTV Present, 6 Nos Required, 32 chanel NVR Required
7	patiya	Upazilla Health Complex, Patia, Chattogram	No				Yes	No	No	No	Yes	0	5 Nos Security Light & 3 Nos Pole are required to replace	
8	rangunia	Upazilla Health Complex, Rangunia, Chattogram	No	0	0	0	Yes	No	No	No	Yes	0	4 Nos Additional Security Light, 2 Nos Pole, 4 Nos CCTV, 1 Nos 32 Port NVR Required	
9	raozan	Upazilla Health Complex, Raozan, Chattogram	No	0	0	0	Yes	No	No	No	Yes	0	3 Nos Security Light should be replaced, Additional 4 Nos CCTV, 4TB Hard Disk needed	
10	satkania	Upazilla Health Complex, satkania, Chattogram	No				Yes	No	Yes	No	Yes	0	Present Security Light supervised by POURASHAVA.	
11	sitakunda	Sitakunda Upazila Health Complex	No				Yes	No		No	Yes	0		

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (If any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	anwara	Upazila Health Complex, Anwara, Chattogram	Staff Quarter, Old Doctor`s Quarter, New Doctor`s Quarter, Family Planning Building, Staff Dormitory				16694.26		3rd & 4th Class Staff Quarters are in unstable condition	No file	No file	3rd & 4th Class Staff Quarters are in unstable condition
2	fatikchhari	Upazila Health Complex, Fatikchhari, Chattogram	Family Planning Center, Residential Building, Mosque, Garage	9						No file	No file	
3	hathazari	Upazila Health Complex, Hathazari, Chattogram	Family Planning Center, Mosque, Garage	3		1	4790.78	4790.78	Building condition is satisfactory	No file	No file	
4	karnaphuli	Upazila Health Complex, Karnaphuli, Chattogram	N/A	0						No file	No file	The building has not been constructed yet
5	rangunia	Upazila Health Complex, Rangunia, Chattogram	Residential Building, Mosque, Garage	13						No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
6	raozan	Upazila Health Complex, Raozan, Chattogram	Union Health & Family Welfare Center, Family Planning Store, Residential Building, Garage, Nurse Quarter, Stuff Quarter						Most of the buildings are in unstable condition	No file	No file	Most of the buildings are in unstable condition
7	sitakunda	Sitakunda Upazila Health Complex	Store (Pharmacy)			1	300	300	Old and vulnerable	No file	No file	
8	sitakunda	Sitakunda Upazila Health Complex	1st Class Quarter (New)		2011	2	2250	4500	Old and vulnerable	No file	No file	
9	sitakunda	Sitakunda Upazila Health Complex	1st Class Quarter (OLD)		1976	3	2250	6750	Old and vulnerable	No file	No file	
10	sitakunda	Sitakunda Upazila Health Complex	2nd class Quarter 800 sft			2	1825	3650	Old and vulnerable	No file	No file	
11	sitakunda	Sitakunda Upazila Health Complex	Dormitory			2	1200	2400	Old and vulnerable	No file	No file	
12	sitakunda	Sitakunda Upazila Health Complex	Old Staff Quarter (3rd Class)		1976	2	1400	2800	Old and vulnerable	No file	No file	
13	sitakunda	Sitakunda Upazila Health Complex	Old Staff Quarter (3rd Class)		1976	2	1400	2800	Old and vulnerable	No file	No file	
14	sitakunda	Sitakunda Upazila Health Complex	Staff Quarter (3rd Class) 600 Sft		2011	2	1400	2800	New Building in use.	No file	No file	
15	sitakunda	Sitakunda Upazila Health Complex	4th class Quarter Building		1976	2	1200	2400	Old and vulnerable	No file	No file	

District Name: Chuadanga

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	alamdanga	Alamdanga Upazila Health complex	1 xlsx	
2	damurhuda	Damurhuda Upazila Health complex	1 xlsx	
3	jibannagar	Jibannagar Upazila Health complex	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	alamdanga	Alamdanga Upazila Health complex		HED		50	1 dwg, 1 pdf	1 pdf	No file	No file	16012.31		No file	No file	No file		
2	damurhuda	Damurhuda Upazila Health complex		HED		50	1 dwg, 1 pdf	1 pdf	No file	No file	16933.82		No file	No file	No file		
3	jibannagar	Jibannagar Upazila Health complex		HED		50	1 dwg, 1 pdf	1 pdf	No file	No file	18713.2		No file	No file	No file		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	32.25	2.25	3	Deep		RCC	R.C.C Fream Structure Building	No file			
2	damurhuda	Upazilla Health Complex		4.5	4	Deep		RCC	R.C.C Fream Structure Building	No file	info not available		
3	jibannagar	Upazilla Health Complex		4.5	4	Deep		RCC	R.C.C Fream Structure Building	No file	info not available		

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga		2		Septic Tank		No		Not Suficient	Describe as Digital Survey		
2	damurhuda	Damurhuda Upazila Health Complex	0	1	0	Septic Tank		No	0				
3	jibannagar	Upazilla Health Complex, jibonnagar	0	1	0	Septic Tank		No	0	Surface Drain	Surface Drain		

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	alamdanga	Alamdanga Upazila Health complex					18				
2	damurhuda	Damurhuda Upazila Health complex					18				
3	jibannagar	Jibannagar Upazila Health complex					25				

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	alamdanga	Upazilla Health Complex, Alamdanga.	0	0	There is no lift installed at present, though the building features a designed core for lift. Existing lift core size= 2400mm x 3000 mm.	42	50		0	7.5	0	40	Not Present	440 Hp Capacity
2	damurhuda	Upazilla Health Complex, Damurhuda	0	0	There is no provision for lift core to installed lift.	20	60		0	7.5	0	New Demand=40 HP	Not Present	440 Hp Capacity
3	jibannagar	Upazilla Health Complex, Jibannagar	0	0	There is no provision for lift core to installed lift.	30	70		0	7.5	0	New Demand=40 HP	Not Present	440 Hp Capacity

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	alamdanga	Upazilla Health Complex, Alamdanga	REB	No	150	150	0	LT, HT, PFI & MDB is serviceable	60	100	0	0	Overhead HT=100 sqmm Dog cable=482 meter, Under Ground HT=50 sqmm XLPE cable=38 meter.	LT Cable size=1C-4x95 sqmm NYY=26 meter,ELT Cable Size=1C-4x25 sqmm NYY=35 meter,MDB Cable Size=1C-4x70 sqmm NYY Cable=45 meter, EMDB Cable Size=1C-4x25 sqmm NYY Cable=45 meter.FDB Cable size=1C-4x25 sqmm NYY Cable=75 meter,EFDB Cable size=1C-4x10 sqmm NYY Cable=75 meter.LT Overhead Line= 50 sqmm ANT Cable=4263 meter.	
2	damurhuda	Upazilla Health Complex, Damurhuda	REB	No	150	150	0	LT, HT, PFI & MDB is serviceable	0	150	0	0	Overhead HT=100 sqmm Dog cable=120 meter, Under Ground HT=50 sqmm XLPE cable= 46 meter.	LT Cable size=1C-4x95 sqmm NYY=25 meter,MDB Cable Size=1C-4x95 sqmm NYY Cable=80 meter,,FDB Cable size=1C-4x25 sqmm NYY Cable=75 meter.LT Overhead Line= 50 sqmm ANT Cable=3353 meter.	
3	jibannagar	Upazilla Health Complex,Jibannagar	REB	No	150	150	0	LT, HT, PFI & MDB is serviceable	0	150	0	0	Overhead HT=100 sqmm Dog cable=330 meter, Under Ground HT=50 sqmm XLPE cable= 42 meter.	LT Cable size=1C-4x95 sqmm NYY=25 meter,MDB Cable Size=1C-4x95 sqmm NYY Cable=80 meter,,FDB Cable size=1C-4x25 sqmm NYY Cable=75 meter.LT Overhead Line= 50 sqmm ANT Cable=3889 meter.	

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	alamdanga	Upazilla Health Complex, Alamdanga.	No	0	0	there is no central medical gas facility installed at this hospital.	Yes	No	No	No	Yes	0		
2	damurhuda	Upazilla Health Complex, Damurhuda.	No	0	0	there is no central medical gas facility installed at this hospital.	Yes	No	No	No	Yes	0		
3	jibannagar	Upazilla Health Complex, jibannagar	No	0	0	there is no central medical gas facility installed at this hospital.	Yes	No	No	No	Yes	0		

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Building-5	2023		3	1407.93	4223.79		No file	No file	
2	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Building-4	2023		1	784.48			No file	No file	
3	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Building-3	2023		1	546.7			No file	No file	
4	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Building-2	2023		1	1156.69			No file	No file	
5	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Mosque	2023		1	1513.09			No file	No file	
6	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Garage-2	2023		1	484.81			No file	No file	
7	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Building-1	2023		1	725.17			No file	No file	
8	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Abandoned Building-4	1973		1	269.32			No file	No file	
9	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Abandoned Building (Padma)-3	1973		1	1241.3			No file	No file	
10	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Abandoned Building-2	1973		1	334.22			No file	No file	
11	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Abandoned Building-1	1973		1	1504.81	1504.81		No file	No file	
12	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Generator Building	2006		1	554.45	554.45		No file	No file	
13	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Store	2006		1	905.47	905.47		No file	No file	
14	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Nurse Building-2	2023		3	1797.27	5391.8		No file	No file	
15	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Nurse Building-1	2023		3	1505.88	4517.65		No file	No file	
16	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Pharmacist	2023		2	2818.23	5636.46		No file	No file	
17	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Family Planning	2023		1	1851.62	1851.62		No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
18	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Garage-1	2023		1	538.09	538.09		No file	No file	
19	alamdanga	Upazilla Health Complex Alamdanga, Chuadanga	Doctor quarters	1973		2	2271.53	4543.05		No file	No file	
20	damurhuda	Upazilla Health Complex, damurhuda	Doctor Quater		1973	2	2749.66		Dilapidated Building	No file	No file	
21	damurhuda	Upazilla Health Complex, damurhuda	Mosque		1973	1	1855.18		Dilapidated Building	No file	No file	
22	jibannagar	Jibannagar Health Complex	Staff Quarter-2		1973	2	2588		Dilapidated Building	No file	No file	
23	jibannagar	Jibannagar Health Complex	Staff Quarter-1		1973	2	2701.5		Dilapidated Building	No file	No file	
24	jibannagar	Jibannagar Health Complex	Dormetory		1973	2	966.28		Dilapidated Building	No file	No file	
25	jibannagar	Jibannagar Health Complex	Nurse Quater-2		1973	2	927.74		Dilapidated Building	No file	No file	
26	jibannagar	Jibannagar Health Complex	Nurse Quater-1		1973	2	1151		Dilapidated Building	No file	No file	

District Name: Cox's Bazar

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	kutubdia	Upazilla Health Complex, Kutubdia	1 xlsx	Information colleted from UHFPO
2	maheshkhali	Upazilla Health Complex, Moheshkhali	1 xlsx	Information collected from UHFPO
3	pekua	Upazilla Health Complex, Pekua	No file	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	maheshkhali	Upazilla Health Complex, Maheshkhali	0	1		Septic Tank		No	0	Compound drain connected to Pouroshova drainage system	Need to construct master drain to cover total area	Waste disposal in health complex compound by their own staff and Pouroshova	There are 5 shallow tubewell

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	maheshkhali	Upazilla Health Complex, Maheshkhali	0	1878	0	0	23	There are RCC road, width ranges from 8 to 12.5 ft. Condition good	No		There is a pond in the complex which area is 35132 sft

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	pekua	Upazilla Health Complex, Pekua	0	0	There is a lift core	40	50		Only Extinguisher	10	0		Autoclave	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	pekua	Upazilla Health Complex, Pekua	REB	No		250			132	0	0	0			

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	pekua	Upazilla Health Complex, Pekua	Yes		20		No	No	No	Yes	Yes	1		

District Name: Cox's_Bazar

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	ramu	Upazilla Health Complex, Ramu	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	kutubdia	Upazilla Health Complex, Kutubdia	2014	HED		20	1 dwg, 1 pdf	No file	No file	No file	6452	21428	No file	No file	1 jpeg		
2	maheshkhali	Upazilla Health Complex, Maheshkhali	1964	PWD	No	50	1 dwg, 1 pdf	No file	No file	No file	5471	6785.51	No file	No file	1 jpeg		
3	pekua	Upazilla Health Complex, Pekua	1995	HED		50	1 dwg, 1 pdf	No file	No file	No file		9175.13	No file	No file	1 jpeg		
4	ramu	Upazilla Health Complex, Ramu	2020	HED		50	1 dwg	No file	No file	No file	7992	7992	No file	No file	10 jpegs		
5	teknaf	Upazilla Health Complex, Teknaf	2008	HED		50	1 dwg, 1 pdf	No file	No file	No file		28950	No file	No file	No file		
6	ukhia	Upazilla Health Complex, Ukhiya				31	1 dwg, 1 pdf	No file	No file	No file	9472	9472	No file	No file	No file		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	kutubdia	Upazilla Health Complex, Kutubdia			3	Footing	0	RCC	No cracks seen.	1 jpeg			
2	maheshkhali	Upazilla Health Complex, Maheshkhali	20	0.67	2	Footing		RCC	The block of male and female ward already abandoned due to severe cracks in ceiling and beam, rebars are being exposed.	1 jpeg	Not Possible		HED constructs a new building of 31 beded named New Male and Female Ward of 1 story with 4 story foundation by the fund of World Bank
3	pekua	Upazilla Health Complex, Pekua			4	Deep	0	RCC	4 storied hospital block with 7 storied foundation. No crack found. Water leakage issue in top floor.	1 jpeg		Regular maintenance including roof treatment	Pre cast pile with 75 feet in length info provided by UNHFPO
4	ramu	31 beded Old Hospital Building, Ramu			1				Old and not in good condition.	No file	Not Possible		Need to demolish
5	ramu	Ramu Upazilla Health Complex (New Main Hospital OPD Building)			3		5		Good	No file	Possible		
6	teknaf	Teknaf Upazilla Health Complex (31 beded Old Hospital Building)	10	2.5	1			Load Bearing Brick	Old and not in good condition.	No file	Not Possible		Need to demolish
7	teknaf	Teknaf Upazilla Health Complex (New Main Hospital OPD Building)	30	2.5	3		4	RCC	Good	No file	Possible		

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
8	ukhia	Ukhiya Upazilla Health Complex (31 beded Old Hospital Building)			2				Old and not in good condition.	No file	Not Possible		
9	ukhia	Ukhiya Upazilla Health Complex (New Main Hospital OPD Building)			3		4		Good	No file	Possible		

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	kutubdia	Upazilla Health Complex, Kutubdia	0	4		Septic Tank		No	0	Used water flowes into a compound ditch	Need to construct master drain to cover total area	Outside canal	No standard medical waste management system.
2	pekua	Upazilla Health Complex, Pekua	0	2		Septic Tank		No		Compound drain connected to Pouroushova drainage system	Need to construct master drain to cover total area		
3	ramu	Ramu Upazilla Health Complex (New Main Hospital OPD Building)		1	No	Septic Tank		No		Area is located at hilly area and that's why drainage facility is based on natural slope.	Need to update some master drain and connecting drain.	Natural Dumping	No standard medical waste management system.
4	teknaf	Teknaf Upazilla Health Complex		5	Teknaf Pouroushova	Septic Tank		No		Good drainage system connected with local pouroushova drain in the main Road.	Need to construct & repair some master drain and connecting drain.	Pouroushova Drainage system	No standard medical waste management system. Local NGO constructed a waste zone to burn the medical waste.
5	ukhia	Ukhiya Upazilla Health Complex (New Main Hospital OPD Building)		7	Water supply facilated by DPHE	Septic Tank		No		Area is located at hilly area and that's why drainage facility is based on natural slope.	Need to construct master drain to cover total area	Natural Dumping	No standard medical waste management system. Local NGO constructed a waste zone to burn the medical waste.

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	kutubdia	Upazilla Health Complex, Kutubdia	0	2245	0	0	18	RCC Rigid pavement, width ranges from 10 to 15 ft.	No	No	There is a pond in the complex which area is 32858 sft
2	pekua	Upazilla Health Complex, Pekua	0	1125.25	0	0	17	RCC road, width ranges from 10 to 13.5 ft. Total	No	No	
3	ramu	Ramu Upazilla Health Complex	400	1690			22	Both Bitumious and RCC road. Width ranges from 10-12 ft	Yes	No	Hilly area
4	teknaf	Teknaf Upazilla Health Complex		2137			30	RCC Rigid pavement, width ranges from 10 to 12 ft.	No	No	Plain Land
5	ukhia	Ukhiya Upazilla Health Complex		3030	750	500	12	There are both bitiminous and RCC road, width ranges from 10 to 12 ft. There is a 250 rft HBB road infront of Adm building.	No	No	Hilly area

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	kutubdia	Upazilla Health Complex, Kutubdia	0	0	0	30	20		Fire Extinguishers, Expired.	3	4		Not Present	
2	ramu	Upazilla Health Complex, Ramu	0	0		22	28		Only Fire Extinguishers	3.5	5.5		Incinerator Type	
3	ukhia	Upazilla Health Complex, Ukhia	0	0		44	6		There are smoke sensors and Fire Extinguishers	6	3		Incinerator Type	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	kutubdia	Upazilla Health Complex, Kutubdia	PDB	No	35	0	0		30	0	40	0			Generator isn't used.
2	ramu	Upazilla Health Complex, Ramu	REB	No	200	300	100		100	0	20				
3	ukhia	Upazilla Health Complex, Ukhia	REB	No		300			150		20				Generator isn't used.

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	kutubdia	Upazilla Health Complex, Kutubdia	Yes		20	Medical Gas System is present but isn't in use.	Yes	No	No	No	Yes	0		
2	ramu	Upazilla Health Complex, Ramu	Yes		50		Yes	Yes	No	No	No	0		
3	ukhia	Upazilla Health Complex, Ukhia	Yes		30	Medical Gas System isn't in operation	Yes	No	No	No	No	0		

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	kutubdia	Kutubdia Upazilla Health Complex	Waste Zone			1	670	670	Semi paka	No file	No file	
2	kutubdia	Kutubdia Upazilla Health Complex	Emergency Building			1	628	628	Good Condition	No file	No file	
3	kutubdia	Kutubdia Upazilla Health Complex	Security Guard			1	220	220	Good Condition	No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
4	kutubdia	Kutubdia Upazilla Health Complex	Old Security Guard			1	220	220		No file	No file	Abandoned
5	kutubdia	Kutubdia Upazilla Health Complex	Extension of Mosque			1	372	372	tin shed	No file	No file	
6	kutubdia	Kutubdia Upazilla Health Complex	Mosque			1	634	634	Good Condition	No file	No file	
7	kutubdia	Kutubdia Upazilla Health Complex	Family Planing			2	1558	3116	Good Condition	No file	No file	Abandoned
8	kutubdia	Kutubdia Upazilla Health Complex	Nurses Quarter			2	1895	3790	Good Condition	No file	No file	
9	kutubdia	Kutubdia Upazilla Health Complex	Nurses Quarter			3	1485	4455	Building in good condition.	No file	No file	
10	kutubdia	Kutubdia Upazilla Health Complex	Doctor's Quarter			2	2356	4712	Building in good condition.	No file	No file	
11	kutubdia	Kutubdia Upazilla Health Complex	Generator room			1	223	223	Building in good condition.	No file	No file	
12	kutubdia	Kutubdia Upazilla Health Complex	Generator room			1	300	300		No file	No file	Abandoned
13	kutubdia	Kutubdia Upazilla Health Complex	Old Health Complex Building			2	5857	11714		No file	No file	Abandoned
14	kutubdia	Kutubdia Upazilla Health Complex	Kitchen			1	515	515	Good Condition	No file	No file	
15	kutubdia	Kutubdia Upazilla Health Complex	Oxygen Cylinder Store			1	302	302		No file	No file	Abandoned
16	maheshkhali	Moheshkhali Upazilla Health Complex	Waiting shed			1	286	286	Tinshed semipacca Building.	No file	No file	
17	maheshkhali	Moheshkhali Upazilla Health Complex	Guard room			1	660	660		No file	No file	Abandoned
18	maheshkhali	Moheshkhali Upazilla Health Complex	Medical waste zone			1	798	798	Tinshed semipacca Building.	No file	No file	
19	maheshkhali	Moheshkhali Upazilla Health Complex	3rd class staff quarter			1	1050	1050		No file	No file	Abandoned
20	maheshkhali	Moheshkhali Upazilla Health Complex	3rd class staff quarter		2007	1	2085	2085		No file	No file	Abandoned
21	maheshkhali	Moheshkhali Upazilla Health Complex	4th class staff quarter		2007	3	1506	4518	Good Condition	No file	No file	
22	maheshkhali	Moheshkhali Upazilla Health Complex	3rd class staff quarter		2008	3	1940	5820	Good Condition	No file	No file	
23	maheshkhali	Moheshkhali Upazilla Health Complex	Staff Dormitory			1	660	660		No file	No file	Abandoned
24	maheshkhali	Moheshkhali Upazilla Health Complex	Garrage		2008	1	840	840	Good Condition	No file	No file	
25	maheshkhali	Moheshkhali Upazilla Health Complex	EPI			1	1180	1180	Good Condition	No file	No file	
26	maheshkhali	Moheshkhali Upazilla Health Complex	Doctor's Quarter			2	2786	4282	Good Condition	No file	No file	
27	maheshkhali	Moheshkhali Upazilla Health Complex	Mosque			1	1000	1000	Good Condition	No file	No file	
28	maheshkhali	Moheshkhali Upazilla Health Complex	Sub-station			1	640	640	Good Condition	No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
29	maheshkhali	Moheshkhali Upazilla Health Complex	Pathology Department			2	446	664	Good Condition	No file	No file	
30	maheshkhali	Moheshkhali Upazilla Health Complex	Blood bank			1	361	361	Semi pucca	No file	No file	
31	maheshkhali	Moheshkhali Upazilla Health Complex	X-ray room			1	490	490	Good Condition	No file	No file	
32	maheshkhali	Moheshkhali Upazilla Health Complex	Generator room			1	232	232	Good Condition	No file	No file	
33	maheshkhali	Moheshkhali Upazilla Health Complex	Old ward building			1	4230	4230		No file	No file	Abandoned
34	maheshkhali	Moheshkhali Upazilla Health Complex	Kitchen			1	456	456	Good Condition	No file	No file	
35	maheshkhali	Moheshkhali Upazilla Health Complex	Kitchen			1	304	304	Good Condition	No file	No file	
36	maheshkhali	Moheshkhali Upazilla Health Complex	Doctor's Quarter			2	2400	4800	Building in good condition.	No file	No file	
37	maheshkhali	Moheshkhali Upazilla Health Complex	Doctor's Dormitory			1	1310	1310		No file	No file	Abandoned
38	maheshkhali	Moheshkhali Upazilla Health Complex	Nurse Dormitory			1	1310	1310		No file	No file	Abandoned
39	maheshkhali	Moheshkhali Upazilla Health Complex	Nurse Dormitory			1	1174	1174	Not in Good Condition	No file	No file	
40	maheshkhali	Moheshkhali Upazilla Health Complex	OPD 3 storied builidng			3	6433	19299	Good Condition	No file	No file	
41	maheshkhali	Moheshkhali Upazilla Health Complex	Family planning store building			1	890	890	Good Condition	No file	No file	Height 20 feet
42	maheshkhali	Moheshkhali Upazilla Health Complex	New male and Female ward		2023	1	3711	3711	Building in good condition.	No file	No file	
43	pekua	Pekua Upazila Health Complex	Family Planning Office Building			2	1536.54	3073.08	New Building. Good Condition	No file	No file	
44	pekua	Pekua Upazila Health Complex	Sub-Station Building			1	571.74	571.74	Old Building, Not in Good Condition	No file	No file	
45	pekua	Pekua Upazila Health Complex	Car Garrage Cum Driver Dormitory			2	565.14	1130.28	PL is lower than the road, Old Building. Not in Good Condition	No file	No file	
46	pekua	Pekua Upazila Health Complex	Ambulane Garrage Cum Driver Dormitory			2	472.54	945.08	PL is lower than the road, Old Building. Not in Good Condition	No file	No file	
47	pekua	Pekua Upazila Health Complex	UHFPO Quarter			1	1569.22	1569.22	New Building. Good Condition	No file	No file	
48	pekua	Pekua Upazila Health Complex	Doctors Dormitory			1	842.29	842.29	New Building. Good Condition	No file	No file	
49	pekua	Pekua Upazila Health Complex	Doctors Quarter			2	2158.96	4317.92	Old Building. Not in good condition.	No file	No file	
50	pekua	Pekua Upazila Health Complex	Class IV Staff Quarter			2	1263.89	2527.78	PL is lower than the road, Old Building. Not in Good Condition	No file	No file	
51	pekua	Pekua Upazila Health Complex	Class III Staff Quarter			2	1369.48	2738.96	PL is lower than the road, Old Building. Not in Good Condition	No file	No file	
52	pekua	Pekua Upazila Health Complex	Nurses Dormitory			1	786.9	786.9	PL is lower than the road, Old Building. Not in Good Condition	No file	No file	
53	pekua	Pekua Upazila Health Complex	Hospital Building (New)		2020	4	9086	36344	New Building. good condition.	No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
54	pekua	Pekua Upazila Health Complex	Hospital Building (Old)		1998	3	8280	24840	Old Building. Not in good condition. (Ramp Condition is High risk)	No file	No file	
55	teknaf	Upazilla Health Complex ,Teknaf	Staff Quarter			1	1455	1455	Moderate Condition	No file	No file	
56	teknaf	Upazilla Health Complex ,Teknaf	Staff Quarter			1	1455	1455	Moderate Condition	No file	No file	
57	teknaf	Upazilla Health Complex ,Teknaf	Staff Quarter			1	1455	1455	Moderate Condition	No file	No file	
58	teknaf	Upazilla Health Complex ,Teknaf	Staff Quarter			1	1455	1455	Moderate Condition	No file	No file	
59	teknaf	Upazilla Health Complex ,Teknaf	Staff Quarter			1	1455	1455	Moderate Condition	No file	No file	
60	teknaf	Upazilla Health Complex ,Teknaf	Staff Quarter			1	1455	1455	Moderate Condition	No file	No file	
61	teknaf	Upazilla Health Complex ,Teknaf	Doctors Residence			1	1455	1455	Moderate Condition	No file	No file	
62	teknaf	Upazilla Health Complex ,Teknaf	Doctors Residence			1	1455	1455	Moderate Condition	No file	No file	
63	teknaf	Upazilla Health Complex ,Teknaf	Influenja Department			1	624	624	Tinshed semipacca Building.	No file	No file	
64	teknaf	Upazilla Health Complex ,Teknaf	Pathology Department			1	2095	2095	Tinshed semipacca Building.	No file	No file	
65	teknaf	Upazilla Health Complex ,Teknaf	Male Ward			1	3057	3057	Tinshed semipacca Building.	No file	No file	
66	teknaf	Upazilla Health Complex ,Teknaf	Female Ward			1	3130	3130	Tinshed semipacca Building.	No file	No file	
67	teknaf	Upazilla Health Complex ,Teknaf	Staff Dormitory		2008	2	1790	3580	Good Condition	No file	No file	4 storied foundation
68	teknaf	Upazilla Health Complex ,Teknaf	Nurses Dormitory		2008	4	1345	5380	Good Condition	No file	No file	
69	teknaf	Upazilla Health Complex ,Teknaf	Saff Dormitory		2008	4	1345	5380	Good Condition	No file	No file	
70	teknaf	Upazilla Health Complex ,Teknaf	Doctors Dormitory		2008	4	2566	10264	Good Condition	No file	No file	
71	teknaf	Upazilla Health Complex ,Teknaf	Guest House		2008	1	1428	1428	Good Condition	No file	No file	

District Name: Cumilla

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	adarsha_sadar	Sadar Upazilla Health Complex	No file	
2	barura	Barura Upazilla Health Complex	1 xlsx	
3	brahmanpara	Brahmanpara Upazilla Health Complex	1 xlsx	
4	burichang	Burichang Upazilla Health Complex	1 xlsx	
5	chandina	Chandin Upazilla Health Complex	No file	
6	chauddagram	Chauddagram Upazilla Health Complex	1 xlsx	
7	daudkandi	Daudkandi Upazilla Health Complex	No file	
8	debidwar	Debidwar Upazilla Health Complex	1 xlsx	
9	homna	Homna Upazilla Health Complex	No file	
10	laksam	Laksam Upazilla Health Complex	1 xlsx	
11	lalmai	Lalmai Upazilla Health Complex	No file	
12	meghna	Meghna Upazilla Health Complex	No file	
13	monohargonj	Monohargong Upazilla Health Complex	1 xlsx	
14	muradnagar	Muradnagar Upazilla Health Complex	No file	
15	nangalkot	Nangalkot Upazilla Health Complex	1 xlsx	
16	sadar south	Sadar South Upazilla Health Complex	1 xlsx	
17	titas	Titas Upazilla Health Complex	No file	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	barura	Barura Upazilla Health Complex					1 pdf	No file	No file	No file	9032	8625	No file	No file	No file		
2	homna	Homna Upazilla Health Complex					1 dwg	No file	No file	No file	10770	9770	No file	No file	No file		
3	meghna	Meghna Upazilla Health Complex					1 dwg	No file	No file	No file	15000	14000	No file	No file	No file		
4	monohargonj	Monohargong Upazilla Health Complex					1 dwg	No file	No file	No file	14300	12800	No file	No file	No file		
5	muradnagar	Muradnagar Upazilla Health Complex					1 dwg	No file	No file	No file	16500	15000	No file	No file	No file		
6	sadar_south	Sadar South Upazilla Health Complex					1 dwg	No file	No file	No file	14000	13000	No file	No file	No file		
7	titas	Titas Upazilla Health Complex		HED			1 dwg	No file	No file	No file	14400	13200	No file	No file	No file		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	barura	Barura Upazilla Health Complex	25	2	2	Footing	2	Load Bearing Brick	Not Good	No file	Not Possible	N/A	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	barura	Barura Upazilla Health Complex				Septic Tank		No		Not Good	Yes	Nearest ditch	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	barura	Barura Upazilla Health Complex	1492	1492	500		20	700 feet	No	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (if any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (if any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	adarsha_sadar	Upazila Health Complex, Comilla Sadar South, Comilla	0	0		20			Not Present	2	0		Not Present	
2	barura	Upazila Health Complex, Barura, Cumilla	0	0	0	14			Not Present	7.5	0		Not Present	
3	brahmanpara	50 Bed Upazila Health Complex Brahmanpara, Cumilla	0			20			NP	2.5	0		Not Present	
4	burichang	UHC, Burichang, Cumilla	0			18			NP	5	0		Not Present	
5	chandina	UCH Chandina	0			60			NP	2.25	0		Not Present	
6	chauddagram	50 Bed Upazila Health Complex Chaudhagram Cumilla	0			30			NP	7	0		Not Present	
7	daudkandi	UHC Daudkandi	0			50			NP	2	0		Not Present	
8	debidwar	Upazila Health Complex Debidwar, Cumilla	0			14			NP	2	0		Not Present	
9	homna	UHC Homna	0			20			NP	2	0		Not Present	
10	laksam	UHC Laksam	0			24			NP	5	0		Not Present	
11	lalmai	UCH Lalmai	0			20			NP	2	0		Not Present	
12	meghna	UCH Meghna	0			30			NP	2	0		Not Present	
13	monohargonj	31 Bed Upazila Health Complex, Monoharganj, Cumilla	0			16			Not Present	2	0		Not Present	
14	muradnagar	UHC Muradnagar	0			18			NP	7.5	0		Not Present	
15	nangalkot	Upazila Health Complex	0			20			NP	2	0		Not Present	
16	sadar_south	UCH Sadar	0			20			NP	2	0		Not Present	
17	titas	UCH Titas	0			20			NP	5	0		Not Present	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	adarsha_sadar	UCH Sadar	PDB	Yes	40			0	0						
2	barura	Barura Upazilla Health Complex	REB	Yes	100	150		Yes	60		0	0			
3	brahmanpara	50 Bed Upazila Health Complex Brahmanpara, Cumilla	REB	Yes		150		Yes	0						
4	burichang	UHC, Burichang, Cumilla	REB	Yes		100		Yes	0						
5	chandina	UCH Chandina	REB	Yes	80	100		Yes	0	0					
6	chauddagram	50 Bed Upazila Health Complex Chaudhagram Cumilla	REB	Yes		150		YES	0			0			
7	daudkandi	UHC Daudkandi	REB	Yes		100		Yes	30						
8	debidwar	Upazila Health Complex Debidwar, Cumilla	REB	Yes		100		Yes	0						
9	homna	UHC Homna	REB	Yes		100		Yes	0						
10	laksam	UHC Laksam	REB	Yes		150		YES	0						
11	lalmi	UCH Lalmai	REB	Yes		100		Yes	0						
12	meghna	UCH Meghna	REB	Yes		150		Present	0						
13	monohargonj	31 Bed Upazila Health Complex, Monoharganj, Cumilla	REB	Yes		150		present	0						
14	muradnagar	UHC Muradnagar	REB	Yes		100		Yes	0						
15	nangalkot	Upazila Health Complex	REB	Yes		100		Yes	40			0			
16	sadar_south	Upazila Health Complex, Comilla Sadar South, Comilla	REB	Yes		100		Yes	30			0			
17	titas	UCH Titas	REB	Yes	50	100		Present	0						

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	adarsha_sadar	UCH Sadar	No				No	No	Yes	No	Yes	0		
2	barura	Barura Upazilla Health Complex	No				No	No	Yes	No	No	0		
3	brahmanpara	50 Bed Upazila Health Complex Brahmanpara, Cumilla	No				No	No	Yes	No	No	0		
4	burichang	UHC, Burichang, Cumilla	No				No	No	Yes	No	No	0		
5	chandina	UCH Chandina	No				No	No	Yes	No	No	0		
6	chauddagram	50 Bed Upazila Health Complex Chaudhagram Cumilla	No				No	No	Yes	Yes	No	0		
7	daudkandi	UHC Daudkandi	No				No	No	Yes	Yes	No	0		
8	debidwar	Upazila Health Complex Debidwar, Cumilla	No				No	No	Yes	No	No	0		
9	homna	UHC Homna	No				Yes	No	Yes	No	No			

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
10	laksam	UHC Laksam	No				No	No	Yes	Yes	Yes	0		
11	lalmai	UHC Lalmai	No				No	No	Yes	No	No	0		
12	meghna	UCH Meghna	No				No	No	Yes	No	No	0		
13	monohargonj	31 Bed Upazila Health Complex, Monoharganj, Cumilla	No				No	No	Yes	Yes	Yes	0		
14	muradnagar	UHC Muradnagar	No				Yes	No	Yes	No	No	0		
15	nangalkot	Upazila Health Complex	No				No	No	Yes	No	No	0		
16	sadar_south	Upazila Health Complex, Comilla Sadar South, Comilla	No				No	No	Yes	Yes	Yes	1		
17	titas	UCH Titas	No				No	No	Yes	No	Yes	0		

District Name: Dhaka

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	dohar	Dohar Upzilla Health Complex	1 xlsx	ok
2	keraniganj	Keranigonj Upzilla Health Complex	1 xlsx	ok
3	nawabganj	Nawabgonj Upzilla Health Complex	1 xlsx	ok

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	dohar	Dohar Upzilla Health Complex		Other			No file	No file	No file	No file			No file	No file	No file		

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	dhamrai	Dhamrai Upazila Health Complex	0	0	0	35	30		Fire Extinguisher	3	0		Not Present	
2	savar	Savar Upazila Health Complex	0	0	0	24	15		Fire Extinguisher	4	0		Not Present	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	dhamrai	Dhamrai Upazila Health Complex	REB	No	180	200	0	MDB,PFI	0	30	0	0	LT Cable=50 Sqmm (60 meter-approximate)		The hospital has a pole-mounted substation..Electricity is being supplied through overhead line.Transformer is running on overload.A new X-ray machine has been installed in the hospital.The X-ray machine could not be operated due to transformer overloading.
2	savar	Savar Upazila Health Complex	REB	No	175	200	0	MDB	6.25	20	0	0	LT Cable=50 sqmm (40 meter-approximate)		The hospital has a pole-mounted substation..Electricity is being supplied through overhead line.Transformer is running on overload.The hospital has two X-ray machines and two OTs.Any one of the X-ray machines is kept running due to transformer overloading.

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	dhamrai	Dhamrai Upazila Health Complex	No	0	0	The hospital does not have Medical Gas Plant. There is portable gas cylinder	No	No	No	Yes	Yes	3		
2	savar	Savar Upazila Health Complex	No	0	0	The hospital does not have Medical Gas Plant. There is portable gas cylinder	No	No	No	Yes	Yes	2		

District Name: Dinajpur

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	birampur	Birampur 50 Bedded Upazila Health Complex	No file	
2	birganj	Upzilla Health Complex, Birgonj	1 xlsx	
3	birol	Upazilla Health Complex, Birol	1 xlsx	Information Provided by Uhfpo
4	bochaganj	Bochaganj 50 Bedded Upazila Health Complex	1 xlsx	Information provided by UHFPO
5	chirirbandar	Chirirbandar 50 Bedded Upazila Health Complex	1 xlsx	Information provided by UHFPO
6	hakimpur	Hakimpur 50 Bedded Upazila Health Complex	1 xlsx	Information provided by UHFPO
7	kaharole	Kaharole 50 Bedded Upazila Health Complex	1 xlsx	Information provided by UHFPO
8	khansama	Upzilla Health Complex, Pakerhat, Khansama	1 xlsx	filled by Hospital Authority
9	parbatipur	Parbatipur 50 Bedded Upazila Health Complex	1 xlsx	Information provided by UHFPO
10	phulbari	Fulbari 50 Bedded Upazila Health Complex	1 xlsx	Information provided by UHFPO

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	birampur	Birampur 50 Bedded Upazila Health Complex	1992	PWD	Yes	50	1 dwg	No file	No file	1 pdf	18488	17565 is Ground Floor, 17565 in 1st Floor	1 dwg	No file	10 jpegs	not Flood Prone Area	31 Bedded Upazila Health Complex has been constructed under PWD (1992) and It has been extended to 50 bedded Upazila Health Complex by HED (2010)
2	birol	Upazilla Health Complex, Birol	1975	PWD	YES	50	1 dwg, 1 pdf	1 pdf	1 pdf	1 pdf	15729	ground floor-15729 sft 1st floor-15729 sft	1 pdf	1 pdf	10 jpgs	not Flood Prone area	old structure constructed by PWD , ONLY New OPD area can be vertically Extended.
3	bochaganj	Bochaganj 50 Bedded Upazila Health Complex	1985	PWD	Yes	50	1 dwg	No file	No file	1 pdf	20358	19340 sft in Ground Floor, 19340 sft in 1st Floor	1 pdf	No file	10 jpegs	not Flood Prone Area	The Old Building has been constructed under PWD (1985) and It has been extended to 50 bedded Upazila Health Complex by HED (2004)
4	chirirbandar	Chirirbandar 50 Bedded Upazila Health Complex	1978	PWD	Yes	50	1 dwg	No file	No file	1 pdf	18363	17445 sft in Ground Floor, 17445 sft in 1st Floor, 8294 sft in 2nd Floor, 8294 sft in 3rd Floor	2 pdfs	1 pdf	2 jpegs, 1 mp4	not Flood Prone Area	The Old Building has been constructed under PWD (1978) and It has been extended to 50 bedded Upazila Health Complex by HED (2015)
5	hakimpur	Hakimpur 50 Bedded Upazila Health Complex		PWD	Yes	50	1 dwg	No file	No file	1 pdf	26874	25530 sft in Ground Floor, 25530 in 1st Floor	1 dwg	No file	10 jpegs	not Flood Prone Area	31 Bedded Upazila Health Complex has been constructed under PWD (1992) and It has been extended to 50 bedded Upazila Health Complex by HED (2010)
6	kaharole	Kaharole 50 Bedded Upazila Health Complex	1981	PWD	Yes	50	1 dwg	No file	No file	1 pdf	33273	14427 sft in Ground Floor, 11851 sft in 1st	1 pdf	1 pdf	9 jpegs	not Flood Prone Area	The Old Building has been constructed under PWD (1981) and It has been extended to 50 bedded

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
												Floor, 6995 sft in 2nd Floor					Upazila Health Complex by HED (2018)
7	khansama	Upzilla Health Complex, Pakerhat, Khansama	1975	HED	YES	50	1 dwg, 1 pdf	1 pdf	No file	1 pdf	15539	gr floor Area-15539 sft, 1st floor Area-15539 sft, 2nd Floor-8352 sft	1 pdf	No file	6 jpegs, 1 mp4	No Risk, or history of flooding	
8	parbatipur	Parbatipur 50 Bedded Upazila Health Complex	1960	PWD	Yes	50	1 dwg	No file	No file	1 jpeg	17597	16720 sft in Ground Floor, 16720 sft in 1st Floor, 550 sft in 2nd Floor	1 dwg	1 pdf	10 jpegs	not Flood Prone Area	31 Bedded Upazila Health Complex has been constructed under PWD (1960) and It has been extended to 50 bedded Upazila Health Complex by HED (2004)
9	phulbari	Fulbari 50 Bedded Upazila Health Complex	1965	PWD	Yes	50	1 dwg	No file	No file	1 pdf	17247	16385 sft in Ground Floor, 16385 sft in 1st Floor	1 dwg	1 pdf	10 jpegs	not Flood Prone Area	31 Bedded Upazila Health Complex has been constructed under PWD (1965) and It has been extended to 50 bedded Upazila Health Complex by HED (2018)

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	birampur	Birampur 50 Bedded Upazila Health Complex	33	2.5	3	Footing		RCC	The Building used as 31 Bedded Upazila Health Complex is a load bearing structure and The New Building used for the Extension to 50 Bedded Upazila Health Complex is Sound Frame Structure.	No file	info not available	Minor Repair has been done	
2	birol	Upazilla Health Complex, Birol	25	1.5	2	Footing	3	RCC	no structural elements are not in good conditions, 31 beded old part need to be reconstructed	No file	Possible	at 2018 minor repair works	for 19 OPD building one floor vertical extension possible, for 31 bed load bearing structure vertical extension not possible
3	bochaganj	Bochaganj 50 Bedded Upazila Health Complex	27	2.5	2	Footing		RCC	The Old Building is a 2 storied Building whose condition is vulnerable and The New Building is a 2 storied RCC Building and Structurally sound.	No file	info not available	None	
4	chirirbandar	Chirirbandar 50 Bedded Upazila Health Complex	40	2.5	4	Footing	5	RCC	The Old Building is a 2 storied Building whose condition is vulnerable and The New Building is 4 storied with 5 storied Foundation and Structurally sound.	No file	Possible	None	
5	hakimpur	Hakimpur 50 Bedded Upazila Health Complex	33	2	3	Footing		RCC	The Building used as 31 Bedded Upazila Health Complex is a load bearing structure and The New Building used for the Extension up to 50 Bedded Upazila Health Complex is Sound Frame Structure.	No file	info not available	Minor Repair has been done	
6	kaharole	Kaharole 50 Bedded Upazila Health Complex	33	2.5	3	Footing	5	RCC	The Old Building is a 2 storied Building with 2 storied Foundation whose condition is poor and The New Building is a 3 storied with 5 storied Foundation and Structurally sound.	No file	Possible	Minor Repair has been done in 2024, 2025	
7	khansama	Upzilla Health Complex, Pakerhat, Khansama	36	2	3	Footing	4	RCC	good condition	No file	Possible		old structure constructed by PWD , ONLY New OPD area can be vertically Extended.

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
8	parbatipur	Parbatipur 50 Bedded Upazila Health Complex	33	2.5	3	Footing		RCC	The Building used as 31 Bedded Upazila Health Complex is a load bearing structure and The New Building used for the Extension up to 50 Bedded Upazila Health Complex is Sound Frame Structure.	No file	info not available	Minor Repair has been done	
9	phulbari	Fulbari 50 Bedded Upazila Health Complex	33	1.5	3	Footing		RCC	The Building used as 31 Bedded Upazila Health Complex is a load bearing structure and The New Building used for the Extension up to 50 Bedded Upazila Health Complex is Sound Frame Structure.	No file	info not available	Minor Repair has been done	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	birampur	Birampur 50 Bedded Upazila Health Complex	0	0	centrifugal pump only	Septic Tank	0	No	0	Working	RCC drainage required	None, Carried by the Municipality	
2	birol	Upazilla Health Complex, Birol	0	0	centrifugal pump only	Septic Tank	0	No	0	working	RCC drainage required	none, carried by municipality	
3	bochaganj	Bochaganj 50 Bedded Upazila Health Complex	0	2	None	Septic Tank	0	No	0	Poor	RCC drainage required	None, Carried by the Municipality	
4	chirirbandar	Chirirbandar 50 Bedded Upazila Health Complex	0	2	None	Septic Tank	0	No	0	Poor	RCC drainage required	None, Carried by the Municipality	
5	hakimpur	Hakimpur 50 Bedded Upazila Health Complex	0	1	centrifugal pump only	Septic Tank	0	No	0	Very Poor	RCC drainage required	None, Carried by the Municipality	
6	kaharole	Kaharole 50 Bedded Upazila Health Complex	0	2	None	Septic Tank	0	No	0	No	RCC drainage required	None, Carried by the Municipality	
7	khansama	Upzilla Health Complex, Pakerhat, Khansama	0	2	Tubewell-5 nos	Septic Tank	0	No	0	partially	yes, width & depth needed to increase	burned by hospitak authority in campus	
8	parbatipur	Parbatipur 50 Bedded Upazila Health Complex	0	1	centrifugal pump only	Septic Tank	0	No	0	Yes but not up to the satisfactory level.	500m drainage facilities is required.	None, Carried by the Municipality	
9	phulbari	Fulbari 50 Bedded Upazila Health Complex	0	0	centrifugal pump only	Septic Tank	0	No	0	Yes but not up to the satisfactory level.	RCC drainage required	None, Carried by the Municipality	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	birampur	Birampur 50 Bedded Upazila Health Complex		1680			28	RCC Road	Yes	Yes	
2	bochaganj	Bochaganj 50 Bedded Upazila Health Complex		1975			12.5	RCC Road	Yes	Yes	
3	chirirbandar	Chirirbandar 50 Bedded Upazila Health Complex		2180			13	Bituminous Carpeting Road	Yes	Yes	

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
4	hakimpur	Hakimpur 50 Bedded Upazila Health Complex		2270			11	RCC Road	Yes	Yes	
5	kaharole	Kaharole 50 Bedded Upazila Health Complex		1995			16	RCC Road	Yes	Yes	
6	khansama	Upzila Health Complex, Pakerhat, Khansama	0	2222	0	0	25	down , water logging at rainy saeson, level need to be inceased	Yes	No	
7	parbatipur	Parbatipur 50 Bedded Upazila Health Complex		2174	2174		30	RCC Road	Yes	Yes	
8	phulbari	Fulbari 50 Bedded Upazila Health Complex		1790			40	RCC Road	Yes	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	birampur	Birampur	0	0	NA	16	16	Additional AC Requirements may vary Depends on Extented Rooms, ICU Unit & Other Unit.	NA	7.5	2		Not Present	
2	birganj	Birganj	0	0	NA	30	30	Additional AC Requirements may vary Depends on Extented Rooms, ICU Unit & Other Unit.	NA	7.5	0		Not Present	
3	birol	Birol	0	0	NA	16	16	Additional AC Requirements may vary Depends on Extented Rooms, ICU Unit & Other Unit.	Operational	7.5	0		Not Present	
4	bochaganj	Bochaganj	0	0	NA	20	20	Additional AC Requirements may vary Depends on Extented Rooms, ICU Unit & Other Unit.	NA	7.5	10		Not Present	
5	chirirbandar	Chirirbandar	0	0	NA	11.5	11.5	Additional AC Requirements may vary Depends on Extented Rooms, ICU Unit & Other Unit.	Not Fully Functional System	7.5	0		Not Present	
6	ghoraghat	Ghoraghat	0	0	NA	14	14	Additional AC Requirements may vary Depends on Extented Rooms, ICU Unit & Other Unit.	NA	7.5	0		Not Present	
7	hakimpur	Hakimpur	0	0	NA	12	12	Additional AC Requirements may vary Depends on Extented Rooms, ICU Unit & Other Unit.	NA	8.5	0		Not Present	
8	kaharole	Kaharole	0	0	NA	16	16	Additional AC Requirements may vary Depends on Extented Rooms, ICU Unit & Other Unit.	NA	5.5	0		Not Present	
9	khansama	Khansama	0	0	NA	30	30	Additional AC Requirements may vary Depends on Extented Rooms, ICU Unit & Other Unit.	NA	13	0		Not Present	
10	nawabganj	Nawabganj	0	0	NA	14	14	Additional AC Requirements may vary Depends on Extented Rooms, ICU Unit & Other Unit.	NA	7.5	10		Not Present	
11	parbatipur	Parbatipur	0	0	NA	11	11	Additional AC Requirements may vary Depends on Extented Rooms, ICU Unit & Other Unit.	Operational	17.5	0		Not Present	
12	phulbari	Phulbari	0	0	NA	15.5	15.5	Additional AC Requirements may vary Depends on Extented	Not Fully Functional System	7.5	0		Not Present	

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
								Rooms, ICU Unit & Other Unit.						

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	birampur	Birampur	REB	Yes	56	0	0	LT, HT, Switch Gear, PFI	5	5	1	0	LT Line Length-440 meter	50 RM	
2	birganj	Birganj	REB	Yes	66	0	0	LT, HT, Switch Gear, PFI	5	5	0	0	LT Line Length-450 meter	50 RM	
3	birol	Birol	REB	Yes	10	0	0	LT, HT, Switch Gear, PFI	10	5	0	0	Not Available	Not Available	
4	bochaganj	Bochaganj	REB	Yes	10	0	0	LT, HT, Switch Gear, PFI	7.5	7.5	0	0	LT Line Length-350 meter	50 RM	
5	chirirbandar	Chirirbandar	REB	Yes	100	150	50	LT, HT, Switch Gear, PFI	0	5	3	0	LT Line Length-22 meter	3x50 Sqmm NYY	
6	ghoraghat	Ghoraghat	REB	Yes	100	100	30	LT, HT, Switch Gear, PFI	5	5	1.5	0	LT Line Length-70 Rft		
7	hakimpur	Hakimpur	REB	Yes	50	0	0	LT, HT, Switch Gear, PFI	5	5	1	0	LT Line Length-430 meter	50 RM	
8	kaharole	Kaharole	REB	Yes	60	315	100	LT, HT, Switch Gear, PFI	50	25	4	0	LT Line Length-450 meter	50 RM	
9	khansama	Khansama	REB	Yes	142.5	315	100	LT, HT, Switch Gear, PFI	10	5	10	0	LT Line Length-550 meter	50 RM	
10	nawabganj	Nawabganj	REB	Yes	60	100	30	LT, HT, Switch Gear, PFI	5	5	1.5	0	LT Line Length-	120 RM	
11	parbatipur	Parbatipur	NESCO	Yes	100	0	0	LT, HT, Switch Gear, PFI	0	5	0	0	LT Line Length-20 meter	3x35 Sqmm NYY	
12	phulbari	Phulbari	NESCO	Yes	100	0	0	LT, HT, Switch Gear, PFI	5	5	2	0	LT Line Length-20 meter	3x10 Sqmm NYY	

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	birampur	Birampur	No	0	0	NA	Yes	No	Yes	Yes	Yes	1	PA System, PABX System, Medical Gas System, Compound and Security light.	
2	birganj	Birganj	No	0	20	Cylinder System	Yes	No	Yes	Yes	Yes	1	PA System, PABX System, Medical Gas System, Compound and Security light.	
3	birol	Birol	No	0	19	Cylinder System 19 Bed	Yes	No	Yes	No	Yes	1	PA System, PABX System, Medical Gas System, Compound and Security light.	
4	bochaganj	Bochaganj	No	0	20	Cylinder System	Yes	No	Yes	No	Yes	1	PA System, PABX System, Medical Gas System, Compound and Security light.	

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
5	chirirbandar	Chirirbandar	No	0	1	Cylinder System	Yes	No	No	Yes	Yes	1	PA System, PABX System, Medical Gas System, Compound and Security light.	
6	ghoraghat	Ghoraghat	No	0	1	Cylinder System	Yes	No	Yes	No	Yes	1	PA System, PABX System, Medical Gas System, Compound and Security light.	
7	hakimpur	Hakimpur	No	0	1	Cylinder System	Yes	No	Yes	No	Yes	1	PA System, PABX System, Medical Gas System, Compound and Security light.	
8	kaharole	Kaharol	No	0	10	Cylinder System	Yes	No	Yes	No	Yes	1	PA System, PABX System, Medical Gas System, Compound and Security light.	
9	khansama	Khansama	No	0	15	Cylinder System	Yes	No	Yes	No	Yes	1	PA System, PABX System, Medical Gas System, Compound and Security light.	
10	nawabganj	Nawabganj	No	0	1	Cylinder System	Yes	No	Yes	No	Yes	1	PA System, PABX System, Medical Gas System, Compound and Security light.	
11	parbatipur	Parbatipur	No	0	1	Cylinder System 1 Bed	Yes	No	Yes	Yes	Yes	1	PA System, PABX System, Medical Gas System, Compound and Security light.	
12	phulbari	Phulbari	No	0	1	Cylinder System 1 Bed	Yes	No	Yes	Yes	Yes	1	PA System, PABX System, Medical Gas System, Compound and Security light.	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	khansama	Upzilla Health Complex, Pakerhat, Khansama	Child Care unit	11	0	0	1000	1000	good	No file	1 jpeg	
2	khansama	Upzilla Health Complex, Pakerhat, Khansama	Store	10	2017	1	1125	1125	good	No file	2 jpegs	
3	khansama	Upzilla Health Complex, Pakerhat, Khansama	Garrage -2	9		1	500	500	repair needed	No file	1 jpeg	
4	khansama	Upzilla Health Complex, Pakerhat, Khansama	3- storied quarter	8	1975	3	3500	7000	vulnerable, not being used	No file	2 jpegs	
5	khansama	Upzilla Health Complex, Pakerhat, Khansama	5-storied doctor quarter	7	2018	5	1200	6000	good condition	No file	1 jpeg	
6	khansama	Upzilla Health Complex, Pakerhat, Khansama	Garrage	6	0	0	1200	1200	repair needed	No file	1 jpeg	
7	khansama	Upzilla Health Complex, Pakerhat, Khansama	3-storied quarter	1	2012	3	1140	3420	good	No file	2 jpegs	constructed between -2015--2012
8	khansama	Upzilla Health Complex, Pakerhat, Khansama	quarter 2 units 04 nos buildings	1,2,3,4	1975	2	1728	3456	vulnerable	No file	4 jpegs	Total renovation or recnstruction required, load bearing structures

District Name: Faridpur

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	alfadanga	Alfadanga Upazila Health Complex, Faridpur	1 xlsx	
2	bhanga	Bhanga Upazila Health Complex, Faridpur	1 xlsx	
3	boalmari	Boalmari Upazila Health Complex, Faridpur	1 xlsx	
4	char bhadrasan	Charbhadrasan Upazila Health Complex, Faridpur	1 xlsx	
5	madhukhali	Madukhali Upazila Health Complex, Faridpur	1 xlsx	
6	nagarkanda	Nagarkanda Upazila Health Complex, Faridpur	1 xlsx	
7	sadarpur	Sadarpur Upazila Health Complex, Faridpur	1 xlsx	
8	saltha	Saltha Upazila Health Complex, Faridpur	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	alfadanga	Alfadanga Upazilla Health Complex, Alfadanga.	2009	HED	Yes	50	1 dwg	No file	1 pdf	1 pdf	6517	6517	1 dwg	No file	2 jpgs, 3 mp4s	2	Vertical Extension not possible
2	bhanga	Bhanga Upazila Health Complex,Faridpur	2002	HED	yes	50	1 pdf	3 jpegs	1 jpeg	1 jpg	8183.98	32735.92	2 dwgs	No file	4 jpgs	2	Vertical Extension not possible. Buildings are in bad condition
3	boalmari	Boalmari Upazilla Health Complex, Alfadanga.	2022	HED	Yes	100	1 dwg	1 jpeg	1 pdf	1 pdf	12776.65	12776.65	1 dwg	No file	3 jpgs	2	Vertical Extension possible, At present 100 Bed Capacity.
4	char_bhadrasan	char bhadrasan Upazila Health Complex,Faridpur	1978	HED	Yes	50	1 dwg	No file	No file	No file	19755	39510	1 dwg	No file	2 jpgs	2	Vertical Extension not possible. Buildings are in bad condition
5	madhukhali	Madhukhali Upazila Health Complex,Faridpur	1978	HED	yes	50	1 dwg, 1 pdf	3 jpgs	No file	1 dwg	14168	24168	2 dwgs	No file	1 mp4	2	Vertical Extension not possible, existing buildings need repair
6	nagarkanda	Nagarkanda Upazila Health Complex,Faridpur	1978	HED	yes	50	2 dwgs	2 jpegs	No file	No file	4930.94	25550.88	2 pdfs	No file	1 mp4	2	50 Bed new building under Construction
7	sadarpur	sadarpur Upazila Health Complex,Faridpur	1985	HED	yes	50	1 dwg	No file	1 jpeg	1 jpeg	11370	22740	No file	No file	6 jpgs	2	Vertical Extension not possible. Buildings are in bad condition
8	saltha	Saltha Upazila Health Complex,Faridpur	2018	HED	yes	50	1 pdf	No file	1 jpeg	1 jpeg	11335	22668	1 dwg	No file	3 jpgs	2	Vertical Extension not possible

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	alfadanga	Alfadanga upazilla health complex, Alfadanga	33	2	3	Deep	6	RCC	Very poor	No file	Not Possible	Not Regularly repaired	Vertical Extension not possible, New Building is required.
2	bhanga	Bhanga Upazila Health Complex,Faridpur	40	2	4	Deep	6	RCC	Good	5 jpegs	Not Possible	Not regularly repaired	Since we have not got structural digital, direct supervision responsibility with construction works, so it is better to do new building without expanding upwards.
3	boalmari	Boalmari Upazilla Health Complex, Alfadanga.	58	2	5	Deep	6	RCC	Suitable	No file	Possible	Not Regularly repaired	Vertical Extension possible, At present 100 Bed Capacity.
4	char bhadrasan	char bhadrasan Upazila Health Complex,Faridpur	30	2	3	Footing	3	RCC	very poor	No file	Not Possible	Not regularly repaired	The main hospital building is dilapidated, requires extensive repairs, drainage system is very poor, sanitary fittings need to be changed.
5	madhukhali	Madhukhali Upazila Health Complex,Faridpur	20	1.5	2	Footing	2	RCC	very poor	5 jpegs	Not Possible	Not regularly repaired	The main hospital building is dilapidated, requires extensive repairs, drainage system is very poor, sanitary fittings need to be changed.
6	nagarkanda	Nagarkanda Upazila Health Complex,Faridpur	48	2.6	4	Deep	6	RCC	Good	No file	Possible	No	New Building is being built for 31 bed. To extend upto 101 bed, vertical extension is not enough.
7	sadarpur	Saltha Upazila Health Complex,Faridpur	20.5	1.5	2	Footing	2	RCC	very poor	No file	Not Possible	Not regularly repaired	The main hospital building is dilapidated, requires extensive repairs, drainage system is very poor, sanitary fittings need to be changed.
8	saltha	Saltha Upazila Health Complex,Faridpur	40	2	4	Deep	4	RCC	Good	1 pdf	Not Possible	Not regularly repaired	The main hospital building is dilapidated, requires extensive repairs, drainage system is very poor, sanitary fittings need to be changed.

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	alfadanga	Alfadanga Upazilla Health Complex, Alfadanga.	5000	1	Municipality	Septic Tank	2000	No	0	Very poor	Need Master Drain required, 300 mm drain, 600 mm drain	No. Waste is removed by municipality vehicles.	Rainwater harvesting system and drainage system is required
2	bhanga	Bhanga Upazila Health Complex,Faridpur	5000	1	no	Septic Tank	2400	No	0	Very poor	Need master drain required ,300mm drain,600 mm drain	No. waste is removed by municipality vehicles.	Rainwater harvesting and drainage system is required. deep Tube-well required.
3	boalmari	Boalmari upazilla Health Complex, Boalmari	2000	0	Municipality	Septic Tank	2000	No	0	Very poor	Need master drain required, 300 mm drain 600 drain	No Waste is removed by municipality vehicles	Rainwater harvesting system and drainage system is required
4	char bhadrasan	char bhadrasan Upazila Health Complex,Faridpur	0	1	no	Septic Tank	2000	No	0	Very poor	Need master drain required ,300mm drain,600 mm drain	No. waste is removed by municipality vehicles.	Rainwater harvesting and drainage system is required. deep Tube-well required.
5	madhukhali	Madhukhali Upazila Health Complex,Faridpur	5000	1	no	Septic Tank	2000	No	0	very poor	master drain required ,300mm drain,600 mm drain	No. waste is removed by municipality vehicles.	Rainwater harvesting and drainage system is required.
6	nagarkanda	Nagarkanda Upazila Health Complex,Faridpur	0	0	Municipality supply	Septic Tank	2000	No	0	Very poor	Need master drain required ,300mm drain,600 mm drain	No. waste is removed by municipality vehicles.	Rainwater harvesting and drainage system is required. deep Tube-well required.
7	sadarpur	Saltha Upazila Health Complex,Faridpur	0	1	no	Septic Tank	2000	No	0	Very poor	Need master drain required ,300mm drain,600 mm drain	No. waste is removed by municipality vehicles.	Rainwater harvesting and drainage system is required. deep Tube-well required.

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
8	saltha	Saltha Upazila Health Complex,Faridpur	0	1	no	Septic Tank	2000	No	5000	Very poor	Need master drain required ,300mm drain,600 mm drain	No. waste is removed by municipality vehicles.	Rainwater harvesting and drainage system is required.

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	alfadanga	Alfadanga Upazila Health Complex, Alfadanga.	700	2000	700	2000	20	There are Internal roads but they are cracked at times, new construction will make them usable and passable.	Yes	Yes	Need New Building and Improve Internal Road and Boundary wall
2	bhanga	Bhanga Upazila Health Complex,Faridpur	0	2200	1800	400	20	There are internal roads but they are cracked at times, new construction will make them usable and passable	No	Yes	Need new boundary wall casuse damaged wall
3	boalmari	Boalmari Upazila Health Complex, Alfadanga.	0	2100	0	2100	18	There are Internal roads but they are cracked at times, new construction will make them usable and passable.	Yes	Yes	Vertical Extension possible, At present 100 Bed Capacity, Improve Boundary wall.
4	char bhadrasan	char bhadrasan Upazila Health Complex,Faridpur	0	2400	500	2400	18	12	Yes	Yes	The main hospital building is dilapidated, requires extensive repairs, drainage system is very poor, sanitary fittings need to be changed.
5	madhukhali	Madhukhali Upazila Health Complex,Faridpur	0	1500	272	1772	20	There are internal roads but they are cracked at times, new construction will make them usable and passable	Yes	Yes	There are internal roads but they are cracked at times, new construction will make them usable and passable and Demolition of boundary wall and construction of new boundary wall is urgent and visual gate is required
6	nagarkanda	Nagarkanda Upazila Health Complex,Faridpur	0	2200	400	2200	18	12	No	Yes	Need new boundary wall casuse damaged wall
7	sadarpur	Saltha Upazila Health Complex,Faridpur	0	1500	500	2000	20	12	Yes	Yes	The main hospital building is dilapidated, requires extensive repairs, drainage system is very poor, sanitary fittings need to be changed.
8	saltha	Saltha Upazila Health Complex,Faridpur	0	1394	1000	393	12	There are internal roads but they are cracked at times, new construction will make them usable and passable	No	Yes	Need new boundary wall casuse damaged wall

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	alfadanga	Alfadanga Upazila Health Complex, Faridpur	0	0	Needed in case of extension	14	20	Repair needed	No fire detection and protective system	7.5	0	Repair and new pump needed	Not Present	Needed
2	bhanga	Bhanga Upazila Health Complex, Faridpur	0	0		38	30		No fire detection and protective system	5.5	3	10 hp submercible and 10 hp centrifugal	Not Present	

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
3	boalmari	Boalmari Upazila Health Complex, Faridpur	2	2	Service and operation needed	15	30	Repair needed	No fire detection and protective system	7.5	0	More submersible and centrifugal pump needed	Not Present	Needed
4	char bhadrasan	Char bhadrasan Upazila Health Complex, Faridpur	0	0	No lift core	16	20	AC servicing and repair needed	No fire detection and protective system	3	0	New pump needed	Not Present	Needed
5	madhukhali	Madhukhali Upazila Health Complex, Faridpur	0	0	No lift core	12	20	N/A	No fire detection and protective system	0	0	30 hp turbine pump present	Not Present	Needed
6	nagarkanda	Nagarkanda Upazila Health Complex, Faridpur	0	0	Lift core is present	8	70	N/A	No	5	2	Demand 10 hp submersible 10hp centrifugal	Not Present	Needed
7	sadarpur	Sadarpur Upazila Health Complex, Faridpur	0	0	If vertical extension is done, then lift needed	12	20	No	ABCE Type fire extinguisher	8	0	10hp(5+5) centrifugal pump needed	Not Present	Needed
8	saltha	Saltha Upazila Health Complex, Faridpur	0	0	No lift core	10	25	N/A	ABCE type fire extinguisher	5	3	N/A	Not Present	Needed

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	alfadanga	Alfadanga Upazila Health Complex, Faridpur	REB	No	40	0	0	No sub station	0	60	0	0	25 RM Underground NYY and 25 ANT Overhead line	25 RM Underground NYY	Substation and generator needed
2	bhanga	Bhanga Upazila Health Complex, Faridpur	WZPDCL	No	100	150	0	Not good	60	200	2	0	50RM Underground NYY and 50ANT Overhead line	MDB-1, FDB-10, EMDB-1, ESPDB-7	
3	boalmari	Boalmari Upazila Health Complex, Faridpur	REB	No	150	250	0	Repair needed	250	0	3	0	50RM Underground NYY and 50ANT Overhead line	70RM Catenary NYY	Repair needed
4	char bhadrasan	Charbhadrasan Upazila Health Complex, Faridpur	REB	No	30	0	0	No sub station	10	60	2	0	25RM Underground NYY and 25ANT Overhead line	25RM Underground NYY	Generator is not functional. Repair needed
5	madhukhali	Madhukhali Upazila Health Complex, Faridpur	WZPDCL	No	80	100	0	Not good	0	60	0	0	35RM Underground NYY and 50ANT Overhead line	35RM Underground NYY	New generator and new service line needed
6	nagarkanda	Nagarkanda Upazila Health Complex, Faridpur	REB	No	100	200	0	No	0	200	0	0	50RM Catenary NYY	35RM Catenary NYY	Only transformer present
7	sadarpur	Sadarpur Upazila Health Complex, Faridpur	PDB	No	30	0	0	No	3	60	0	0	25RM Catenary NYY	25RM Catenary NYY	Substation and generator are needed
8	saltha	Saltha Upazila Health Complex, Faridpur	REB	No	40	200	0	Repair needed	0	60	0	0	50RM Underground And 50 ANT Overhead line	50RM Underground NYY	Generator needed and solar panel can be installed

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	alfadanga	Alfadanga Upazila Health Complex, Faridpur	No	0	0	Needed	No	No	Yes	No	Yes	0	Conference system, medical gas plant and more CCTV needed	Huge scarcity of modern facilities
2	bhanga	Bhanga Upazila Health Complex, Faridpur	No	0	0	NA	No	No	No	No	Yes	0	Compound security, light, sound system, pabx system needed	CCTV is inadequate
3	boalmari	Boalmari Upazila Health Complex, Faridpur	Yes				Yes	No	Yes	No	Yes	0	N/A	Repair needed
4	char bhadrasan	Charbhadrasan Upazila Health Complex, Faridpur	No	0	0	Needed	No	No	No	No	Yes	0	Security system needed	Huge scarcity of modern facilities
5	madhukhali	Madhukhali Upazila Health Complex, Faridpur	No	0	0	Needed	No	No	Yes	No	Yes	0	Medical gas plant and waste management needed	
6	nagarkanda	Nagarkanda Upazila Health Complex, Faridpur	No	0	0	There is no medical gas system	No	No	No	No	No	0	Essential systems are needed	Huge scarcity of modern facilities
7	sadarpur	Sadarpur Upazila Health Complex, Faridpur	No	0	0	Medical gas plant inactive	Yes	No	No	No	Yes	0	N/A	Lacks modern facilities
8	saltha	Saltha Upazila Health Complex, Faridpur	No	0	0	Needed	Yes	No	No	No	Yes	0	Medical gas facility needed	Manpower shortage is hindering service

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	alfadanga	Alfadanga Upazila Health Complex, Alfadanga.	Doctor Dormitory,Nurses Dormitory staff quarter	5	1994	5	2000	12195	Poor	No file	No file	The main hospital building is dilapidated,requires extensive repair, drainage system is very poor, sanitary fittings need to be changed.
2	bhanga	Bhanga Upazila Health Complex,Faridpur	Doctor;s dormitory nos 2 ,Nurse's Dormitory nos 1, 3rd class nos 2	5	2002	2	2003	12057	very poor required repair	1 jpeg	No file	The main hospital building is dilapidated, requires extensive repairs, drainage system is very poor, sanitary fittings need to be changed.
3	boalmari	Boalmari Upazilla Health Complex, Alfadanga.	staff quarter	5	1994	5	2000	7000	Very poor required repair	No file	No file	Vertical Extension possible, At present 100 Bed Capacity.
4	char bhadrasan	char bhadrasan Upazila Health Complex,Faridpur	Doctor;s dormitory nos 2 ,Nurse's Dormitory nos2	5	1984	3	2005	12213	very poor required repair	No file	No file	The main hospital building is dilapidated, requires extensive repairs, drainage system is very poor, sanitary fittings need to be changed.
5	madhukhali	Madhukhali Upazila Health Complex,Faridpur	office's Quarter ,Nurse's Dormitory nos 1, 3rd class nos 1, 4th class nos 2	6	1974	2	2003	12570	very poor required repair	No file	1 mp4	The main hospital building is dilapidated, requires extensive repairs, drainage system is very poor, sanitary fittings need to be changed.
6	nagarkanda	Nagarkanda Upazila Health Complex,Faridpur	Doctor;s dormitory nos 1 ,Nurse's Dormitory nos 1, 3rd class nos 4	12	1985	2	2003	12570	very poor required repair	1 pdf	3 jpegs	31 bed building is under construction. Repair needed for other buildings
7	sadarpur	sadarpur Upazila Health Complex,Faridpur	Doctor;s dormitory nos 2 ,Nurse's Dormitory nos 1, 3rd class nos 2	5	1985	2	2003	12120	very poor required repair	No file	No file	The main hospital building is dilapidated, requires extensive repairs, drainage system is very poor, sanitary fittings need to be changed.
8	saltha	Saltha Upazila Health Complex,Faridpur	Doctor;s dormitory nos 2 ,Nurse's Dormitory nos2	5	2018	3	2122	11205	very poor required repair	1 jpeg	No file	The main hospital building is dilapidated, requires extensive repairs, drainage system is very poor, sanitary fittings need to be changed.

District Name: Feni

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	chhagalnaiya	Chhagalnaiya Upazila Health Complex, Feni	1 xlsx	
2	daganbhuiyan	Daganbhuiyan Upazila Health Complex, Feni	1 xlsx	
3	fulgazi	Fulgazi Upazila Health Complex, Feni	1 xlsx	
4	parshuram	Parshuram Upazila Health Complex, Feni	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	daganbhuiyan	Daganbhuiyan Upazila Health Complex, Feni	1996	HED	N/A	50	1 dwg	No file	No file	No file			No file	No file	No file		
2	fulgazi	Fulgazi Upazila Health Complex, Feni	2002	HED	N/A	50	No file	No file	No file	No file			No file	No file	No file		
3	sonagazi	Sonagazi Upazila Health Complex, Feni	1965	HED	N/A	50	1 dwg	No file	No file	No file			No file	No file	No file		

District Name: Gaibandha

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	gobindaganj	UHC Gobaindaganj ,Gaibandha	1 .xlsx	
2	palashbari	UHC, Palasbari, Gaibandha	1 .xlsx	
3	phulchhari	UHC Fulchori ,Gaibandha	1 .xlsx	
4	sadullapur	UHC Sadullapur ,Gaibandha	1 .xlsx	
5	sagatta	UHC Sagatta ,Gaibandha	1 .xlsx	
6	sundarganj	UHC Sundarganj,Gaibandha	1 .xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	gobindaganj	UHC Gobaindaganj ,Gaibandha	2024	HED	Yes	100	1 dwg	1 jpeg	No file	No file	32000	31500	1 dwg	No file	2 jpegs		CAD file in this Upazila is uploaded temporarily.
2	palashbari	Upazilla Health Complex, Palasbari, Gaibandha	1983	PWD	Yes	50	1 dwg	1 jpeg	No file	No file	24000		1 dwg	1 jpeg	3 jpegs		
3	phulchhari	UHC Fulchori ,Gaibandha	1998	PWD	Yes	50	1 dwg	1 jpeg	No file	No file	23500		1 dwg	No file	3 jpegs		
4	sadullapur	UHC Sadullapur ,Gaibandha	1983	PWD	Yes	50	1 dwg	1 jpeg	No file	No file	24500		1 dwg	1 pdf	5 jpgs		
5	sagatta	UHC Sagatta ,Gaibandha	1983	PWD	Yes	50	1 dwg	1 jpeg	No file	No file	24000		1 dwg	1 jpeg	6 jpegs		
6	sundarganj	UHC Sundarganj,Gaibandha	1983	PWD	Yes	50	1 dwg	1 jpeg	No file	No file	24500		1 dwg	1 jpeg	2 jpegs		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	gobindaganj	UHC Gobaindaganj ,Gaibandha	66	3	6	Deep	7	RCC	good	No file	Possible	Its a new hospital Building	
2	palashbari	Upazilla Health Complex, Palasbari, Gaibandha (New building)	33	1.5	3	Footing	4	RCC	good	No file	Possible	minor renovation in past years	
3	palashbari	Upazilla Health Complex, Palasbari, Gaibandha (Old building)	22	0.5	2	Footing	2	Load Bearing Brick	poor	No file	Not Possible	minor renovation in past years	
4	phulchhari	UHC Fulchori ,Gaibandha new building	33	2	3	Footing	4	RCC	good	No file	Possible	minor renovation in past years	
5	phulchhari	UHC Fulchori ,Gaibandha old building	22	1	2	Footing	2	Load Bearing Brick	poor	No file	Not Possible	minor renovation in past years	
6	sadullapur	UHC Sadullapur ,Gaibandha new building	33	2	3	Footing	4	RCC	good	No file	Possible	minor renovation in past years	

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
7	sadullapur	UHC Sadullapur ,Gaibandha old building	22	1	2	Footing	2	Load Bearing Brick	poor	No file	Not Possible	minor renovation in past years	
8	sagatta	UHC Sagatta ,Gaibandha new building	33	2	3	Footing	4	RCC	good	No file	Possible	minor renovation in past years	
9	sagatta	UHC Sagatta ,Gaibandha old building	22	1	2	Footing	2	Load Bearing Brick	poor	No file	Not Possible	minor renovation in past years	
10	sundarganj	UHC Sundarganj,Gaibandha	33	2	3	Footing	4	RCC	good	No file	Possible	minor renovation in past years	
11	sundarganj	UHC Sundarganj,Gaibandha old building	22	1	2	Footing	2	Load Bearing Brick	poor	No file	Not Possible	minor renovation in past years	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	gobindaganj	UHC Gobaindaganj ,Gaibandha	6000	1	no	Septic Tank	1500	No	0	good	master drain is needed	outside of campus	
2	palashbari	Upazilla Health Complex, Palasbari, Gaibandha	0	1	no	Septic Tank	2200	No	0	poor	master drain is needed	pond in the campus	
3	phulchhari	UHC Fulchori ,Gaibandha	0	1	no	Septic Tank	1000	No	0	poor	master drain is needed	outside of campus	
4	sadullapur	UHC Sadullapur ,Gaibandha	0	1	no	Septic Tank	1000	No	0	poor	master drain is needed	pond in the campus	
5	sagatta	UHC Sagatta ,Gaibandha	0	1	0	Septic Tank	1000	No	0	poor	master drain is needed	outside of campus	
6	sundarganj	UHC Sundarganj,Gaibandha	0	1	no	Septic Tank	1000	No	0	poor	master drain is needed	outside of campus	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	gobindaganj	UHC Gobaindaganj ,Gaibandha	0	2500		200	14	16 ft rcc roads which are not in good condition	No		
2	palashbari	Upazilla Health Complex, Palasbari, Gaibandha	0	2500	250	1249.99	24	the widths of road are 16ft,12ft and 10ft. length of road is 2000m. most of the roads are damaged .	Yes	Yes	
3	phulchhari	UHC Fulchori ,Gaibandha	0	1500		250	12	16 ft rcc roads which are not in good condition	Yes	No	
4	sadullapur	UHC Sadullapur ,Gaibandha	0	2500	0	500	20	16 ft rcc roads which are not in good condition	Yes	Yes	
5	sagatta	UHC Sagatta ,Gaibandha	0	3000	0	500	12	16 ft rcc roads which are not in good condition	Yes	Yes	
6	sundarganj	UHC Sundarganj,Gaibandha	0	2400		1000	12	12 ft rcc roads which are not in good condition	Yes	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	gobindaganj	UHC Gobaindaganj ,Gaibandha	1	1		60	10		yes	10	10		Others	pit burning
2	palashbari	Upazilla Health Complex, Palasbari, Gaibandha	0	0	NA	28	20		Nothing	7.49	0	demand of 20 HP Pump	Not Present	Medical Waste plant is required.
3	phulchhari	UHC Fulchori ,Gaibandha	0	0	NA	22	10	the number of tons calculated in new and old buildings	Nothing	5.5	0	demand of 20 HP Pump	Not Present	
4	sadullapur	UHC Sadullapur ,Gaibandha	0	0	NA	16	29.99	the number of tons calculated in new and old buildings	Nothing	5.5	0	demand of 20 HP Pump	Not Present	
5	sagatta	UHC Sagatta ,Gaibandha	0	0	no	38	30	the number of tons calculated in new and old buildings	Nothing	5.5	0	demand of 20 HP Pump	Not Present	
6	sundarganj	UHC Sundarganj,Gaibandha	0	0	0	16	20	the number of tons calculated in new and old buildings	Nothing	5.5	0	demand of 20 HP Pump	Not Present	Medical Waste plant is required.

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	gobindaganj	UHC Gobaindaganj ,Gaibandha	NESCO	Yes	250	400	150	HT	100	0	10	0			
2	palashbari	Upazilla Health Complex, Palasbari, Gaibandha	NESCO	Yes	81	150	69	separate MDB for every building	0	100	0	0	LT Cable in every separate building having RM 50 in Hospital buildings AND 10RM LT connections in others building	6rm cable from MDB to SBD	
3	phulchhari	UHC Fulchori ,Gaibandha	REB	No	90	150	60	separate MDB for every building	0	100	0	0	LT Cable in every separate building having RM 50 in Hospital buildings AND 10RM LT connections in others building	6rm cable from MDB to SBD ,Cable condition is not good	
4	sadullapur	UHC Sadullapur ,Gaibandha	REB	No	90	150	60	LT	0	100	0	0	LT Cable in every separate building having RM 50 in Hospital buildings AND 10RM LT connections in others building	6rm cable from MDB to SBD ,Cable condition is not good	
5	sagatta	UHC Sagatta ,Gaibandha	REB	No	150	250	100	LT	0	100	0	0	LT Cable in every separate building having RM 50 in Hospital buildings AND 10RM LT connections in others building	6rm cable from MDB to SBD ,Cable condition is not good	
6	sundarganj	UHC Sundarganj,Gaibandha	REB	No	80	100	20	LT	10	100	0	0	LT Cable in every separate building having RM 50 in Hospital buildings AND 10RM LT	6rm cable from MDB to SBD ,Cable condition is not good	

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
													connections in others building		

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	gobindaganj	UHC Gobaindaganj ,Gaibandha	Yes				Yes	No	Yes	No	Yes	0	CCTV system is not enough	
2	palashbari	Upazilla Health Complex, Palasbari, Gaibandha	Yes		15	There is a Medical Gas System in this hospital but it does not work .	Yes	No	No	No	Yes	0	CCTV system is not enough	
3	phulchhari	UHC Fulchori ,Gaibandha	No	0	0	NA	Yes	No	No	No	Yes	0	CCTV system is not enough	
4	sadullapur	UHC Sadullapur ,Gaibandha	No	0	0	NA	Yes	No	No	No	Yes	0	CCTV system is not enough	
5	sagatta	UHC Sagatta ,Gaibandha	No	0	0	NA	Yes	No	No	No	Yes	0	CCTV system is not enough	
6	sundarganj	UHC Sundarganj,Gaibandha	No	0			Yes	No	No	No	Yes	0	CCTV system is not enough	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	gobindaganj	UHC Gobaindaganj ,Gaibandha	STAFF QUATERS	5	1980	10	10000	9800	damaged	No file	No file	
2	palashbari	UHC Palashbari , Gaibandha	dorm	2	1983	4	3200	3000	damaged	No file	No file	
3	palashbari	UHC Palashbari ,Gaibandha	doctor quatre	2	1983	3	2400	2200	1 nos build in 1983 is damaged and other 1 nos build in 2012 are good in condition	No file	No file	
4	palashbari	UHC Palashbari , Gaibandha	STAFF QUATERS	4	1983	8	6000	5500	2 nos build in 1983 is damaged and other 2 nos build in 2012 are not good in condition	No file	1 jpeg	
5	palashbari	Upazilla Health Complex, Palasbari, Gaibandha	OPD	1	2012	1	6500	6400	not enough space for OPD building, but the hospital is using some room from new building .	No file	No file	
6	phulchhari	UHC Fulchori ,Gaibandha	dorm	1	1997	2	4000	3799.98	damaged	No file	No file	
7	phulchhari	UHC Fulchori ,Gaibandha	doctor quatre	2	1983	4	2500	2300	1 nos build in 1997 is damaged and other 1 nos build in 2014 is good in condition	No file	No file	
8	phulchhari	UHC Fulchori ,Gaibandha	STAFF QUATERS	3	1983	6	2500	2300	damaged	No file	2 jpegs	
9	phulchhari	UHC Fulchori ,Gaibandha	OPD	1	2014	1	3000	2800	GOOD	No file	No file	
10	sadullapur	UHC Sadullapur ,Gaibandha	dorm	1	1983	1	850	800	damaged	No file	No file	
11	sadullapur	UHC Sadullapur ,Gaibandha	doctor quatre	4	1983	5	10000	9500	3 nos build in 1983 is damaged and other 1 nos build in 2010 are good in condition	No file	No file	
12	sadullapur	UHC Sadullapur ,Gaibandha	STAFF QUATERS	5	1983	7	8000	7800	3 nos build in 1983 is damaged and other 2 nos build in 2010 are good in condition	No file	3 jpgs	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
13	sadullapur	UHC Sadullapur ,Gaibandha	OPD	1	2010	1	7500	7400	GOOD	No file	No file	OPD Building is in the ground floor of new building but the are is not enough .
14	sagatta	UHC Sagatta ,Gaibandha	dorm	1	1983	1	1600	1500	damaged	No file	No file	
15	sagatta	UHC Sagatta ,Gaibandha	doctor quatre	2	1983	4	2500	2400	1 nos build in 1983 is damaged and other 1 nos build in 2010 are good in condition	No file	No file	
16	sagatta	UHC Sagatta ,Gaibandha	STAFF QUATERS	4	1983	8	2500	2400	2 nos build in 1983 is damaged and other 2 nos build in 2010 are good in condition	No file	3 jpegs	
17	sagatta	UHC Sagatta ,Gaibandha	OPD	1	2014	1	5500	5199.99	GOOD	No file	No file	
18	sundarganj	UHC Sundarganj,Gaibandha	dorm	1	1983	1	800	750	build in 1983 and it is damaged	No file	No file	
19	sundarganj	UHC Sundarganj,Gaibandha	doctor quatre	1	2014	2	2000	1800	GOOD	No file	1 jpeg	
20	sundarganj	UHC Sundarganj,Gaibandha	STAFF QUATERS	9	1983	19	18000	17500	7 nos build in 1983 is damaged and other 2 nos build in 2014 are good in condition	No file	5 jpegs	
21	sundarganj	UHC Sundarganj,Gaibandha	OPD	1	2014	1	6500	6200	not enough space for OPD building, but the hospital is using some room from new building .	No file	No file	

District Name: Gopalganj

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	kashiani	Kashiani Upazila Health Complex	1 xlsx	
2	kotalipara	Kotalipara Upazila Health Complex	1 xlsx	
3	muksudpur	Muksudpur Upazila Health Complex	1 xlsx	
4	tungipara	Tungipara Upazila Health Complex	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	kashiani	Kashiani Upazila Health Complex	2021	HED	Yes	100	No file	No file	No file	1 jpeg			No file	No file	4 jpegs		Land Area 10.5 acres (Aprox)
2	kotalipara	Kotalipara Upazila Health Complex	2021	HED	Yes	100	No file	No file	No file	1 jpeg			No file	No file	3 jpegs		Land Area 7.5 acres (Aprox)
3	muksudpur	Muksudpur Upazila Health Complex	2021	HED	Yes	100	No file	No file	No file	1 jpeg	128000	16000	No file	No file	4 jpegs		
4	tungipara	Tungipara Upazila Health Complex	2021	HED	Yes	100	No file	No file	No file	1 jpeg			No file	No file	3 jpegs		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	kashiani	Kashiani Upazila Health Complex (New 4 Stroyed Building)	44	2.5	4			RCC	Good	No file	info not available		Boundary wall renovation, Master Drain required
2	kashiani	Kashiani Upazila Health Complex (Old 4 Stroyed Building)	44	2.5	4			RCC	Good	No file	info not available		Boundary wall renovation, Master Drain required
3	kotalipara	Kotalipara Upazila Health Complex (New Building)	55	2.5	5			RCC	Good	No file	info not available		Boundary wall renovation required
4	kotalipara	Kotalipara Upazila Health Complex (Old Building)	33	2.5	3			RCC	Good	No file	info not available		Boundary wall renovation required
5	muksudpur	Muksudpur Upazila Health Complex (Bhobon-A)	44	2.5	4			RCC	Good	No file	info not available		Boundary wall renovation required, Ramp Required
6	muksudpur	Muksudpur Upazila Health Complex (Bhobon-B)	44	2.5	4			RCC	Good	No file	info not available		Boundary wall renovation required, Ramp Required
7	tungipara	Tungipara Upazila Health Complex (3 Stroyed Building)	33	2	3			RCC	Good	No file	info not available		Boundary wall renovation required
8	tungipara	Tungipara Upazila Health Complex (4 Stroyed Building)	44	2	4			RCC	Good	No file	info not available		Boundary wall renovation required

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	kashiani	Kashiani Upazila Health Complex			1 nos submersible pump-10 HP	Septic Tank		No		Yes	Renovation Required		2 Nos Deep Tubewell Required
2	kotalipara	Kotalipara Upazila Health Complex			1 nos submersible pump-10 HP	Septic Tank		No		Yes	Yes		1 Nos Deep Tubewell Required
3	muksudpur	Muksudpur Upazila Health Complex			From Muksudpur Poursova	Septic Tank		No		Yes	Renovation Required		2 Nos Deep Tubewell Required
4	tungipara	Tungipara Upazila Health Complex			From Tungipara Poursova	Septic Tank		No		Yes	Renovation Required		1 Nos Deep Tubewell Required

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	kashiani	Kashiani Upazila Health Complex					20	Good, 16 ft wide	Yes	No	
2	kotalipara	Kotalipara Upazila Health Complex					20	Good, 16 ft wide	Yes	No	
3	muksudpur	Muksudpur Upazila Health Complex					20	Good, 16 ft wide	Yes	No	
4	tungipara	Tungipara Upazila Health Complex					20	Good, 16 ft wide	Yes	No	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (If present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	kashiani	Kashiani Upazila Health Complex	2	0	Non Functioning, Maintenance required	30	40	Split Type AC, Repair Required	Fire Extingiture	10		Existing 400' Boring, 1 Deep Tubewell Required	Not Present	Medical Waste Management System Required
2	kotalipara	Kotalipara Upazila Health Complex	2	0	Non Functioning	26	30	Split Type AC, Repair Required	Fire Extingiture	10		No deep tubewell & reserver, 1 Deep Tubewell & reserver Required	Not Present	Medical Waste Management System Required
3	muksudpur	Muksudpur Upazila Health Complex	0		2 lift core available	60	20	Split Type AC, Repair Required	Fire Extingiture			No deep tubewell & reserver, 1 Deep Tubewell Required	Not Present	Medical Waste Management System Required
4	tungipara	Tungipara Upazila Health Complex	0		Lift Required	50	20	23 nos Split Type, 2 nos window type	Fire Extingiture			No deep tubewell & reserver, 1 Deep Tubewell & reserver Required	Not Present	Medical Waste Management System Required

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	kashiani	Kashiani Upazila Health Complex	REB	Yes	250	315	65	Good	120	100			150 Sqmm XLPE Cable		Generator is non functional, Maintenance required
2	kotalipara	Kotalipara Upazila Health Complex	REB	Yes	250	315	65	Good	110	100			150 Sqmm XLPE Cable		Generator is non functional, Maintenance required, Ring Main Unit is not existed
3	muksudpur	Muksudpur Upazila Health Complex	REB	Yes	300	415	115	Good	15	200			150 Sqmm XLPE Cable		Generator is non functional, Maintenance required
4	tungipara	Tungipara Upazila Health Complex	REB	Yes	150	200	50	Good	15	150			120 Sqmm XLPE Cable		Generator is non functional, Maintenance required

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	kashiani	Kashiani Upazila Health Complex	Yes				Yes	No	Yes	No	Yes			10 nos IPS Functioning.
2	kotalipara	Kotalipara Upazila Health Complex	Yes				Yes	Yes	Yes	Yes	Yes			
3	muksudpur	Muksudpur Upazila Health Complex	Yes				Yes	No	Yes	No	Yes			08 nos IPS Functioning.
4	tungipara	Tungipara Upazila Health Complex	Yes			Medical Gas Plant	Yes	Yes	Yes	No	Yes			O2 Generation Plant available, Non Functioning

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	kashiani	Kashiani Upazila Health Complex	Residential Quarter							No file	No file	Residential Doctor, Nurse Quarter Needed
2	kotalipara	Kotalipara Upazila Health Complex	Residential Quarter							No file	No file	Residential Doctor, Nurse Quarter Needed
3	muksudpur	Muksudpur Upazila Health Complex	Residential Quarter							No file	No file	Residential Doctor, Nurse Quarter Needed
4	tungipara	Tungipara Upazila Health Complex	Residential Quarter							No file	No file	Residential Doctor, Nurse Quarter Needed

District Name: Jamalpur

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	bakshiganj	Bakshiganj Upazila Health Complex	1 xlsx	Filled by concerned uhc authority
2	dewanganj	Dewanganj Upazila Health Complex	1 xlsx	Filled by concerned uhc authority
3	islampur	Islampur Upazila Health Complex	1 xlsx	Filled by concerned uhc authority
4	madarganj	Madarganj Upazila Health Complex	1 xlsx	Filled by concerned uhc authority
5	melandaha	Melandah Upazila Health Complex	1 xlsx	Filled by concerned uhc authority
6	sarishabari	Sarishabari Upazila Health Complex	1 xlsx	Filled by concerned uhc authority

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	bakshiganj	Bakshiganj Upazila Health Complex	1993	PWD	no	50	No file	1 pdf	3 pdfs	4 pdfs	16975	GF-16975, FF-15075, 2nd F-5000	1 pdf	1 pdf	1 jpeg	flood risk tends to zero as per local authorities comments	
2	dewanganj	Dewanganj Upazila Health Complex	1983	PWD	yes	50	1 dwg, 1 pdf	1 pdf	2 jpegs, 1 pdf	1 jpeg	20900	GF-20200, FF-15900	1 jpeg, 1 pdf	No file	2 jpegs, 1 mp4	Hospital building and compound totally water logged During heavy rainfall and flood	Plinth area and floor area considered including newly constructed OPD building which is constructed in 2012.
3	islampur	Islampur Upazila Health Complex	1983	PWD	yes	50	1 dwg, 1 pdf	1 pdf	1 pdf	1 pdf	17442	GF-16764, FF-15273	1 jpeg, 2 pdfs	1 pdf	2 jpegs, 1 mp4	flood risk tends to zero as per local authorities comments	Plinth area and floor area considered including newly constructed OPD building which is constructed in 2012.
4	madarganj	Madarganj Upazila Health Complex	2012	HED	no	100	No file	1 pdf	1 pdf	1 pdf	22473	GF-22473, FF-22473, 2nd F-20913, 3RD F-20500	1 pdf	1 pdf	1 jpeg, 1 mp4	flood risk tends to zero as per local authorities comments	new hospital building constructed in 2018
5	melandaha	Melandah Upazila Health Complex	1985	PWD	no	50	1 dwg, 1 pdf	No file	1 pdf	1 pdf	19119	GF-19119, FF-19119	1 dwg, 2 pdfs	1 pdf	1 jpeg, 1 mp4	flood risk tends to zero as per local authorities comments	
6	sarishabari	Sarishabari Upazila Health Complex	1992	PWD	no	50	No file	1 pdf	1 pdf	1 pdf	12900	GF-12900, FF-11710	1 pdf	1 pdf	1 jpeg	Hospital building and compound totally water logged During heavy rainfall and flood	

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	bakshiganj	Bakshiganj Upazila Health Complex	27	2	2	Footing	2	RCC		No file	Not Possible		
2	dewanganj	Dewanganj Upazila Health Complex	24	1	2	Footing	2	RCC		No file	Not Possible	Renovated	OPD is constructed in 2011 with four storied foundation two storied building.
3	islampur	Islampur Upazila Health Complex	24	1.5	2	Footing	2	RCC		No file	Not Possible		4 storied OPD building can be vertically extended.
4	madarganj	Madarganj Upazila Health Complex	47	2	4	Footing	4	RCC		No file	Not Possible		
5	melandaha	Melandah Upazila Health Complex	25.5	2	2	Footing	2	Load Bearing Brick	Brick foundation	No file	Not Possible	Renovated	
6	sarishabari	Sarishabari Upazila Health Complex	21	1	2	Footing	2	Load Bearing Brick	n/a	No file	Not Possible	Renovated and retrofitted	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	bakshiganj	Bakshiganj Upazila Health Complex	0	1	no	Septic Tank	1600	No	0	no	2000 rft	no	minimum 1 deep tube well is needed
2	dewanganj	Dewanganj Upazila Health Complex	0	1	no	Septic Tank	1000	No	0	no	2200 rft	no	
3	islampur	Islampur Upazila Health Complex	0	1	no	Septic Tank	800	No	0	0	2500	river	minimum 1 deep tube well is needed.
4	madarganj	Madarganj Upazila Health Complex	0	1	no	Septic Tank	2000	No	0	no	2000 rft	kharka beel	
5	melandaha	Melandah Upazila Health Complex	0	1	no	Septic Tank	950	No	0	no	2000 rft	no	minimum 1 deep tube well is needed.
6	sarishabari	Sarishabari Upazila Health Complex	0	1	no	Septic Tank	3200	No	0	600 rft	700 rft	river	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	bakshiganj	Bakshiganj Upazila Health Complex	0	2552	0	0	22	2120 rft, average road width-12 ft, bituminous road, need to be repaired.	Yes	Yes	existing boundary need to be vertical extension with brick work and barbed wire.
2	dewanganj	Dewanganj Upazila Health Complex	0	2300	1000	2000	20	Length-2800 rft, average width-12 ft made with rcc, cc with herren bone bond.	Yes	Yes	
3	islampur	Islampur Upazila Health Complex	0	2100	0	1700	14	Length-1100 rft, average width-12 ft made with rcc, cc and herren bone bond.	Yes	Yes	
4	madarganj	Madarganj Upazila Health Complex	0	2000	0	1000	18	2200 rft, average width-10 ft rcc road.	Yes	No	

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
5	melandaha	Melandah Upazila Health Complex	0	2000	0	500	20	1200 rft, width-12 ft. RCC road. Need to be reconstructed.	Yes	Yes	Site development will be needed.
6	sarishabari	Sarishabari Upazila Health Complex	0	1724	0	0	18	1200 rft, width 10 ft	Yes	Yes	Existing boundary wall need to be reconstructed. At least 2' Site development is needed throughout the c

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	bakshiganj	Bakshigonj Upazila Health Complex	0	0		18	12		Not present	5	0		Not Present	
2	dewanganj	Dewanganj Upazila Health Complex	0	0		12	10		Not present	7.5	0		Not Present	
3	islampur	Islampur Upazila Health Complex	0	0		10	14		Not present	12	0		Not Present	
4	madarganj	Madarganj Upazila Health Complex	0	0		30	20		Not present	6	0		Not Present	
5	melandaha	Melandaha Upazila Health Complex	0	0		16	8		Not present	5.5	0		Not Present	
6	sarishabari	Sarishabari Upazila Health Complex	0	0		8	12		Not present	10	0		Not Present	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	bakshiganj	Bakshigonj Upazila Health Complex	REB	Yes	45	0	0	MDB	0	20	0	0	50rm and 110m		
2	dewanganj	Dewanganj Upazila Health Complex	REB	Yes	45	0	0	MDB	0	0	0	0	50rm and 100m		
3	islampur	Islampur Upazila Health Complex	REB	Yes	45	0	0	MDB	0	0	0	0	50rm and 100m		
4	madarganj	Madarganj Upazila Health Complex	REB	Yes	200	0	0	MDB	0	40	0	0	100rm and 120m		
5	melandaha	Melandaha Upazila Health Complex	REB	Yes	40	0	0	MDB	0	10	0	0	35rm and 100m		

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
6	sarishabari	Sarishabari Upazila Health Complex	PDB	Yes	200	0	0	MDB	0	20	0	0	100rm and 105m		

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	bakshiganj	Bakshiganj Upazila Health Complex	No	0			Yes	No	No	No	No	0	SPD	
2	dewanganj	Dewanganj Upazila Health Complex	No	0			No	No	No	No	No	0	SPD	
3	islampur	Islampur Upazila Health Complex	Yes	0			No	No	No	No	No	0	SPD	
4	madarganj	Madarganj Upazila Health Complex	Yes	0			Yes	No	No	No	No	0	SPD	
5	melandaha	Melandaha Upazila Health Complex	No	0			No	No	No	No	No	0	SPD	
6	sarishabari	Sarishabari Upazila Health Complex	Yes	0			Yes	No	No	No	No	0	SPD	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	bakshiganj	Bakshiganj Upazila Health Complex	Waste disposal	1	2014	1	300	300	repairable	No file	No file	
2	bakshiganj	Bakshiganj Upazila Health Complex	Mosque	1	2014	1	1500	1500	good	No file	No file	
3	bakshiganj	Bakshiganj Upazila Health Complex	Garage	1	1993	1	441	441	repairable	No file	1 jpeg	
4	bakshiganj	Bakshiganj Upazila Health Complex	Pump House	1	1993	1	136	136	repairable	No file	1 jpeg	
5	bakshiganj	Bakshiganj Upazila Health Complex	Doctors quarter	1	2014	2	1250	2500	good	No file	1 jpeg	
6	bakshiganj	Bakshiganj Upazila Health Complex	Nurses Dormitory (Senior)	1	2014	3	1000	3000	good	No file	1 jpeg	
7	bakshiganj	Bakshiganj Upazila Health Complex	Nurses Dormitory (Junior)	1	2014	2	800	1600	good	No file	1 jpeg	
8	bakshiganj	Bakshiganj Upazila Health Complex	DHFPO quarter	1	1993	1	1000	1000	repairable	No file	1 jpeg	
9	bakshiganj	Bakshiganj Upazila Health Complex	M.O.S quarter	1	1993	3	2225	6675	repairable	No file	1 jpeg	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
10	bakshiganj	Bakshiganj Upazila Health Complex	Doctors dormitory	1	1993	1	1700	1700	repairable	No file	1 jpeg	
11	bakshiganj	Bakshiganj Upazila Health Complex	4 nurses quarter	1	1993	1	717	717	repairable	No file	1 jpeg	
12	bakshiganj	Bakshiganj Upazila Health Complex	3rd class quarter	1	1993	4	1425	5700	repairable	No file	1 jpeg	
13	bakshiganj	Bakshiganj Upazila Health Complex	4th class quarter	1	1993	2	1142	2284	repairable	No file	1 jpeg	
14	dewanganj	Dewanganj Upazila Health Complex	OPD	1	2012	2	6761	13172	Repairable	No file	1 jpeg	4-Storeyed foundation
15	dewanganj	Dewanganj Upazila Health Complex	Nurses quarter	1	2008	2	1850	3700	Repairable	No file	1 jpeg	
16	dewanganj	Dewanganj Upazila Health Complex	doctors quarter new	1	2008	2	2300	4600	Repairable	No file	1 jpeg	
17	dewanganj	Dewanganj Upazila Health Complex	staff nurses quarter	1	2007	2	1850	3700	Repairable	No file	1 jpeg	
18	dewanganj	Dewanganj Upazila Health Complex	student Hostel male and female	2	1983	1	4347	4347	dilapidated	No file	1 jpeg	To be demolished, area per building
19	dewanganj	Dewanganj Upazila Health Complex	Doctors quarter	5	1983	1	1150	1150	dilapidated	No file	1 jpeg	To be demolished, area per building
20	dewanganj	Dewanganj Upazila Health Complex	Garage	1	1983	1	840	840	dilapidated	No file	No file	To be demolished
21	dewanganj	Dewanganj Upazila Health Complex	Associate Doctors quarter	2	1983	1	4350	4350	dilapidated	No file	1 jpeg	To be demolished, area per building
22	dewanganj	Dewanganj Upazila Health Complex	4th class quarter	1	1983	1	1550	1550	dilapidated	No file	1 jpeg	To be demolished
23	dewanganj	Dewanganj Upazila Health Complex	Nurses quarter	1	1983	2	2616	5232	dilapidated	No file	1 jpeg	To be demolished
24	islampur	Islampur Upazila Health Complex	OPD	1	2012	2	6761	13172	Repairable	No file	1 jpeg	4-Storeyed foundation
25	islampur	Islampur Upazila Health Complex	Pump House	1	2007	1	202	202	Repairable	No file	1 jpeg	
26	islampur	Islampur Upazila Health Complex	Nurses quarter	1	2008	2	1850	3700	Repairable	No file	1 jpeg	
27	islampur	Islampur Upazila Health Complex	Pharmasyst quarter	1	1983	2	1800	3600	dilapidated	No file	1 jpeg	To be demolished
28	islampur	Islampur Upazila Health Complex	4th class quarter	1	1983	2	2800	5600	dilapidated	No file	1 jpeg	To be demolished
29	islampur	Islampur Upazila Health Complex	Garage	1	1983	2	550	1100	Repairable	No file	1 jpeg	
30	islampur	Islampur Upazila Health Complex	Medical Assistant Quarter-1	1	2008	3	2000	6000	dilapidated	No file	1 jpeg	To be demolished
31	islampur	Islampur Upazila Health Complex	Medical Assistant Quarter	1	1983	2	1200	2400	dilapidated	No file	1 jpeg	To be demolished
32	islampur	Islampur Upazila Health Complex	Nurses Dormitory	1	1983	1	1500	1500	dilapidated	No file	1 jpeg	To be demolished
33	islampur	Islampur Upazila Health Complex	Doctors quarter old	1	1983	2	3500	7000	Repairable	No file	1 jpeg	
34	islampur	Islampur Upazila Health Complex	Doctors quarter	1	2008	2	2570	5140	Repairable	No file	1 jpeg	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
35	madarganj	Madarganj Upazila Health Complex	Garage with driver shed	1	2012	2	600	1200	good	No file	1 jpeg	
36	madarganj	Madarganj Upazila Health Complex	Mosque	1	2026	1	1050	1050		No file	1 jpeg	Under construction
37	madarganj	Madarganj Upazila Health Complex	Waste Disposal Plant	1	2012	1	360	360	good	No file	1 jpeg	
38	madarganj	Madarganj Upazila Health Complex	Pump House	1	2012	1	400	400	good	No file	1 jpeg	
39	madarganj	Madarganj Upazila Health Complex	Garage	1	2012	1	550	550	good	No file	1 jpeg	
40	madarganj	Madarganj Upazila Health Complex	Oxygen Plant	1	2012	1	240	240	good	No file	1 jpeg	
41	madarganj	Madarganj Upazila Health Complex	Family Planning office	1	2012	2	2200	4400	good	No file	1 jpeg	
42	madarganj	Madarganj Upazila Health Complex	Doctors quarter	1	2012	4	2100	8400	good	No file	1 jpeg	
43	madarganj	Madarganj Upazila Health Complex	nurses quarter	2	2012	4	1650	6600	good	No file	1 jpeg	Per building
44	madarganj	Madarganj Upazila Health Complex	MOS Quarter	1	2012	3	1600	4800	good	No file	1 jpeg	
45	melandaha	Melandah Upazila Health Complex	Doctors quarter	1	2008	2	3000	6000	repairable	No file	1 jpeg	
46	melandaha	Melandah Upazila Health Complex	RTC officers quarter	1	2008	1	754	754	repairable	No file	1 jpeg	
47	melandaha	Melandah Upazila Health Complex	Dilapidated Doctors quarter	1	1985	3	3962	11886	Need to be demolished	No file	1 jpeg	
48	melandaha	Melandah Upazila Health Complex	Family Planning office	1	2008	2	1414	2828	repairable	No file	No file	
49	melandaha	Melandah Upazila Health Complex	Nurses quarter	1	2008	2	1782	3564	repairable	No file	1 jpeg	
50	melandaha	Melandah Upazila Health Complex	Pump House	1	1985	1	165	165	Need to be demolished	No file	1 jpeg	
51	melandaha	Melandah Upazila Health Complex	Dilapidated Nurses Dormitory	1	1985	1	2700	2700	Need to be demolished	No file	1 jpeg	
52	melandaha	Melandah Upazila Health Complex	Garage with driver accommodation	1	2008	2	400	800	repairable	No file	1 jpeg	
53	melandaha	Melandah Upazila Health Complex	RTC Quarter	1	1985	1	600	600	Need to be demolished	No file	1 jpeg	
54	melandaha	Melandah Upazila Health Complex	Garage	1	1985	1	220	220	Need to be demolished	No file	1 jpeg	
55	melandaha	Melandah Upazila Health Complex	Dilapidated Assistant Doctors quarter	1	1985	2	1500	3000	Need to be demolished	No file	1 jpeg	
56	melandaha	Melandah Upazila Health Complex	Dilapidated Nurses quarter	1	1985	2	1500	3000	Need to be demolished	No file	1 jpeg	
57	melandaha	Melandah Upazila Health Complex	Assistant Doctors quarter	1	1985	2	1415	2830	repairable	No file	1 jpeg	
58	melandaha	Melandah Upazila Health Complex	Nurses quarter	1	2008	3	1500	4500	repairable	No file	1 jpeg	
59	melandaha	Melandah Upazila Health Complex	quarter rtc	1	2008	1	1900	1900	repairable	No file	1 jpeg	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
60	melandaha	Melandah Upazila Health Complex	Kitchen	1	2008	1	700	700	repairable	No file	1 jpeg	
61	melandaha	Melandah Upazila Health Complex	Hostel Male	1	2008	1	2400	2400	repairable	No file	1 jpeg	
62	melandaha	Melandah Upazila Health Complex	Hostel Female	1	2008	2	2435	4870	repairable	No file	1 jpeg	
63	melandaha	Melandah Upazila Health Complex	Oxygen Plant	1	2008	1	256	256	repairable	No file	1 jpeg	
64	melandaha	Melandah Upazila Health Complex	Store building	1	2007	1	820	820	repairable	No file	1 jpeg	
65	melandaha	Melandah Upazila Health Complex	Mosque under construction	1	2026	1	2130	2130	-	No file	1 jpeg	
66	melandaha	Melandah Upazila Health Complex	Ticket counter	1	2012	1	630	630	repairable	No file	1 jpeg	
67	sarishabari	Sharishabari Upazila Health Complex	Garage	1	2012	2	850	850	repairable	No file	1 jpeg	
68	sarishabari	Sharishabari Upazila Health Complex	Imam shed	1	2012	1	375	375	repairable	No file	1 jpeg	
69	sarishabari	Sharishabari Upazila Health Complex	Medical Waste pit	1	1992	1	540	540	repairable	No file	No file	
70	sarishabari	Sharishabari Upazila Health Complex	Mosque	1	1992	1	1178	1178	repairable	No file	1 jpeg	
71	sarishabari	Sharishabari Upazila Health Complex	Store building	1	1992	1	900	900	repairable	No file	1 jpeg	
72	sarishabari	Sharishabari Upazila Health Complex	Pump House	1	1992	1	144	144	repairable	No file	1 jpeg	
73	sarishabari	Sharishabari Upazila Health Complex	Oxygen Plant	1	1992	1	264	264	repairable	No file	No file	
74	sarishabari	Sharishabari Upazila Health Complex	M.O.S quarter	1	1992	1	2400	2400	repairable	No file	1 jpeg	
75	sarishabari	Sharishabari Upazila Health Complex	Doctors dormitory	1	2008	1	1700	1700	repairable	No file	1 jpeg	
76	sarishabari	Sharishabari Upazila Health Complex	Doctors dormitory	1	2009	2	2108	4200	repairable	No file	1 jpeg	
77	sarishabari	Sharishabari Upazila Health Complex	Doctors dormitory	1	2008	1	2304	2304	repairable	No file	1 jpeg	
78	sarishabari	Sharishabari Upazila Health Complex	6 nurses dorm	1	2012	1	2400	2400	repairable	No file	1 jpeg	
79	sarishabari	Sharishabari Upazila Health Complex	3rd class quarter	2	1992	1	1800	1800	To be demolished	No file	1 jpeg	
80	sarishabari	Sharishabari Upazila Health Complex	4th class quarter	2	1992	1	1796	1796	To be demolished	No file	1 jpeg	

District Name: Jashore

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	1 xlsx	Data Collected from Civil Surgeon Office, Jashore & UHFPO, Abhaynagar Office
2	bagherpara	Bagherpara Upzilla Health Complex (DGHS-ID-10001741)	1 xlsx	Data Collected from Civil Surgeon office, Jashore & UHFPO, Bagherpara Office
3	jhikargachha	Jhikargacha Upzilla Health Complex (DGHS-ID-10001759)	1 xlsx	Data Collected from Civil Surgeon Office, Jashore & UHFPO, Jhikargacha Office
4	keshabpur	Keshabpur Upzilla Health Complex (DGHS-ID-10001760)	1 xlsx	Data Collected from Civil Surgeon Office, Jashore & UHFPO, Keshabpur Office
5	manirampur	Manirampur Upzilla Health Complex (DGHS-ID-10001763)	1 xlsx	Data Collected from Civil Surgeon Office, Jashore & UHFPO, Manirampur Office
6	sharsha	Sharsha Upzilla Health Complex (DGHS-ID-10001768)	1 xlsx	Data Collected from Civil Surgeon Office, Jashore & UHFPO, Sharsha Office

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	2004	HED	Yes	20	1 pdf	1 pdf	No file	No file	0	0	1 pdf	No file	1 jpg		
2	abhaynagar	Abhaynagar Upzilla Health Complex (Old Building)	1962	PWD	Yes	30	1 pdf	1 pdf	No file	No file	0	0	1 pdf	No file	1 jpg		
3	bagherpara	Bagherpara Upzilla Health Complex (DGHS-ID-10001741)	2004	HED	Yes	20	1 pdf	1 pdf	No file	No file	0	0	1 pdf	No file	1 jpg		
4	bagherpara	Bagherpara Upzilla Health Complex (Old Building)	1978	PWD	Yes	31	1 pdf	1 pdf	No file	No file	0	0	1 pdf	No file	1 jpg		
5	jhikargachha	Jhikargacha Upzilla Health Complex (DGHS-ID-10001759)	2014	PWD	Yes	19	1 pdf	1 pdf	No file	No file	7592.33	7592.33	1 pdf	No file	1 jpg		
6	jhikargachha	Jhikargacha Upzilla Health Complex(old Building)	1964	PWD	Yes	31	1 pdf	1 pdf	No file	No file	6489.34	6489.34	1 pdf	No file	1 jpg		
7	keshabpur	Keshabpur Upzilla Health Complex (DGHS-ID-10001760)	1978	PWD	Yes	50	1 pdf	1 pdf	No file	No file	16651.77		1 pdf	No file	No file		
8	keshabpur	Keshabpur Upzilla Health Complex (Old Building)	1978	PWD		50	1 pdf	1 pdf	No file	No file	16651.77		1 dwg	No file	1 jpg		
9	manirampur	Manirampur Upzilla Health Complex (DGHS-ID-10001763)	2004	HED	Yes	20	1 pdf	1 pdf	No file	No file	0	0	1 pdf	No file	1 jpg		
10	manirampur	Manirampur Upzilla Health Complex (Old Building)	1974	PWD	Yes	31	1 pdf	1 pdf	No file	No file	0	0	1 pdf	No file	1 jpg		

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
11	sharsha	Sharsha Upzilla Health Complex (DGHS-ID-10001768)	2014	PWD	Yes	19	1 pdf	1 pdf	No file	No file	3797.21	3797.21	1 pdf	No file	1 jpg		
12	sharsha	Sharsha Upzilla Health Complex (Old Building)	1962	PWD	Yes	31	1 pdf	1 pdf	No file	No file	8424.06	8424.06	1 pdf	No file	1 jpg		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	20.5	1	2	Footing	2	Load Bearing Brick	Good in condition	No file	Not Possible		
2	abhaynagar	Abhaynagar Upzilla Health Complex (Old Building)	12	1	1	Footing	1	Load Bearing Brick	Need to be demolish	No file	Not Possible		
3	bagherpara	Bagherpara Upzilla Health Complex (DGHS-ID-10001741)	20.5	1	2	Footing	2	Load Bearing Brick	Good in condition	No file	Not Possible		
4	bagherpara	Bagherpara Upzilla Health Complex (Old Building)	12	1	1	Footing	1	Load Bearing Brick	Need to be demolish	No file	Not Possible		
5	jhikargachha	Jhikargachha Upzilla Health Complex (DGHS-ID-10001759)	20.5	2	2	Footing	2	Load Bearing Brick	Good Condition	No file	Not Possible		
6	jhikargachha	Jhikargachha Upzilla Health Complex(Old Building)	12	2	1	Footing	1	Load Bearing Brick		No file	Not Possible		
7	keshabpur	Keshabpur Upzilla Health Complex (DGHS-ID-10001760)	20.5	1	2	Footing	2	RCC	Need to be demolish	No file	Not Possible		
8	keshabpur	Keshabpur Upzilla Health Complex (old building)	20.5	1	2	Footing	2	Load Bearing Brick	Need to be demolish	No file	Not Possible		
9	manirampur	Manirampur Upzilla Health Complex (DGHS-ID-10001763)	32	1	3	Footing	3	Load Bearing Brick	Good in condition	No file	Not Possible		
10	manirampur	Manirampur Upzilla Health Complex (Old Building)	20.5	1	2	Footing	2	Load Bearing Brick	Need to be demolish	No file	Not Possible		
11	sharsha	Sharsha Upzilla Health Complex (DGHS-ID-10001768)	30.5	1	3	Footing	3	RCC		No file	Not Possible		
12	sharsha	Sharsha Upzilla Health Complex (Old Building)	20.5	1	2	Footing	2	Load Bearing Brick		No file	Not Possible		

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	0	2	Not now	Others		No	0	Open shallow brick masonry drain	Required drainage facility to resolve the water logging facility	Pourosova drain and pourosova waste colloection system	
2	bagherpara	Bagherpara Upzilla Health Complex (DGHS-ID-10001741)	0	2	Not now	Others		No	0	Open shallow brick masonry drain	Required drainage facility to resolve the water logging facility	Pourosova drain and pourosova waste colloection system	

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
3	jhikargachha	Jhikargacha Upzilla Health Complex (DGHS-ID-10001759)	0	2	0	Others	0	No	0	N/A		Pourosova	
4	keshabpur	Keshabpur Upzilla Health Complex (DGHS-ID-10001760)	0	2	Not now	Others		No	0	Open shallow brick masonry drain	Required drainage facility to resolve the water logging facility	Pourosova drain and pourosova waste colloection system	
5	manirampur	Manirampur Upzilla Health Complex (DGHS-ID-10001763)	0	2	Not now	Others		No	0	Open shallow brick masonry drain	Required drainage facility to resolve the water logging facility	Pourosova drain and pourosova waste colloection system	
6	sharsha	Sharsha Upzilla Health Complex (DGHS-ID-10001768)	0	1	No	Others	0	No	0			N/A	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)		4	8		17	Internal RCC Road same to the level of outside main road	Yes	Yes	
2	bagherpara	Bagherpara Upzilla Health Complex (DGHS-ID-10001741)		4	8		17	Internal RCC Road same to the level of outside main road	Yes	Yes	
3	jhikargachha	Jhikargacha Upzilla Health Complex (DGHS-ID-10001759)		4			17	RCC road	Yes	Yes	
4	keshabpur	Keshabpur Upzilla Health Complex (DGHS-ID-10001760)		4	8		17	Internal RCC Road same to the level of outside main road	Yes	Yes	
5	manirampur	Manirampur Upzilla Health Complex (DGHS-ID-10001763)		4	8		17	Internal RCC Road same to the level of outside main road	Yes	Yes	
6	sharsha	Sharsha Upzilla Health Complex (DGHS-ID-10001768)		1990			20	RCC	Yes	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	0	0	NO	6	20	Split AC at OT	Fire Extinguishing System	3	0		Incinerator Type	Collected waste deposited in a confined tank. this tank is made of brick masonry structure.
2	bagherpara	Bagherpara Upzilla Health Complex (DGHS-ID-10001741)	0	0	NO	6	20	Split AC at OT	Fire Extinguishing System	3	0		Incinerator Type	Collected waste deposited in a confined tank. this tank is made of brick masonry structure.
3	jhikargachha	Jhikargacha Upzilla Health Complex (DGHS-ID-10001759)	0	0		4	20		Fire Extinguisher System	3	0		Incinerator Type	

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
4	keshabpur	Keshabpur Upzilla Health Complex (DGHS-ID-10001760)	0	0	NO	6	20	Split AC at OT	Fire Extinguishing System	3	0		Incinerator Type	Collected waste deposited in a confined tank. this tank is made of brick masonry structure.
5	manirampur	Manirampur Upzilla Health Complex (DGHS-ID-10001763)	0	0	NO	6	20	Split AC at OT	Fire Extinguishing System	3	0		Incinerator Type	Collected waste deposited in a confined tank. this tank is made of brick masonry structure.
6	sharsha	Sharsha Upzilla Health Complex (DGHS-ID-10001768)	0	0		4	20		Fire Extinguisher System	3	0		Incinerator Type	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	REB	Yes	80	0	0		0	0	0	0			
2	bagherpara	Bagherpara Upzilla Health Complex (DGHS-ID-10001741)	REB	Yes	80	0	0		0	0	0	0			
3	jhikargachha	Jhikargacha Upzilla Health Complex (DGHS-ID-10001759)	REB	Yes	80	0	0		0	0	0	0			
4	keshabpur	Keshabpur Upzilla Health Complex (DGHS-ID-10001760)	REB	Yes	80	0	0		0	0	0	0			
5	manirampur	Manirampur Upzilla Health Complex (DGHS-ID-10001763)	REB	Yes	80	0	0		0	0	0	0			
6	sharsha	Sharsha Upzilla Health Complex (DGHS-ID-10001768)	REB	Yes	80	0	0		0	0	0	0			

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	No	0	0		Yes	No	No	Yes	Yes	1	Attach	
2	bagherpara	Bagherpara Upzilla Health Complex (DGHS-	No	0	0		Yes	No	No	Yes	Yes	1	Attach	

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
		ID-10001741)												
3	jhikargachha	Jhikargacha Upzilla Health Complex (DGHS-ID-10001759)	No	0	0		Yes	No	No	Yes	Yes	1	Attach	
4	keshabpur	Keshabpur Upzilla Health Complex (DGHS-ID-10001760)	No	0	0		Yes	No	No	Yes	Yes	1	Attach	
5	manirampur	Manirampur Upzilla Health Complex (DGHS-ID-10001763)	No	0	0		Yes	No	No	Yes	Yes	1	Attach	
6	sharsha	Sharsha Upzilla Health Complex (DGHS-ID-10001768)	No	0	0		Yes	No	No	Yes	Yes	1	Attach	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	Nurse Dormitory	2	1982	1	1313.19	1313.19	Need to be demolished	No file	No file	
2	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	Nurse Dormitory	1	1981	1	1313.19	1313.19	Need to be demolished	No file	No file	
3	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	4th Class Staff Quarter	3	1981	3	1550	4650	Need to be demolished	No file	No file	
4	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	4th Class Staff Quarter	2	1983	3	1420.83	4262.49	Need to be demolished	No file	No file	
5	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	4th Class Staff Quarter	1	1983	3	1420.83	4262.49	Need to be demolished	No file	No file	
6	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	3rd Class Staff Quarter	3	1982	2	1453.12	2906.24	Need to be demolished	No file	No file	
7	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	3rd Class Staff Quarter	2	1982	2	1453.12	2906.24	Need to be demolished	No file	No file	
8	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	3rd Class Staff Quarter	1	1982	2	1453.12	2906.24	Need to be demolished	No file	No file	
9	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	Medical officer Quater	2	1982	3	1453.12	4359.36	Need to be demolished	No file	No file	
10	abhaynagar	Abhaynagar Upzilla Health Complex (DGHS-ID-10001737)	Medical officer Quater	1	1981	3	5155.91	15467.73	Need to be demolished	No file	No file	
11	bagherpara	Bagherpara Upzilla Health Complex (DGHS-ID-10001741)	4th Class Staff Quarter		1980	2	2258.26	4516.52	Need to be demolished	No file	No file	
12	bagherpara	Bagherpara Upzilla Health Complex (DGHS-ID-10001741)	3rd Class Staff Quarter		1980	2	6894.93	13789.86	Need to be demolished	No file	No file	
13	bagherpara	Bagherpara Upzilla Health Complex (DGHS-ID-10001741)	Nurse Dormitory		1980	1	1223.21	1223.21	Need to be demolished	No file	No file	
14	bagherpara	Bagherpara Upzilla Health Complex (DGHS-ID-10001741)	Medical officer Quater		1980	3	6633.15	19899.45	Need to be demolished	No file	No file	
15	jhikargachha	Jhikargacha Upzilla Health Complex (DGHS-ID-10001759)	Health Care	2	2014	2	7592.33	15184.66	Good Condition	No file	No file	
16	jhikargachha	Jhikargacha Upzilla Health Complex (DGHS-ID-10001759)	Health Care	1	1994	1	6489.34	6489.34	Good Condition	No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
17	keshabpur	Keshabpur Upzilla Health Complex (DGHS-ID-10001760)	4th Class Staff Quarter		1970	2	2250.84	4501.68	Need to be demolished	No file	No file	
18	keshabpur	Keshabpur Upzilla Health Complex (DGHS-ID-10001760)	3rd Class Staff Quarter		1978	2	6617.65	13235.3	Need to be demolished	No file	No file	
19	keshabpur	Keshabpur Upzilla Health Complex (DGHS-ID-10001760)	Nurse Dormitory		1978	1	1440.74	1440.74	Need to be demolished	No file	No file	
20	keshabpur	Keshabpur Upzilla Health Complex (DGHS-ID-10001760)	Medical officer Quater		1979	3	6267.28	18801.84	Need to be demolished	No file	No file	
21	manirampur	Manirampur Upzilla Health Complex (DGHS-ID-10001763)	4th Class Staff Quarter		1980	2	2555.67	5111.34	Need to be demolished	No file	No file	
22	manirampur	Manirampur Upzilla Health Complex (DGHS-ID-10001763)	3rd Class Staff Quarter		1976	2	5202.09	10404.18	Need to be demolished	No file	No file	
23	manirampur	Manirampur Upzilla Health Complex (DGHS-ID-10001763)	Nurse Dormitory		1976	1	1225.47	1225.47	Need to be demolished	No file	No file	
24	manirampur	Manirampur Upzilla Health Complex (DGHS-ID-10001763)	Medical officer Quater		1976	3	6776.41	20329.23	Need to be demolished	No file	No file	
25	sharsha	Sharsha Upzilla Health Complex (DGHS-ID-10001768)	Doctor's Dormitory		2014	3	1044.07	3132.21	Good Condition	No file	No file	
26	sharsha	Sharsha Upzilla Health Complex (DGHS-ID-10001768)	Doctor's Dormitory		2014	3	2271.16	6813.48	Good Condition	No file	No file	
27	sharsha	Sharsha Upzilla Health Complex (DGHS-ID-10001768)	Family Planning Office		2014	3	2271.16	6813.48	Good Condition	No file	No file	
28	sharsha	Sharsha Upzilla Health Complex (DGHS-ID-10001768)	Sharsha Upzilla Health Complex (Hospital)		2014	2	4559.93	9119.86	Good Condition	No file	No file	
29	sharsha	Sharsha Upzilla Health Complex (DGHS-ID-10001768)	Sharsha Upzilla Health Complex (Hospital)		2014	1	1717.26	1717.26	Good Condition	No file	No file	
30	sharsha	Sharsha Upzilla Health Complex (DGHS-ID-10001768)	Mosque		2014	2	0	0	Good Condition	No file	1 jpg	

District Name: Jhalokathi

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	kathalia	Upazilla Health Complex, Kathalia	1 xlsx	
2	nalchity	Nalchity Upazila Health Complex, Nalchity.	1 xlsx	
3	rajapur	Upazilla Health Complex, Rajapur	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	kathalia	Upazilla Health Complex, Kathalia (New Building)	2012	HED	0	50	1 dwg, 1 pdf	1 pdf	1 dwg	1 dwg	7260	Ground Floor Area-7260 Sq.ft, First Floor Area-6331 Sq.ft, Second Floor Area-4575 Sq.ft	1 dwg	No file	3 jpegs	2 Ft	
2	nalchity	Upazilla Health Complex, Nalchity (New Building)	2012	HED	0	19	1 dwg, 1 pdf	1 pdf	1 dwg	1 dwg	7265	Ground Floor Area-7265 Sq.ft, First Floor Area-6570 Sq.ft, Second Floor Area-4196 Sq.ft.	1 dwg	No file	3 jpegs	2 Ft	
3	nalchity	Upazilla Health Complex, Nalchity (Old Building)	1975	PWD	0	31	1 dwg, 1 pdf	1 pdf	1 dwg	1 dwg	8830	Ground Floor Area-8830 Sq.ft, First Floor Area-8416 Sq.ft	1 dwg	No file	10 jpegs	1.5 Ft	
4	rajapur	Upazilla Health Complex, Rajapur ((New Building)	2012	HED	0	19	1 dwg, 1 pdf	1 pdf	1 dwg	1 dwg	7265	Ground Floor Area-7265 Sq.ft, First Floor Area-6331 Sq.ft	1 dwg	No file	8 jpegs	2 Ft	
5	rajapur	Upazilla Health Complex, Rajapur (Old Building)	1975	PWD	0	31	1 dwg, 1 pdf	1 pdf	1 dwg	1 dwg	8659	Ground Floor Area-8659 Sq.ft, First Floor Area-8186 Sq.ft.	1 dwg	No file	9 jpegs	2 Ft	

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	kathalia	Upazilla Health Complex, Kathalia (New Building)	33	2	3	Deep	3	RCC	Structural Condition : Good	No file	Possible	No	
2	nalchity	Nalchity Upazila Health Complex (New Building)	43	2	3	Deep	3	RCC	New Building: Good Condition	No file	Possible	No	
3	nalchity	Upazilla Health Complex, Nalchity (Old Building)	32	1.5	2	Footing	2	Load Bearing Brick	Old Building : Not Good	No file	Not Possible	No	
4	rajapur	Upazilla Health Complex, Rajapur (New Building)	32	2	2	Deep	2	RCC	New Building: Good,	No file	Possible	No	
5	rajapur	Upazilla Health Complex, Rajapur (Old Building)	30	1.5	2	Footing	2	Load Bearing Brick	Old Building : Not Good	No file	Not Possible	No	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	kathalia	Upazilla Health Complex, Kathalia (New Building)	0	1	No	Septic Tank	0	No	0	Master drain connect with adjacent river	No	Inside hospital compound	
2	nalchity	Nalchity Upazila Health Complex, Nalchity. (New Building)	0	0	No	Others		No	0	Master drain connect with adjacent khal	No	Inside hospital compound	
3	nalchity	Upazilla Health Complex, Nalchity (Old Building)	0	1	No	Others	0	No	0	Master drain connect with adjacent khal	No	Inside hospital compound	
4	rajapur	Upazilla Health Complex, Rajapur (New Building)	0	0	No	Others	0	No	0	Master drain connect with adjacent khal	No	Inside hospital compound	
5	rajapur	Upazilla Health Complex, Rajapur (Old Building)	0	1	No	Septic Tank	0	No	0	Master drain connect with adjacent khal	No	Inside hospital compound	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	kathalia	Upazilla Health Complex, Kathalia (New Building)	0	2109	0	0	10	RCC Road ,Wide-8 ft, Length-946 ft.	No	No	
2	nalchity	Upazilla Health Complex, Nalchity (New Building)	0	0	0	0	0		Yes	No	
3	nalchity	Upazilla Health Complex, Nalchity (Old Building)	0	2697	0	0	15	RCC Road ,Wide-8 ft, Length-1450 ft.	Yes	Yes	
4	rajapur	Upazilla Health Complex, Rajapur (New Building)	0	0	0	0	0		Yes	No	
5	rajapur	Upazilla Health Complex, Rajapur (Old Building)	0	1948	0	0	30	RCC Road ,Wide-8 ft, Length-1593 ft.	Yes	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	kathalia	Upazilla Health Complex, Kathalia (New Building)	0	0	No	10	10	No	No	2	0	No	Not Present	No
2	nalchity	Upazilla Health Complex, Nalchity (New Building)	0	0	No	10	10	No	No	0	0	No	Others	No
3	nalchity	Upazilla Health Complex, Nalchity (Old Building)	0	0	No	12	10	No	No	3	0	No	Others	No
4	rajapur	Upazilla Health Complex, Rajapur	0	0	No	10	6	No	No	0	0	No	Others	No

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
		(New Building)												
5	rajapur	Upazilla Health Complex, Rajapur (Old Building)	0	0	No	20	25	No	No	3	0	No	Others	No

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	kathalia	Upazilla Health Complex, Kathalia (New Building)	PDB	No	12	0	0	No	0	5	0	0	No	No	
2	nalchity	Upazilla Health Complex, Nalchity (New Building)	REB	Yes	20	0	0	No	0	5	0	0	No	No	
3	nalchity	Upazilla Health Complex, Nalchity (Old Building)	REB	Yes	20	0	0	No	0	10	0	0	No	No	
4	rajapur	Upazilla Health Complex, Rajapur (New Building)	REB	Yes	15	0	0	No	0	10	0	0	No	No	
5	rajapur	Upazilla Health Complex, Rajapur (Old Building)	REB	Yes	30	0	0	No	0	10	0	0	No	No	

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	kathalia	Upazilla Health Complex, Kathalia (New Building)	Yes	0	10	No	Yes	No	Yes	No	Yes	1	Need Fire Extinguisher - 10 pcs	
2	nalchity	Upazilla Health Complex, Nalchity (New Building)	Yes	0	0	No	Yes	No	Yes	No	Yes	1	Need Fire Extinguisher - 10 pcs	
3	nalchity	Upazilla Health Complex, Nalchity (Old Building)	Yes	0	8	No	Yes	No	Yes	No	Yes	1	Need Fire Extinguisher - 20 pcs	
4	rajapur	Upazilla Health Complex, Rajapur (New Building)	Yes	0	11	No	Yes	No	Yes	No	Yes	1	Need Fire Extinguisher - 10 pcs	
5	rajapur	Upazilla Health Complex, Rajapur (Old Building)	Yes	0	9	No	Yes	No	Yes	No	Yes	1	Need Fire Extinguisher - 20 pcs	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	kathalia	Upazilla Health Complex, Kathalia	1							No file	No file	
2	nalchity	Upazilla Health Complex, Nalchity	Upazilla Health Complex, Nalchity	2	2012	3				No file	No file	
3	rajapur	Upazilla Health Complex, Rajapur	1							No file	No file	

District Name: Jhenaidah

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	harinakundu	Harinakundu Upazila Health Complex, Jhenaidah	No file	
2	kaliganj	Kaliganj Upazila Health Complex, Jhenaidah	No file	
3	kotchandpur	Koychandpur Upazila Health Complex,Jhnaidah	No file	
4	maheshpur	Mahespur Upazila Health Complex, Jhenaidah	No file	
5	shailkupa	Shailkupa Upazila Health Complex, Jhenaidah	No file	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	harinakundu	Harinakundu Upazila Health Complex, Jhenaidah	1984	HED	No	50	No file	No file	No file	No file			No file	No file	5 jpgs		
2	kaliganj	Kaliganj Upazila Health Complex, Jhenaidah	1984	HED	No	50	1 pdf	No file	1 jpg	1 pdf	33337.62	16668.82	1 pdf	No file	No file		Demolish the existing building for new consyruction
3	kotchandpur	Kotchandpur Upazila Health Complex, Jhenaidah	1984	HED	Yes	100	1 pdf	1 pdf	1 jpg	1 jpg			1 jpg	No file	2 jpgs		Existing Bed Number 100. It needs to renevation.
4	maheshpur	Mahespur Upazila Health Complex, Jhenaidah	1984	HED	Yes	50	1 pdf	No file	1 pdf	1 pdf	48901.71	16300.57	1 pdf	No file	No file		
5	shailkupa	Shailkupa Upazila Health Complex, Jhenaidah	1984	HED	No	50	1 pdf	1 pdf	1 pdf	1 pdf	25959.93	8653.31	1 pdf	No file	4 jpgs		Existing Bed Number 50. Existing 6 storied Foundation 3 storied buildin can be vertical extension and another 4 storied Foundation with 3 storied building can be vertical extension. No building need to be demolish.

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	harinakundu	Harinakundu Upazila Health Complex, Jhenaidah	22	2	2	Footing	4	RCC	well	No file	Possible		
2	kaliganj	Kaliganj Upazila Health Complex, Jhenaidah	22	2	2	Footing	2	Load Bearing Brick	bad	No file	Not Possible		
3	kotchandpur	Kotchandpur Upazila Health Complex, Jhenaidah	50.5	0.5	5	Deep	5	RCC	well	No file	Not Possible		Renovation is to be needed.

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
4	maheshpur	Mahespur Upazila Health Complex, Jhenaidah	30.5	0.48	3	Footing	4	RCC	no so good	No file	Possible		
5	shailkupa	Shailkupa Upazila Health Complex, Jhenaidah	33	2.5	3		6	RCC	well	No file	Possible		3 No story can be extension and another building 1 story can be vertical extension with renovation

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	harinakundu	Harinakundu Upazila Health Complex, Jhenaidah	3000	1		Septic Tank	719.99	No		Brick Masonry drain work	Insufficient Drainage Facility	Drain	New RCC Drain can be construction with septic tank
2	kaliganj	Kaliganj Upazila Health Complex, Jhenaidah	3000	1		Septic Tank	720	No		Brick Masonry drain work	Insufficient Drainage Facility	Drain	New RCC Drain can be construction with septic tank
3	kotchandpur	Kotchandpur Upazila Health Complex, Jhenaidah	7000	1		Septic Tank	360	No		Brick Masonry drain work	Insufficient Drainage Facility		New RCC Drain can be construction with septic tank
4	maheshpur	Mahespur Upazila Health Complex, Jhenaidah	5000	1		Septic Tank	720	No		Brick Masonry drain work	Insufficient Drainage Facility	Drain	New RCC Drain can be construction with septic tank
5	shailkupa	Shailkupa Upazila Health Complex, Jhenaidah	7000	1		Septic Tank	720	No		Brick Masonry drain work		Drain	New RCC Drain can be construction with septic tank

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	harinakundu	Harinakundu Upazila Health Complex, Jhenaidah					25	RCC Road but condition is not so good	Yes	Yes	
2	kaliganj	Kaliganj Upazila Health Complex, Jhenaidah		1496			12	RCC Road but condition is not so good	Yes	Yes	Boundary wall renovation required
3	kotchandpur	Kotchandpur Upazila Health Complex, Jhenaidah		2137.7			25	RCC Road but condition is not so good	Yes	Yes	Small amount of site improvement requird
4	maheshpur	Mahespur Upazila Health Complex, Jhenaidah		3020				RCC Road but condition is not so good	Yes	Yes	
5	shailkupa	Shailkupa Upazila Health Complex, Jhenaidah	0				20	RCC Road but condition is not so good	Yes	Yes	Existing Bed Number 50. Existing 4 storied Foundation 2 storied buildin can be vertical extension and another 2storied Foundation with 2 storied building can be demolish and new building will be constructed

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	harinakundu	Harinakundu Upazila Health Complex, Jhenaidah			No lift present	20	100		No system. But it to be Need.	2	2	Additional Deep tubewell with motor required	Not Present	Need
2	harinakundu	Harinakundu Upazila Health Complex, Jhenaidah	0	0	If vertical Extension need to be lift	20	100		No system. But it to be Need.	1.98	2	Additional Deep tubewell with motor required	Not Present	Need
3	kaliganj	Kaliganj Upazila Health Complex, Jhenaidah			No lift present	20	100		No system. But it to be Need.	2	2	Additional Deep tubewell with motor required	Not Present	Need
4	kotchandpur	Kotchandpur Upazila Health Complex, Jhenaidah	1	1		40	100		Need it	2	2	Additional Deep tubewell with motor required	Not Present	Need
5	maheshpur	Mahespur Upazila Health Complex, Jhenaidah			No lift present	20	100		No system. But it to be Need.	2	2	Additional Deep tubewell with motor required	Not Present	Need

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	harinakundu	Harinakundu Upazila Health Complex, Jhenaidah	REB	Yes						500					
2	kaliganj	Kaliganj Upazila Health Complex, Jhenaidah	REB	Yes											
3	kotchandpur	Kotchandpur Upazila Health Complex, Jhenaidah	PDB	Yes				good	50	500	0.5				
4	maheshpur	Mahespur Upazila Health Complex, Jhenaidah	WZPDCL	Yes				Not good		500					
5	shailkupa	Shailkupa Upazila Health Complex, Jhenaidah	WZPDCL	No	200	300	500	Not good	50	400	0	1			

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	harinakundu	Harinakundu Upazila Health Complex, Jhenaidah	No				Yes	No	No	No	Yes	2		
2	kaliganj	Kaliganj Upazila Health Complex, Jhenaidah	No				Yes	No	No	No	Yes	2		EM renovation and mention item extra need

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
3	kotchandpur	Kotchandpur Upazila Health Complex, Jhenaidah	Yes			Insufficient	Yes	No	No	Yes	Yes	2		EM renovation and mention item extra need
4	maheshpur	Mahespur Upazila Health Complex, Jhenaidah	No				Yes	No	No	No	Yes	1		EM renovation and mention item extra need
5	shailkupa	Shailkupa Upazila Health Complex, Jhenaidah	No				Yes	No	No	No	Yes	2		

District Name: Joypurhat

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	akkelpur	Akkelpur Upazila Health Complex	1 xlsx	ok
2	kalai	Kalai Upazila Health Complex	1 xls	ok
3	khetlal	Khetlal Upazila Health Complex	1 xlsx	ok
4	panchbibi	Panchbibi Upazila Health Complex	1 xlsx	ok

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	akkelpur	Akkelpur upazila health complex, Kalai, Joypurhat.		PWD	not available	50	1 dwg, 1 pdf	No file	No file	1 pdf			1 pdf	No file	No file		ok
2	kalai	kalai upazila health complex, Kalai, Joypurhat.		PWD	not available	50	1 dwg, 1 pdf	No file	No file	1 pdf			No file	No file	No file		ok
3	khetlal	khetlal upazila health complex, Kalai, Joypurhat.		PWD	not available	50	1 dwg, 1 pdf	No file	No file	1 pdf			No file	No file	No file		ok
4	panchbibi	panchbibi upazila health complex, Kalai, Joypurhat.		PWD			1 dwg, 1 pdf	No file	No file	1 pdf			No file	No file	No file		ok

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	akkelpur	Akkelpur Upazila Health Complex, Akkelpur, Joypurhat .	20	2	2	Footing	2	Load Bearing Brick	2 storied building with 2 storied foundation.	No file	Not Possible	construction on 1987	existing bed number at this building is 50
2	kalai	Kalai Upazila Health Complex, Kalai, Joypurhat (New Building).	30	3	3	Footing	6	RCC	3 storied building with 6 storied foundation.	No file	Possible	construction on 2006	existing bed number at this building is 19
3	kalai	Kalai Upazila Health Complex, Kalai, Joypurhat (Old Building).	10	2	1	Footing	1	Load Bearing Brick	Single storied Brick Structured building .	No file	Not Possible	construction on 1983	Used for office purpose.
4	kalai	Kalai Upazila Health Complex, Kalai, Joypurhat (Old Building).	20	2	2	Footing	2	Load Bearing Brick	2 storied Brick Structured building .	No file	Not Possible	construction on 1983	existing bed number at this building is 31
5	khetlal	Khetlal Upazila Health Complex, Khetlal, Joypurhat (New Building).	30	3	3	Footing	6	RCC	3 storied building with 6 storied foundation.	No file	Possible	construction on 2006	Used for Hospital and Administrative purpose.
6	khetlal	Khetlal Upazila Health Complex, Khetlal, Joypurhat (Old Building).	10	2	1	Footing	1	Load Bearing Brick	Single storied Brick Structured building .	No file	Not Possible	construction on 1985	Used for Hospital and Administrative purpose.
7	khetlal	Khetlal Upazila Health Complex, Khetlal, Joypurhat (Old Building).	20	2	2	Footing	2	Load Bearing Brick	2 storied Brick Structured building .	No file	Not Possible	construction on 1985	Used for Hospital and Administrative purpose.

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
8	panchbibi	Panchbibi Upazila Health Complex, Panchbibi, Joypurhat (New Building).	30	3	3	Footing	6	RCC	3 storied building with 6 storied foundation.	No file	Possible	construction on 2006	
9	panchbibi	Panchbibi Upazila Health Complex, Panchbibi, Joypurhat (Old Building).	20	2	2	Footing	2	Load Bearing Brick	2 storied Brick Structured building .	No file	Not Possible	construction on 1983	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	akkelpur	Akkelpur Upazila Health Complex, Akkelpur, Joypurhat .	0	3	Required UGWR	Septic Tank	10000	No	0	exist 1to 2 feet depht drain	Required 1 to 3 feet depht drain	at Joypurhat Sadar 17 km from Akkelpur Upazila health Complex.	
2	kalai	Kalai Upazila Health Complex, Kalai, Joypurhat .	0	3	Required UGWR	Septic Tank	10000	No	0	exist 1to 3 feet depht drain	Required 1 to 3 feet depht drain	at Joypurhat Sadar 15 km from kalai Upazila health Complex.	
3	khetlal	Khetlal Upazila Health Complex, Khetlal, Joypurhat .	0	3	Required UGWR	Septic Tank	10000	No	0	exist 1to 3 feet depht drain	Required 1 to 3 feet depht drain	at Joypurhat Sadar 14 km from Khetlal Upazila health Complex.	
4	panchbibi	Panchbibi Upazila Health Complex, Panchbibi, Joypurhat .	0	3	Required UGWR	Septic Tank	10000	No	0	exist 1to 3 feet depht drain	Required 1 to 3 feet depht drain	at Joypurhat Sadar 12 km from Panchbibi Upazila health Complex.	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	akkelpur	Akkelpur Upazila Health Complex, Akkelpur, Joypurhat .	0	2091	0	320	24	Exist Rigid and Flexible Pavement.	No	No	
2	kalai	Kalai Upazila Health Complex, Kalai, Joypurhat .	735	1830	0	340	14	Exist Rigid and Flexible Pavement.	Yes	No	
3	khetlal	Khetlal Upazila Health Complex, Khetlal, Joypurhat .	0	1945	0	260	16	Exist Rigid and Flexible Pavement.	Yes	No	
4	panchbibi	Panchbibi Upazila Health Complex, Panchbibi, Joypurhat .	0	3020	0	280	12	Exist Rigid and Flexible Pavement.	Yes	No	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	akkelpur	Akkelpur Upazila Health Complex, Akkelpur, Joypurhat .	2 Storied Hospital and Administrative Building	1	1987	2	7500	15000	Used as 50 beded Hospital and Administrative Building.	No file	No file	
2	kalai	kalai upazila health complex, Kalai, Joypurhat.	3 storied quarter	1	2006	3	1400	4200	usable	No file	No file	ok
3	kalai	kalai upazila health complex, Kalai, Joypurhat.	3 storied upazila family planing office	1	2016	3	1600	4800	usable	No file	No file	ok

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
4	kalai	Kalai Upazila Health Complex, Kalai, Joypurhat .	Single Storied Administrative Building	1	1983	1	2200	2200	Used as Hospital and Administrative Building.	No file	No file	
5	kalai	Kalai Upazila Health Complex, Kalai, Joypurhat .	2 Storied Administrative Building	1	1983	2	5200	10400	Used as 31 beded Hospital and Administrative Building.	No file	No file	
6	kalai	Kalai Upazila Health Complex, Kalai, Joypurhat .	Health Complex Building	1	2006	3	6500	17500	Used as 19 beded Hospital Building.	No file	No file	
7	khetlal	Khetlal Upazila Health Complex, Khetlal, Joypurhat .	Single Storied Hospital and Administrative Building	1	1985	1	2500	2500	Used as Hospital and Administrative Building.	No file	No file	
8	khetlal	Khetlal Upazila Health Complex, Khetlal, Joypurhat .	2 Storied Hospital and Administrative Building	1	1985	2	7000	14000	Used as Hospital and Administrative Building.	No file	No file	
9	khetlal	Khetlal Upazila Health Complex, Khetlal, Joypurhat .	3 storied Health Complex Building	1	2006	3	7500	22500	Used as Hospital and Administrative Building.	No file	No file	
10	panchbibi	Panchbibi Upazila Health Complex, Panchbibi, Joypurhat .	2 Storied Administrative Building	1	1983	2	9500	19000	Used as Hospital and Administrative Building.	No file	No file	
11	panchbibi	Panchbibi Upazila Health Complex, Panchbibi, Joypurhat .	3 Storied Health Complex Building	1	2006	3	7500	22500	Used as Hospital Building.	No file	No file	

District Name: Khagrachhari

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	dighinala	Dighinala Upazilla Health Complex	No file	
2	guimara	Guimara Upazilla Health Complex	No file	
3	lakshmichhari	Lakshmichhari Upazilla Health Complex	No file	
4	mahalchhari	Mahalchhari Upazilla Health Complex	No file	
5	manikchhari	Manikchhari Upazilla Health Complex	No file	
6	matiranga	Matiranga Upazilla Health Complex	No file	
7	panchhari	Panchhari Upazilla Health Complex	No file	
8	ramgarh	Ramgarh Upazilla Health Complex	No file	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	dighinala	Dighinala Upazilla Health Complex	1924	PWD	Available	31	No file	No file	No file	1 dwg	11264.48		No file	No file	8 jpgs, 1 mp4	-11 ft from EGL	Old Semi-pucca 01-storied 31 bed hospital is being used. 50 bed hospital construction is underway. (3-storied building with 4-storied foundation)
2	guimara	Guimara Upazilla Health Complex					No file	No file	No file	No file			No file	No file	No file		Yet to be constructed.
3	lakshmichhari	Lakshmichhari Upazilla Health Complex	1999	HED	Available	50	No file	No file	No file	1 dwg	19088.78		No file	No file	7 jpgs, 1 mp4	-5 ft from EGL	Old 01-storied 31 bed hospital is being used. 50 bed hospital construction is underway. (04-storied building)
4	mahalchhari	Mahalchhari Upazilla Health Complex	1984	PWD	Available	31	No file	No file	No file	1 dwg	9302.7		No file	No file	7 jpgs, 1 mp4	N/A (Top of the hill)	02-storied building
5	manikchhari	Manikchhari Upazilla Health Complex	2017	HED	Available	50	No file	No file	No file	1 dwg	11444.6		No file	No file	4 jpgs	-11 ft from EGL	04-storied building
6	matiranga	Matiranga Upazilla Health Complex	1997	HED	Available	31	No file	No file	No file	1 dwg	17997.11		No file	No file	4 jpgs	-8 ft from EGL	
7	panchhari	Panchhari Upazilla Health Complex	1997	HED	Available	10	No file	No file	No file	1 dwg	18249.97		No file	No file	4 jpgs	N/A (Top of the hill)	
8	ramgarh	Ramgarh Upazilla Health Complex	2013	HED	Available	50	No file	No file	No file	1 jpg	15227.69		No file	No file	7 jpgs, 1 mp4	N/A	

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	dighinala	Dighinala Upazilla Health Complex	12	3	1	Footing	1	Load Bearing Brick		No file	Not Possible		
2	guimara	N/A								No file			
3	lakshmichhari	Lakshmichhari Upazilla Health Complex	12	3	1	Footing	1	RCC		No file	info not available		
4	mahalchhari	Mahalchhari Upazilla Health Complex	24		2	Footing	2	RCC		No file	info not available		
5	manikchhari	Manikchhari Upazilla Health Complex	48	3	4	Footing	4	RCC		No file	info not available		
6	matiranga	Matiranga Upazilla Health Complex	12	1.5	1	Footing	1	RCC		No file	info not available		
7	panchhari	Panchhari Upazilla Health Complex	12		1	Footing	1	Load Bearing Brick		No file	info not available		
8	ramgarh	Ramgarh Upazilla Health Complex	36		3	Footing	5	RCC		No file	Possible		

District Name: Khulna

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	batiaghata	Batiaghata Upazila Health Complex	No file	
2	dacope	Dacope Upazila Health Complex	1 xlsx	
3	dighalia	Upazila Health Complex, Digholia, Khulna	No file	
4	dumuria	Dumuria Upazila Health Complex	No file	
5	koyra	Koyra Upazila Health Complex	1 xlsx	কয়রা উপজেলা স্বাস্থ্য কমপ্লেক্সটি ৫০ শয্যা বিশিষ্ট বলা হলেও বর্তমানে যে তিনতলা ভবনটিতে হাসপাতালের কার্যক্রম চালু আছে সেটি ১৯ শয্যা বিশিষ্ট। এই ভবনটির নির্মাণ কাজ ২০১০ সালে সমাপ্ত হয়। এছাড়া এই ভবনটির পশ্চিম পার্শ্বে পুরাতন ৩১ শয্যা বিশিষ্ট ভবনের জায়গাতে একটি নতুন ভবন এর ফাউন্ডেশন এর কাজ আংশিক সমাপ্ত হয়ে দৈনন্দিন পড়ে রয়েছে।
6	paikgachha	Paikgacha Upazila Health Complex	1 xlsx	ok
7	phultala	Upazila Health Complex, Fultola, Khulna	No file	
8	rupsha	Upazila Health Complex, Rupsha, Khulna	No file	
9	terokhada	Upazila Health Complex, Terokhada, Khulna	No file	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	batiaghata	Batiaghata Upazila Health Complex	2015	HED	YES	50	No file	No file	No file	No file	8188	24564	No file	No file	7 jpegs, 1 mp4	DL 1.35 & HWL 2.97/1400	ok
2	dacope	Dacope Upazila Health Complex	1973	Other	YES	50	No file	No file	No file	No file	6300	25200	No file	No file	7 jpegs	DL 1.35 & HWL 2.97/1400	ok
3	dighalia	Upzila Health Complex (50 Bed), ,Bhabon-1,Digholia.		HED	Yes	31	1 dwg	No file	No file	No file			No file	No file	No file		
4	dighalia	Upzila Health Complex (50 Bed),Bhabon-2,Digholia.	2013	HED	Yes	19	No file	No file	No file	No file			No file	No file	No file		
5	dumuria	Dumuria Upazila Health Complex (NEW BUILDING)	2023	HED	YES	31	1 dwg, 1 pdf	No file	No file	1 pdf	8419.42	25258.26	1 pdf	No file	1 jpeg	HFL 99.6 (Plinth Level-100 ft)	ok
6	dumuria	Dumuria Upazila Health Complex (OLD BUILDING)	2014	HED	YES	19	1 dwg, 1 pdf	No file	No file	1 pdf	5953.51	17860.55	1 pdf	No file	2 jpegs	HFL 99.6 (Plinth Level-100 ft)	ok
7	koyra	Koyra Upazila Health Complex	2010	HED	Yes	19	1 dwg, 1 pdf	3 jpgs	1 dwg, 1 pdf	1 dwg, 1 pdf	6500	Total Floor Area-18000 sft (approx)	1 pdf	No file	5 jpgs	DL 1.35 & HWL 2.97/1400	

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
8	paikgachha	Paikgacha Upazila Health Complex (NEW BUILDING)	2015	HED	No	19	1 dwg, 1 pdf	No file	No file	1 pdf	7703	18955	1 pdf	No file	2 jpegs	HFL 96.968 (Plinth Level-100 ft)	ok
9	paikgachha	Paikgacha Upazila Health Complex (OLD BUILDING)	1997	HED	No	31	1 dwg, 1 pdf	No file	No file	1 pdf	14988	24536	1 pdf	No file	2 jpegs	HFL 96.968 (Plinth Level-100 ft)	ok
10	phultala	Upzila Health Complex (50 Bed), Phultola.		HED	No	50	1 pdf	No file	No file	No file			No file	No file	No file		
11	rupsha	Upazila Health complex , Rupsha		HED	No	50	1 jpeg	No file	No file	No file			No file	No file	No file		
12	terokhada	Upazila health complex(50 bed) terokhada		HED	Yes	50	1 jpeg	No file	No file	No file			No file	No file	No file		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	batiaghata	Batiaghata Upazila Health Complex	30	2	3	Footing	3	RCC	New Hospital Building of 50 Beds is constructed in 2015 which is 3-storied with 3-storied foundation. Old Hospital Building is constructed in 1976, which is used as administration building which is 2-storied. Condition of Old Building is very vulnerable.	No file	Not Possible		ok
2	dacope	Dacope Upazila Health Complex	10.25	2.5	4	Footing	4	RCC	OK	No file	Not Possible		
3	dighalia	Upzila Health Complex (50 Bed), Bhabon-2,Digholia.			3	Footing	4	RCC	Good	No file	Possible		
4	dighalia	Upzila Health Complex (50 Bed), Bhabon-1,Digholia.			2	Footing		RCC	Damaged abd Risky & dangerous to use	No file	Not Possible	no	
5	dumuria	Dumuria Upazila Health Complex (NEW BUILDING)	33	2	3	Footing	3	RCC	ok	No file	Not Possible	No Records	ok
6	dumuria	Dumuria Upazila Health Complex (OLD BUILDING)	33	2	3	Footing	3	RCC	ok	No file	Not Possible	Two years back	ok
7	koyra	Koyra Upazila Health Complex	32	3	3	Deep	5	RCC	The Building was built in 2010 by HED. It is a 3 storied building with 5 storied foundation.	No file	Possible		
8	paikgachha	Paikgacha Upazila Health Complex (NEW BUILDING)	30.48	1.83	3	Footing	3	RCC	New Hospital Building of 19 Beds is constructed in 2015 which is 3-storied with 3-storied foundation.	No file	Not Possible		
9	paikgachha	Paikgacha Upazila Health Complex (OLD BUILDING)	20.32	1.83	2	Footing	2	RCC	Old Hospital Building of 31 Beds is constructed in 1997, which has four blocks (2 Nos 1-storied and 2 Nos 2-storied). Condition of Old Hospital Building is very vulnerable.	No file	Not Possible		
10	phultala	Upzila Health Complex (50 Bed), Phultola.			2	Footing	2	RCC	Not good	No file	Not Possible		
11	terokhada	Upzila Health Complex (50 Bed), terokhada			2			RCC		No file			

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	batiaghata	Batiaghata Upazila Health Complex	0	1	No other water supply facility	Septic Tank	2550	No		Existing Drainage facility is not enough for drainage	Drainage facility is required	There is a local Canal (Khal) near the Hospital area	ok
2	dacope	Dacope Upazila Health Complex				Septic Tank	200	No					
3	dighalia	Upzila Health Complex (50 Bed), Digholia.	0	1		Septic Tank		No	0	poor drainage facilities			
4	dumuria	Dumuria Upazila Health Complex	0	5	No other water supply facility	Septic Tank	2550	Yes		Existing Drainage facility is not enough for drainage	Proper drainage facility is required	Upazila Master Drain is located 300 ft far from the Hospital boundary line	ok
5	koyra	Koyra Upazila Health Complex		1	Existing Pond	Septic Tank		No		Improper Drainage facilities	Need a planned drainage facility.	River	
6	paikgachha	Paikgacha Upazila Health Complex	0	2	No other water supply facility	Septic Tank	1700	No		Existing Drainage facility is not enough for drainage	Proper drainage facility is required	There is a local Canal (Khal) near the Hospital area	ok

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	batiaghata	Batiaghata Upazila Health Complex	0	2000	0	2000	14	Internal Road with is 10 ft	Yes	Yes	ok
2	dacope	Dacope Upazila Health Complex							No	Yes	
3	dighalia	Upzila Health Complex (50 Bed), Digholia.					13	Good		Yes	
4	dumuria	Dumuria Upazila Health Complex		1841		1000	18	12	Yes	Yes	ok
5	koyra	Koyra Upazila Health Complex		1800		300	13	The Internal road width - 14 ft and Pavement Type -rigid pavement	No	Yes	
6	paikgachha	Paikgacha Upazila Health Complex		1971	1000		12	8	No	Yes	ok

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional Info (Capacity, Demand etc)
1	batiaghata	Batiaghata Upazila health Complex	0	0	0	20	30	0	0	5.5	0	Centrifugal Pump System	Not Present	0
2	dacope	Daccop Upazila health Complex	0	0	0	20	30	0	0	0	10	Submersible Pump System	Not Present	0
3	dumuria	Dumuria Upazila health Complex	0	0	0	22	30	0	0	5.5	0	Centrifugal Pump System	Not Present	0

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional Info (Capacity, Demand etc)
4	koyra	Koyra Upazila Health Complex	0	0	N/A	24	40	N/A	Not Found	1	0	Demand: 02 nos centrifugal pump & 2 nos submersible pump. repair need: 01 nos submersible pump	Not Present	As per drawing and design
5	paikgachha	Paikgacha upazila health complex	0	0	NA	14	30	As per drawing and design	Not Found	3	0	As per drawing and design	Not Present	As per drawing and design

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	batiaghata	Batiaghata Upazila health Complex	REB	No	100	150	100	0	6	30	0	0	100 Meter, 50 Rm	100 Meter, 50 Rm	As per drawing and design
2	dacope	Daccop Upazila health Complex	REB	No	100	150	150	0	10	30	0	0	50	50	As per drawing and design
3	dumuria	Dumuria Upazila health Complex	REB	No	80	100	80	0	6	24	0	0	50 Meter, 50 Rm	50 Meter, 50 Rm	As per drawing and design
4	koyra	Koyra Upazila Health Complex	REB	Yes	150	200	50		0	100	0	0			As per drawing and design
5	paikgachha	Paikgachha upazila health complex	REB	Yes	300	0	0	0	0	300	0	0	70	70	As per drawing and design

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	batiaghata	Batiaghata Upazila health Complex	No	0	0	0	Yes	No	Yes	No	Yes	0	Medical Gas System, Compound & Security Light, PA/PABX System	As per drawing and design
2	dacope	Daccop Upazila health Complex	No	0	0	0	Yes	No	Yes	No	Yes	0	Medical Gas System, Compound & Security Light, PA/PABX System	As per drawing and design
3	dumuria	Dumuria Upazila health Complex	No	0	0	0	Yes	No	Yes	No	Yes	0	Medical Gas System, Compound & Security Light, PA/PABX System	As per drawing and design
4	koyra	Koyra upazila health complex	Yes	10	5	As per drawing and design.	Yes	Yes		Yes	Yes	1	As per drawing and design	As per drawing and design
5	paikgachha	Paikgachha upazila health complex	Yes	0	0	As per drawing and design.	Yes	No	Yes	Yes	Yes	1	As per drawing and design	As per drawing and design

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	dighalia	Upazila Health Complex,Digholia	Building No 1							No file	10 jpgs	
2	phultala	Upazila Health Complex,Fultola	Building No 1							No file	2 jpgs	

District Name: Kishoreganj

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	astagram	50 Bed Astagram Upazila Health Complex	1 xlsx	ok
2	astagram	50 Bed Astagram Upazilla Health Complex	1 xlsx	
3	bajitpur	Bajitpur upazilla health complex	1 xlsx	ok
4	bhairab	100 Bed Bhairab Upazilla Health Complex	1 xlsx	
5	hossainpur	50 Bed Hossainpur Upazilla Health Complex	1 xlsx	
6	itna	Itna upazilla health complex	1 xlsx	ok
7	karimganj	Karimganj upazilla health complex	1 xlsx	ok
8	katiadi	100 Bed Katiadi Upazilla Health Complex	1 xlsx	
9	kuliarchar	Kuliarchar upazilla health complex	1 xlsx	ok
10	mithamain	50 Bed Mithamain Upazilla Health Complex	1 xlsx	
11	mithamain	50 Bed Mithamoin Upazila Health Complex	1 xlsx	ok
12	nikli	Nikli upazilla health complex	1 xlsx	ok
13	pakundia	50 Bed Pakundia Upazilla Health Complex	1 xlsx	
14	tarail	Tarail upazilla health complex	1 xlsx	ok

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Avallability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	astagram	31 Bed Austagram Upazila Health Complex	1968	PWD	Yes	31	1 dwg	No file	1 pdf	No file	14500	12000	No file	No file	No file		ok
2	astagram	50 Bed Astagram upazilla health complex	1968	HED	Yes	50	1 dwg	1 pdf	8 jpegs, 1 pdf	1 dwg, 1 pdf	15840	15080	No file	No file	8 jpegs		
3	bajitpur	19 Bed Bajitpur upazilla health complex	2016	HED	Yes	19	1 pdf	No file	1 pdf	1 pdf	7500	7300	1 pdf	No file	6 jpegs		ok
4	bajitpur	31 Bed Bajitpur upazilla health complex	1964	Other	Yes	31	1 pdf	No file	1 pdf	1 pdf	7500	4500	1 pdf	No file	7 jpegs, 1 mp4		ok
5	bhairab	50 Bed Bhairab Upazilla Health Complex	1965	PWD	yes	50	1 dwg	No file	No file	No file	20052	19750	No file	No file	No file		
6	bhairab	100 Bed Bhairab Upazilla Health Complex	2024	HED	yes	100	1 dwg	No file	No file	No file	50750	50750	No file	No file	No file		
7	hossainpur	19 Bed Hossainpur upazilla health complex	2010	HED	Yes	19	1 dwg, 1 pdf	No file	1 pdf	1 dwg, 2 pdfs	8500	7300	No file	No file	7 jpegs		ok

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
8	hossainpur	31 Bed Hossainpur upazilla health complex	1965	PWD	Yes	31	1 dwg, 1 pdf	No file	1 pdf	No file	8500	7300	No file	No file	7 jpegs		ok
9	itna	19 Bed Itna upazilla health complex	2010	HED	Yes	19	No file	No file	1 pdf	No file	7500	7300	No file	No file	4 jpegs		ok
10	itna	31 Bed Itna upazilla health complex	1965	PWD	Yes	31	No file	No file	1 pdf	No file	5052	5052	No file	No file	8 jpegs, 1 mp4		ok
11	karimganj	19 Bed Karimganj upazilla health complex	2010	HED	Yes	19	1 dwg	No file	1 pdf	No file	8500	7300	No file	No file	2 jpegs		
12	karimganj	31 Bed Karimganj upazilla health complex	1965	PWD	NO	31	1 dwg	No file	1 pdf	No file	8500	8052	No file	No file	5 jpegs		ok
13	katiadi	50 Bed Katiadi Upazilla Health Complex	1965	PWD	yes	50	1 dwg	No file	No file	No file	20052	19750	No file	No file	2 jpegs		
14	katiadi	100 Bed Katiadi Upazilla Health Complex	2024	HED	yes	100	1 dwg	No file	No file	No file	50750	50750	No file	No file	3 jpegs		
15	kuliarchar	19 Bed Kuliarchar upazilla health complex	2010	HED	Yes	19	1 pdf	No file	1 pdf	1 pdf	5500	4500	No file	No file	No file		ok
16	kuliarchar	31 Bed Kuliarchar upazilla health complex	1984	PWD	Yes	31	1 pdf	No file	1 pdf	1 pdf	8052	8052	No file	No file	7 jpegs, 1 mp4		ok
17	mithamain	31 Bed Mithamoin Upazila Health Complex	1968	PWD	Yes	31	1 dwg	No file	1 pdf	No file	14520	12500	No file	No file	No file		ok
18	mithamain	50 Bed Mithamoin upazilla health complex	1968	HED	Yes	50	1 dwg	1 pdf	2 pdfs	1 dwg, 1 pdf	16650	16150	1 pdf	No file	9 jpegs		
19	nikli	19 Bed Nikli upazilla health complex	2010	HED	Yes	19	1 pdf	No file	1 pdf	1 pdf	8500	7300	No file	No file	5 jpegs, 1 mp4		ok
20	nikli	31 Bed Nikli upazilla health complex		PWD	Yes	31	1 pdf	No file	1 pdf	1 pdf	8500	7300	No file	No file	5 jpegs, 1 mp4		ok
21	pakundia	19 Bed Pakundia upazilla health complex	2010	HED	Yes	19	1 dwg, 1 pdf	No file	1 pdf	1 dwg, 1 pdf	8500	7300	No file	No file	6 jpegs		
22	pakundia	31 Bed Pakundia upazilla health complex	1965	PWD	Yes	31	1 dwg, 1 pdf	No file	1 pdf	No file	8500	7300	No file	No file	6 jpegs		ok

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
23	tarail	19 Bed Tarail upazilla health complex	2010	HED	Yes	19	1 pdf	No file	1 pdf	1 pdf	8500	7300	No file	No file	No file		
24	tarail	31 Bed Tarail upazilla health complex	1965	PWD	Yes	31	1 pdf	No file	1 pdf	No file	8500	7300	No file	No file	No file		ok

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	astagram	19 Bed Astagram upazilla health complex	37	2	3	Footing	3	RCC		No file	Not Possible	NA	ok
2	astagram	31 Bed Austagram Upazila Health Complex	27	2	2	Footing	2	RCC		No file	Not Possible	NA	ok
3	bajitpur	19 Bed Bajitpur upazilla health complex	41	2	3	Footing	3	RCC	good	No file	Not Possible	NA	ok
4	bajitpur	31 Bed Bajitpur upazilla health complex	27	1	2	Footing	2	Load Bearing Brick	"There are cracks and damp plaster in several places of the building."	No file	Not Possible	NA	ok
5	bhairab	50 Bed Bhairab Upazilla Health Complex	51	2	4	Footing	4	RCC	Not Good	No file	Not Possible	NA	
6	bhairab	100 Bed Bhairab Upazilla Health Complex	87	2.5	7	Deep	7	RCC	Good	No file	Not Possible	NA	
7	hossainpur	19 Bed Hossainpur upazilla health complex	37	2	3	Footing	3	RCC	"There are damp plaster in several places of the building."	No file	Not Possible	NA	ok
8	hossainpur	31 Bed Hossainpur upazilla health complex	27	1	2	Footing	2	RCC	"There are cracks and damp plaster in several places of the building."	No file	Not Possible	NA	ok
9	itna	19 Bed Itna upazilla health complex	37	2	3	Footing	3	RCC	"There are damp plaster in several places of the building."	No file	Not Possible	NA	ok
10	itna	31 Bed Itna upazilla health complex	27	1	2	Footing	2	RCC	"There are cracks and damp plaster in several places of the building."	No file	Not Possible	NA	ok
11	karimganj	19 Bed Karimganj upazilla health complex	37	2	3	Footing	3	RCC	"There are damp plaster in several places of the building."	No file	Not Possible	NA	ok
12	karimganj	31 Bed Karimganj upazilla health complex	27	1	2	Footing	2	RCC	"There are cracks and damp plaster in several places of the building."	No file	Not Possible	NA	
13	katiadi	50 Bed Katiadi Upazilla Health Complex	51	2	4	Footing	4	RCC	Not Good	No file	Not Possible	NA	
14	katiadi	100 Bed Katiadi Upazilla Health Complex	87	2.5	7	Deep	7	RCC	Good	No file	Not Possible	NA	
15	kuliarchar	19 Bed Kuliarchar upazilla health complex	37	2	3	Footing	3	RCC	"There are damp plaster in several places of the building."	No file	Not Possible	NA	ok
16	kuliarchar	31 Bed Kuliarchar upazilla health complex	27	1	2	Footing	2	Load Bearing Brick	"There are cracks and damp plaster in several places of the building."	No file	Not Possible	NA	ok

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
17	mithamain	19 Bed Mithamoin upazilla health complex	37	2	3	Footing	3	RCC		No file	Not Possible	NA	
18	mithamain	31 Bed Mithamoin Upazila Health Complex	27	2	2	Footing	2	RCC		No file	Not Possible	NA	
19	nikli	19 Bed Nikli upazilla health complex	37	2	3	Footing	3	RCC	"There are damp plaster in several places of the building."	No file	Not Possible	NA	ok
20	nikli	31 Bed Nikli upazilla health complex	27	1	2	Footing	2	RCC	"There are cracks and damp plaster in several places of the building."	No file	Not Possible	NA	ok
21	pakundia	19 Bed Pakundia upazilla health complex	37	2	3	Footing	3	RCC	"There are damp plaster in several places of the building."	No file	Not Possible	NA	ok
22	pakundia	31 Bed pakundia upazilla health complex	27	1	2	Footing	2	RCC	"There are cracks and damp plaster in several places of the building."	No file	Not Possible	NA	
23	tarail	19 Bed Tarail upazilla health complex	37	2	3	Footing	3	RCC	"There are damp plaster in several places of the building."	No file	Not Possible	NA	ok
24	tarail	31 Bed Tarail upazilla health complex	13	1	1	Footing	1	Load Bearing Brick	"There are cracks and damp plaster in several places of the building."	No file	Not Possible	NA	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	astagram	Austagram Upazila Health Complex	0	1		Septic Tank		No					
2	bajitpur	19 Bed Bajitpur upazilla health complex		1		Septic Tank	200	No		Not Good	Proper drainage system must be ensured.	Municipal Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system
3	bajitpur	31 Bed Bajitpur upazilla health complex	0	1	Municipal Water Supply	Septic Tank	200	No	0	Not Good	Proper drainage system must be ensured.	Municipal Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system
4	bhairab	31 Bed Bhairab Upazilla Health Complex		2	Municipal Water Supply System	Septic Tank	400	No		Not Good	Proper drainage system must be ensured	Garbage Dumping Area	
5	hossainpur	19 Bed Hossainpur upazilla health complex		1	Municipal Water Supply	Septic Tank	200	No		Not Good	Proper drainage system must be ensured.	District Municipal Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system
6	hossainpur	31 Bed Hossainpur upazilla health complex	0	1	Municipal Water Supply	Septic Tank	200	No	0	Not Good	Proper drainage system must be ensured.	District Municipal Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system
7	itna	19 Bed Itna upazilla health complex		1	NA	Septic Tank	200	No	0	Not Good	Proper drainage system must be ensured.	Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system
8	itna	31 Bed Itna upazilla health complex	0	1	NA	Septic Tank	200	No	0	Not Good	Proper drainage system must be ensured.	Local Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system
9	karimganj	19 Bed Karimganj upazilla health complex		1		Septic Tank	200	No		Not Good	Proper drainage system must be ensured.	Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
10	karimganj	31 Bed Karimganj upazilla health complex	0	1		Septic Tank	200	No	0	Not Good	Proper drainage system must be ensured.	Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system
11	katiadi	31 Bed Katiadi Upazilla Health Complex		2	Municipal Water Supply System	Septic Tank	400	No		Not Good	Proper drainage system must be ensured	Garbage Dumping Area	
12	kuliarchar	19 Bed Kuliarchar upazilla health complex		1	NA	Septic Tank	200	No		Not Good	Proper drainage system must be ensured.	Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system
13	kuliarchar	31 Bed Kuliarchar upazilla health complex	0	1	NA	Septic Tank	200	No	0	Not Good	Proper drainage system must be ensured.	Municipal Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system
14	mithamain	Mithamoin Upazila Health Complex	0	1		Septic Tank		No					
15	nikli	19 Bed Nikli upazilla health complex		1	NA	Septic Tank	200	No		Not Good	Proper drainage system must be ensured.	Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system
16	nikli	31 Bed Nikli upazilla health complex	0	1	NA	Septic Tank	200	No	0	Not Good	Proper drainage system must be ensured.	Local Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system
17	pakundia	19 Bed Pakundia upazilla health complex		1	Municipal Water Supply	Septic Tank	200	No		Not Good	Proper drainage system must be ensured.	District Municipal Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system
18	pakundia	31 Bed Pakundia upazilla health complex	0	1	Municipal Water Supply	Septic Tank	200	No	0	Not Good	Proper drainage system must be ensured.	District Municipal Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system
19	tarail	19 Bed Tarail upazilla health complex		1		Septic Tank	200	No		Not Good	Proper drainage system must be ensured.	Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system
20	tarail	31 Bed Tarail upazilla health complex	0	1		Septic Tank	200	No	0	Not Good	Proper drainage system must be ensured.	Garbage Dumping Area	Need Minimum 900 ft depth Deeptubewell and other supply distribution system

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	astagram	Austagram Upazila Health Complex	1800	1000			12	Not Good	Yes	Yes	
2	bajitpur	Bajitpur upazilla health complex	0	1920	0	1200	12	Not Good	Yes	Yes	ok
3	bhairab	31 Bed Bhairab Upazilla Health Complex		2300		1800	30	Not Good	Yes	Yes	
4	hossainpur	Hossainpur upazilla health complex	0	2300	0	2000	40	Good	Yes	Yes	
5	itna	Itna upazilla health complex	0	1200	0	2000	16	Not Good	No	Yes	
6	karimganj	Karimganj upazilla health complex	0	2100	0		20	Not Good	Yes	Yes	
7	katiadi	31 Bed Katiadi Upazilla Health		2300		1900	30	Not Good	Yes	Yes	

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
		Complex									
8	kuliarchar	Kuliarchar upazilla health complex	0	2400	0	2000	12	Not Good	Yes	Yes	
9	mithamain	Mithamoin Upazila Health Complex	1600	600			12	Not Good	Yes	Yes	
10	nikli	Nikli upazilla health complex	0	1800	0	2000	12	Not Good	Yes	Yes	
11	pakundia	pakundia upazilla health complex	0	2600	0	2000	40	Not Good	Yes	Yes	
12	tarail	Tarail upazilla health complex	0	2300	0		30	Not Good	No	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional Info (Capacity, Demand etc)
1	astagram	50 beded Upazilla Health Complex Austagram	0	0	1 no Passenger & 1 no Bed Lift Need	4	30	OT, X ray , ECG & Other Places Ac Need As per Design. HVAC System Need	Have Some Fire Extinguisher But Expired.Need Fire Safety Automation System	5.5	3	Submersible & Centrifugal Pump Capacity Need Increse	Not Present	Must be need (Incinerator ,WTP & STP)
2	bajitpur	50 beded Upazilla Health Complex Bajitpur	0	0	1 no Passenger & 1 no Bed Lift Need	6	30	OT, X ray , ECG & Other Places Ac Need As per Design. HVAC System Need	Have Some Fire Extinguisher But Expired.Need Fire Safety Automation System	5.5	3	Submersible & Centrifugal Pump Capacity Need Increse	Not Present	Must be need (Incinerator ,WTP & STP)
3	bhairab	100 beded Upazilla Health Complex Bhairab	0	0	1 no Passenger & 1 no Bed Lift Need	10	30	OT, X ray , ECG & Other Places Ac Need As per Design. HVAC System Need	Have Some Fire Extinguisher But Expired.Need Fire Safety Automation System	7.5	5	Submersible & Centrifugal Pump Capacity Need Increse	Not Present	Must be need (Incinerator ,WTP & STP)
4	hossainpur	50 beded Upazilla Health Complex Hossenpur	0	0	1 no Passenger & 1 no Bed Lift Need	10	30	OT, X ray , ECG & Other Places Ac Need As per Design. HVAC System Need	Have Some Fire Extinguisher But Expired.Need Fire Safety Automation System	5.5	3	Submersible & Centrifugal Pump Capacity Need Increse	Not Present	Must be need (Incinerator ,WTP & STP)
5	itna	50 beded Upazilla Health Complex Itna	0	0	1 no Passenger & 1 no Bed Lift Need	4	30	OT, X ray , ECG & Other Places Ac Need As per Design. HVAC System Need	Have Some Fire Extinguisher But Expired.Need Fire Safety Automation System	5.5	3	Submersible & Centrifugal Pump Capacity Need Increse	Not Present	Must be need (Incinerator ,WTP & STP)
6	karimganj	50 beded Upazilla Health Complex Karimganj	0	0	1 no Passenger & 1 no Bed Lift Need	6	30	OT, X ray , ECG & Other Places Ac Need As per Design. HVAC System Need	Have Some Fire Extinguisher But Expired.Need Fire Safety Automation System	5.5	3	Submersible & Centrifugal Pump Capacity Need Increse	Not Present	Must be need (Incinerator ,WTP & STP)
7	katiadi	100 beded Upazilla Health Complex Katiadi	0	0	1 no Passenger & 1 no Bed Lift Need	10	30	OT, X ray , ECG & Other Places Ac Need As per Design. HVAC System Need	Have Some Fire Extinguisher But Expired.Need Fire Safety Automation System	7.5	5	Submersible & Centrifugal Pump Capacity Need Incresee	Not Present	Must be need (Incinerator ,WTP & STP)
8	kuliarchar	50 beded Upazilla Health Complex Kuliarchar	0	0	1 no Passenger & 1 no Bed Lift Need	4	30	OT, X ray , ECG & Other Places Ac Need As per Design. HVAC System Need	Have Some Fire Extinguisher But Expired.Need Fire Safety Automation System	5.5	3	Submersible & Centrifugal Pump Capacity Need Increse	Not Present	Must be need (Incinerator ,WTP & STP)
9	mithamain	50 beded Upazilla Health Complex Mithamoin	0	0	1 no Passenger & 1 no Bed Lift Need	6	30	OT, X ray , ECG & Other Places Ac Need As per Design. HVAC System Need	Have Some Fire Extinguisher But Expired.Need Fire Safety Automation System	5.5	3	Submersible & Centrifugal Pump Capacity Need Increse	Not Present	Must be need (Incinerator ,WTP & STP)

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
10	nikli	50 beded Upazilla Health Complex Nikli	0	0	1 no Passenger & 1 no Bed Lift Need	4	30	OT, X ray , ECG & Other Places Ac Need As per Design. HVAC System Need	Have Some Fire Extinguisher But Expired. Need Fire Safety Automation	5.5	3	Submersible & Centrifugal Pump Capacity Need Increase	Not Present	Must be need (Incinerator ,WTP & STP)
11	pakundia	50 beded Upazilla Health Complex Pakundia	0	0	1 no Passenger & 1 no Bed Lift Need	8	30	OT, X ray , ECG & Other Places Ac Need As per Design. HVAC System Need	Have Some Fire Extinguisher But Expired.Need Fire Safety Automation System	5.5	3	Submersible & Centrifugal Pump Capacity Need Increase	Not Present	Must be need (Incinerator ,WTP & STP)
12	tarail	50 beded Upazilla Health Complex Tarail	0	0	1 no Passenger & 1 no Bed Lift Need	4	30	OT, X ray , ECG & Other Places Ac Need As per Design. HVAC System Need	Have Some Fire Extinguisher But Expired.Need Fire Safety Automation System	5.5	3	Submersible & Centrifugal Pump Capacity Need Increase	Not Present	Must be need (Incinerator ,WTP & STP)

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (KVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	astagram	50 beded Upazilla Health Complex Astagram	REB	No	50	0	0	Not Present (Pole Mounted 75 KVA transformer Installon H pole)	0	100	0	0	LT Service Cable 4*50 Rm NYY, Length 95 mtr Approximate	4*25 Rm NYY Service Cable ,Length 150 mtr Approximate	Sub-Station Capacity need 500 KVA For Present & Future Load, Instead of Generator Roof Top Hybrided Solar Energy Can be Install, If Solar System Install Gegerator Will 50 KVA For OT & Other related Important Places
2	bajitpur	50 beded Upazilla Health Complex Bajitpur	PDB	No	60	0	0	Sub- Station Components Not Present (HT cable, LT Panel, HT Panel) Only Pole Mounting Transformer exit on H pole	0	100	0	0	LT Service Cable 4*50 Rm NYY, Length 95 mtr Approximate	4*25 & 4* 10 Rm NYY Service Cable ,Length 130 mtr Approximate	Sub-Station Capacity need increse to 500 KVA For Present & Future Load, Roof Top Hybrided Solar System Can be Install For Emergency Load. If Solar System Install Generator Will be 30 KVA For OT & Other Important Place.
3	bhairab	100 beded Upazilla Health Complex Bhairab	PDB	Yes	160	315	155	HT cable, LT Panel, HT Panel, MDB & EMDB	100	0	0	3	3C*95 Rm HT Cable, Approximate 85 mtr Length	4* 50 Rm NYY ,Approximate 100 mtr Length	Sub-Station Capacity need 500 KVA For Present & Future Load, Instead of Generator Roof Top Hybrided Solar Energy Can be Install, If Solar System Install Gegerator Will 50 KVA For OT & Other related Important Places
4	hossainpur	50 beded Upazilla Health Complex Hossainpur	REB	Yes	60	0	0	Not Present (Pole Mounted 75 KVA transformer Install on H pole)	0	100	0	0	LT Service Cable 4*50 Rm NYY, Length 90 mtr Approximate	4*25 NYY & 4*10 NYY Rm Service Cable ,Length 180 mtr Approximate	Sub-Station Capacity need increse to 500 KVA For Present & Future Load, Roof Top Hybrided Solar System Can be Install For Emergency Load. If Solar System Install Generator Will be 30 KVA For OT & Other Important Place.
5	itna	50 beded Upazilla Health Complex Itna	REB	No	50	0	0	Not Present (Pole Mounted 75 KVA transformer Installon H pole)	0	100	0	0	LT Service Cable 4*50 Rm NYY, Length 50 mtr Approximate	4*25 & 4* 10 Rm NYY Service Cable ,Length 90 mtr Approximate	Sub-Station Capacity need 500 KVA For Present & Future Load, Instead of Generator Roof Top Hybrided Solar Energy Can be Install, If Solar System Install Gegerator Will 50 KVA For OT & Other related Important Places
6	karimganj	50 beded Upazilla Health	REB	Yes	60	0	0	Not Present (Pole Mounted 75 KVA	0	100	0	0	LT Service Cable 4*50 Rm NYY,	4*25 & 4* 10 Rm NYY Service Cable	Sub-Station Capacity need 500 KVA For Present & Future Load, Instead of Generator Roof Top

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
		Complex Karimganj						transformer Install on H pole)					Length 90 mtr Approximate	,Length 155 mtr Approximate	Hybrid Solar Energy Can be Install, If Solar System Install Gegerator Will 50 KVA For OT & Other related Important Places
7	katiadi	100 beded Upazilla Health Complex Katiadi	PDB	Yes	150	315	160	HT cable, LT Panel, HT Panel, MDB & EMDB	100	0	0	2	3C*95 Rm HT Cable, Approximate 110 mtr Length	4* 50 Rm NYY ,Approximate 140 mtr Length	Sub-Station Capacity need 500 KVA For Present & Future Load, Instead of Generator Roof Top Hybrid Solar Energy Can be Install, If Solar System Install Gegerator Will 50 KVA For OT & Other related Important Places
8	kuliarchar	50 beded Upazilla Health Complex Kuliarchar	REB	No	60	0	0	Not Present (Pole Mounted 75 KVA transformer on H pole)	0	100	0	0	LT Service Cable 4*50 Rm NYY, Length 75 mtr Approximate	4*25 & 4* 10 Rm NYY Service Cable ,Length 190 mtr Approximate	Sub-Station Capacity need increse to 500 KVA For Present & Future Load, Roof Top Hybrid Solar System Can be Install For Emergency Load. If Solar System Install Generator Will be 30 KVA For OT & Other Important Place.
9	mithamain	50 beded Upazilla Health Complex Mithamoin	REB	No	60	0	0	Sub- Station Components Not Present (HT cable, LT Panel, HT Panel) Only Pole Mounting Transformer exit on H pole	0	100	0	0	LT Service Cable 4*50 Rm NYY, Length 105 mtr Approximate	4*25 & 4* 10 Rm NYY Service Cable ,Length 140 mtr Approximate	Sub-Station Capacity need increse to 500 KVA For Present & Future Load, Roof Top Hybrid Solar System Can be Install For Emergency Load. If Solar System Install Generator Will be 30 KVA For OT & Other Important Place.
10	nikli	50 beded Upazilla Health Complex Nikli	REB	No	60	0	0	Sub- Station Components Not Present (HT cable, LT Panel, HT Panel) Only Pole Mounting Transformer exit on H pole	0	100	0	0	LT Service Cable 4*50 Rm NYY, Length 70 mtr Approximate	4*25 & 4* 10 Rm NYY Service Cable ,Length 150 mtr Approximate	Sub-Station Capacity need 500 KVA For Present & Future Load, Instead of Generator Roof Top Hybrid Solar Energy Can be Install, If Solar System Install Gegerator Will 50 KVA For OT & Other related Important Places
11	pakundia	50 beded Upazilla Health Complex Pakundia	REB	Yes	60	0	0	Not Present (Pole Mounted 75 KVA transformer Install on H pole)	0	100	0	0	LT Service Cable 4*50 Rm NYY, Length 80 mtr Approximate	4*25 & 4* 10 Rm NYY Service Cable ,Length 160 mtr Approximate	Sub-Station Capacity need increse to 500 KVA For Present & Future Load, Roof Top Hybrid Solar System Can be Install For Emergency Load. If Solar System Install Generator Will be 30 KVA For OT & Other Important Place.
12	tarail	50 beded Upazilla Health Complex Tarail	REB	No	60	0	0	Not Present (Pole Mounted 75 KVA transformer Install on H pole)	0	100	0	0	LT Service Cable 4*50 Rm NYY, Length 120 mtr Approximate	4*25 & 4* 10 Rm NYY Service Cable ,Length 190 mtr Approximate	Sub-Station Capacity need increse to 500 KVA For Present & Future Load, Roof Top Hybrid Solar System Can be Install For Emergency Load. If Solar System Install Generator Will be 30 KVA For OT & Other Important Place.

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	astagram	50 beded Upazilla Health Complex Astragram	No	0	0	only Have Some Oxygen Syllinder . Mordern Central Medical Gas Facility Need For All Bed.	Yes	No	No	No	No	0	Existing Compound & Security Light, CCTV System are Partial Need More, Wifi System partial, PABX System Need.	Pure Drinking Water , Automated Laundry System, Central PA Sound , Remote Monitoring System & BMS Facilities Need.

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
2	bajitpur	50 beded Upazilla Health Complex Bajitpur	No	0	0	only Have Some Oxygen Syllinder . Mordern Central Medical Gas Facility Need For All Bed.	Yes	No	No	No	Yes	1	Existing Compound & Security Light, CCTV System are Partial Need More, Wifi System partial, PABX System Need.	Pure Drinking Water , Automated Laundry System, Central PA Sound , Remote Monitoring System & BMS Facilities Need.
3	bhairab	100 beded Upazilla Health Complex Bhairab	No	0	0	only Have Some Oxygen Syllinder . Mordern Central Medical Gas Facility Need For All Bed.	Yes	No	No	No	Yes	2	Existing Compound & Security Light, CCTV System are Partial Need More, Wifi System partial, PABX System Need.	Pure Drinking Water , Automated Laundry System, Central PA Sound , Remote Monitoring System & BMS Facilities Need.
4	hossainpur	50 beded Upazilla Health Complex Hossainpur	No	0	0	only Have Some Oxygen Syllinder . Mordern Central Medical Gas Facility Need For All Bed.	Yes	Yes	No	No	Yes	0	Existing Compound & Security Light are Partial Need More, Wifi System partial, PABX System Need	Pure Drinking Water , Automated Laundry System, Central PA Sound , Remote Monitoring System & BMS Facilities Need.
5	itna	50 beded Upazilla Health Complex Itna	No	0	0	only Have Some Oxygen Syllinder . Mordern Central Medical Gas Facility Need For All Bed.	Yes	No	No	No	Yes	0	Existing Compound & Security Light, CCTV System are Partial Need More, Wifi System partial, PABX System Need.	Pure Drinking Water , Automated Laundry System, Central PA Sound , Remote Monitoring System & BMS Facilities Need.
6	karimganj	50 beded Upazilla Health Complex Karimganj	No	0	0	only Have Some Oxygen Syllinder . Mordern Central Medical Gas Facility Need For All Bed.	Yes	No	No	No	Yes	0	Existing Compound & Security Light, CCTV System are Partial Need More, Wifi System partial, PABX System Need.	Pure Drinking Water , Automated Laundry System, Central PA Sound , Remote Monitoring System & BMS Facilities Need.
7	katiadi	100 beded Upazilla Health Complex Katiadi	No	0	0	only Have Some Oxygen Syllinder . Mordern Central Medical Gas Facility Need For All Bed.	Yes	No	No	No	Yes	2	Existing Compound & Security Light, CCTV System are Partial Need More, Wifi System partial, PABX System Need.	Pure Drinking Water , Automated Laundry System, Central PA Sound , Remote Monitoring System & BMS Facilities Need.
8	kuliarchar	50 beded Upazilla Health Complex Kuliarchar	No	0	0	only Have Some Oxygen Syllinder . Mordern Central Medical Gas Facility Need For All Bed.	Yes	No	No	No	Yes	0	Existing Compound & Security Light, CCTV System are Partial Need More, Wifi System partial, PABX System Need.	Pure Drinking Water , Automated Laundry System, Central PA Sound , Remote Monitoring System & BMS Facilities Need.
9	mithamain	50 beded Upazilla Health Complex Mithamoin	No	0	0	only Have Some Oxygen Syllinder . Mordern Central Medical Gas Facility Need For All Bed.	Yes	No	No	No	Yes	0	Existing Compound & Security Light, CCTV System are Partial Need More, Wifi System partial, PABX System Need.	Pure Drinking Water , Automated Laundry System, Central PA Sound , Remote Monitoring System & BMS Facilities Need.
10	nikli	50 beded Upazilla Health Complex Nikli	No	0	0	only Have Some Oxygen Syllinder . Mordern Central Medical Gas Facility Need For All Bed.	Yes	No	No	No	Yes	0	Existing Compound & Security Light, CCTV System are Partial Need More, Wifi System partial, PABX System Need.	Pure Drinking Water , Automated Laundry System, Central PA Sound , Remote Monitoring System & BMS Facilities Need.
11	pakundia	50 beded Upazilla Health Complex Pakundia	No	0	0	only Have Some Oxygen Syllinder . Mordern Central Medical Gas Facility Need For All Bed.	Yes	No	No	No	Yes	0	Existing Compound & Security Light, CCTV System are Partial Need More, Wifi System partial, PABX System Need.	Pure Drinking Water , Automated Laundry System, Central PA Sound , Remote Monitoring System & BMS Facilities Need.
12	tarail	50 beded Upazilla Health Complex Tarail	No	0	0	only Have Some Oxygen Syllinder . Mordern Central Medical Gas Facility Need For All Bed.	Yes	No	No	No	Yes	1	Existing Compound & Security Light, CCTV System are Partial Need More, Wifi System partial, PABX System Need.	Pure Drinking Water , Automated Laundry System, Central PA Sound , Remote Monitoring System & BMS Facilities Need.

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	astagram	50 Bed Astagram Upazilla Health Complex	Doctors Quarter	2	1968	1	1200	1000		No file	No file	
2	bajitpur	Bajitpur upazilla health complex	Garrage	1	1964	1	120	120	"There are cracks and damp plaster in several places of the building."	No file	No file	NA

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
3	bajitpur	Bajitpur upazilla health complex	Staff Quarter (Old)	1	1964	1	2700	2700	"There are cracks and damp plaster in several places of the building."	No file	No file	NA
4	bajitpur	Bajitpur upazilla health complex	Nurse Quarter (Old)	2	1964	1	1400	2800	"There are cracks and damp plaster in several places of the building."	No file	No file	NA
5	bajitpur	Bajitpur upazilla health complex	Nurse Quarter (New)	1	2016	2	1000	2000	Good	No file	No file	NA
6	bajitpur	Bajitpur upazilla health complex	Doctor Quarter	1	1964	2	3000	4500	"There are cracks and damp plaster in several places of the building."	No file	No file	NA
7	bajitpur	Bajitpur upazilla health complex	RMO Quarter	1	1964	1	1800	1800	"There are cracks and damp plaster in several places of the building."	No file	No file	NA
8	bajitpur	Bajitpur upazilla health complex	UHFPO Quarter	1	1964	1	1800	1800	"There are cracks and damp plaster in several places of the building."	No file	No file	NA
9	itna	Itna upazilla health complex	Garrage	1	1965	1	600	600	Small.	No file	No file	NA
10	itna	Itna upazilla health complex	Nurses Dormitory	1	1965	1	800	800	"There are cracks and damp plaster in several places of the building."	No file	No file	NA
11	itna	Itna upazilla health complex	UHFPO Quarter	1	1965	1	1600	2400	"There are cracks and damp plaster in several places of the building."	No file	No file	NA
12	kuliarchar	Kuliarchar upazilla health complex	Staff Quarter	2	1965	2	1600	2400	"There are cracks and damp plaster in several places of the building."	No file	No file	
13	kuliarchar	Kuliarchar upazilla health complex	Garrage	1	1965	1	600	600	Small.	No file	No file	
14	kuliarchar	Kuliarchar upazilla health complex	Nurses Dormitory	1	1965	2	1600	2400	"There are cracks and damp plaster in several places of the building."	No file	No file	
15	kuliarchar	Kuliarchar upazilla health complex	Doctors Quarter	2	1965	2	1600	2400	"There are cracks and damp plaster in several places of the building."	No file	No file	
16	mithamain	50 Bed Mithamoin Upazila Health Complex	Nurses Dormitory	1	1965	3	1600	2400		No file	No file	
17	mithamain	50 Bed Mithamoin Upazila Health Complex	Staff Quarter (Old)	3	1968	1	1600	1200		No file	No file	
18	mithamain	50 Bed Mithamoin Upazila Health Complex	Doctors Quarter	1	1968	3	1600	2400		No file	No file	
19	nikli	Kuliarchar upazilla health complex	Staff Quarter	2	1965	2	1600	2400	"There are cracks and damp plaster in several places of the building."	No file	No file	
20	nikli	Kuliarchar upazilla health complex	Garrage	1	1965	1	600	600	Small.	No file	No file	
21	nikli	Kuliarchar upazilla health complex	Nurses Dormitory	1	1965	2	1600	2400	"There are cracks and damp plaster in several places of the building."	No file	No file	
22	nikli	Kuliarchar upazilla health complex	Doctors Quarter	2	1965	2	1600	2400	"There are cracks and damp plaster in several places of the building."	No file	No file	

District Name: Kurigram

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	bhurungamari	Upazila Health Complex, Bhurungamari, Kurigram	1 xlsx	ok
2	char_rajibpur	Upazila Health Complex, Char Rajibpur, Kurigram	1 xlsx	ok
3	chilmari	Upazila Health Complex, Chilmari, Kurigram	1 xlsx	ok
4	nageshwari	Upazila Health Complex, Nageshwari, Kurigram	1 xlsx	ok
5	phulbari	Upazila Health Complex, Phulbari, Kurigram	1 xlsx	Ok
6	rajarhat	Upazila Health Complex, Rajarhat, Kurigram	1 xlsx	ok
7	raumari	Upazila Health Complex, Roumari, Kurigram	No file	ok
8	ulipur	Upazila Health Complex, Ulipur, Kurigram	1 xlsx	ok

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	bhurungamari	Upazila Health Complex, Bhurungamari, Kurigram	1980	PWD	Yes	50	1 dwg	No file	No file	No file	2000	2200	No file	1 jpg	5 jpgs	1.5 feet	
2	chilmari	Upazila Health Complex, Chilmari, Kurigram	1968	PWD		50	1 dwg	No file	No file	No file			No file	No file	No file	4 feet	
3	nageshwari	Upazila Health Complex, Nageshwari, Kurigram	1984	HED	yes	50	1 dwg	No file	No file	No file			No file	No file	No file	1 feet	
4	phulbari	Upazila Health Complex, Phulbari, Kurigram	1985	HED	Yes	50	1 dwg	No file	No file	No file	3240	3240	No file	2 jpegs	4 jpegs	No	
5	rajarhat	Rajarhat Upazila Health Complex, Rajarhat, Kurigram	1980	PWD	Yes	50	1 dwg	No file	No file	No file	3000	3200	No file	1 pdf	5 jpgs	1.5 feet	
6	ulipur	Upazila Health Complex, Ulipur, Kurigram	1968	PWD		50	No file	No file	No file	No file			No file	No file	No file	2 feet	

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	bhurungamari	Upazila Health Complex, Bhurungamari, Kurigram2	23	2	2	Footing	2	Load Bearing Brick	not good	No file	Not Possible	minor repair	
2	char_rajibpur	Upazila Health Complex, Char Rajibpur, Kurigram	35	2.49	3	Footing	3	RCC	Old RCC Buliding	No file	Not Possible	Minor renovation is occurred	

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
3	nageshwari	Upazila Health Complex, Nageshwari, Kurigram	25	3	2	Footing	2	Load Bearing Brick	not good	No file	Not Possible	minor repair	"Although the hospital has an approved capacity of 50 beds, the current number of patients is three to four times higher than its capacity. Therefore, to ensure quality healthcare services for patients, it is highly necessary to urgently increase the hospital's bed capacity and infrastructural facilities."
4	phulbari	Upazila Health Complex, Phulbari, Kurigram	25	2	2	Footing	2	Load Bearing Brick	not good	No file	Not Possible	minor repair	
5	rajarhat	Rajarhat Upazila Health Complex, Rajarhat, Kurigram	23	2	2	Footing	2	Load Bearing Brick	not good	No file	Not Possible	minor repair	
6	raumari	Upazila Health Complex, Roumari, Kurigram	25	2.5	2	Footing	2	RCC	Old RCC Building	No file	Not Possible	Minor renovation is occurred	
7	ulipur	50-Bed Ulipur Upizila Health Complex (Doctors Quarter building- 1200sft)	25	2.5	2	Footing	2	Load Bearing Brick	Medium good Condition	No file	Not Possible	Minor renovation is occurred	
8	ulipur	50-Bed Ulipur Upizila Health Complex (Medical Officers Quarter building- 1000sft)	36	2.5	3	Footing	3	Load Bearing Brick	Medium good Condition	No file	Not Possible	Minor renovation is occurred	
9	ulipur	50-Bed Ulipur Upizila Health Complex (New OPD building)	25	2.5	2	Footing	2	RCC	Good Condition	No file	Not Possible	Minor renovation is occurred	
10	ulipur	50-Bed Ulipur Upizila Health Complex (Nurses Dormatory building- 1200sft)	13	1.5	1	Footing	1	Load Bearing Brick	Medium good Condition	No file	Not Possible	Minor renovation is occurred	
11	ulipur	50-Bed Ulipur Upizila Health Complex (Old building)	25	2.5	2	Footing	2	Load Bearing Brick	Building has been recommended condemned by HED	No file	Not Possible	Minor renovation is occurred	
12	ulipur	50-Bed Ulipur Upizila Health Complex (Second Class Quarter building- 800sft)	25	1.5	2	Footing	2	Load Bearing Brick	Bad Condition	No file	Not Possible	Minor renovation is occurred	
13	ulipur	50-Bed Ulipur Upizila Health Complex (Staf Quarter building- 600sft)	13	1.5	1	Footing	1	Load Bearing Brick	Bad Condition	No file	Not Possible	Minor renovation is occurred	
14	ulipur	50-Bed Ulipur Upizila Health Complex (Staf Quarter building- 600sft)	13	1.5	1	Footing	1	Load Bearing Brick	Bad Condition	No file	Not Possible	Minor renovation is occurred	
15	ulipur	50-Bed Ulipur Upizila Health Complex (Staf Quarter building- 600sft)	25	1.5	2	Footing	2	Load Bearing Brick	Very Bad Condition	No file	Not Possible	Minor renovation is occurred	
16	ulipur	50-Bed Ulipur Upizila Health Complex (Staf Quarter building- 600sft)	36	1.5	3	Footing	3	Load Bearing Brick	Bad Condition	No file	Not Possible	Minor renovation is occurred	

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	bhurungamari	Upazila Health Complex, Bhurungamari, Kurigram	0	0	Shallow Tube well	Septic Tank	800	No	0	600	400	Locally	
2	char_rajibpur	Upazila Health Complex, Char Rajibpur, Kurigram	0	1	No	Septic Tank	1200	No	0	broken condition	Yes	Selected land of Upazil Porishad	
3	nageshwari	Upazila Health Complex, Nageshwari, Kurigram	0	0	Shallow tube well 02 nos	Septic Tank	1200	No	0	510 feet	1760 feet	municipality	
4	phulbari	Upazila Health Complex, Phulbari, Kurigram	0	2		Septic Tank	1400	No	0	400	600	municipality	
5	rajarhat	Rajarhat Upazila Health Complex, Rajarhat, Kurigram	0	0	Shallow Tube well	Septic Tank	800	No	0	500	600	Locally	
6	raumari	Upazila Health Complex, Roumari, Kurigram	0	1	No	Septic Tank	800	No	0	broken condition	Yes	Selected land of Upazil Porishad	
7	ulipur	50-Bed Ulipur Upazila Healt Complex	0	1	0	Septic Tank	500	No	0	no	Yes	Pourasava	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	bhurungamari	Upazila Health Complex, Bhurungamari, Kurigram	0	2140	0	1000	16	Old Rcc Road	Yes	Yes	need boundary wall Repair & height increase and birbed wire needed
2	char_rajibpur	Upazila Health Complex, Char Rajibpur, Kurigram	0	2000	0	0	15	Repair and new road need	Yes	Yes	
3	nageshwari	Upazila Health Complex, Nageshwari, Kurigram	0	975	0	1749	14	1400 feet	Yes	Yes	
4	phulbari	Upazila Health Complex, Phulbari, Kurigram	0	2008	0	0	18			Yes	need boundary wall height increase and birbed wire needed
5	rajarhat	Rajarhat Upazila Health Complex, Rajarhat, Kurigram	0	2210	0	0	18	Old Rcc Road	Yes	Yes	need boundary wall height increase and birbed wire needed
6	raumari	Upazila Health Complex, Roumari, Kurigram	0	1500	0	0	50	Repair and new road need	No	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	bhurungamari	Upazilla Health Complex, Bhurungamari, Kurigram	0	0	0	0	20	0	0	0	10	20 HP Submarsible Pump	Not Present	0
2	char_rajibpur	Upazilla Health Complex, Char-rajibpur, Kurigram	0	0	0	18	20	0	0	5.5	3	20 HP Submarsible Pump	Not Present	0
3	chilmari	Upazilla Health Complex, Chilmari, Kurigram	0	0	0	2	20	0	0	7.5	3	20 HP Submarsible Pump	Not Present	

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
4	nageshwari	Upazilla Health Complex, Nageshwari, Kurigram	0	0	0	0	20	0	0	0	10	20 HP Submersible Pump	Not Present	0
5	phulbari	Upazilla Health Complex, Phulbari, Kurigram	0	0	0	0	20	0	0	0	13	20 HP Submersible Pump	Not Present	0
6	rajarhat	Upazilla Health Complex, Rajarhat, Kurigram	0	0	0	2	20	0	0	0	20	20 HP Submersible Pump	Not Present	0
7	raumari	Upazilla Health Complex, Raumari, Kurigram	0	0	0	0	20	0	0	5.5	3	20 HP Submersible Pump	Not Present	0
8	ulipur	Upazilla Health Complex, Ulipur, Kurigram	0	0	0	4	20	0	0	3	2	0	Not Present	0

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	bhurungamari	Upazila Health Complex, Bhurungamari, kurigram	REB	Yes	50	30	0	0	0	20	0	0	0	0	0
2	char_rajibpur	Upazila Health Complex, Char-rajibpur, kurigram	REB	Yes	150	150	0	0	0	20	0	0	0	0	0
3	chilmari	Upazila Health Complex, Chilmari, kurigram	REB	Yes	100	100	0	0	0	20	0	0	0	0	0
4	nageshwari	Upazila Health Complex, nageshwari, kurigram	REB	Yes	25	25	0	0	0	20	0	0	0	0	0
5	phulbari	Upazila Health Complex, phulbari, kurigram	REB	Yes	0	0	0	0	0	20	0	0	0	0	0
6	rajarhat	Upazila Health Complex, rajarhat, kurigram	REB	Yes	10	10	0	0	0	20	0	0	0	0	0
7	raumari	Upazila Health Complex, raumari, kurigram	REB	Yes	100	100	0	0	0	20	0	0	0	0	0
8	ulipur	Upazila Health Complex, ulipur, kurigram	REB	Yes	50	50	0	0	0	20	0	0	0	0	0

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	bhurungamari	Upazila Health Complex, Bhurungamari, kurigram	No	0	0	0	No	No	Yes	No	Yes	1	N/A	N/A
2	char_rajibpur	Upazila Health Complex, Char-rajibpur, kurigram	No	0	0	0	No	No	Yes	No	Yes	1	N/A	N/A
3	chilmari	Upazila Health Complex, Chilmari, kurigram	No	0	0	0	No	No	Yes	No	Yes	1	N/A	N/A
4	nageshwari	Upazila Health Complex, nageshwari, kurigram	No	0	0		No	No	Yes	No	Yes	1	N/A	N/A
5	phulbari	Upazila Health Complex, phulbari, kurigram	No	0			No	No	Yes	No	Yes	1	N/A	N/A
6	rajarhat	Upazila Health Complex, rajarhat, kurigram	No	0	0		No	No	Yes	No	Yes	1	N/A	N/A
7	raumari	Upazila Health Complex, raumari, kurigram	No	0	0	0	No	No	Yes	No	Yes	1	N/A	N/A
8	ulipur	Upazila Health Complex, ulipur, kurigram	No	0	0	0	No	No	Yes	No	Yes	1	N/A	N/A

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	bhurungamari	Upazila Health Complex, BHURUNGAMARI, Kurigram	Oxygen plant		2021	1	264	264	good	No file	No file	new constructed
2	bhurungamari	Upazila Health Complex, BHURUNGAMARI, Kurigram	Garrage		1984	1	483	483	not good	No file	No file	old building
3	bhurungamari	Upazila Health Complex, BHURUNGAMARI, Kurigram	sub station		1984	1	624	624	not good	No file	No file	old building
4	bhurungamari	Upazila Health Complex, BHURUNGAMARI, Kurigram	pump house		1984	1	400	400	not good	No file	No file	old building
5	bhurungamari	Upazila Health Complex, BHURUNGAMARI, Kurigram	4th class Quarter		1984	1	1026	1026	not good	No file	No file	old building
6	bhurungamari	Upazila Health Complex, BHURUNGAMARI, Kurigram	3rd class Quarter		1984	2	2970	5940	not good	No file	No file	old building
7	bhurungamari	Upazila Health Complex, BHURUNGAMARI, Kurigram	nurses dormetory	2	2009	4	988	3952	not good	No file	No file	new constructed
8	bhurungamari	Upazila Health Complex, BHURUNGAMARI, Kurigram	nurses dormetory	1	1984	1	1500	1500	not good	No file	No file	old building
9	bhurungamari	Upazila Health Complex, BHURUNGAMARI, Kurigram	Officers quarter		1984	3	3800	11400	not good	No file	No file	old building
10	bhurungamari	Upazila Health Complex, BHURUNGAMARI, Kurigram	OPD Building		2009	4	8178	32712	good	No file	No file	new constructed

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
11	nageshwari	Upazila Health Complex, Nageshwari, Kurigram	Oxygen plant		2021	1	264	264	good	No file	No file	new constructed
12	nageshwari	Upazila Health Complex, Nageshwari, Kurigram	Garragge		1984	1	483	483	not good	No file	No file	old building
13	nageshwari	Upazila Health Complex, Nageshwari, Kurigram	sub station		1984	1	624	624	not good	No file	No file	old building
14	nageshwari	Upazila Health Complex, Nageshwari, Kurigram	pump house		1984	1	400	400	not good	No file	No file	old building
15	nageshwari	Upazila Health Complex, Nageshwari, Kurigram	4th class Quarter		1984	1	1026	1026	not good	No file	No file	old building
16	nageshwari	Upazila Health Complex, Nageshwari, Kurigram	3rd class Quarter		1984	2	2970	5940	not good	No file	No file	old building
17	nageshwari	Upazila Health Complex, Nageshwari, Kurigram	nurses dormetory	2	2009	4	988	3952	not good	No file	No file	new constructed
18	nageshwari	Upazila Health Complex, Nageshwari, Kurigram	nurses dormetory	1	1984	1	1500	1500	not good	No file	No file	old building
19	nageshwari	Upazila Health Complex, Nageshwari, Kurigram	Officers quarter		1984	3	3800	11400	not good	No file	No file	old building
20	nageshwari	Upazila Health Complex, Nageshwari, Kurigram	OPD Building		2009	4	8178	32712	good	No file	No file	new constructed
21	phulbari	Upazila Health Complex, Phulbari, Kurigram	Oxygen plant		2021	1	192	192	good	No file	No file	new constructed
22	phulbari	Upazila Health Complex, Phulbari, Kurigram	Garragge		1977	1	300	300	not good	No file	No file	old building
23	phulbari	Upazila Health Complex, Phulbari, Kurigram	pump house		1977	1	214	214	Abandoned	No file	No file	old building
24	phulbari	Upazila Health Complex, Phulbari, Kurigram	4th class Quarter		1977	2	1458	2916	Abandoned	No file	No file	Old Building
25	phulbari	Upazila Health Complex, Phulbari, Kurigram	1st class Quarter		2005	2	1910	3820	good	No file	No file	new constructed
26	phulbari	Upazila Health Complex, Phulbari, Kurigram	3rd class dormetory	2	1977	2	2890	5780	not good	No file	No file	old building
27	phulbari	Upazila Health Complex, Phulbari, Kurigram	600 Sq.Ft Staff Quartar	1	1977	2	1348	2696	not good	No file	No file	old building
28	phulbari	Upazila Health Complex, Phulbari, Kurigram	nurses dormetory		1977	1	1500	2999.99	not good	No file	No file	old building
29	phulbari	Upazila Health Complex, Phulbari, Kurigram	Consaltnt quarter		2005	2	2496	4992	good	No file	No file	new constructed
30	phulbari	Upazila Health Complex, Phulbari, Kurigram	OPD Building		2009	4	8178	32712	good	No file	No file	new constructed
31	rajarhat	Rajarhat Upazila Health Complex,Rajarhat ,Kurigram	Oxygen plant		2021	1	264	264	good	No file	No file	new constructed
32	rajarhat	Rajarhat Upazila Health Complex,Rajarhat ,Kurigram	Garragge		1986	1	483	483	not good	No file	No file	old building
33	rajarhat	Rajarhat Upazila Health Complex,Rajarhat ,Kurigram	sub station		1986	1	624	624	not good	No file	No file	old building
34	rajarhat	Rajarhat Upazila Health Complex,Rajarhat ,Kurigram	pump house		1986	1	400	400	not good	No file	No file	old building
35	rajarhat	Rajarhat Upazila Health Complex,Rajarhat ,Kurigram	4th class Quarter		1986	1	1000	1026	not good	No file	No file	old building

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
36	rajarhat	Rajarhat Upazila Health Complex,Rajarhat ,Kurigram	3rd class Quarter		1986	2	1500	5940	not good	No file	No file	old building
37	rajarhat	Rajarhat Upazila Health Complex,Rajarhat ,Kurigram	nurses dormetory	2	2009	4	1800	3952	not good	No file	No file	new constructed
38	rajarhat	Rajarhat Upazila Health Complex,Rajarhat ,Kurigram	nurses dormetory	1	1986	1	1500	1500	not good	No file	No file	old building
39	rajarhat	Rajarhat Upazila Health Complex,Rajarhat ,Kurigram	Officers quarter		1986	3	3700	11400	not good	No file	No file	old building
40	rajarhat	Rajarhat Upazila Health Complex,Rajarhat ,Kurigram	OPD Building		2008	4	8400	32712	good	No file	No file	new constructed

District Name: Kushtia

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	bheramara	Bheramara Upazilla Health Complex	1 xlsx	ok
2	daulatpur	Daulatpur Upazilla Health Complex	1 xlsx	ok
3	khoksa	Khoksha Upazilla Health Complex	1 xlsx	ok
4	kumarkhali	Kumarkhali Upazilla Health Complex	1 xlsx	ok
5	mirpur	Mirpur Upazilla Health Complex	1 xlsx	ok

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	bheramara	Bheramara Upazilla Health Complex		PWD	Available	50	1 dwg	No file	3 pdfs	1 dwg	15500	GF=15500 FF=15000	No file	No file	No file		ok
2	daulatpur	Daulatpur Upazilla Health Complex		HED	Available	50	1 dwg	No file	3 pdfs	1 dwg	14500	GF=14500, FF=14000	No file	No file	No file		ok
3	khoksa	Khoksha Upazilla Health Complex		HED	Available	50	1 dwg	No file	3 pdfs	1 dwg	15500	GF=15500, FF=15000	No file	No file	No file		ok
4	kumarkhali	Kumarkhali Upazilla Health Complex		HED	Available	50	1 dwg	No file	3 pdfs	1 dwg	15500	GF=15500 FF=15000	No file	No file	No file		ok
5	mirpur	Mirpur Upazilla Health Complex		HED	Available	50	1 dwg	No file	3 pdfs	1 dwg	15500	GF=15500, FF=15000	No file	No file	No file		ok

District Name: Lakshmipur

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	kamalnagar	kamalnagar uhc	No file	ok
2	raipur	Raipur Upazila Health Complex	1 xlsx	ok
3	ramganj	Ramganj Upazila Health Complex	1 xlsx	ok
4	ramgati	Ramgati upazila health complex	No file	ok

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	kamalnagar	kamalnagar uhc	1972	Other	no	50	1 dwg	No file	4 pdfs	1 pdf	20198.43	Ground floor =20198.43& 1st floor=20198.43 sft	1 jpeg, 1 pdf	No file	7 jpegs, 1 mp4		
2	raipur	Raipur Upazila Health Complex	2004	HED	675	50	1 dwg	No file	1 pdf	1 pdf	6826	6826,6826	1 pdf	No file	4 jpegs	Road Level+1'-0"	There are two seperate buildings in raipur health complex. This is first one of them. It appears that the building can be vertically extended.
3	raipur	Raipur Upazila Health Complex	1972	PWD	675	50	1 dwg	No file	1 pdf	1 pdf	10357	10357,10357	1 pdf	No file	2 jpegs, 1 mp4	Road Level+1'-0"	There are two seperate buildings in raipur health complex. This is second one of them. The building is in poor condition and is not Possible vertical Extension.
4	ramganj	Ramganj Upazila Health Complex	2004	HED	370	50	No file	No file	3 pdfs	1 pdf	6175	6175,6175,3087	1 pdf	No file	4 jpegs	Road Level+2'-0"	It appears that the building can be vertically extended.
5	ramganj	Ramganj Upazila Health Complex	1972	PWD	370	50	1 dwg	No file	1 pdf	1 pdf	13402	13402,13402	1 pdf	No file	2 jpegs, 1 mp4	Road Level+1'-0"	This buildings built in 1972 and in poor condition. cant Vertical Extension.
6	ramgati	Ramgati upazila health complex	2006	HED	no	31	1 dwg	No file	1 jpeg, 3 pdfs	1 pdf	8293.44	Ground floor =8293.44 sft , 1st floor = 8293.44 sft	1 pdf	No file	8 jpegs		Ramgati upazila health complex Total land area -2.50 Acar. Construction of 101 bed hospital building requires at least 5 to 6 acres of land. moreover, it is not possible to vertical extension the existing hospital building.

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	kamalnagar	kamalnagar uhc	20.5	2	2	Footing	0	RCC	bad	No file	Not Possible		
2	raipur	Raipur Upazila Health Complex	21	1.5	2	Footing		RCC	Good	No file	Possible		Condition are Good
3	raipur	Raipur Upazila Health Complex	21	1.5	2	Footing	0	Load Bearing	Not Good	No file	Not Possible		This building condition is in poor and is a load-bearing building. Verical Extension

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
								Brick					not possible.
4	ramganj	Ramganj Upazila Health Complex	21	2.5	2	Footing		RCC	Good	No file	Possible		It appears that the building can be vertically extended.
5	ramganj	Ramganj Upazila Health Complex	21	2.5	2	Footing		Load Bearing Brick	Not Good	No file	Not Possible		This buildings built in 1972, which is in poor condition and is a load-bearing building.
6	ramgati	Ramgati upazila health complex	21	2.5	2	Footing	2	RCC	bad	No file	Not Possible		

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	kamalnagar	kamalnagar uhc	20000	2		Septic Tank		No					
2	raipur	Raipur Upazila Health Complex	0	1	Need Deep Tubewell & UGWR	Septic Tank	0	No	0	Not Suffecient	Master Drair, Surface Drain etc	Nearest pond, Powrosova Drain	ok
3	ramganj	Ramganj Upazila Health Complex	0	1	Need Deep Tubewell & UGWR	Septic Tank	0	No	0	Not Suffecient	Master Drair, Surface Drain etc	Nearest pond	ok
4	ramganj	Ramgati upazila health complex	0	2		Septic Tank		No					

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	kamalnagar	kamalnagar uhc		2046			25	Rcc	Yes	Yes	
2	raipur	Raipur Upazila Health Complex	0	2149	550	0	25	Good	Yes	Yes	ok
3	ramganj	Ramganj Upazila Health Complex	0	1621		0	13	Not Good	Yes	No	
4	ramgati	Ramgati upazila health complex		1436			15	Rcc road	No	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	kamalnagar	Kamalnagar Upazila Health Complex	0			10	2	10 ton AC needs to be repaired/replaced.	4 nos Fire Extinguisher	0	10		Autoclave	
2	raipur	Raipur Upazila Health Complex	0			10	2	8 ton AC needs to be repaired/replaced.	4 nos Fire Extinguisher	0	12		Autoclave	
3	ramganj	Ramganj Upazila Health Complex	0			10	2	6 ton AC needs to be repaired/replaced.	3 nos Fire Extinguisher	0	15		Autoclave	
4	ramgati	Ramgati Upazila Health Complex	0			10	2	8 ton AC needs to be repaired/replaced.	5 nos Fire Extinguisher	0	10		Autoclave	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	kamalnagar	Kamalnagar Upazila Health Complex	REB	No	35	100	55	No PFI,HT Switchgear	30	0	0	0			
2	raipur	Raipur Upazila Health Complex	REB	No	40	100	40	No PFI,HT Switchgear	50	0	0	0			
3	ramganj	Ramganj Upazila Health Complex	REB	No	40	100	40	No PFI,HT Switchgear	50	0	0	0			
4	ramgati	Ramgati Upazila Health Complex	REB	No	30	100	50	No PFI,HT Switchgear	50	0	0	0			

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	kamalnagar	Kamalnagar Upazila Health Complex	Yes	0	5		Yes	No	Yes	No	Yes	1	N/A	
2	raipur	Raipur Upazila Health Complex	Yes	0	5		Yes	No	Yes	No	Yes	1	N/A	
3	ramganj	Ramganj Upazila Health Complex	Yes	0	5		Yes	No	Yes	No	Yes	1	N/A	
4	ramgati	Ramgati Upazila Health Complex	Yes	0	5		Yes	No	Yes	No	Yes	1	N/A	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	kamalnagar	kamalnagar uhc	3rd class staff quarter	1	1985	3	2000	6000	good	No file	No file	
2	kamalnagar	kamalnagar uhc	2nd class staff quarter	1	1985	2	2500	5000	good	No file	No file	
3	kamalnagar	kamalnagar uhc	Medical officer quarter	1		2	3000	6000	good	No file	No file	
4	raipur	Raipur Upazila Health Complex	Doctors Dormitory	6	1972	2	1500	3000	not good	No file	No file	ok
5	raipur	Raipur Upazila Health Complex	Nurse Quarter	5	1972	2	1200	2400	good	No file	No file	ok
6	raipur	Raipur Upazila Health Complex	Doctors quarter	4	1972	2	1500	3000	good	No file	No file	ok
7	raipur	Raipur Upazila Health Complex	2nd Class Staff Quarter	3	1972	1	1200	1200	not good	No file	No file	ok
8	raipur	Raipur Upazila Health Complex	4th Class Staff Quarter	2	2004	2	2500	5000	good	No file	No file	ok

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
9	raipur	Raipur Upazila Health Complex	3rd Class Staff Quarter	1	2004	3	1500	4500	good	No file	No file	ok
10	ramganj	Ramganj Upazila Health Complex	Residential		1972	0	1600	4800		No file	No file	
11	ramgati	Ramgati upazila health complex	4th class staff quarter	1	2006	2	1500	3000	good	No file	No file	
12	ramgati	Ramgati upazila health complex	3rd class staff quarter	1	2006	2	1500	3000	good	No file	No file	
13	ramgati	Ramgati upazila health complex	Nurse dormitory	1	2006	1	800	800	good	No file	No file	
14	ramgati	Ramgati upazila health complex	Doctors dormitory	1	2006	1	800	800	good	No file	No file	
15	ramgati	Ramgati upazila health complex	Doctors quarter	1	2006	1	3000	3000	good	No file	No file	

District Name: Lalmonirhat

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	aditmari	Aditmari 50 beded Upazilla Hospital.	No file	
2	hatibandha	Hatibandha 50 beded Upazilla Hospital.	No file	
3	kaliganj	Kaliganj 50 beded Upazilla Hospital.	No file	
4	patgram	Patgram 50 beded Upazilla Hospital.	No file	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	aditmari	Aditmari 50 beded Upazilla Hospital.	1999	HED	Available	50	1 dwg	1 pdf	1 pdf	1 pdf	40406	19279	No file	1 pdf	8 jpegs		Existing Hospital Compound is above than the Road Level.
2	hatibandha	Hatibandha 50 beded Upazilla Hospital.	1980	HED	Available	31	1 pdf	No file	1 pdf	1 pdf	13963	8601	1 pdf	No file	9 jpegs	Plinth Level 12inch above of highest flood level which ever is greater.	Needs to renovate the building. Floor level and Road level seems to be same level.
3	kaliganj	Kaliganj 50 beded Upazilla Hospital.	1961	PWD	Available	31	1 dwg	1 pdf	No file	1 pdf	12024	21950	1 jpeg	No file	10 jpegs	No flood zone	The Old Building needs to be Renovated
4	patgram	Patgram 50 beded Upazilla Hospital.	1974	PWD	Available	31	1 dwg	1 pdf	No file	No file	10371	20743	No file	No file	9 jpegs	No flood zone	Needs to renovate the building.

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	aditmari	Aditmari 50 beded Upazilla Hospital.	31.25	2.5	3	Footing	4	RCC	RCC Frame Structure . Structural condition is good.	No file	Possible	No	Needs to renovate the building.
2	aditmari	Aditmari 50 beded Upazilla Hospital.	20.66	2	2	Footing		Load Bearing Brick		No file	Not Possible		The Old Building needs to be Renovated
3	hatibandha	Hatibandha 50 beded Upazilla Hospital.	21	2.5	2	Footing	4	RCC	RCC Frame Structure . Structural condition is good.	No file		No	Needs to renovate the building.
4	hatibandha	Hatibandha 50 beded Upazilla Hospital.	21	2.25	2	Footing	2	RCC	Vulnerable, Should dismantle.	No file	Not Possible	No	should dismantle
5	kaliganj	Kaliganj 50 beded Upazilla Hospital.	31	2.5	3	Footing	4	RCC	RCC Frame Structure . Structural condition is good.	1 pdf	Possible	No	Needs to renovate the building.
6	kaliganj	Kaliganj 50 beded Upazilla Hospital.	21	1.5	2	Footing	2	Load Bearing Brick	Usable	No file	Not Possible	No	Needs to renovate the building.
7	patgram	Patgram 50 beded Upazilla Hospital.	31	2.5	3	Footing	4	RCC	RCC Frame Structure . Structural condition is good.	No file	Possible	No	Needs to renovate the building.
8	patgram	Patgram 50 beded Upazilla Hospital.	20	2.25	2	Footing	2	RCC	Usable	No file	Not Possible	No	Needs to renovate the building.

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	aditmari	Aditmari 50 beded Upazilla Hospital.	0	1	No other source.	Septic Tank	2000	No	0	Surface Drain	Compound Drainage system. Making pond to Dispose the rain water.	The Rain Water goes to public land during rainy season.	Drainage system should be improved
2	hatibandha	Hatibandha 50 beded Upazilla Hospital.	0	0	No other source.	Septic Tank	2000	No	0	Surface Drain but not working. stagnate condition exist.	Surface drain and compound drain.	public land. Need to make a pond.	Drainage system should be improved
3	kaliganj	Kaliganj 50 beded Upazilla Hospital.	0	1	no	Septic Tank	2000	No	0	No compound drain. Surface drain exist.	Compound Drainage system. Making pond to Dispose the rain water.	The Rain Water goes to public land during rainy season.	Drainage system should be improved
4	patgram	Patgram 50 beded Upazilla Hospital.	0	1	No other source.	Septic Tank	2000	No	0	Surface Drain	Compound Drainage system. Making pond to Dispose the rain water.	public land. Need to make a pond.	Drainage system should be improved

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	aditmari	Aditmari 50 beded Upazilla Hospital.	0	1800	0	900	24	RCC Road with 10ft, 12ft width.	Yes	Yes	Internal Roads need to be repaired.
2	hatibandha	Hatibandha 50 beded Upazilla Hospital.	0	1956	0	0	30	RCC Road with 10ft, 12ft width.	Yes	Yes	Boundary height needs to be increased, Roads needs to be repaired, New boundary gate to be constructed.
3	kaliganj	Kaliganj 50 beded Upazilla Hospital.	0	1800	1000	500	30	RCC Road with 10ft, 12ft width.	Yes	Yes	Internal Roads need to be repaired.
4	patgram	Patgram 50 beded Upazilla Hospital.	0	1800	0	1000	12	RCC Road with 10ft, 12ft width.	Yes	Yes	Need to rise the hight the boundary wall.

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (If present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	aditmari	Aditmari 50 beded Upazilla Hospital.	0	0	Available of Space to set the Lifts	30	20	Additional Ac wiring and Duct Work needed	There is no fire detection system only have some fire extinguisher and fire ball	5.5	0	Need 1 no Dol Starter for existing submersible pump.	Not Present	Plenty of Available Land to fix up the medical waste management.
2	hatibandha	Hatibandha 50 beded Upazilla Hospital.	0	0	Available of Space to set the Lifts	30	20	Additional Ac wiring and Duct Work needed	There is no fire detection system only have some fire extinguisher and fire ball	0	2	Need 1 no Dol Starter for existing submersible pump.	Not Present	Plenty of Available Land to fix up the medical waste management.
3	kaliganj	Aditmari 50 beded Upazilla Hospital.	0	0	Available of Space to set the Lifts	10	30	Additional Ac wiring and Duct Work needed	There is no fire detection system only have some fire extinguisher and fire ball	1	0	Need 1 no Dol Starter for existing submersible pump.	Not Present	Plenty of Available Land to fix up the medical waste management.
4	patgram	Patgram 50 beded Upazilla Hospital.	0	0	Available of Space to set the Lifts	10	30	Additional Ac wiring and Duct Work needed	There is no fire detection system only have some fire extinguisher and fire ball	1	0	Need 1 no Dol Starter for existing submersible pump.	Not Present	Plenty of Available Land to fix up the medical waste management.

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	aditmari	Aditmari 50 beded Upazilla Hospital.	REB	Yes	100	100	0	0	0.05	100	0	0	HT =28m,70rm nyy. LT=20m, 35rm nyy(Hospital Building), LT=20m,16rm nyy at OPD Block	MDB to FDB=16rm nyy length=50m(Hospital), 10rm nyy length=35m(OPD Building).	Point Wearing, Switch socket, Switch board, Circuit Breaker Etc needs to be repaired/Changed.
2	aditmari	Aditmari 50 beded Upazilla Hospital.	REB	Yes	100	100	0								
3	hatibandha	Hatibandha 50 beded Upazilla Hospital.	PDB	Yes	300	100	200	00	0	80	0	0	HT =28m,70rm nyy. LT=20m, 35rm nyy(Hospital Building), LT=20m,16rm nyy at OPD Block	MDB to FDB=16rm nyy length=50m(Hospital), 10rm nyy length=35m(OPD Building).	Point Wearing, Switch socket, Switch board, Circuit Breaker Etc needs to be repaired/Changed.
4	kaliganj	Kaliganj 50 beded Upazilla Hospital.	NESCO	No	300	100	200	00	0	80	0	0	HT =28m,70rm nyy. LT=20m, 35rm nyy(Hospital Building), LT=20m,16rm nyy at OPD Block	MDB to FDB=16rm nyy length=50m(Hospital), 10rm nyy length=35m(OPD Building).	Point Wearing, Switch socket, Switch board, Circuit Breaker Etc needs to be repaired/Changed.
5	patgram	Patgram 50 beded Upazilla Hospital.	NESCO	Yes	300	100	200	00	0	80	0	0	HT =28m,70rm nyy. LT=20m, 35rm nyy(Hospital Building), LT=20m,16rm nyy at OPD Block	MDB to FDB=16rm nyy length=50m(Hospital), 10rm nyy length=35m(OPD Building).	Point Wearing, Switch socket, Switch board, Circuit Breaker Etc needs to be repaired/Changed.

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	aditmari	Aditmari 50 beded Upazilla Hospital.	Yes	0	20	Medical Gas Plant system needs to be set up.	Yes	No	No	No	No	2		
2	hatibandha	Hatibandha 50 beded Upazilla Hospital.	No	0	0	Medical Gas Plant system needs to be set up.	No	No	No	No	Yes	0		
3	kaliganj	Kaliganj 50 beded Upazilla Hospital.	No	0	0	Medical Gas Plant system needs to be set up.	No	No	No	No	No	1		
4	patgram	Patgram 50 beded Upazilla Hospital.	No	0	0	Medical Gas Plant system needs to be set up.	No	No	No	No	No	1		

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	aditmari	Aditmari 50 beded Upazilla Hospital.	Nurses Dormitory.	01	1999	1	750	750	Structural condition is good. Needs to renovate the building.	No file	1 jpeg	Needs to renovate the building.
2	aditmari	Aditmari 50 beded Upazilla Hospital.	800sft Third class staff quarter.	01	2012	2	800	1600	Structural condition is good. Needs to renovate the building.	No file	1 jpeg	Needs to renovate the building.
3	aditmari	Aditmari 50 beded Upazilla Hospital.	1000sft Third class staff quarter.	02	1999	2	1000	2000	Structural condition is good. Needs to renovate the building.	No file	1 jpeg	Needs to renovate the building.

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
4	aditmari	Aditmari 50 beded Upazilla Hospital.	600sft Fourth class staff quarter.	01	2012	2	600	1199.99	Structural condition is good. Needs to renovate the building.	No file	1 jpeg	Needs to renovate the building.
5	aditmari	Aditmari 50 beded Upazilla Hospital.	1000sft Fourth class staff quarter.	01	1999	2	999.99	2000	Structural condition is good. Needs to renovate the building.	No file	1 jpeg	Needs to renovate the building.
6	aditmari	Aditmari 50 beded Upazilla Hospital.	750sft Doctors quarter	01	1999	2	750	1500	Structural condition is good. Needs to renovate the building.	No file	1 jpeg	Needs to renovate the building.
7	aditmari	Aditmari 50 beded Upazilla Hospital.	1000 sft Doctors quarter.	04	1999	2	1000	2000	Structural condition is good. Needs to renovate the building.	No file	9 jpegs	Needs to renovate the building.
8	hatibandha	Hatibandha 50 beded Upazilla Hospital.	1200sft Nurses Dormetory	01	1980	1	1200	1200	Not usable	1 jpeg	No file	dismantling Needed.
9	hatibandha	Hatibandha 50 beded Upazilla Hospital.	600sft Fourth class staff quarter.	04	1980	2	1200	4800	three structure was built in 1980 and these are vulnerable and one structure was build in 2008 and provision of vertical extension.	1 pdf	1 jpeg	The Old Building needs to be Renovated
10	hatibandha	Hatibandha 50 beded Upazilla Hospital.	800sft Nurses quarter	01	2008	2	1600	3200	Usable	1 pdf	1 jpeg	usable, provision of vertical extension.
11	hatibandha	Hatibandha 50 beded Upazilla Hospital.	1000 sft Doctors quarter.	02	1980	2	2000	4000	One structure is built in 1980 and the another is built in 2008.Structural condition is good. Needs to renovate the building.	1 pdf	1 jpeg	Needs to renovate the building.
12	kaliganj	Kaliganj 50 beded Upazilla Hospital.	1000sft Third class staff quarter.	02	1961	1	2000	2000	Usable but condition is not good.	1 pdf	2 jpegs	Needs to renovate the building.
13	kaliganj	Kaliganj 50 beded Upazilla Hospital.	2500 sft Fourth class staff quarter.	01	1961	1	2500	2500	Usable but condition not good.	1 pdf	1 jpeg	Needs to renovate the building. Floor level and Road level seems to be same level.
14	kaliganj	Kaliganj 50 beded Upazilla Hospital.	750sft Nurses quarter	02	2004	2	1500	2250	Usable but condition is not good.	1 pdf	1 jpeg	Needs to renovate the building.
15	kaliganj	Kaliganj 50 beded Upazilla Hospital.	Doctors quarter	2	1961	2	2500	5000	1 Quatar usable and 1 Quatar not Usable.	1 pdf	3 jpegs	Needs to renovate the building. 1st quatar need to dismentaling.

District Name: Madaripur

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	kalkini	৫০ শয্যা বিশিষ্ট উপজেলা স্বাস্থ্য কমপ্লেক্স	1976	HED		50	1 dwg	1 pdf	No file	No file	9000		1 dwg	No file	1 jpeg		
2	rajoir	৫০ শয্যা বিশিষ্ট উপজেলা স্বাস্থ্য কমপ্লেক্স	1968	HED		50	1 dwg	1 pdf	No file	No file	25200	8400	1 dwg	No file	1 jpeg		
3	shibchar	১০০ শয্যা বিশিষ্ট উপজেলা স্বাস্থ্য কমপ্লেক্স	2025	HED		100	1 dwg	1 pdf	No file	No file	120000	20000	1 dwg	No file	1 jpeg		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	kalkini	৫০ শয্যা বিশিষ্ট উপজেলা স্বাস্থ্য কমপ্লেক্স	24	2	2	Footing		RCC		No file	info not available		
2	rajoir	৫০ শয্যা বিশিষ্ট উপজেলা স্বাস্থ্য কমপ্লেক্স	36	2.5	3	Footing	4	RCC		No file	Possible		

District Name: Magura

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	mohammadpur	Upazila Health Complex, Mohammadpur, Magura.	No file	
2	shalikha	Upazila Health Complex, Shalikha, Magura.	No file	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	mohammadpur	Upazila Health Complex, Mohammadpur, Magura.				50	1 dwg	No file	No file	No file			No file	No file	No file		
2	shalikha	Upazila Health Complex, Shalikha, Magura.				50	1 dwg	No file	No file	No file			No file	No file	No file		
3	sreepur	Upazila Health Complex, Sreepur, Magura.	1983	PWD	Adequate	50	No file	No file	No file	No file			No file	No file	No file		

Water Supply and Sanitation

[illegible]

District Name: Manikganj

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	daulatpur	50 beded Daulatpur Upazila Health Complex, Manikganj	1 xlsx	ok
2	ghior	50 beded Ghior Upazila Health Complex, Manikganj	1 xlsx	
3	harirampur	50 beded Harirampur Upazila Health Complex, Manikganj	1 xlsx	ok
4	saturia	50 beded Saturia Upazila Health Complex, Manikganj	1 xlsx	ok
5	shibalaya	50 beded Hospital, Shibalaya, Manikganj	No file	
6	singair	50 beded Hospital ,Singair, Manikganj	1 xlsx	ok

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	daulatpur	Daulatpur Upazila 50-bedded Helth Complex,Manikganj	1980	PWD	yes	50	1 dwg	1 pdf	1 dwg	1 dwg	15264	7632	1 dwg	No file	1 mp4	স্থানীয় লোকজনের সাথে কথা বলে জানা যায় যে ১৯৯৮ সালের বন্যাত্তেও ভবনটিতে বন্যার পানি প্রবেশ করেনি।	
2	ghior	Ghior Upzila 50-bedded Helth Complex, Manikganj	1980	PWD	yes	19	1 dwg	1 pdf	1 dwg	1 dwg	7737	2579	1 dwg	No file	1 mp4	স্থানীয় লোকজনের সাথে কথা বলে জানা যায় ভবনটিতে এ পর্যন্ত বন্যার পানি প্রবেশ করেনি।	হাসপাতাল ভবনটির ৫০ শয্যা বলা হলেও ১৯ শয্যা বিশিষ্ট রেখে জরাজীর্ণ ৩১ শয্যা বিশিষ্ট হাসপাতাল ভবনটি ইতোমধ্যেই ভেঙ্গে ফেলা হয়েছে।
3	harirampur	50 beded Harirampur Upazila Health Complex, Manikganj	1990	PWD	No	50	1 dwg, 1 pdf	1 pdf	1 pdf	1 pdf	20000	40000	1 pdf	No file	3 jpegs, 3 mp4s		
4	saturia	50 beded Saturia Upazila Health Complex, Manikganj	1990	HED	yes	50	1 pdf	1 jpeg	1 pdf	1 pdf	11000	40000	1 pdf	No file	4 jpegs, 3 mp4s		
5	shibalaya	Shibalaya Upazila 50-bedded Helth Complex, Manikganj	1980	PWD	yes	50	1 dwg	2 pdfs	2 pdfs	2 pdfs	11986	4268	3 dwgs	No file	2 mp4s	স্থানীয় লোকজনের সাথে কথা বলে জানা যায় যে হাসপাতাল ভবনটিতে এ পর্যন্ত বন্যার পানি প্রবেশ করেনি।	
6	singair	Singair Upazila 50-bedded Health Complex, Singair, Manikganj	1975	PWD	yes	50	1 pdf	1 pdf	1 pdf	1 pdf	20000	40000	1 pdf	1 jpeg	6 jpegs, 3 mp4s	According to 1988 flood, 2ft above from PL	

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	daulatpur	Daulatpur Upazila 50-bedded Helth Complex,Manikganj	20	2	2	Footing	3	RCC	পুরাতন ভবনটি সংস্কার করে ব্যবহার উপযোগী করা যাবে। ২০১০ সালে নির্মিত ভবনটির উর্ধ্বমুখী সম্প্রসারণ করা যাবে।	1 pdf	Possible	অবগত নই।	

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
2	ghior	Ghior Upzila 50-bedded Helth Complex, Manikganj	30	3	3	Footing	4	RCC	The Hospital building was built in 2010 has RCC frame structure and 1 floor vertical extension is possible.	1 pdf	Possible	অবগত নই।	
3	harirampur	50 beded Harirampur Upazila Health Complex, Manikganj	27	2	2	Footing	3	RCC	New building has RCC structure which can be vertically extended. Old building has load bearing wall structure, has 2 floors and csnot be vertically extended	No file	Possible		New building has RCC structure which can be vertically extended. Old building has load bearing wall structure, has 2 floors and csnot be vertically extended
4	saturia	50 beded Saturia Upazila Health Complex, Manikganj	37	2.5	3	Footing	4	RCC	Can be vertically extended for at least 1 floor of the main hospital building	No file	Possible		
5	shibalaya	Shibalaya Upazila 50-bedded Helth Complex, Manikganj	40	2	4	Footing	4	RCC	পুরাতন ভবনটি সংস্কার করে ব্যবহার উপযোগী করা যাবে। ২০১৪ সালে নির্মিত ভবনটির উর্ধ্বমুখী সম্প্রসারণ করা যাবে।	1 pdf	Possible	অবগত নই।	
6	singair	Singair Upazila 50-bedded Health Complex, Singair, Manikganj	27	1	2	Footing	2	Load Bearing Brick	Load bearing Structure, old building, Structurally functional, further vertical extension is not possible. 1 new building where OT and OPD is situated was built in 2014 has RCC frame structure and 1 floor vertical extension is possible for that building	No file	Possible		vertical extension is possible for OPD building which has RCC frame structure

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	daulatpur	Daulatpur Upazila 50-bedded Helth Complex, Manikganj	0	1	নাই	Septic Tank	2200	No		ড্রেনেজ ব্যবস্থা ভালো নয়। ময়লা পানি উন্মুক্ত স্থানে ফেলা হয়।	যথাযত ড্রেনেজ ব্যবস্থা গ্রহণ করা প্রয়োজন।	হাসপাতাল এর সামনে উপজেলার মাস্টার ড্রেন রয়েছে।	কোনো আন্ডার গ্রাউন্ড ওয়াটার রিজার্ভার নেই। পাম্প থেকে পানি সরাসরি ওভারেহেড রিজার্ভারে যায়।
2	ghior	Ghior Upzila 50-bedded Helth Complex, Manikganj	0	1	নাই	Septic Tank	1100	No		ড্রেনেজ ব্যবস্থা ভালো নয়। ময়লা পানি উন্মুক্ত স্থানে ফেলা হয়।	যথাযত ড্রেনেজ ব্যবস্থা গ্রহণ করা প্রয়োজন।	হাসপাতাল এর সামনে উপজেলার মাস্টার ড্রেন রয়েছে।	কোনো আন্ডার গ্রাউন্ড ওয়াটার রিজার্ভার নেই। পাম্প থেকে পানি সরাসরি ওভারেহেড রিজার্ভারে যায়।
3	harirampur	50 beded Harirampur Upazila Health Complex, Manikganj	0	2	None	Septic Tank	1600	No	0	Needs proper drainage facility	Needs proper drainage facility	Does not have proper waste and water disposal loaction	
4	saturia	50 beded Saturia Upazila Health Complex, Manikganj	4000	2	None	Septic Tank	1600	No	0	has a relatively better drainage facility	Needs proper drainage facility	does not have a proper waste diposal location. Nearby pond is acting as rain water disposal location	
5	shibalaya	Shibalaya Upazila 50-bedded Helth Complex, Manikganj	0	1	ইহা ছাড়াও উপজেলা পরিষদ হতে পানি সরবারহ করা হয়।	Septic Tank	2200	No		ড্রেনেজ ব্যবস্থা ভালো নয়। ময়লা পানি উন্মুক্ত স্থানে ফেলা হয়।	যথাযত ড্রেনেজ ব্যবস্থা গ্রহণ করা প্রয়োজন।	হাসপাতাল এর সামনে খাল রয়েছে।	কোনো আন্ডার গ্রাউন্ড ওয়াটার রিজার্ভার নেই। পাম্প থেকে পানি সরাসরি ওভারেহেড রিজার্ভারে যায়।
6	singair	Singair Upazila 50-bedded Health Complex, Singair, Manikganj	4500	2	None	Septic Tank	1600	No	0	Has a drainage system which is not functioning properly	Needs a new proper designed drainage facility	does not have a proper waste diposal location. Nearby pond is acting as rain water disposal location	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	daulatpur	Daulatpur Upazila 50-bedded Helth Complex,Manikganj	0	2000	0	2000	24	আরসিসি রাস্তা রয়েছে তবে কিছু কিছু জায়গায় রাস্তা ব্যবহার অনুপযোগী হয়ে পড়েছে।	Yes	No	বাউভারি ওয়ালটি এক দিকে হেলে গিয়েছে যা আপাত দৃষ্টিতে ঝুঁকিপূর্ণ।
2	ghior	Ghior Upzila 50-bedded Helth Complex, Manikganj	0	2030	500	1530	40	হাসপাতাল এর সামনের প্রধান সড়ক এর তুলনায় অভ্যন্তরীণ রাস্তা নীচু।	No	Yes	হাসপাতাল এর সামনের প্রধান সড়ক নতুন হওয়ায় হাসপাতাল এর অভ্যন্তরীণ রাস্তা নীচু হওয়ায় অভ্যন্তরীণ উচু করা প্রয়োজন।
3	harirampur	50 beded Harirampur Upazila Health Complex, Manikganj	0	1500	0	0	20	Has good internal road system	Yes	Yes	Boundary wall needs to be vertically extended
4	saturia	50 beded Saturia Upazila Health Complex, Manikganj	0	1400	0	0	14	Has internal road system	Yes	Yes	
5	shibalaya	Shibalaya Upazila 50-bedded Helth Complex, Manikganj	0	1860	0	1000	48	আরসিসি রাস্তা রয়েছে তবে কিছু কিছু জায়গায় রাস্তা ব্যবহার অনুপযোগী হয়ে পড়েছে।	Yes	No	বাউভারি ওয়ালটির বেশ কিছু অংশ ভাঙ্গা।
6	singair	Singair Upazila 50-bedded Health Complex, Singair, Manikganj	0	1400	0	0	12	Has good internal road system	Yes	Yes	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	daulatpur	Daulatpur Upazila 50-bedded Helth Complex,Manikganj	Doctor's quarter, Nurses Quarter, Stuff quarter	6	1984	2	14000	26800	3 Nos are functinal, other 3 nos need renovation	No file	9 jpegs	উপজেলা স্বাস্থ্য ও পরিবার পরিকল্পনা অফিসার এর পৃথক কোনো কোয়ার্টার নেই।
2	ghior	Ghior Upzila 50-bedded Helth Complex, Manikganj	Doctor's quarter, Nurses Quarter, Stuff quarter	5	1984	2	8420	13170	1 Nos are functinal, other 4 nos need renovation	No file	9 jpegs	উপজেলা স্বাস্থ্য ও পরিবার পরিকল্পনা অফিসার এর পৃথক কোনো কোয়ার্টার নেই।
3	harirampur	50 beded Harirampur Upazila Health Complex, Manikganj	Doctor's quarter, Nurses Quarter, Stuff quarter	8			6500	16000	Buildings are in good condition	No file	4 jpegs, 1 mp4	
4	saturia	50 beded Saturia Upazila Health Complex, Manikganj	Doctor's quarter, Nurses Quarter, Stuff quarter	7		3	6700	18000	4 Buildings are in good condition, some renovation are needed. 3 buildings are abandoned	1 jpeg	5 jpegs	
5	shibalaya	Shibalaya Upazila 50-bedded Helth Complex, Manikganj	Doctor's quarter, Nurses Quarter, Stuff quarter	7	1984	2	9150	18300	4 Nos are functinal, other 3 nos need renovation	No file	4 jpegs, 1 mp4	উপজেলা স্বাস্থ্য ও পরিবার পরিকল্পনা অফিসার এর পৃথক কোনো কোয়ার্টার নেই।
6	singair	Singair Upazila 50-bedded Health Complex, Singair, Manikganj	Doctor's quarter, Nurses Quarter, Stuff quarter	6		2	7000	14000	3 Nos are functinal, other 3 nos need renovation	No file	3 jpegs	

District Name: Meherpur

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	gangni	Gangni Upazilla Health Complex	1 xlsx	ok
2	mujibnagar	Mujibnagar Upazilla Health Complex	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	gangni	Gangni Upazilla Health Complex	2017	HED	Not Available	50	1 dwg, 1 pdf	No file	1 dwg	No file	29172	GF=7293,1st F=7293,2nd F=7293,3rd F=7293	No file	No file	7 jpgs	Plinth Level= 12" above of highest flood level which ever is greather.	
2	mujibnagar	Mujibnagar Upazilla Health Complex	2008	HED	Yes	50	1 dwg	1 pdf	No file	No file	29172	GF=7293,1st F=7293,2nd F=7293,3rd F=7293	1 pdf	No file	10 jpgs	No Flood Records	

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	gangni	Gangni Upazilla Health Complex	44	2.5	4	Footing	4	RCC	Well	No file	Not Possible	N/A	
2	mujibnagar	Mujibnagar Upazilla Health Complex	44	3	4	Footing	4	RCC	Good	No file	Not Possible		

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	gangni	Gangni Upazilla Health Complex	15000	2	No	Septic Tank		No		Not well	New drain construction required	Gangni powrashova	
2	mujibnagar	Mujibnagar Upazilla Health Complex	20000	2	No	Septic Tank	2500	No	0	open		No	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	gangni	Gangni Upazilla Health Complex					58	New road construction needed	No	No	
2	mujibnagar	Mujibnagar Upazilla Health Complex					25	Follow Digital survey	No	No	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	gangni	Gangni Upazila Health Complex	0	0		12	25			10			Not Present	
2	mujibnagar	Mujibnagar Upazila Health Complex	0	0	0	26	20			10			Not Present	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	gangni	Gangni Upazila Health Complex	REB	Yes	100	100	0	Transformer 100KVA, HT Cable-3C X 90 Sqmm,LT Switchgear,PFI	40	400	0	0	HT Cable -3C X 90 Sqmm 35 Meter,LT Cable Transformer to LT Switchgear ,PFI And Overhead Line-1c-4X50 Rm And Overhead ANT Cable	MDB,FDB cable 1C-4X16 rm,Length 400 meter	
2	mujibnagar	Mujibnagar Upazila Health Complex	REB	Yes	80				60	400			LT Cable-1C-4X35 Rm (Nyy),LT Cable 40 Meter	FDB,MDB Service Cable 1C-4X16 Rm,1C-4X10 RM,Length-350	

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	gangni	Gangni Upazila Health Complex	Yes	0	0		No	No	No	No	Yes	0		
2	mujibnagar	Mujibnagar Upazila Health Complex	No	0			Yes	No	No	No	Yes	0		

District Name: Moulvibazar

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	barlekha	50 Bedded Upazila Health Complex, Baralekha, Moulvibazar	1 xlsx	none
2	juri	50 Bedded Upazila Health Complex, Juri, Moulvibazar	1 xlsx	None
3	kulaura	50 Bedded Upazila Health Complex, Kulaura, Moulvibazar	1 xlsx	none
4	rajnagar	31 Bedded Upazila Health Complex, Rajnagar, Moulvibazar	1 xlsx	none

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	barlekha	50 Bedded Upazila Health Complex, Baralekha, Moulvibazar	2018	HED	4 acres	50	No file	No file	No file	No file	6536	6436	No file	No file	No file	Often flooded.	N/A
2	juri	50 Bedded Upazila Health Complex, Juri, Moulvibazar	2018	HED	3 acres	50	No file	No file	No file	No file	14000	13800	No file	No file	No file	Often flooded.	N/A
3	kulaura	50 Bedded Upazila Health Complex, Kulaura, Moulvibazar	2005	HED	4 acres	50	No file	No file	No file	No file	5493	4743	No file	No file	No file	Often flooded.	N/A
4	rajnagar	31 Bedded Upazila Health Complex, Rajnagar, Moulvibazar	2021	HED	3 acres	31	No file	No file	No file	No file	10800	8800	No file	No file	No file	Often flooded.	N/A

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	barlekha	50 Bedded Upazila Health Complex, Baralekha, Moulvibazar	33	3	3	Deep	5	RCC	Good	No file	Possible	no	N/A
2	juri	50 Bedded Upazila Health Complex, Juri, Moulvibazar	42	3	4	Deep	4	RCC	Good	No file	Not Possible	no	N/A
3	kulaura	50 Bedded Upazila Health Complex, Kulaura, Moulvibazar	21	2	2	Deep	5	RCC	Good	No file	Possible	no	N/A
4	rajnagar	31 Bedded Upazila Health Complex, Rajnagar, Moulvibazar	31.5	3	3	Deep	3	RCC	Good but there is active water logging .	No file	Not Possible	no	N/A

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	barlekha	50 Bedded Upazila Health Complex, Baralekha, Moulvibazar	0	2	none	Septic Tank		No	0	poor and old	yes.	Main drain	none

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
2	juri	50 Bedded Upazila Health Complex, Juri, Moulvibazar	0	2	none	Septic Tank		No	0	good	no	Main drain	none
3	kulaura	50 Bedded Upazila Health Complex, Kulaura, Moulvibazar	0	1	none	Septic Tank		No	0	poor	yes.	Main drain	none
4	rajnagar	31 Bedded Upazila Health Complex, Rajnagar, Moulvibazar	0	1	none	Septic Tank		No	0	poor	yes.	Main drain	none

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	barlekha	50 Bedded Upazila Health Complex, Baralekha, Moulvibazar	0	1672		0	20	average width 7ft, flexible pavement, old and need to repair	Yes	Yes	None
2	juri	50 Bedded Upazila Health Complex, Juri, Moulvibazar	0	1448		0	14	average width 7ft, flexible pavement, old and need to repair	Yes	Yes	None
3	kulaura	50 Bedded Upazila Health Complex, Kulaura, Moulvibazar	0	1672		0	14	average width 7ft, flexible pavement, old and need to repair	Yes	Yes	None
4	rajnagar	31 Bedded Upazila Health Complex, Rajnagar, Moulvibazar	0	1448		0	14	average width 7ft, flexible pavement, old and need to repair	No	Yes	None

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional Info (Capacity, Demand etc)
1	barlekha	50 Bedded Upazila Health Complex, Baralekha, Moulvibazar	0	0	There is no lift in the Hospital Building.	7	15		Only fire extinguisher available. There is no Fire Detection and Protection system.	4	0	insufficient	Not Present	
2	juri	50 Bedded Upazila Health Complex, Juri, Moulvibazar	0	0	There is no lift in the Hospital Building.	6	6		Only fire extinguisher available. There is no Fire Detection and Protection system.	14	0		Not Present	
3	kulaura	50 Bedded Upazila Health Complex, Kulaura, Moulvibazar	0	0	There is no lift in the Hospital Building.	5	22		Only fire extinguisher available. There is no Fire Detection and Protection system.	5	0	insufficient	Not Present	
4	rajnagar	31 Bedded Upazila Health Complex, Rajnagar, Moulvibazar	0	0	There is no lift in the Hospital Building.	6	20		Only fire extinguisher available. There is no Fire Detection and Protection system.	5	0	insufficient	Not Present	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	barlekha	50 Bedded Upazila Health Complex, Baralekha, Moulvibazar	REB						10		0				
2	juri	50 Bedded Upazila Health Complex, Juri, Moulvibazar	PDB						23		0				
3	kulaura	50 Bedded Upazila Health Complex, Kulaura, Moulvibazar	PDB						0		0				
4	rajnagar	31 Bedded Upazila Health Complex, Rajnagar, Moulvibazar	REB						0		0				

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	barlekha	50 Bedded Upazila Health Complex, Baralekha, Moulvibazar	No		50	Oxygen cylinder gas is used	No	No	No	No	Yes	1	Computer and other medical equipments	
2	juri	50 Bedded Upazila Health Complex, Juri, Moulvibazar	No		50	Oxygen cylinder gas is used	No	No	No	No	Yes	1	Computer and other medical equipments	
3	kulaura	50 Bedded Upazila Health Complex, Kulaura, Moulvibazar	No		50	Oxygen cylinder gas is used	No	No	No	No	Yes	1	Computer,AC and other medical equipments	
4	rajnagar	31 Bedded Upazila Health Complex, Rajnagar, Moulvibazar	No		31	Oxygen cylinder	No	No	No	No	Yes	0	Computer and other medical equipments	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	barlekha	50 Bedded Upazila Health Complex, Baralekha, Moulvibazar	Dormitory and others	7			13475	1250	old building and need repair maintenance	No file	1 jpeg	None
2	juri	50 Bedded Upazila Health Complex, Juri, Moulvibazar	Dormitory and others	5	1995		9625	9450	old building and need repair maintenance	No file	1 jpeg	None
3	kulaura	50 Bedded Upazila Health Complex, Kulaura, Moulvibazar	Dormitory and others	7	1980		10500	9800	old building and need repair maintenance	No file	1 jpeg	None
4	rajnagar	31 Bedded Upazila Health Complex, Rajnagar, Moulvibazar	Dormitory and others	9	1990	2	13500	12800	old building and need repair maintenance	No file	1 jpeg	None

District Name: Munshiganj

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	gazaria	Gazaria Upazila Health Complex	1 xlsx	
2	gazaria	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .	No file	
3	louhajang	Louhajang Upazila Health Complex	1 xlsx	
4	louhajang	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .	No file	
5	sirajdikhan	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .	No file	
6	sirajdikhan	Sirajdikhan Upazila Health Complex	1 xlsx	
7	sreenagar	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .	No file	
8	sreenagar	Sreenagar Upazila Health Complex	1 xlsx	
9	tongibari	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .	No file	
10	tongibari	Tongibari Upazila Health Complex	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	gazaria	Gazaria Upazilla Health Complex	2008	HED	As per Digital Survey	50	1 dwg	No file	1 dwg	No file		32948.08	No file	No file	8 jpgs		
2	gazaria	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .					No file	No file	No file	No file			No file	No file	No file		
3	louhajang	Louhaganj Upazilla Health Complex	2005	HED	As per Digital Survey	50	1 dwg	No file	1 dwg	No file		37744.1	No file	No file	7 jpegs, 3 jpgs		
4	louhajang	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .					No file	No file	No file	No file			No file	No file	No file		
5	sirajdikhan	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .					No file	No file	No file	No file			No file	No file	No file		
6	sirajdikhan	Sirajdikhan Upazilla Health Complex	2007	HED	As per Digital Survey	50	1 dwg	No file	1 dwg	No file		35943.94	No file	No file	10 jpegs		
7	sreenagar	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .					No file	No file	No file	No file			No file	No file	No file		
8	sreenagar	Sreenagar Upazilla Health Complex	2013	HED		50	1 dwg	No file	1 dwg	No file		34312.94	No file	No file	10 jpegs		
9	tongibari	Project Name : Construction/Upgradation of					No file	No file	No file	No file			No file	No file	No file		

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
		101-Bed Upazila Health Complex (UHC) .															
10	tongibari	Tongibari Upazilla Health Complex	2008	HED	As per Digital Survey	50	1 dwg	No file	1 dwg	No file		34039.47	No file	No file	5 jpegs, 5 jpgs		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	gazaria	Gazaria Upazilla Health Complex	20.5	1	2	Deep	4	RCC	The mainn hospital building is divided into two portion. The old building was constructed during 1988 and new building was constructed on 2008.	No file	Possible	Not Found	Vertical extension of new building is possible but core cutting test needed for column capacity .
2	louhajang	Louhajang Upazilla Health Complex	30.5	1.65	4	Deep	4	RCC	The mainn hospital building is divided into two portion. The old building was constructed during 205	No file	Not Possible	Not Found	Vertical extension of new building is not possible .
3	sirajdikhan	Sirajdikhan Upazilla Health Complex	30.5	1.18	2	Deep	4	RCC	The mainn hospital building is divided into two portion. The old building was constructed during 1968 and new building was constructed on 2007.	No file	Possible	Not Found	Vertical extension of new building is possible but core cutting test needed for column capacity .
4	sreenagar	Sreenagar Upazilla Health Complex	30.5	1.18	2	Deep	4	RCC	The mainn hospital building is divided into two portion. The old building was constructed during 1978 and new building was constructed on 2013.	No file	Possible	Not Found	Vertical extension of new building is possible but core cutting test needed for column capacity .
5	tongibari	Tongibari Upazilla Health Complex	30.5	1.51	2	Deep	4	RCC	The mainn hospital building is divided into two portion. The old building was constructed during 1985 and new building was constructed on 2008.	No file	Possible	Not Found	Vertical extension of new building is possible but core cutting test needed for column capacity .

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	gazaria	Gazaria Upazila Health Complex		1	N/A	Septic Tank	0	No	0	Surfacu U drain	Adequate drainage facilities are required at Sreenagar Upazila Health Complex to ensure proper wastewater management and prevent waterlogging	no	
2	louhajang	Louhajang Upazila Health Complex		1	N/A	Septic Tank	0	No	0	Surfacu U drain	Adequate drainage facilities are required at Sreenagar Upazila Health Complex to ensure proper wastewater management and prevent waterlogging	no	
3	sirajdikhan	Sirajdikhan Upazila Health Complex		1	N/A	Septic Tank	0	No	0	Surfacu U drain	Adequate drainage facilities are required at Sreenagar Upazila Health Complex to ensure proper wastewater management and prevent waterlogging	no	
4	sreenagar	Sreenagar Upazila Health Complex		1	N/A	Septic Tank	0	No	0	Surfacu U drain	Adequate drainage facilities are required at Sreenagar Upazila Health Complex to ensure proper wastewater management and prevent waterlogging	no	
5	tongibari	Tongibari Upazila Health Complex		1	N/A	Septic Tank	0	No	0	Surfacu U drain	Adequate drainage facilities are required at Sreenagar Upazila Health Complex to ensure proper wastewater management and prevent waterlogging	no	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	gazaria	Gazaria Upazilla Health Complex		1550.17			18.5	The internal roads within the complex are generally in good condition and suitable for daily use. However, some sections have minor cracks and broken pavement that require repair. Routine maintenance and timely repairs are recommended to ensure safe and smooth traffic movement and to prevent further deterioration.	Yes		
2	louhajang	Louhajang Upazilla Health Complex		1957.58			18.1	The internal road network is generally in good condition and provides adequate access throughout the office complex. Some localized damaged areas and surface cracks have been observed and should be repaired to maintain safety and usability.	Yes		
3	sirajdikhan	Sirajdikhan Upazilla Health Complex		2369.17			18.3	Most internal roads are well-maintained and suitable for regular vehicular movement. However, a few sections show signs of pavement deterioration and require minor repair and maintenance work.	Yes		
4	sreenagar	Sreenagar Upazilla Health Complex		1991.08			14.2	The roads within the complex are functional and in satisfactory condition overall. Isolated areas with broken pavement and surface defects should be addressed to prevent further damage and ensure smooth traffic flow.	Yes		
5	tongibari	Tongibari Upazilla Health Complex		1603.42			12.4	The internal roads are generally stable and serviceable, supporting daily operations effectively. Minor damaged portions and uneven surfaces were noted in some locations, and timely repairs are recommended to improve road conditions.	Yes		

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	gazaria	Project Name : Construction/Upgradation of 101-Bed Upazilla Health Complex (UHC) .	0			8			10 nos fire extinguisher	7.5	0		Not Present	
2	louhajang	Project Name : Construction/Upgradation of 101-Bed Upazilla Health Complex (UHC) .	0			16			30 nos fire extinguisher	7.5	0		Not Present	
3	sirajdikhan	Project Name : Construction/Upgradation of 101-Bed Upazilla Health Complex (UHC) .	0	0		20			10 nos fire extinguisher	7.5	0		Not Present	
4	sreenagar	Project Name : Construction/Upgradation of 101-Bed Upazilla Health Complex (UHC) .	0			22			8 nos fire extinguisher	7.5	0		Not Present	
5	tongibari	Project Name : Construction/Upgradation of 101-Bed Upazilla Health Complex (UHC) .	0			16			10 nos fire extinguisher	7.5	0		Not Present	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	gazaria	Project Name : Construction/Upgradation of 101-Bed Upazilla Health Complex (UHC) .	REB		125						0	0			

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
2	louhajang	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .	REB		125						0	0			
3	sirajdikhan	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .	REB		125						0	0			
4	sreenagar	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .	REB		125						0	0			
5	tongibari	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .	REB		125						0	0			

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	gazaria	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .	No				Yes	No	Yes	No	Yes	0		
2	louhajang	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .	No				Yes	No	Yes	No	Yes	0		
3	sirajdikhan	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .	No				Yes	No	Yes	No	Yes	0		
4	sreenagar	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .	No				Yes	No	Yes	No	Yes	0		
5	tongibari	Project Name : Construction/Upgradation of 101-Bed Upazila Health Complex (UHC) .	No				Yes	No	Yes	No	Yes	0		

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	gazaria	Gazaria Upazila Health Complex	Quarter buildings-6, Abandoned buildings (Pucca + Semi-pucca)-9, Mosque-1, Pump house-1, Garage-1							No file	No file	
2	louhajang	Louhajang Upazila Health Complex	Quarter buildings (1/2/3/4 storied)-5, Residential (Semi-pucca)-1, Abandoned building-2, Family Planning Office -1, Mosque-1, Garage (Semi-pucca)-1.							No file	No file	
3	sirajdikhan	Sirajdikhan Upazila Health Complex	Quarter buildings-9 (2 Storied- 3, 3 Storied-1, 4 Storied-4, 1 Storied-1), Abandoned buildings (4 Storied)-3, Mosque-1, Family Planning Office-1, Garage (Semi/Pucca)-3, Shop (Semi-Pucca)-5, Water Pump-1.							No file	No file	
4	sreenagar	Sreenagar Upazila Health Complex	Residential hostel building - 1, Staff quarters (Pucca 3 storied quarters - 2, Pucca 2 storied quarters - 7, Pucca 1 storied quarters - 5), Mosque - 1, Garages (semi-pucca) - 2, Tin-shed							No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
			residential buildings - 3, Abandoned building - 1									
5	tongibari	Tongibari Upazila Health Complex	Staff Quarters (Pucca 1-storied-9, Pucca 1-storied abandoned building-1, Substation-1, Additional abandoned structures-2, Garage-1							No file	No file	

District Name: Mymensingh

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	bhaluka	Bhaluka Upazilla Health Complex	1 xlsx	ok
2	dhobaura	Dhobaura UHC	No file	ok
3	fulbaria	Fulbaria upazila health complex	No file	
4	gafargaon	Gafargaon Upazilla Health Complex	1 xlsx	ok
5	gauripur	Gouripur UHC	No file	ok
6	haluaghat	Haluaghat UHC	No file	ok
7	ishwarganj	Ishwarganj UHC	No file	ok
8	muktagachha	Muktagacha Health Complex	No file	ok
9	nandail	Nandail UHC	No file	ok
10	phulpur	Phulpur UHC	No file	ok
11	tarafund	Tarakakanda Upazila Health Complex	No file	ok
12	trishal	Trishal upazila health complex	No file	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	bhaluka	Bhaluka Upazilla Health Complex	1983	PWD	Yes	50	1 dwg	No file	No file	No file			No file	No file	1 jpeg		
2	dhobaura	Dhobaura UHC	2009	HED	Yes	19	1 dwg	No file	No file	No file	8650	17300	No file	No file	No file		
3	dhobaura	Dhobaura UHC	1983	PWD	available	31	1 dwg	No file	No file	No file	11872	23744	No file	No file	1 jpg		
4	gafargaon	Gafargaon Upazilla Health Complex	1978	PWD	Yes	50	1 dwg	No file	No file	No file			No file	No file	1 jpeg		
5	gauripur	Gouripur UHC	2009	HED		19	1 dwg	No file	No file	No file	6776	20328	No file	No file	No file		
6	gauripur	Gouripur Upazila Health Complex	1983	PWD		31	1 dwg	No file	No file	No file	8725	15750	No file	No file	1 jpg		
7	haluaghat	Haluaghat UHC	2009	HED	yes	19	1 dwg	No file	No file	No file	6500	13000	No file	No file	1 jpg		
8	haluaghat	Haluaghat UHC	1983	PWD	yes	31	1 dwg	No file	No file	No file	10500	20800	No file	No file	1 jpg		
9	ishwarganj	Ishwarganj UHC	2009	HED	yes	19	1 dwg	No file	No file	No file	7600	15200	No file	No file	1 jpg		
10	ishwarganj	Ishwarganj UHC	1983	PWD	yes	31	1 dwg	No file	No file	No file	8900	17800	No file	No file	1 jpg		
11	muktagachha	Muktagacha Health Complex	1972	PWD	not available	50	1 dwg	No file	No file	No file	14951	14951	No file	No file	2 jpegs		
12	nandail	Nandail UHC	2021	HED		19	1 dwg	No file	No file	No file	6776	27104	No file	No file	No file		
13	nandail	Nandail UHC	1983	PWD	1.84 acre	31	1 dwg	No file	No file	No file	11209	22418	No file	No file	1 jpg		
14	phulpur	Phulpur UHC	2009	HED		19	1 dwg	No file	No file	No file	6776	13553	No file	No file	No file		

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
15	phulpur	Phulpur Upazila Health Complex	1983	PWD		31	1 dwg	No file	No file	No file	11209	22418	No file	No file	1 jpg		
16	tarafund	Tarakanda UHC	2021	HED	yes but pond	50	1 dwg	No file	No file	No file	13080	51320	No file	No file	1 jpg		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	bhaluka	Bhaluka Upazilla Health Complex	22	2	2	Footing	2	Load Bearing Brick	Normal. Needs repair and maintenance.	No file	Not Possible		
2	dhobaura	Dhobaura UHC	23.5	2	2	Footing	2	RCC		No file	Not Possible		
3	gafargaon	Gafargaon Upazilla Health Complex	20.83	0.83	2	Footing	2	Load Bearing Brick	Not good, Needs repair and renovations	No file	Not Possible		
4	gaupur	Gouripur Upazila Health Complex	43.6	2.5	4	Footing	4	RCC	Normal.Needs repair and maintainance.	No file	Not Possible		
5	gaupur	Gouripur Upazila Health Complex	23.5	2.5	2	Footing	2	Load Bearing Brick	Needs repairs and renovations	No file	Not Possible		
6	haluaghat	Haluaghat UHC	23.5	2	2	Footing	2	Load Bearing Brick	visible cracks in slab	No file	Not Possible		
7	ishwarganj	Ishwarganj UHC	23.5	2.5	2	Footing	2	Load Bearing Brick		No file	Not Possible		
8	muktagachha	Muktagacha Health Complex	22	2	2	Footing	2	Load Bearing Brick	old	No file	Not Possible		
9	nandail	Nandail UHC	41.92	2.5	4	Footing	6	RCC	New building	No file	Possible		
10	nandail	Nandail UHC	23.5	2	2	Footing	2	Load Bearing Brick	Not good, Needs repairs and renovations	No file	Not Possible		
11	phulpur	Phulpur Upazila Health Complex	23.67	2.5	2	Footing	2	RCC	Good	No file	Not Possible		
12	phulpur	Phulpur Upazila Health Complex	23.5	2	2	Footing	2	Load Bearing Brick	Routine structural audits and maintenance are necessary.	No file	Not Possible		
13	tarafund	Tarakanda UHC	42	2.5	4	Mat	6	RCC	Good	No file	Possible		

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	bhaluka	Bhaluka Upazilla Health Complex	0	1	No	Septic Tank		No		No	Required	River	
2	gafargaon	Gafargaon Upazilla Health Complex	0	1	No	Septic Tank		No		No	Required	Not available	
3	gaupur	Gouripur Upazila Health Complex	0	2	facility utilize any alternative water sources-Not available	Septic Tank		No			Required	Not available	
4	muktagachha	Muktagacha Health Complex	0	1	No	Septic Tank		No	0	No	Yes	River	
5	nandail	Nandail UHC	0	2	No	Septic Tank		No					

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
2	gafargaon	Gafargaon Upazilla Health Complex													

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	bhaluka	Bhaluka Upazilla Health Complex												
2	gafargaon	Gafargaon Upazilla Health Complex												

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	bhaluka	Bhaluka Upazilla Health Complex	Dormitory building		1983	1			good but need repair	No file	No file	
2	bhaluka	Bhaluka Upazilla Health Complex	Family planning building		2012	2			good but need repair	No file	No file	
3	bhaluka	Bhaluka Upazilla Health Complex	3rd class staff quarter	2	1983	2			Not good	No file	No file	
4	bhaluka	Bhaluka Upazilla Health Complex	2nd class staff quarter		2007	2			good but need repair	No file	No file	
5	bhaluka	Bhaluka Upazilla Health Complex	RMO residence		1983	2			Not good	No file	No file	
6	bhaluka	Bhaluka Upazilla Health Complex	THO residence		1983	2			Not good	No file	No file	
7	bhaluka	Bhaluka Upazilla Health Complex	Hospital office building		1983	1			old	No file	No file	
8	bhaluka	Bhaluka Upazilla Health Complex	Hospital office building		1983	1			old	No file	No file	
9	bhaluka	Bhaluka Upazilla Health Complex	Hospital building (OPD)		2007	2			good	No file	No file	
10	bhaluka	Bhaluka Upazilla Health Complex	Emergency Obstetric Care		2000	2			good	No file	No file	
11	bhaluka	Bhaluka Upazilla Health Complex	Troma center		2003	3			good	No file	No file	
12	gafargaon	Gafargaon Upazilla Health Complex	1-storied family planning building		1978	1			Not use, To be dismantling	No file	No file	
13	gafargaon	Gafargaon Upazilla Health Complex	1-storied hospital building (old)		1978	1			Not good. Needs repair and renovations	No file	No file	
14	gafargaon	Gafargaon Upazilla Health Complex	Pump house		2012	1			good	No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
15	gafargaon	Gafargaon Upazilla Health Complex	2nd class staff quarter		2009	2			good but need repair	No file	No file	
16	gafargaon	Gafargaon Upazilla Health Complex	4th class staff quarter		1978	2			Not use, To be dismantling	No file	No file	
17	gafargaon	Gafargaon Upazilla Health Complex	3rd class staff quarter		1978	3			Not use, To be dismantling	No file	No file	
18	gafargaon	Gafargaon Upazilla Health Complex	2-storied 1st class doctors quarter		2009	2			good but need repair	No file	No file	
19	gafargaon	Gafargaon Upazilla Health Complex	RMO residence		1978	1			Not use, To be dismantling	No file	No file	
20	gafargaon	Gafargaon Upazilla Health Complex	THO residence		1978	1			Not use, To be dismantling	No file	No file	
21	gafargaon	Gafargaon Upazilla Health Complex	2-storied 1st class doctors quarter		1978	2			Not good. Needs repair and renovations	No file	No file	
22	gafargaon	Gafargaon Upazilla Health Complex	3-storied hospital building (new)		2009	3			good	No file	No file	
23	gafargaon	Gafargaon Upazilla Health Complex	Family planning building		2013	2			good but need repair	No file	No file	
24	gauripur	Gouripur Upazila Health Complex	2 storied garage		2009	2	656	1312	good. Needs repairs and renovations	No file	No file	
25	gauripur	Gouripur Upazila Health Complex	1-storied substation building		1983	1	978	978	Not good. Needs repairs and renovations	No file	No file	
26	gauripur	Gouripur Upazila Health Complex	2-storied family planning office		2009	2	1760	3520	good. Needs repair and renovation.	No file	No file	
27	gauripur	Gouripur Upazila Health Complex	2 storied staff quarter New		1983	2	1060	2120	Not good. Needs repairs and renovations	No file	No file	
28	gauripur	Gouripur Upazila Health Complex	1-storied abandoned building		1983	1	987	987	Not good. Needs repairs and renovations	No file	No file	
29	gauripur	Gouripur Upazila Health Complex	2-storied Staff Quarter		1983	2	1027	2054	Not good. Needs repair and renovation.	No file	No file	
30	gauripur	Gouripur Upazila Health Complex	3-storied Staff Quarter		1983	3	986	2958	Not good,Needs repairs and renovations	No file	No file	
31	gauripur	Gouripur Upazila Health Complex	1-storied Staff Quarter		1983	1	2000	2000	Not good, Needs repairs and renovations	No file	No file	
32	gauripur	Gouripur Upazila Health Complex	4-storied Staff Quarter		1983	4	1725	6900	Not good, Needs repairs and renovations	No file	No file	
33	gauripur	Gouripur Upazila Health Complex	2-storied Staff Quarter		1983	2	2347	4694	Not good, Needs repairs and renovations	No file	No file	
34	gauripur	Gouripur Upazila Health Complex	3-storied Staff Quarter		1983	3	2538	7614	Not good, Needs repairs and renovations	No file	No file	
35	haluaghat	Haluaghat Upazila Health Complex	garage		2024	1	250	250	good	No file	No file	
36	haluaghat	Haluaghat Upazila Health Complex	1-storied toilet		2024	1	150	150	good	No file	No file	
37	haluaghat	Haluaghat Upazila Health Complex	1-storied family planning office		2021	1	1700	1700	good	No file	No file	
38	haluaghat	Haluaghat Upazila Health Complex	1-storied generator room		2024	1	265	265	Not good, Needs repairs and renovations	No file	No file	
39	haluaghat	Haluaghat Upazila Health Complex	semi pucca abandoned		1983	1	280	280	Not good.	No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
40	haluaghat	Haluaghat Upazila Health Complex	pump room		2021	1	120	120	good	No file	No file	
41	haluaghat	Haluaghat Upazila Health Complex	1-storied garage building		2021	1	320	320	Not good, Needs repairs and renovations	No file	No file	
42	haluaghat	Haluaghat Upazila Health Complex	1-storied mosque		2021	1	1500	1500	Not good, Needs repairs and renovations	No file	No file	
43	haluaghat	Haluaghat Upazila Health Complex	2-storied 4th class quarter		1983	2	1400	2800	Not good, Needs repairs and renovations	No file	No file	
44	haluaghat	Haluaghat Upazila Health Complex	2-storied 4th class quarter		2009	2	1200	2400	Not good, Needs repairs and renovations	No file	No file	
45	haluaghat	Haluaghat Upazila Health Complex	2-storied 3rd class Quarter		1983	2	1800	3600	Not good, Needs repairs and renovations	No file	No file	
46	haluaghat	Haluaghat Upazila Health Complex	4-storied 3rd class Quarter		2009	4	1800	7200	Not good, Needs repairs and renovations	No file	No file	
47	haluaghat	Haluaghat Upazila Health Complex	1-storied Nurse dormitory-1		2009	1	1050	1050	Not good, Needs repairs and renovations	No file	No file	
48	haluaghat	Haluaghat Upazila Health Complex	1-storied Nurse dormitory-2		1983	1	700	700	Not good, Needs repairs and renovations	No file	No file	
49	haluaghat	Haluaghat Upazila Health Complex	3-storied doctor Quarter		2009	3	2250	6750	Not good, Needs repairs and renovations	No file	No file	
50	haluaghat	Haluaghat Upazila Health Complex	2-storied doctor Quarter		1983	2	1650	3300	Not good, Needs repairs and renovations	No file	No file	
51	haluaghat	Haluaghat Upazila Health Complex	waste disposal shed		2009	1	400	400	Not good, Needs repairs and renovations	No file	No file	
52	haluaghat	Haluaghat Upazila Health Complex	1-storied toilet 2 nos		2021	1	300	300	good	No file	No file	
53	haluaghat	Haluaghat Upazila Health Complex	1-storied family planning office		2021	1	950	950	good	No file	No file	
54	haluaghat	Haluaghat Upazila Health Complex	1-storied abandoned building		1983	1	620	620	Not good.	No file	No file	
55	haluaghat	Haluaghat Upazila Health Complex	1-storied abandoned garage		1983	1	230	230	Not good.	No file	No file	
56	haluaghat	Haluaghat Upazila Health Complex	2 storied abandoned quarter		1983	2	1060	2120	Not good.	No file	No file	
57	haluaghat	Haluaghat Upazila Health Complex	1-storied abandoned building		1983	1	430	430	Not good.	No file	No file	
58	haluaghat	Haluaghat Upazila Health Complex	1-storied abandoned building		1983	1	1350	1350	Not good.	No file	No file	
59	haluaghat	Haluaghat Upazila Health Complex	2-storied third class quarter		1983	2	1400	2800	Not good, Needs repairs and renovations	No file	No file	
60	haluaghat	Haluaghat Upazila Health Complex	1-storied RMO Quarter		1983	1	1350	1350	Not good, Needs repairs and renovations	No file	No file	
61	haluaghat	Haluaghat Upazila Health Complex	1-storied RMO Quarter		2009	1	1350	1350	good	No file	No file	
62	haluaghat	Haluaghat Upazila Health Complex	1-storied Nurse dormitory		2009	1	1610	1610	Not good, Needs repairs and renovations	No file	No file	
63	haluaghat	Haluaghat Upazila Health Complex	2-storied Nurse Quarter		1983	2	1900	3800	Not good, Needs repairs and renovations	No file	No file	
64	haluaghat	Haluaghat Upazila Health Complex	2-storied doctor Quarter-2		1983	2	2300	4600	Not good, Needs repairs and renovations	No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
65	haluaghat	Haluaghat Upazila Health Complex	2-storied doctor Quarter-1		2009	2	2900	5800	Not good, Needs repairs and renovations	No file	No file	
66	muktagachha	Muktagacha Health Complex	1 storied Family Planning store		1972	1	892	892	Not good, Need to Dismantled	No file	1 jpg	
67	muktagachha	Muktagacha Health Complex	1st Class Doctors Quarter 2storey		2012	2	2370	4740	Good	No file	1 jpeg	
68	muktagachha	Muktagacha Health Complex	garraage		2012	1	450	450	Not so Good	No file	1 png	
69	muktagachha	Muktagacha Health Complex	4 th Class Quarter		1972	4	1350	5400	Not in use To be Dismantled	No file	1 png	
70	muktagachha	Muktagacha Health Complex	3rd Class Quarter-2		2012	2	1480	2960	Good	No file	1 png	
71	muktagachha	Muktagacha Health Complex	3rd Class Quarter with 4 story		1972	4	1350	5400	Need to Dismantled	No file	1 png	
72	muktagachha	Muktagacha Health Complex	2 storied 2nd class staff Quarter		2012	2	1920	3840	Good	No file	1 png	
73	muktagachha	Muktagacha Health Complex	Nurses Dormitory		1972	1	1050	1050	old, Need to Dismantled	No file	1 png	
74	muktagachha	Muktagacha Health Complex	1st Class Doctors Quarter		1972	3	1151	3453	Not so Good, need to be dismantled	No file	1 png	
75	muktagachha	Muktagacha Health Complex	1 class Officers Quarter		1972	2	1600	3200	Not so Good, need to be dismantled	No file	1 png	
76	nandail	Nandail Upazila Health Complex	1 storied mosque		2021	1	1315	1315	good	No file	No file	
77	nandail	Nandail Upazila Health Complex	1-storied substation building		2021	1	904	904	good	No file	No file	
78	nandail	Nandail Upazila Health Complex	2-storied family planning office		2021	2	829	1658	good	No file	No file	
79	nandail	Nandail Upazila Health Complex	2 storied abandoned quarter		1983	2	1102	2204	Not good. Needs repairs and renovations	No file	No file	
80	nandail	Nandail Upazila Health Complex	1-storied abandoned building		1983	1	1306	987	Not good.	No file	No file	
81	nandail	Nandail Upazila Health Complex	1-storied hall building		1983	1	915	915	Not good.	No file	No file	
82	nandail	Nandail Upazila Health Complex	4-storied Staff Quarter		2021	4	1800	7200	good	No file	No file	
83	nandail	Nandail Upazila Health Complex	1-storied Staff Quarter		1983	1	1356	1356	Not good, Needs repairs and renovations	No file	No file	
84	nandail	Nandail Upazila Health Complex	4-storied doctor Quarter		2021	4	2228	8912	good	No file	No file	
85	nandail	Nandail Upazila Health Complex	2-storied doctor Quarter		2021	2	2719	5438	good	No file	No file	
86	nandail	Nandail Upazila Health Complex	3-storied doctor Quarter		2021	3	2706	8118	good	No file	No file	
87	phulpur	Phulpur Upazila Health Complex	700 sft Staff Quarter building-2		1983	2	700	1400		No file	No file	
88	phulpur	Phulpur Upazila Health Complex	700 sft Staff quarter building-1		1983	2	700	1400		No file	No file	
89	phulpur	Phulpur Upazila Health Complex	Garage Building		2009	2	912	1824	Normal	No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
90	phulpur	Phulpur Upazila Health Complex	Staff Quarter-2		1983	2	1600	3200	Not good, Needs repairs and renovations	No file	No file	
91	phulpur	Phulpur Upazila Health Complex	Staff Quarter-1		1983	2	1600	3200	Not good,Needs repairs and renovations	No file	No file	
92	phulpur	Phulpur Upazila Health Complex	Nurses Dormitory		1983	1	900	900	Not good. Needs repair and renovation.	No file	No file	
93	phulpur	Phulpur Upazila Health Complex	03 storied Doctors Quarter		1983	3	3200	8000	Not good. Needs repairs and renovations	No file	No file	
94	phulpur	Phulpur Upazila Health Complex	2 storied Doctors quarter New		2009	2	2000	4000	Good, Needs repairs and renovations	No file	No file	

District Name: Naogaon

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	atrai	Atrai Upazilla Helth Complex New Building	1 xlsx	ok
2	atrai	Atrai Upazilla Helth Complex OLD Building	1 xlsx	ok
3	badalgachhi	Badalgachhi Upazilla Helth Complex New Bilding	1 xlsx	ok
4	badalgachhi	Badalgachhi Upazilla Helth Complex OLD Building	1 xlsx	ok
5	dhamoirhat	Dhamoirhat Upazilla Helth Complex New Building	1 xlsx	ok
6	dhamoirhat	Dhamoirhat Upazilla Helth Complex OLD Building	1 xlsx	ok
7	mahadebpur	Mahadebpur Upazilla Helth Complex New Building	1 xlsx	ok
8	mahadebpur	Mahadebpur Upazilla Helth Complex OLD Building	1 xlsx	ok
9	manda	Manda Upazilla Helth Complex New Building	1 xlsx	ok
10	manda	Manda Upazilla Helth Complex OLD Building	1 xlsx	ok
11	niamatpur	Niamatpur Upazilla Helth Complex New Building	1 xlsx	ok
12	niamatpur	Niamatpur Upazilla Helth Complex OLD Building	1 xlsx	ok
13	patnitala	Patnitala Upazilla Helth Complex New Building	1 xlsx	ok
14	patnitala	Patnitala Upazilla Helth Complex OLD Building	1 xlsx	ok
15	porsha	Porsha Upazilla Helth Complex New Building	1 xlsx	ok
16	porsha	Porsha Upazilla Helth Complex OLD Building	1 xlsx	ok
17	raninagar	Raninagar Upazilla Helth Complex New Building	1 xlsx	ok
18	raninagar	Raninagar Upazilla Helth Complex OLD Buildng	1 xlsx	ok
19	sapahar	Sapahar Upazilla Helth Complex New Building	1 xlsx	ok
20	sapahar	Sapahar Upazilla Helth Complex OLD Building	1 xlsx	ok

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	atrai	Atrai Upazilla Helth Complex New Building	2010	HED	5.3955 acre	20	1 dwg	No file	No file	No file	6734	6734	No file	No file	No file		
2	atrai	Atrai Upazilla Helth Complex OLD Building	1985	PWD	5.3955 acre	30	1 dwg	No file	No file	No file	10745	10745	No file	No file	No file		
3	badalgachhi	Badalgachhi Upazilla Helth Complex New Building	2011	HED	5.872818 acre	20	1 pdf	No file	No file	No file			No file	No file	No file		
4	badalgachhi	Badalgachi Upazilla Helth Complex OLD Building	1985	PWD	5.872818 acre	30	1 pdf	No file	No file	No file			No file	No file	No file		
5	dhamoirhat	Dhamoirhat Upazilla Helth	2006	HED	7.00150 acre	20	1 pdf	No file	No file	No file	6734	6734	No file	No file	No file		

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
		Complex New Building															
6	dhamoirhat	Dhamoirhat Upazilla Helth Complex Old Building	1986	PWD	7.00150 acre	30	1 pdf	No file	No file	No file	10745	10745	No file	No file	No file		
7	mahadebpur	Mohadevpur Upazilla Helth Complex New Building	2011	HED	6.14 acre	20	1 dwg	No file	No file	No file	6734	6734	No file	No file	No file		
8	mahadebpur	Mohadevpur Upazilla Helth Complex OLD Building	1986	PWD	6.14 acre	30	1 dwg	No file	No file	No file	10745	10745	No file	No file	No file		
9	manda	Manda Upazilla Helth Complex New Building	2011	HED	5.589 acre	20	1 dwg	No file	No file	No file			No file	No file	No file		
10	manda	Manda Upazilla Helth Complex OLD Building	1986	PWD	5.589 acre	30	1 dwg	No file	No file	No file			No file	No file	No file		
11	niamatpur	Niamatpur Upazilla Helth Complex New Building	2011	HED		20	1 dwg	No file	No file	No file			No file	No file	No file		
12	niamatpur	Niamatpur Upazilla Helth Complex OLD Building	1986	PWD		30	1 dwg	No file	No file	No file			No file	No file	No file		
13	patnitola	Patnitola Upazilla Helth Complex New Building	2010	HED	4.67978 acre	20	1 pdf	No file	No file	No file	6734	6734	No file	No file	No file		
14	patnitola	Patnitola Upazilla Helth Complex OLD Building	1986	PWD	4.67978 acre	30	1 pdf	No file	No file	No file	10745	10745	No file	No file	No file		
15	raninagar	Raninagar Upazilla Helth Complex New Building	2011	HED		20	1 dwg	No file	No file	No file			No file	No file	No file		
16	raninagar	Raninagar Upazilla Helth Complex OLD Building	1986	PWD		30	1 dwg	No file	No file	No file			No file	No file	No file		

CIVIL Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	atrai	Atrai Upazilla Helth Complex New Building	21	2.17	2	Deep	4	RCC	Usable	No file	Possible	Renovation is Carried out	
2	atrai	Atrai Upazilla Helth Complex OLD Building	24	1	2	Footing	2	Load Bearing Brick	Vulnerable Building	No file	Not Possible	Renovation is Carried out	
3	badalgachhi	Badalgachhi Upazilla Helth Complex New Building	21	2.17	2	Deep	4	RCC	Usable	No file	Possible	Renovation is Carried out	

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
4	badalgachhi	Badalgachhi Upazilla Helth Complex OLD Building	24	1	2	Footing	2	Load Bearing Brick	Not suitable for use	No file	Not Possible	Renovation is Carried out	
5	dhamoirhat	Dhamoirhat Upazilla Helth Complex New Building	21	2.17	2	Deep	4	RCC	Usable	No file	Possible	Renovation is Carried out	
6	dhamoirhat	Dhamoirhat Upazilla Helth Complex OLD Building	24	1	2	Footing	2	Load Bearing Brick	Not suitable for use	No file	Not Possible	Renovation is Carried out	
7	mahadebpur	Mahadebpur Upazilla Helth Complex New Building	21	2.17	2	Deep	4	RCC	Usable	No file	Possible	Renovation is Carried out	
8	mahadebpur	Mahadebpur Upazilla Helth Complex OLD Building	24	1	2	Footing	2	Load Bearing Brick	Vulnerable Building	No file	Not Possible	Renovation is Carried out	
9	manda	Manda Upazilla Helth Complex New Building	21	2.17	2	Deep	4	RCC	Usable	No file	Possible	Renovation is Carried out	
10	manda	Manda Upazilla Helth Complex OLD Building	24	1	2	Footing	2	Load Bearing Brick	Not suitable for use	No file	Not Possible	Renovation is Carried out	
11	niamatpur	Niamatpur Upazilla Helth Complex New Building	21	2.17	2	Deep	4	RCC	Usable	No file	Possible	Regular renovation is Carried out	
12	niamatpur	Niamatpur Upazilla Helth Complex OLD Building								No file			
13	niamatpur	Niamatpur Upazilla Helth Complex OLD Building	24	1	2	Footing	2	Load Bearing Brick	Vulnerable Building	No file	Not Possible	Regular renovation is Carried out	
14	patnitala	Patnitala Upazilla Helth Complex New Building	21	2.17	2	Deep	4	RCC	Usable	No file	Possible	Renovation is Carried out	
15	patnitala	Patnitala Upazilla Helth Complex OLD Building	24	1	2	Footing	2	Load Bearing Brick	Vulnerable Building	No file	Not Possible	Renovation is Carried out	
16	porsha	Porsha Upazilla Helth Complex New Building	32	2.17	3	Deep	4	RCC	Usable	No file	Possible	Renovation is Carried out	
17	porsha	Porsha Upazilla Helth Complex OLD Building	24	1	2	Footing	2	Load Bearing Brick	Not suitable for use	No file	Not Possible	Regular renovation is Carried out	
18	raninagar	Raninagar Upazilla Helth Complex New Building	21	2.17	2	Deep	4	RCC	Usable	No file	Possible	Renovation is Carried out	
19	raninagar	Raninagar Upazilla Helth Complex OLD Buildng	24	1	1	Footing	2	Load Bearing Brick	Vulnerable Building	No file	Not Possible	Renovation is Carried out	
20	sapahar	Sapahar Upazilla Helth Complex New Building	21	2.17	2	Deep	4	RCC	Usable	No file	Possible	Renovation is Carried out	
21	sapahar	Sapahar Upazilla Helth Complex OLD Building	24	1	2	Footing	2	Load Bearing Brick	Vulnerable Building	No file	Not Possible	Renovation is Carried out	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	badalgachhi	Badalgachhi Upazilla Helth Complex Building		1		Septic Tank		No					
2	dhamoirhat	Dhamoirhat Upazilla Helth Complex Building		1		Septic Tank		No					

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
3	mahadebpur	Mahadebpur Upazilla Helth Complex Building		1		Septic Tank		No					
4	manda	Manda Upazilla Helth Complex Building		1		Septic Tank		No					
5	niamatpur	Niamatpur Upazilla Helth Complex Building		1		Septic Tank		No					
6	niamatpur	Niamatpur Upazilla Helth Complex OLD Building											
7	patnitala	Patnitala Upazilla Helth Complex Building		1		Septic Tank		No					
8	porsha	Porsha Upazilla Helth Complex Building		1		Septic Tank		No					
9	porsha	Porsha Upazilla Helth Complex New Building											
10	raninagar	Raninagar Upazilla Helth Complex Building		1		Septic Tank		No					

District Name: Narail

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	kalia	Kalia Upozila Health Complex	1 xlsx	
2	lohagara	Lohagara Upozila Health Complex	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	kalia	Kalia Upozila Health Complex	2005	HED	Avilable	11	1 dwg, 1 pdf	No file	No file	No file	7395.25	GF-2465.01, FF-2465.01, 2F-2465.01	No file	No file	No file	8 feet	
2	lohagara	Lohagara Upozila Health Complex	2015	HED	Not Avilable	19	1 pdf	No file	1 pdf	No file	15574.66	GF=5191.55,1F=5191.55, 2F=5191.55	No file	No file	No file	8 feet	

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	lohagara	Lohagara Upozila Health Complex	30	2	3	Footing	6	RCC	RCC Structure Foundation	No file	Possible	New Construction for 30 Bed	Vertical Extension is Possible

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	lohagara	Lohagara Upozila Health Complex	0	1	No	Septic Tank	11.12	No	0	Poor	Need	Some drainage is done to the nearby municipal drain.	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	lohagara	Lohagara Upozila Health Complex	0	879	533	0	200	400	Yes	Yes	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	lohagara	Lohagara Upozila Health Complex	20 Bed Hospital (Very Old Brick structural), Doctor Quarter	15	1990		1000	15000	Very old building without 1 Nos building	No file	No file	

District Name: Narayanganj

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	araiharar	Araiharar Upazila Health Complex	1 xlsx	ok
2	rupganj	Rupganj Upazila Health Complex	1 xlsx	
3	sonargaon	Upazila Health Complex, Sonargaon.	1 xlsx	ok

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	araiharar	Araiharar Upazila Health Complex	1974	PWD	2400 sft pond is exist	50	1 pdf	1 pdf	1 pdf	1 pdf	8024	15778	1 pdf	No file	1 jpeg	0.8 m	
2	bandar	Upazila Health Complex, bandar.	1995	PWD	no	50	1 pdf	1 pdf	1 pdf	1 pdf	8600	gf=8600 ff=8600 2ndf=5785	1 pdf	No file	1 mp4	6.08m	
3	rupganj	Rupganj Upazila Health Complex	1972	PWD	0	50	1 dwg, 1 pdf	1 jpeg	1 pdf	1 pdf	15778	Old Building- GF 8024, 1st Fl 7500 and New building GF 7754, 1st Fl 7754 , 2nd fl 4000	No file	No file	1 jpeg	0.6m on respect of Sitalakkhaya River	This building is abandoned. This building needs to be demolished. New building need to be constructed
4	sonargaon	Upazila Health Complex, Sonargaon.	1970	PWD	68 decimal plot of land is situated adjacent to the existing premises.	50	1 dwg	1 pdf	1 pdf	1 pdf	8024	Gf=8024 ff=8024 new building gf=7754 ff=7754 2ndf=7754	1 jpeg	No file	1 mp4	7.85	The existing old building was constructed in 1970 and has a plinth area 8024 sqft and two storied foundation. A new building was constructed in 2022 with a plinth area of 7754.00 sqft. The building has a five-story foundation and currently stands as a three-story structure with17 beds

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	araiharar	Araiharar Upazila Health Complex	22	1	2	Footing	2	Load Bearing Brick	Building is abounded. Need to be re constructed	No file	Not Possible	Unknown	
2	bandar	Upazila Health Complex, bandar.	30	2	3	Footing	3	RCC	not good	1 pdf	info not available	unknown	প্লিন্থ এরিয়াঃ ৮৬০০ বর্গফুট (২ তলা ভবনের আংশিক ওয় তলা আরসিসি ফ্রেম স্ট্রাকচার) নির্মাণ সালঃ ১৯৯৫ নির্বাহক এজেন্সিঃ গণপূর্ত অধিদপ্তর বর্তমান স্ট্রাকচারাল অবস্থাঃ ভবনটিতে ৫০ শয্যার হাসপাতাল কার্যক্রম চলমান। মেরামতের অভাবে ভবনটির বিভিন্ন স্থানে প্লাস্টার খসে পড়ছে। ভবনটি ব্যবহার উপযোগী। ভবনটির ভীত কত তলা তার তথ্য খুঁজে পাওয়া যায়নি তবে আপাতত মনে হচ্ছে ৩তলা ভীত বিশিষ্ট।
3	rupganj	Rupganj Upazila Health Complex	24	2.5	2	Footing	2	Load Bearing Brick	This building is abandoned. This building needs to be demolished. New building need to be constructed	No file	Not Possible	Unknown	

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
4	sonargaon	Upazila Health Complex, Sonargaon.	20.5	0.5	2	Footing	2		Risky	1 pdf	Not Possible	unknown	The existing old building was constructed in 1970 and has a plinth area 8024 sqft and two storied foundation. This building is risky.

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	araihazar	Araihazar Upazila Health Complex	0	1	No	Septic Tank	0	No	0	Little	Yes	No	
2	bandar	Upazila Health Complex, bandar.	0	2	0	Septic Tank	0	No	0	no	yes	no	
3	rupganj	Rupganj Upazila Health Complex	0	1	No	Septic Tank	0	No	0	Yes, but little capacity	Yes	Shitakkhya River	
4	sonargaon	Upazila Health Complex, Sonargaon.	0	2	0	Septic Tank	0	No	0	no	yes	no	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	araihazar	Araihazar Upazila Health Complex	0	1700	0	1700	15	10	Yes	No	
2	bandar	Upazila Health Complex, bandar.	0	1479.83	401.58	0	28	Internal road width 24.75 ft	No	No	
3	rupganj	Rupganj Upazila Health Complex	500	900	500	200	50	20 ft width	Yes	No	
4	sonargaon	Upazila Health Complex, Sonargaon.	0	1981.5	402	1079	16	Internal road width 15.5 ft	No	No	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional Info (Capacity, Demand etc)
1	araihazar	Araihazar Upazila Health Complex	0	0		20	40		Fire Extinguisher only, insufficient	60	0		Not Present	
2	bandar	Bandar Upazilla Health Complex	0	0	0	26	40		Fire Extinguisher 10nos (Date expired)	20	22	Centrifugal completely faulty/damaged, Submersible Running	Not Present	Needed
3	rupganj	Rupganj Upazila Health Complex	0	0	N/A	30	40		Fire Extinguishers (Expired)	22.5	10	3 Nos 7.5HP pumps are running, 02 Nos Centrifugal Pump completely damaged condition	Not Present	
4	sonargaon	Sonargaon Upazila Health Complex	0	0		18	40		Fire Extinguisher only, insufficient, few expired	60	0		Not Present	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	araiharar	Araiharar Upazila Health Complex	REB	Yes	110	111	0	Partial Functional, Needs	30	150	0	0	100RM (DOG) Aluminium HT Cable (overhead length=120m), 100RM aluminium WASP overhead cable	25RM, 16RM	
2	bandar	Bandar Upazila Health Complex	REB	Yes	200	200	0	LT panel damaged, PFI running, MDB partial running	0	150	0	0	95RM LT Cable , Aluminium Cable DoG 100RM HT Cable	100 WASP overhead, 25RM, 10RM,	
3	rupganj	Rupganj Upazila Health Complex	REB	Yes	200	200	0	Needs Repair	10	150	0	0	100RM (DOG) Aluminium HT Cable (overhead length=120m), 100RM aluminium WASP overhead cable	25RM, 16 RM and 10RM cable	
4	sonargaon	Sonargaon Upazila Health Complex	REB	Yes	110	111	0	Partial Functional, Needs repair/replacement	0	150	0	0	100RM (DOG) Aluminium HT Cable (overhead length=120m), 100RM aluminium WASP overhead cable	25RM, 16 RM and 10RM cable	

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	araiharar	Araiharar Upazila Health Complex	No	0	0	No Medical gas plant present	No	No	No	No	No	0	All Ancillary Electrical Items need to install	
2	bandar	Bandar Upazila Health Complex	No	0	0	Full Medical Gas System required with VIE tank piping system	Yes	No	No	No	No	0	Compound Security light, PA and Sound System, Computer Network system, PABX system, CCTV system, Neon Poly sign board required	
3	rupganj	Rupganj Upazila Health Complex	No	0	0		Yes	Yes	No	No	Yes	1	CCTV system is insufficient, PA system only present in Seminar Room, Compound & Security Light insufficient, PABX & Internet System need to be installed	Need to install Lightning protection system
4	sonargaon	Sonargaon Upazila Health Complex	No	0	0	No medical gas plant existing	No	No	No	No	Yes	0	All Ancillary Electrical Items need to install, CCTV is present but insufficient and outdated	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	araiharar	Araiharar Upazila Health Complex	Doctors Dormitory	1	1974	1	1200	1200	Abandoned	No file	1 jpeg	
2	araiharar	Araiharar Upazila Health Complex	Old Staff Quarter building	3	1974	1	4500	4500	Need to be new constructed	No file	1 jpeg	ok
3	araiharar	Araiharar Upazila Health Complex	old Nurse quarter building	1	1974	2	1400	2800	Need to be new constructed	No file	1 jpeg	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
4	araihazar	Araihazar Upazila Health Complex	Old doctor Quarter building	1	1974	2	2200	4400	Need to be new constructed	No file	1 jpeg	
5	bandar	Upazila Health Complex, bandar.	Mosque	1	2010	1	1038	0.01	usable	No file	1 jpeg	Usable
6	bandar	Upazila Health Complex, bandar.	Garage	1	2010	1	500	500	usable	No file	1 jpeg	Usable
7	bandar	Upazila Health Complex, bandar.	Garrage cum driver residence	1	1995	2	350	700	Abandoned	No file	1 jpeg	Abandoned building
8	bandar	Upazila Health Complex, bandar.	UH & FPO Residence	1	1995	1	1000	1000	Unusable	No file	1 jpeg	Unusable
9	bandar	Upazila Health Complex, bandar.	Family Planning office	1	2010	2	1650	3300	usable	No file	1 jpeg	usable
10	bandar	Upazila Health Complex, bandar.	1250 sft Quarter	1	1995	3	2780	8340	Unusable	No file	1 jpeg	Unusable
11	bandar	Upazila Health Complex, bandar.	1000 sft Quarter	1	1995	2	2280	4560	Unusable	No file	1 jpeg	Unusable
12	bandar	Upazila Health Complex, bandar.	Nurses Dormitory	1	1995	1	1600	1600	Usable	No file	1 jpeg	Usable
13	bandar	Upazila Health Complex, bandar.	600 sft residential building	1	1995	3	1720	5160	Usable	No file	1 jpeg	Usable
14	bandar	Upazila Health Complex, bandar.	800 sft residential building	1	1995	2	1800	3600	Usable	No file	1 jpeg	Usable
15	bandar	Upazila Health Complex, bandar.	Employee Quarter-2	1	1995	2	1250	2500	Usable	No file	1 jpeg	Usable
16	bandar	Upazila Health Complex, bandar.	Employee Quarter-1	1	1995	2	3088	6176	Usable	No file	1 jpeg	Usable
17	rupganj	Rupganj Upazila Health Complex	Old Staff Quarter building	1	1972	2	2000	4000	Need to be new constructed	No file	1 jpeg	
18	rupganj	Rupganj Upazila Health Complex	Old doctor Quarter building	1	1972	2	2100	4200	Need to be new constructed	No file	1 jpeg	
19	rupganj	Rupganj Upazila Health Complex	Staff Quarter	1	2008	3	1500	4500	livable	No file	1 jpeg	
20	rupganj	Rupganj Upazila Health Complex	Doctor Quarter	1	2008	3	2200	6600	livable	No file	1 jpeg	
21	sonargaon	Upazila Health Complex, Sonargaon.	Sub-station	1	2018	1	1450	1450	Usable	No file	1 jpeg	Usable.
22	sonargaon	Upazila Health Complex, Sonargaon.	Mosque	1	2018	2	3022	6044	Usable	No file	1 jpeg	Usable Mosque
23	sonargaon	Upazila Health Complex, Sonargaon.	1200 sft residential building	1	2018	2	2620	5240	Usable	No file	1 jpeg	Usable , Doctors Qtr.
24	sonargaon	Upazila Health Complex, Sonargaon.	1000 sft residential building	1	2018	1	1150	1150	Usable	No file	1 jpeg	Usable , Doctors Qtr.
25	sonargaon	Upazila Health Complex, Sonargaon.	1000 sft residential building	1	2018	2	3150	6300	Usable	No file	1 jpeg	Usable , Doctors Qtr.
26	sonargaon	Upazila Health Complex, Sonargaon.	800 sft residential building	1	2018	2	1850	2800	Usable	No file	1 jpeg	Usable
27	sonargaon	Upazila Health Complex, Sonargaon.	600 sft residential building	1	2018	3	1350	2400	Usable	No file	1 jpeg	Usable
28	sonargaon	Upazila Health Complex, Sonargaon.	500 sft residential building	1	1970	1	2500	2500	Abandoned	No file	1 jpeg	Abandoned building

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
29	sonargaon	Upazila Health Complex, Sonargaon.	800 sft residential building	1	1970	2	1800	3600	Abandoned	No file	1 jpeg	Abandoned building
30	sonargaon	Upazila Health Complex, Sonargaon.	600 sft residential building	1	1970	3	1350	4050	Abandoned	No file	1 jpeg	Abandoned building

District Name: Narsingdi

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	belabo	Belabo Upazila Health complex	1 xlsx	
2	monohardi	Monohordi Upazila Health Complex	No file	
3	palash	Palash Upazila Health Complex	No file	
4	raipura	Raipura Upazila Health Complex	No file	
5	shibpur	Shibpur 50 -Bed Upazilla Helth Complex	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	belabo	Belabo Upazila Health complex	1985	PWD	yes	50	1 dwg	1 pdf	1 pdf	1 dwg	51100	GF=23450,1st floor=23450,2nd floor=4200	1 dwg	No file	9 jpegs		
2	palash	Palash Upazila Health Complex	1993	PWD	Yes	50	1 dwg	No file	No file	1 pdf	7085	7085	1 dwg	No file	1 jpeg		
3	raipura	Raipura Upazila Health complex	1982	PWD	yes	50	1 dwg	1 pdf	1 pdf	No file	51100	GF=23450,1st floor=23450,2nd floor=4200	1 dwg	No file	4 jpegs		
4	shibpur	Shibpur 50 - Bed Upazilla Helth Complex	1983	PWD	yes	50	1 dwg	1 pdf	1 pdf	1 dwg	510100	GF-23000, 1st Floor- 23000, 2nd Floor- 4200	1 dwg	No file	No file		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	belabo	Belabo 50 -Bed Upazilla Helth Complex (New Building)	33	2	3	Footing	4	RCC	Good	No file	Not Possible	Light Repair	
2	belabo	Belabo Upazila Health complex(Old building)	22	2	2	Footing	4	Load Bearing Brick	not good	No file	Not Possible	light repair	
3	raipura	Raipura Upazila Health complex(new building)	33	2	3	Footing		RCC		No file	info not available		
4	raipura	Raipura Upazila Health complex(Old building)	22	2	2	Footing		Load Bearing Brick		No file	Not Possible		
5	shibpur	Shibpur 50 -Bed Upazilla Helth Complex (New Building)	33	2	3	Footing	4	RCC	Good	No file	Not Possible	Light Repair	
6	shibpur	Shibpur 50 -Bed Upazilla Helth Complex (Old Building)	22	2	2	Footing	3	Load Bearing Brick	Not Good	No file	Not Possible	Light Repair	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	belabo	Belabo Upazila Health complex	30000	1		Septic Tank	0	No	0	not good	yes	canel in 400 ft	
2	raipura	Raipura Upazila Health complex	30000	1		Septic Tank	0	No		not good		drain in 100 ft	
3	shibpur	Shibpur 50 -Bed Upazilla Helth Complex	30000	1		Septic Tank		No	0	Not Good	yes	cannel/Pouroslove drainage System	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	belabo	Belabo Upazila Health complex		1590			18	internal road average 12 ft	No	Yes	
2	raipura	Raipura Upazila Health complex		1980			14	internal road average 10 ft			
3	shibpur	Shibpur 50 -Bed Upazilla Helth Complex		2155			18	avarage 17 ft wide Road infront of Hospital other road 10 ft	No	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional Info (Capacity, Demand etc)
1	belabo	Belabo Upazilla Health Complex	0	0		6	36		Not available	10	0	Demand: 14HP, Repair needed: 2 nos submersible pump	Not Present	
2	monohardi	Monohardi Upazilla Health Complex	0			24	40		Not available	5	3	Demand: 12HP, Repair: 2 submersible pump	Not Present	
3	palash	polash Upazilla Health Complex	0	0	N/A	12	40		Not available	10	0	Demand: 14HP, Repair needed: 2 nos submersible pump	Not Present	
4	raipura	Raipura Upazilla Health Complex	0	0	N/A	10	40		Not available	10	0	Demand: 14HP, Repair needed: 2 nos submersible pump	Not Present	
5	shibpur	Shibpur Upazilla Health Complex	0			6	36		Not available	2	1	Demand: 10HP, Repair needed: 1 submersible pump	Not Present	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	belabo	Belabo Upazilla Health Complex	REB	Yes	65	75	0	not available	0	150	0	0	50rm Aluminium cable, Length 110 mtr Transformer to overhead pole;	50 sqmm NYY, Length 350 mtr (overhead pole to MDB)	

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
2	monohardi	Monohardi Upazilla Health Complex	REB	Yes	100	150	0	Repair/maintenance required for LT, HT, PFI, MDB.	0	150	0	0	HT-50 sqmm cable, Length 90mtr: LT-70sqmm NYY Cable, 110 mtr	50 sqmm NYY, Length 300mtr (overhead pole to MDB)	
3	palash	polash Upazilla Health Complex	REB	Yes	25	35	0	not available	0	150	0	0	50 sqmm Aluminium cable, Length 200' Transformer to overhead pole;	16 sqmm NYY, Length 250' overhead pole to MDB	
4	raipura	Raipura Upazilla Health Complex	REB	Yes	25	35	0	not available	0	150	0	0	50 sqmm Aluminium cable, Length 250' Transformer to overhead pole;	16 sqmm NYY, Length 240' overhead pole to MDB	
5	shibpur	Shibpur Upazilla Health Complex	REB	Yes	35	45	0	not available	0	150	0	0	50rm Aluminium cable, Length 50mtr Transformer to overhead pole;	25 sqmm NYY, Length 150mtr (overhead pole to MDB)	

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	belabo	Belabo Upazilla Health Complex	No	0	0		Yes	No	No	No	Yes	0	medical gas plant, cctv, pabx, security light, computer network, pa system	Lightning protection system is required
2	monohardi	Monohardi Upazilla Health Complex	No	0	0		Yes	No	No	No	Yes	0	medical gas plant, cctv, pabx, security light, computer network, pa system	Lightning protection system is required
3	palash	polash Upazilla Health Complex	No	0	0		Yes	No	No	No	Yes	1	medical gas plant, cctv, pabx, security light, computer network, pa system	Lightning protection system is required
4	raipura	Raipura Upazilla Health Complex	No	0	0		Yes	No	No	No	Yes	1	medical gas plant, cctv, pabx, security light, computer network, pa system	Lightning protection system is required
5	shibpur	Shibpur Upazilla Health Complex	No	0	0		Yes	No	No	No	Yes	0	medical gas plant, cctv, pabx, security light, computer network, pa system	Lightning protection system is required

District Name: Natore

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	bagatipara	Bagatipara Upazila Health Complex, Natore	No file	
2	baraigram	Boraigram Upazila Health Complex, Natore	No file	
3	gurudaspur	Gurudaspur Upazila Health Complex, Natore	No file	
4	lalpur	Lalpur Upazila Health Complex, Natore	No file	
5	naldanga	Naldanga Upazila Health Complex, Natore	No file	
6	singra	Singra Upazila Health Complex, Natore	No file	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	bagatipara	Bagatipara Upazila Health Complex, Natore	1985	HED	Available	31	1 dwg	No file	1 pdf	1 jpeg	23970	New Building GF- 8640.00 sft, 1st Floor-8640.00 sft, 2nd Floor-8640.00 sft. Old Building GF-15330.00 sft, 1st Floor-15330.00 sft	1 jpeg	No file	7 jpegs	NA	NA
2	baraigram	Boraigram Upazila Health Complex, Natore	1973	Other		50	1 dwg	No file	No file	No file	16312	New Building GF- 7066.00 sft, 1st Floor-7066.00 sft, 2nd Floor-7066.00 sft, 3rd Floor-7066.00 sft. Old Building GF-9246.00 sft, 1st Floor-9246.00 sft	No file	No file	No file		
3	gurudaspur	Gurudaspur Upazila Health Complex, Natore	1973	Other		50	1 dwg	No file	No file	No file	17436	Old Building GF- 8331.00 sft, 1st Floor-8331.00 sft. New Building GF- 6509.00, 1st Floor- 6509.00 sft. EPI GF- 2596.00 sft, 1st Floor- 2596.00 sft	No file	No file	No file		
4	lalpur	Lalpur Upazila Health Complex, Natore	1973	HED		50	1 dwg	No file	No file	No file	16150	GF-16150.00, 1st Floor- 16150.00	No file	No file	No file		
5	naldanga	Naldanga Upazila Health Complex, Natore	2018	HED	Available	31	1 dwg	No file	No file	No file	10829	GF- 10829.00 sft, 1st Floor- 10455.00 sft, 2nd Floor- 10455.00.00 sft, 3rd Floor- 94500.00 Sft	No file	No file	6 jpegs, 1 mp4		
6	singra	Singra Upazila Health Complex, Natore	1960	Other	Available	50	1 dwg	No file	No file	No file	13797.51	Old Building GF- 7454.72 sft, 1st Floor-7454.72 sft. New Building GF- 6342.79 sft , 1st Floor- 6342.79 sft, 2nd Floor- 6342.79 sft, 3rd Floor- 2200.00 sft	No file	No file	7 jpegs		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	bagatipara	Bagatipara Upazila Health Complex, Natore (New Building)	31	2	3	Deep	5	RCC	Old building- Brick Structure	No file	Possible		
2	bagatipara	Bagatipara Upazila Health Complex, Natore (Old building)	21	1	2		2	Load Bearing Brick	2 storied Brick Foundation	No file	Not Possible		
3	baraigram	Boraigram Upazila Health Complex, Natore (New Building)	2	44	4	Mat	4	RCC	RCC frame Structure Building	No file	Not Possible		
4	baraigram	Boraigram Upazila Health Complex, Natore (Old Building)	2	22	2	Footing	2	RCC	RCC frame Structure Building	No file	Not Possible		
5	gurudaspur	Gurudaspur Upazila Health Complex, Natore (New Building)	2	33	3	Footing	3	RCC	RCC frame Structure Building	No file	Not Possible		
6	gurudaspur	Gurudaspur Upazila Health Complex, Natore (Old Building)	1.5	22	2	Footing	2	RCC		No file	Not Possible		
7	lalpur	Lalpur Upazila Health Complex, Natore	1.5	22	2			RCC		No file	Not Possible		
8	naldanga	Naldanga Upazila Health Complex, Natore	2.5	44	4	Mat	5	RCC	RCC frame Structure Building	No file	Not Possible	New Building	
9	singra	Singra Upazila Health Complex, Natore (New Building)	2.75	44	4	Mat	4	RCC	RCC frame Structure Building	No file	Not Possible		
10	singra	Singra Upazila Health Complex, Natore (Old Building)	1.5	22	2	Footing	2	RCC		No file	Not Possible		

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	bagatipara	Bagatipara Upazila Health Complex, Natore	0	2	2.00 Nos Hand Tubewell	Septic Tank	0	No	0	460.25 Rm	250.00 Rm	NA	
2	baraigram	Boraigram Upazila Health Complex, Natore	0	2	2.00 Nos Hand Tubewell	Septic Tank	0	No	0	1325.00	950.00	None	
3	gurudaspur	Gurudaspur Upazila Health Complex, Natore	0	2	2.00 Nos Hand Tubewell	Septic Tank	0	No	0	Apron Drain 853.00 Rft	2300.00 rft	Pond	
4	lalpur	Lalpur Upazila Health Complex, Natore	0	2	2.00 Nos Hand Tubewell	Septic Tank	0	No	0	1140.00 rft	2250.00 Rft	None	
5	naldanga	Naldanga Upazila Health Complex, Natore	0	1	2 Nos Hand Tubewell	Septic Tank	0	No	0	1940.00 ft	720.00 ft	Pond	
6	singra	Singra Upazila Health Complex, Natore	0	2	2.00 Nos Hand Tubewell	Septic Tank	0	No	0	Apron Drain 1150.00 Rft	1750.00 Rft	River	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	bagatipara	Bagatipara Upazila Health Complex, Natore	0	2362	0	0	12	RCC Road	Yes	No	
2	baraigram	Boraigram Upazila Health Complex, Natore		2442			18	RCC Road		No	
3	gurudaspur	Gurudaspur Upazila Health Complex, Natore		2458			18	RCC Road		No	
4	lalpur	Lalpur Upazila Health Complex, Natore		2300			33	RCC Road	Yes	Yes	
5	naldanga	Naldanga Upazila Health Complex, Natore			750	0	12	RCC Road	No	No	
6	singra	Singra Upazila Health Complex, Natore		1771		500	12	RCC Road		Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	bagatipara	Bagatipara Upazila Health Complex, Natore	0	0	0	16			None	2	0		Not Present	
2	baraigram	Baraigram Upazila Health Complex, Natore	0	0	0	14	0	0	0	30	0	0	Not Present	0
3	gurudaspur	Gurudaspur Upazila Health Complex, Natore	0	0	0	22	0	0	0	18	0	0	Not Present	0
4	lalpur	Lalpur Upazila Health Complex, Natore	0	0	0	20	0	0	0	18		0	Not Present	0
5	naldanga	Naldanga Upazila Health Complex, Natore	0	0	0	16			none	17	0		Not Present	
6	singra	singra Upazila Health Complex, Natore	0	0	0	20	0	0	0	18	0	0	Not Present	0

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	bagatipara	Bagatipara Upazila Health Complex, Natore	REB	Yes	30	150		Yes	60		5	0	HT-95 Rm, LT-70 Rm		
2	baraigram	Baraigram Upazila Health	REB	Yes	80	150	0	0	6	5	0	0	0	0	

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
		Complex, Natore													
3	gurudaspur	Gurudaspur Upazila Health Complex, Natore	REB	Yes	80	0	0	old existing	10	0	0	0	0	0	
4	lalpur	Lalpur Upazila Health Complex, Natore	REB	Yes	80	0	0	old existing	5.2		0	0	0	0	
5	naldanga	Naldanga Upazila Health Complex, Natore	REB	Yes	80	150	0	new	40	0	5	0	0	0	
6	singra	Singra Upazila Health Complex, Natore	REB	Yes	80	0	0	old existing	0	0	0	0	0	0	

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	bagatipara	Bagatipara Upazila Health Complex, Natore	No	0	0		Yes	No	No	No	Yes	0		
2	baraigram	Baraigram Upazila Health Complex, Natore	No	0	0	0	No	No	No	No	Yes	0	0	0
3	gurudaspur	Gurudaspur Upazila Health Complex, Natore	No	0	0	0	No	No	No		Yes	0	0	0
4	lalpur	Lalpur Upazila Health Complex, Natore	No	0	0	0	Yes	No	No	No	Yes	0	0	0
5	naldanga	Naldanga Upazila Health Complex, Natore	No	0	0	0	Yes	No	No	No	Yes	0	0	0
6	singra	Singra Upazila Health Complex, Natore	No	0	0	0	No	No	No	No	Yes	0	0	0

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	bagatipara	Bagatipara Upazila Health Complex, Natore	Hospital Old Building	11	1985	2	15330	30660	Useable	No file	1 jpeg	
2	bagatipara	Bagatipara Upazila Health Complex, Natore	OPD Building (New Building)	10	2022	3	8640	25920	Useable	1 pdf	1 jpeg	
3	bagatipara	Bagatipara Upazila Health Complex, Natore	Sub station building	9		1	535			No file	1 jpeg	
4	bagatipara	Bagatipara Upazila Health Complex, Natore	Staff Quarter	8	2022	2	976	1952	Useable	No file	1 jpeg	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
5	bagatipara	Bagatipara Upazila Health Complex, Natore	Staff Quarter	7	1985	2	1314	2628	Useable	No file	1 jpeg	
6	bagatipara	Bagatipara Upazila Health Complex, Natore	Nurse Quater	6	1985	2	527	1054	Useable	No file	1 jpeg	
7	bagatipara	Bagatipara Upazila Health Complex, Natore	Staff Quarter	5	1985	2	1312	2624	Useable	No file	1 jpeg	
8	bagatipara	Bagatipara Upazila Health Complex, Natore	Doctor Dormitory	4		2	1285	2571	Useable	No file	1 jpeg	
9	bagatipara	Bagatipara Upazila Health Complex, Natore	Doctors Consultant Dormitory	3	2022	5	1132	5660	Useable	No file	2 jpegs	
10	bagatipara	Bagatipara Upazila Health Complex, Natore	Nurse Dormitory	2	2022	5	982	4909	Useable	No file	2 jpegs	
11	bagatipara	Bagatipara Upazila Health Complex, Natore	ARM Quarter	1	2022	2	1440	2880	Useable	No file	1 jpeg	
12	baraigram	Boraigram Upazila Health Complex, Natore	Mosque	15		1	1130	1130		No file	1 jpeg	
13	baraigram	Boraigram Upazila Health Complex, Natore	Wash Block	14		1	678	678		No file	1 jpeg	
14	baraigram	Boraigram Upazila Health Complex, Natore	Family Planning 2 Std Bldg	13		2	1378	2756		No file	1 jpeg	
15	baraigram	Boraigram Upazila Health Complex, Natore	Doctors Dormitory 3 Std Bldg	12		3	2794	8382		No file	1 jpeg	
16	baraigram	Boraigram Upazila Health Complex, Natore	Doctor & Consultant Dormitory 4std Bldg	11		4	1124	4496		No file	1 jpeg	
17	baraigram	Boraigram Upazila Health Complex, Natore	Family Planning Conference 1 Std Bldg	10		1	928	928		No file	1 jpeg	
18	baraigram	Boraigram Upazila Health Complex, Natore	Ambulance garrage cum Driver Shed 2Std Bldg	9		2	333	666		No file	1 jpeg	
19	baraigram	Boraigram Upazila Health Complex, Natore	Staff Dormitory 2 std Bldg	8		2	972	1944		No file	1 jpeg	
20	baraigram	Boraigram Upazila Health Complex, Natore	Pump House	6		1	343	343		No file	1 jpeg	
21	baraigram	Boraigram Upazila Health Complex, Natore	Nurse Dormitory 3 std Bldg	5		3	984	2952		No file	1 jpeg	
22	baraigram	Boraigram Upazila Health Complex, Natore	Sub Station Bldg	4		1	597	597		No file	1 jpeg	
23	baraigram	Boraigram Upazila Health Complex, Natore	Third Class Staff Qtr 1 Std Bldg	3		1	646	646		No file	1 jpeg	
24	baraigram	Boraigram Upazila Health Complex, Natore	Third Class Staff Qtr 2 Std Bldg	2	1973	2	2915	5830		No file	1 jpeg	
25	baraigram	Boraigram Upazila Health Complex, Natore	Fouth Class Staff Qtr 2 Std Bldg	1	1973	2	1651	3302		No file	1 jpeg	
26	baraigram	Boraigram Upazila Health Complex, Natore (New Building)	Garrage	7		1	432	432		No file	1 jpeg	
27	gurudaspur	Gurudaspur Upazila Health Complex, Natore	Mosque	15		1	1551	1551		No file	1 jpeg	
28	gurudaspur	Gurudaspur Upazila Health Complex, Natore	Family Conference 1 Std Bldg	14		1	920	920		No file	1 jpeg	
29	gurudaspur	Gurudaspur Upazila Health Complex, Natore	Ambulance garrage 1 Std Buldg	12		1	368	368		No file	1 jpeg	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
30	gurudaspur	Gurudaspur Upazila Health Complex, Natore	Family Planning Office	10		2	921	1842		No file	1 jpeg	
31	gurudaspur	Gurudaspur Upazila Health Complex, Natore	Garrage 1 Std Bldg	10		1	393	393		No file	1 jpeg	
32	gurudaspur	Gurudaspur Upazila Health Complex, Natore	Hasnahrena Doctors Dormitory 2 Std Bldg	9		2	2813	5626		No file	1 jpeg	
33	gurudaspur	Gurudaspur Upazila Health Complex, Natore	Rojonigondha Nurses Dormitory 2Std Bldg	8		2	2324	4648		No file	1 jpeg	
34	gurudaspur	Gurudaspur Upazila Health Complex, Natore	Shully 2 std Staff Qtr	7	1973	2	1795	3590		No file	1 jpeg	
35	gurudaspur	Gurudaspur Upazila Health Complex, Natore	Pump House	6		1	471	471		No file	1 jpeg	
36	gurudaspur	Gurudaspur Upazila Health Complex, Natore	Surovi 1 Std Staff Qtr	5	1973	1	1163	1163		No file	1 jpeg	
37	gurudaspur	Gurudaspur Upazila Health Complex, Natore	Polash 2 Std Staff Qtr	4	1973	2	813	1626		No file	1 jpeg	
38	gurudaspur	Gurudaspur Upazila Health Complex, Natore	Bokul 2 Std Staff Qtr	3	1973	2	1074	2148		No file	1 jpeg	
39	gurudaspur	Gurudaspur Upazila Health Complex, Natore	Maloti 1 Std Staff Qtr	2	1973	1	613	613		No file	1 jpeg	
40	gurudaspur	Gurudaspur Upazila Health Complex, Natore	Sonali 2 Std Staff Qtr	1	1973	2	2878	5756		No file	1 jpeg	
41	gurudaspur	Gurudaspur Upazila Health Complex, Natore (Old Building)	Oxyzen 1 Std Bldg	11		1	257	257		No file	1 jpeg	
42	lalpur	Lalpur Upazila Health Complex, Natore	Mosque	9		1	1980			No file	1 jpeg	
43	lalpur	Lalpur Upazila Health Complex, Natore	Family Planing Store 1 std	8		1	914			No file	1 jpeg	
44	lalpur	Lalpur Upazila Health Complex, Natore	Jamuna 2 std Qtr	7		2	1358	2716		No file	1 jpeg	
45	lalpur	Lalpur Upazila Health Complex, Natore	Surma 2std Qtr	6			1342	2684		No file	No file	
46	lalpur	Lalpur Upazila Health Complex, Natore	Titas 2 std Qtr	5		2	1963	3926		No file	1 jpeg	
47	lalpur	Lalpur Upazila Health Complex, Natore	Meghna 3 std Qtr	4		3	1442	4326		No file	1 jpeg	
48	lalpur	Lalpur Upazila Health Complex, Natore	Meghna 2 std Qtr	3		2	1544	3088		No file	1 jpeg	
49	lalpur	Lalpur Upazila Health Complex, Natore	Karatoya 2 std	2		2	2764	5528		No file	1 jpeg	
50	lalpur	Lalpur Upazila Health Complex, Natore	Padma 3 Std Qtr	1		3	2602	7806		No file	1 jpeg	
51	naldanga	Naldanga Upazila Health Complex, Natore	Garrage Cum Driver shade	9	2018	2	260	522	Useable	No file	1 jpeg	
52	naldanga	Naldanga Upazila Health Complex, Natore	Staff Quarter	8	2018	5	955	4775	Useable	No file	1 jpeg	
53	naldanga	Naldanga Upazila Health Complex, Natore	Nurse Quarter	7	2018	3	1822	5468	Useable	No file	1 jpeg	
54	naldanga	Naldanga Upazila Health Complex, Natore	Dormitory	6	2018	5	1036	5184	Useable	No file	1 jpeg	
55	naldanga	Naldanga Upazila Health Complex, Natore	RMO Quarter	5	2018	2	2350	4700	Useable	No file	1 mp4	
56	naldanga	Naldanga Upazila Health Complex, Natore	TSA Quarter	4	2018	2	1600	3200	Useable	No file	1 jpeg	
57	naldanga	Naldanga Upazila Health Complex, Natore	Doctors Quarter	3	2018	4	1608	6430	Useable	No file	1 jpeg	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
58	naldanga	Naldanga Upazila Health Complex, Natore	Doctor Dormitory	2	2018	5	1200	60000	Useable	No file	1 jpeg	
59	naldanga	Naldanga Upazila Health Complex, Natore	Hospital Buiding	1	2018	4	10829	41894	Useable	No file	6 jpegs, 1 mp4	
60	singra	Singra Upazila Health Complex, Natore	Mosque	20		1	1636	1636		No file	1 jpeg	
61	singra	Singra Upazila Health Complex, Natore	Ambulance garrage	19		1	400	400		No file	1 jpeg	
62	singra	Singra Upazila Health Complex, Natore	1 std Psychotherapy Bldg	18		1	368	368		No file	1 jpeg	
63	singra	Singra Upazila Health Complex, Natore	UHNFPD 1 Std Qtr	17		1	314	314		No file	1 jpeg	
64	singra	Singra Upazila Health Complex, Natore	Pump House	16		1	490	490		No file	1 jpeg	
65	singra	Singra Upazila Health Complex, Natore	Sub station building	15		1	170	170		No file	1 jpeg	
66	singra	Singra Upazila Health Complex, Natore	Third Class Staff Qtr 2 Std Bldg	14		2	789	1578		No file	1 jpeg	
67	singra	Singra Upazila Health Complex, Natore	3rd Class Staff Qtr 3 Std Bldg	13		3	1883	5649		No file	1 jpeg	
68	singra	Singra Upazila Health Complex, Natore	Family Planning Office 2 Std Bldg	12		2	1204	2408		No file	1 jpeg	
69	singra	Singra Upazila Health Complex, Natore	Rojonigondha Nurses Dormitory 1 Std Bldg	11	1960	1	1236	1236		No file	1 jpeg	
70	singra	Singra Upazila Health Complex, Natore	Driver Shed	10	1960	1	387	387		No file	1 jpeg	
71	singra	Singra Upazila Health Complex, Natore	Ambulance garrage	9	1960	1	258	258		No file	1 jpeg	
72	singra	Singra Upazila Health Complex, Natore	3rd Class Staff Qtr 2	8	1960	1	594	594		No file	1 jpeg	
73	singra	Singra Upazila Health Complex, Natore	Doctor Dormitory	7	1960	1	1060	1060		No file	1 jpeg	
74	singra	Singra Upazila Health Complex, Natore	3rd Class Staff Qtr 1 Std Bldg	6	1960	1	574	574		No file	1 jpeg	
75	singra	Singra Upazila Health Complex, Natore	Field Training Center 1 Std Bldg	5	1960	1	1563	1563		No file	1 jpeg	
76	singra	Singra Upazila Health Complex, Natore	Staff Dormitory 1 std Bldg	4	1960	1	2220	2220		No file	1 jpeg	
77	singra	Singra Upazila Health Complex, Natore	Doctors 2 Std Qrt	3	1960	2	1586	3172		No file	1 jpeg	
78	singra	Singra Upazila Health Complex, Natore	Garrage	2	1960	1	278	278		No file	1 jpeg	
79	singra	Singra Upazila Health Complex, Natore	Medical Waste Disposal Shed	1	2021	1	530	530		No file	1 jpeg	

District Name: Netrokona

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	atpara	Atpara Upazila health complex	1 xlsx	ok
2	durgapur	Upazila heath complex Durgapur	1 xlsx	ok
3	kalmakanda	Upazila heath complex kalmakanda	1 xlsx	ok

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	atpara	Upazila health Complex Atpara	1982	PWD		50	No file	No file	No file	No file	5200	10400	No file	No file	No file		ok
2	barhatta	Barhatta Upazila helth Complex	1985	PWD	N/A	50	1 dwg, 1 pdf	No file	No file	No file		5000	No file	No file	1 jpg		ok
3	durgapur	Upazila heath complex Durgapur	1983	PWD	N/A	50	1 pdf	No file	No file	No file	5100	10400	1 pdf	No file	1 jpeg	0	ok
4	kalmakanda	Upazila heath complex kalmakanda	1984	PWD	yes	50	No file	No file	No file	No file	5200	10400	No file	No file	No file	6.55 m	ok
5	kendua	Kendua Upazila helth Complex	1962	PWD	N/A	50	1 dwg, 1 pdf	No file	No file	No file	10000	GF 10000 FF 10000 2nd 5000	1 pdf	No file	10 jpegs		ok
6	khaliajuri	Khaliajuri Upazila Health Complex	1998	PWD		50	1 dwg, 1 pdf	No file	No file	No file	4800	9600	No file	No file	No file		ok
7	madan	Madan Upazila Health Complex	1975	PWD	N/A	50	1 dwg, 1 pdf	No file	No file	No file	4800	9600	No file	No file	No file		ok
8	mohanganj	Mohonganj Upazilla health complex (100 bed)	2023	HED	yes	100	No file	No file	No file	1 pdf	21252		1 pdf	No file	1 jpg		
9	purbadhala	Purbodhola Upozilla Health Complex	1983	PWD	yes	50	No file	No file	1 png	No file	5000	10000	1 jpeg	No file	1 png	unknown	

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	atpara	Upazila health Complex Atpara	23	3	2	Footing	2	RCC	Average	No file	Not Possible	unknown	ok
2	barhatta	Barhatta Upazila helth Complex			2	Footing	2	RCC	Average	No file	Not Possible	unknown	ok
3	durgapur	Upazila heath complex Durgapur	20.5	1.27	2	Footing	2	RCC	Average	No file	Not Possible	Unknown	ok
4	kalmakanda	Upazila heath complex kalmakanda	22	2	2	Footing		RCC	Average	No file	Not Possible	Unknown	ok

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
5	kendua	Kendua Upazila helth Complex	11.5	3	2	Footing	2	RCC	stuctural condition no significant damage shown	No file	Not Possible	unknown	ok
6	khaliajuri	Khaliajuri Upazila Health Complex	22	2.5	2	Footing		RCC		No file	Not Possible		ok
7	madan	Madan Upazila Health Complex	22	1.25	2	Footing		RCC		No file	Not Possible		ok
8	mohanganj	Mohonganj Upazilla health complex (100 bed)	3	40	4	Mat	7	RCC	Good (Building constructed in the year 2023)	No file	Possible	unknown	UHFPO doesn't have a residence.
9	purbadhala	Purbodhola Upozilla Health Complex	11.5	2.5	2	Footing	2	RCC	average	No file	Not Possible		

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	atpara	Upazila health Complex Atpara	0	1	Only from deep tubewell	Septic Tank	880	No	0	Not sufficient drainage facilities	Need Master drain along with surface drain	Canal 12 ft away from north side boundary wall	ok
2	barhatta	Barhatta Upazila helth Complex		1	n/a	Septic Tank		No		Not sufficient drainage facilities	Need Master drain along with surface drain		ok
3	durgapur	Upazila heath complex Durgapur	0	1	N/A	Septic Tank	1300	No	0	Not sufficient drainage facilities.	Need master drain with sufficient surface drain	Canal 20ft away form west side boundary wall.	ok
4	kalmakanda	Upazila heath complex kalmakanda		1	N/A	Septic Tank		No	0	Not sufficient drainage facilities	Need master drain with sufficient surface drain	River	ok
5	kendua	Kendua Upazila Health Complex	0	1	N/A	Septic Tank	25000	No	0	Not sufficient drainage facilities	Need Master drain along with surface drain	No available disposal location	ok
6	khaliajuri	Khaliajuri Upazila Health Complex		1	N/A	Septic Tank		No		Not sufficient drainage facilities	Need Master drain along with surface drain		
7	madan	Madan Upazila Health Complex		1	n/a	Septic Tank		No		Not sufficient drainage facilities	Need Master drain along with surface drain		
8	mohanganj	Mohonganj Upazilla health complex (100 bed)	0	2	unknown	Septic Tank		No	0	Insufficient	Need Master drain alongwith surface drain	Municipality drain	
9	purbadhala	Purbodhola Upozilla Health Complex		1		Septic Tank		No		Poor Condition	yes	unknown	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	atpara	Upazila health Complex Atpara		1210		270	12	HBB and CC road average width 8 ft	Yes	Yes	ok
2	barhatta	Barhatta Upazila helth Complex	0	1125	500	200	12	HBB and CC road average width 8 ft	Yes	Yes	ok

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
3	durgapur	Upazila heath complex Durgapur	0	2256	970	299	12.25	HBB road width average 12 ft and cc road with average width 10 ft ft	Yes	Yes	ok
4	kalmakanda	Upazila heath complex kalmakanda	0	2256	970	200	12.25	cc road with average width 7 ft	Yes	Yes	ok
5	kendua	Kendua Upazila Health Complex		1530		250	14.99	HBB and CC road average width 8 ft, condition some dame shown	No	Yes	ok
6	khaliajuri	Khaliajuri Upazila Health Complex	2444				12	CC road average width 8 ft	Yes	Yes	
7	madan	Madan Upazila Health Complex		1372		343	15	CC road average width 8 ft	No	Yes	ok
8	mohanganj	Mohonganj Upazilla health complex (100 bed)	0	2200	0	0	14.99				
9	purbadhala	Purbodhola Upozilla Health Complex	800	1000	200	250	8	8 feet width R.C.C Road	Yes	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	atpara	50 Bed Upazila Hospital, Atpara, Netrokona.	0	0	1no bed lift needs to be installed	6	30	Existing AC needs to be repaired.	only fire extinguisher exists	3	0	5.5 HP 2 nos. Submersible pump required, need repair of existing pump	Not Present	On average, about 2/3 tons of medical waste is generated every day. Medical waste management needs to be done.
2	barhatta	50 Bed Upazila Hospital, Barhatta, Netrokona.	0	0	1no bed lift needs to be installed	15	40	Existing AC needs to be repaired.	only fire extinguisher exists	10	0	3 HP 3 nos. Submersible pump required, need repair of existing pump	Not Present	On average, about 2/3 tons of medical waste is generated every day. Medical waste management needs to be done.
3	durgapur	50 Bed Upazila Hospital, Durgapur, Netrokona.	0	0	1no bed lift needs to be installed	6	30	Existing AC needs to be repaired.	only fire extinguisher exists	3	0	5.5 HP 2 nos. Submersible pump required, need repair of existing pump	Not Present	On average, about 2/3 tons of medical waste is generated every day. Medical waste management needs to be done.
4	kalmakanda	50 Bed Upazila Hospital, Kalmakanda, Netrokona.	0	0	1no bed lift needs to be installed	9	20	Existing AC needs to be repaired.	only fire extinguisher exists	5.5	0	5.5 HP 2 nos. Submersible pump required, need repair of existing pump	Not Present	On average, about 2 tons of medical waste is generated every day. Medical waste management needs to be done.
5	kendua	50 Bed Upazila Hospital, kendua, Netrokona.	0	0	1no bed lift needs to be installed	8	30	Existing AC needs to be repaired.	only fire extinguisher exists	3	0	5.5 HP 2 nos. Submersible pump required, need repair of existing pump	Not Present	On average, about 2/3 tons of medical waste is generated every day. Medical waste management needs to be done.
6	khaliajuri	50 Bed Upazila Hospital, khaliajuri, Netrokona.	0	0	1no bed lift needs to be installed	17	30	Existing AC needs to be repaired.	only fire extinguisher exists	6	0	5.5 HP 2 nos. Submersible pump required, need repair of existing pump	Not Present	On average, about 2/3 tons of medical waste is generated every day. Medical waste management needs to be done.
7	madan	50 Bed Upazila Hospital, Madan, Netrokona.	0	0	1no bed lift needs to be installed	6	30	Existing AC needs to be repaired.	only fire extinguisher exists	3	0	5.5 HP 2 nos. Submersible pump required, need repair of existing pump	Not Present	On average, about 2/3 tons of medical waste is generated every day. Medical waste management needs to be done.

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
8	mohanganj	50 bed Mohanganj Upazila helth Complex, Netrokona.	0	0	2nos bed lift needs to be installed.	30	60	Existing AC needs to be repaired.	only Fire Extinguisher System.	11	0	5.5HP 2nos submersible pump needs to be installed with deep tube well.	Not Present	On average, about 2 tons of medical waste is generated every day. Medical waste management needs to be done.
9	purbadhala	50 Bed Upazila Hospital	0	0		9	30	Need repair of existing AC	No But required	3	0	5.5 HP 2 nos. Submersible pump required, need repair of existing pump	Not Present	Need

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	atpara	50 Bed Upazila Hospital, Atpara, Netrokona.	REB	No	75	75	0	LT panel, HT panel and PFI panel does not exist as there are Pole Mounting drum type Transformer on Electric Poles.	0	50	0	0	4*50Rm NYY -100 meter cable for service cable	4*25Rm NYY -300 meter(appr.) for FDBs cable .	315KVA in door type Sub-sation Needs to be installed for old Buildings. Need small generator for OT
2	barhatta	50 Bed Upazila Hospital, Barhatta, Netrokona.	REB	No	150	150	0	LT panel, HT panel and PFI panel exist	100	0	0	0	3*70Rm XLPE -50 meter cable for service cable	4*95Rm NYY -200 meter(appr.) 4*50Rm NYY -300 meter(appr.), 4*70Rm NYY -200 meter(appr.) ,4*16Rm NYY -100 meter(appr.) for MDBs	Need small generator for OT
3	durgapur	50 Bed Upazila Hospital, Durgapur, Netrokona.	REB	No	100	75	0	LT panel, HT panel and PFI panel does not exist as there are Pole Mounting drum type Transformer on Electric Poles.	0	50	0	0	4*50Rm NYY -100 meter cable for service cable	4*25Rm NYY -300 meter(appr.) for FDBs cable .	400KVA in door type Sub-sation Needs to be installed. Need small generator for OT.
4	kalmakanda	50 Bed Upazila Hospital, Kalmakanda, Netrokona.	REB	No	120	75	0	LT panel, HT panel and PFI panel does not exist as there are Pole Mounting drum type Transformer on Electric Poles.	0	0	0	0	4*50Rm NYY -100 meter cable for service cable	4*25Rm NYY -300 meter(appr.) for FDBs cable .	400KVA in door type Sub-sation Needs to be installed. Need small generator for OT.
5	kendua	50 Bed Upazila Hospital, kendua, Netrokona.	REB	No	120	75	0	LT panel, HT panel and PFI panel does not exist as there are Pole Mounting drum type Transformer on Electric Poles.	0	50	0	0	4*50Rm NYY -100 meter cable for service cable	4*25Rm NYY -300 meter(appr.) for FDBs cable .	400KVA in door type Sub-sation Needs to be installed. Need small generator for OT.
6	khaliajuri	50 Bed Upazila Hospital, khaliajuri, Netrokona.	REB	No	120	150	0	LT panel, HT panel and PFI panel exist .	40	50	0	0	3*70Rm XLPE -50 meter cable for service cable	4*95Rm NYY -200 meter(appr.) 4*50Rm NYY -300 meter(appr.), 4*70Rm NYY -200 meter(appr.) ,4*16Rm NYY -100 meter(appr.) for MDBs	Need small generator for OT.
7	madan	50 Bed Upazila Hospital, Madan, Netrokona.	REB	No	120	75	0	LT panel, HT panel and PFI panel does not exist as there are Pole Mounting drum type	0	50	0	0	4*50Rm NYY -100 meter cable for service cable	4*25Rm NYY -200 meter for FDB cable for service cable	400KVA in door type Sub-sation Needs to be installed. Need small generator for OT.

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
								Transformer on Electric Poles.							
8	mohanganj	100 Bed Upazila Hospital, Mohanganj, Netrokona.	REB	No	252	315	0	LT panel, HT panel and PFI panel exist .	100	50	6	0	3*95Rm XLPE -100 meter cable for service cable	4*95Rm NYY -200 meter(appr.) 4*50Rm NYY -300 meter(appr.), 4*70Rm NYY -200 meter(appr.) ,4*16Rm NYY -100 meter(appr.) for MDBs	Need small generator for OT.
9	purbadhala	50 Bed Upazila Hospital	REB	No	200	315	115	LT HT PFI MDB	100	0	0	0	95 RM XLP HT Cable 150 Meter	4*195 RM NYY 500 Meter, 4*95 RM NYY 200 Meter, 4*50 RM NYY 250 Meter, 4*25 RM NYY 220 Meter, 4*10 RM NYY 240 Meter	Need small generator for OT

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	atpara	50 Bed Upazila Hospital, Atpara, Netrokona.	No	0	0	50 bed Medical gas system needs to be installed.	Yes		No	No	No	2	Existing security lights are not adequate.	
2	barhatta	50 Bed Upazila Hospital, Barhatta, Netrokona.	Yes	0	31	.Exsiting Medical gas sytem needs to be repaired and extension.	Yes	No	No	No	No	0	Existing security lights are not adequate.	
3	durgapur	50 Bed Upazila Hospital, Durgapur, Netrokona.	No	0	0	50 bed Medical gas system needs to be installed.	Yes	No	No	No	Yes	2	Existing security lights and CCTV System are not adequate.	
4	kalmakanda	50 Bed Upazila Hospital, Kalmakanda, Netrokona.	No	0	36	14 bed Medical gas system needs to be installed and Exsinting Medical gas System needs to be repaired.	Yes	No	No	No	No	0	Existing security lights are not adequate.	
5	kendua	50 Bed Upazila Hospital, kendua, Netrokona.	Yes	0	31	19 bed Medical gas system needs to be installed and existing system needs to be repaired.	Yes	No	No	No	No	0	Existing security lights are not adequate.	
6	khaliajuri	50 Bed Upazila Hospital, khaliajuri, Netrokona.	No	0	0	50 bed Medical gas system needs to be installed.	Yes	No	No	No	No	0	Existing security lights are not adequate.	
7	madan	50 Bed Upazila Hospital, Madan, Netrokona.	Yes	0	31	19 bed Medical gas system needs to be installed.	Yes	No	No	No	No	0	Existing security lights are not adequate.	
8	mohanganj	100 Bed Upazila Hospital, Mohanganj, Netrokona.	Yes		99	Exsiting Medical gas sytem needs to be repaired and extension.	Yes	No	No	No	Yes	1	Existing security lights and CCTV System are not adequate.	
9	purbadhala	50 Bed Upazila Hospital	No	0	0	50 bed Medical gas system needs to be installed.	Yes	No	No	No	No	1	Existing security lights are not adequate.	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	atpara	Upazila health Complex Atpara	First class Quarter	1	1995	3	2000	6000	Average	No file	No file	ok
2	barhatta	Barhatta Upazila helth Complex	First class Quarter	1	1985	2	2000	4000	Average	No file	No file	
3	durgapur	Upazila heath complex Durgapur	Nurses quater	1						No file	No file	ok
4	kalmakanda	Upazila heath complex kalmakanda	Nurses quater	1		2	2000	4000	average	No file	No file	ok
5	kendua	Kendua Upazila Health Complex	Hospital Building	3	1923	3	5000	15000	good newly construct	No file	No file	ok
6	madan	Madan Upazila helth Complex	First class Quarter	1	2000	3	2000	6000	Average	No file	No file	ok
7	mohanganj	Mohonganj Upazilla health complex (100 bed)	consultant & Rmo Quarter	1	2023	4	1050	4000	good	No file	1 jpg	
8	purbadhala	Purbodhola Upozilla Health Complex	Doctors Quater	1	1983	2	800	1600	poor condition	No file	1 jpeg	

District Name: Nilphamari

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	dimla	Upazilla Health Complex , Dimla.	1 xlsx	ok
2	domar	Upazilla Health Complex , Domar.	1 xlsx	ok
3	jaldhaka	Upazilla Health Complex , Jaldhaka.	1 xlsx	ok
4	kishoreganj	Upazilla Health Complex , Kishorgong.	1 xlsx	ok

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	dimla	Upazilla Health Complex , Dimla.	0	Other	Available.	50	No file	1 pdf	1 pdf	No file	15588	Building-1: GF: 7578, 1st F: 7007 Building-2: GF: 8010, 1st F: 6630	No file	No file	8 jpegs	Not Found	n/a
2	domar	Upazilla Health Complex , Domar.	0	Other	Available.	50	No file	1 pdf	1 pdf	No file	15980	Building-1: GF: 7970, 1st F: 6935, Building-2: GF: 8010, 1st F: 6630	No file	No file	3 jpegs	Not Found	n/a
3	jaldhaka	Upazilla Health Complex , Jaldhaka.	0	Other	Available.	50	No file	1 pdf	1 pdf	No file	15980	Building-1: GF: 7970, 1st F: 6935 Building-2: GF: 8010, 1st F: 6630, 2nd F: 5440	No file	No file	2 jpegs	Not Found	n/a
4	kishoreganj	Upazilla Health Complex , Kishorgong.	0	Other	Available.	50	No file	1 pdf	1 pdf	No file	15980	Building-1: GF: 7970, 1st F: 6935 Building-2: GF: 8010, 1st F: 6630, 2nd F: 5440	No file	No file	4 jpegs	Not Found	n/a

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	dimla	Upazilla Health Complex , Dimla.	20	2	2	Footing	2	RCC	Structural Integrity: ok. Drainage & Core Damage: roof condition not good. Feasibility Assessment: reparable.	No file	info not available	info no available	n/a
2	domar	Upazilla Health Complex , Domar.	20	2	2	Footing	2	RCC	Structural Integrity: ok. Drainage & Core Damage: roof condition not good. Feasibility Assessment: reparable.	No file	info not available	info no available	n/a
3	jaldhaka	Upazilla Health Complex , Jaldhaka.	20	2	2	Footing	2	RCC	Structural Integrity: ok. Drainage & Core Damage: Drain and roof condition not good. Feasibility Assessment: reparable.	No file	info not available	info no available	n/a
4	kishoreganj	Upazilla Health Complex , Kishorgong.	20	2	2	Footing	2	RCC	Structural Integrity: ok. Drainage & Core Damage: roof condition not good. Feasibility Assessment: reparable.	No file	info not available	info no available	n/a

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	dimla	Upazilla Health Complex , Dimla.	0	1	n/a	Septic Tank	0	No	0	poor	Needed	n/a	n/a
2	domar	Upazilla Health Complex , Domar.	0	1	n/a	Septic Tank	0	No	0	poor	Needed	n/a	n/a
3	jaldhaka	Upazilla Health Complex , Jaldhaka.	0	1	n/a	Septic Tank	0	No	0	poor	Needed	n/a	n/a
4	kishoreganj	Upazilla Health Complex , Kishorgong.	0	1	n/a	Septic Tank	0	No	0	poor	Needed	n/a	n/a

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	dimla	Upazilla Health Complex , Dimla.	0	1420	0	600	12	Total length of internal road is 900 rft. The road need to be repair and renovation. Need to construction new road at least 950 rft.	Yes	Yes	n/a
2	domar	Upazilla Health Complex , Domar.	0	1340	450	320	16	Total length of internal road is 740 rft. The road need to be repair and renovation. Need to construction new road at least 860 rft.	Yes	Yes	n/a
3	jaldhaka	Upazilla Health Complex , Jaldhaka.	0	1030	0	450	12	Total length of internal road is 780 rft. The road need to be repair and renovation. Need to construction new road at least 650 rft.	Yes	Yes	n/a
4	kishoreganj	Upazilla Health Complex , Kishorgong.	0	960	0	480	16	Total length of internal road is 850 rft. The road need to be repair and renovation. Need to construction new road at least 1000 rft.	Yes	Yes	n/a

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (If present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	dimla	Upazilla Health Complex , Dimla.	0	0	0	16	20	n/a	No Fire Detection and Protection System.	2	0	Need at least 04 Centrifugal Pump	Not Present	Need Medical Waste Management System
2	domar	Upazilla Health Complex , Domar.	0	0	0	15	20	n/a	No Fire Detection and Protection System.	2	0	Need at least 04 Centrifugal Pump	Not Present	Need Medical Waste Management System
3	jaldhaka	Upazilla Health Complex , Jaldhaka.	0	0	0	16	20	n/a	No Fire Detection and Protection System.	2	0	Need at least 04 Centrifugal Pump	Not Present	Need Medical Waste Management System
4	kishoreganj	Upazilla Health Complex , Kishorgong.	0	0	0	16	20	n/a	No Fire Detection and Protection System.	2	0	Need at least 04 Centrifugal Pump	Not Present	Need Medical Waste Management System

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	dimla	Upazilla Health Complex , Dimla.	NESCO	Yes	40	0	0	0	0	10	0	0	35-50 RM length: 60-80 rft LT	0	n/a
2	domar	Upazilla Health Complex , Domar.	DESCO	Yes	40	0	0	0	0	10	0	0	35-50 RM length: 60-80 rft LT	0	n/a
3	jaldhaka	Upazilla Health Complex , Jaldhaka.	NESCO	Yes	40	0	0	0	0	10	0	0	35-50 RM length: 60-80 rft LT	0	n/a
4	kishoreganj	Upazilla Health Complex , Kishorgong.	NESCO	Yes	40	0	0	0	0	10	0	0	35-50 RM length: 60-80 rft LT	0	n/a

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	dimla	Upazilla Health Complex , Dimla.	No	0	0	n/a	No	No	No	No	Yes	0	Need Medical Gas Facility, Compound and Security Light, Sound and PA System, computer networks, PABX System, Neon Poly sign board.	n/a
2	domar	Upazilla Health Complex , Domar.	No	0	0	n/a	No	No	No	No	Yes	0	Need Medical Gas Facility, Compound and Security Light, Sound and PA System, computer networks, PABX System, Neon Poly sign board.	n/a
3	jaldhaka	Upazilla Health Complex , Jaldhaka.	No	0	0	n/a	No	No	No	No	Yes	0	Need Medical Gas Facility, Compound and Security Light, Sound and PA System, computer networks, PABX System, Neon Poly sign board.	n/a
4	kishoreganj	Upazilla Health Complex , Kishorgong.	No	0	0	n/a	No	No	No	No	Yes	0	Need Medical Gas Facility, Compound and Security Light, Sound and PA System, computer networks, PABX System, Neon Poly sign board.	n/a

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	dimla	Upazilla Health Complex , Dimla.	Residential Quarter	0	0	2	1800	3600	repairable	No file	No file	n/a
2	domar	Upazilla Health Complex , Domar.	Residential Quarter	0	0	2	2500	5000	repairable	No file	No file	n/a
3	jaldhaka	Upazilla Health Complex , Jaldhaka.	Residential Quarter	0	0	2	2000	4000	repairable	No file	No file	n/a
4	kishoreganj	Upazilla Health Complex , Kishorgong.	Residential Quarter	0	0	2	2200	4400	repairable	No file	No file	n/a

District Name: Pabna

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	atgharia	Atgharia Upazila Health Complex, Pabna.	1 xlsx	OK
2	bera	Bera Upazila Health Complex, Pabna	1 xlsx	OK
3	bhangura	Bhangura Upazila Health complex	1 xlsx	ok
4	chatmohar	Chatmohar Upazila Health complex	1 xlsx	ok
5	faridpur	Faridpur Upazila Health complex	1 xlsx	ok
6	santhia	Santhia Upazila Health Complex, Pabna	1 xlsx	ok
7	sujanagar	Sujanagar Upazila Health Complex, Pabna	1 xlsx	OK

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	atgharia	Atgharia Upazila Health Complex, Pabna	1966	PWD	N/A	31	1 dwg, 1 pdf	No file	No file	No file	5400	GF- 5450 Sft, FF- 5000 Sft	1 pdf	1 pdf	4 jpegs	N/A	OK
2	bera	Bera Upazila Health Complex, Pabna	1965	PWD	Not applicable	50	1 dwg	No file	No file	No file		GF-5500, FF -5000	1 pdf	No file	No file	NA	OK
3	bhangura	Bhangura Upazila Health complex	2014	HED	NA	19	1 dwg	No file	No file	No file			No file	No file	No file		
4	bhangura	Bhangura Upazila Health complex	1980	PWD	NA	31	1 dwg, 1 pdf	No file	No file	No file			No file	No file	1 jpeg		
5	chatmohar	Chatmohar Upazila Health complex	2009	HED	availabe	19	1 dwg	No file	No file	No file			No file	No file	No file		
6	chatmohar	Chatmohar Upazila Health complex	1974	PWD	availabe	31	1 dwg, 1 pdf	No file	No file	No file			No file	No file	1 jpeg		
7	faridpur	Faridpur Upazila Health complex	2006	HED	availabe	19	1 dwg	No file	No file	No file			No file	No file	No file		
8	faridpur	Faridpur Upazila Health complex	1982	PWD	availabe	31	1 dwg, 1 pdf	No file	No file	No file			No file	No file	1 jpeg		
9	santhia	Santhia Upazila Health Complex, Pabna	1965	PWD	Not Applicable	50	1 dwg	1 jpeg	No file	No file	5500	GF-5500, FF -5000	1 pdf	No file	7 jpegs	NA	OK
10	sujanagar	Sujanagar Upazila Health Complex, Pabna	1967	PWD	Not applicable	50	1 dwg	No file	No file	No file	5500	GF- 5450 Sft, FF- 5000 Sft	1 pdf	No file	No file	NA	OK

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	atgharia	Atgharia Upazila Health Complex, Pabna	20	2	2	Footing	2	Load Bearing Brick	Demase	No file	Not Possible	Renovated	OK
2	bera	Bera Upazila Health Complex, Pabna	20	2.5	2	Footing	2	Load Bearing Brick	Retrofittable	No file	Not Possible	Renovated	ok
3	bhangura	Bhangura Upazila Health complex	30	2	3	Footing	6	RCC		No file	Possible		
4	bhangura	Bhangura Upazila Health complex	20	2	2	Footing	2	RCC		No file	Not Possible		
5	chatmohar	Chatmohar Upazila Health complex	30	1.5	3	Footing	4	RCC	Not good	No file	Not Possible		
6	chatmohar	Chatmohar Upazila Health complex	20	1.5	2	Footing	2	RCC	Structural cracks in beam, slab, spalling of concretein slab	No file	Not Possible		
7	chatmohar	Chatmohar Upazila Health complex								No file			
8	faridpur	Faridpur Upazila Health complex	20	1.5	2	Footing	2	RCC	Not Good	No file	Not Possible		
9	santhia	Santhia Upazila Health Complex, Pabna	20	2	2	Footing	2	Load Bearing Brick	Column, Beam & Slab is Heair crack .	No file	info not available	Renovated	OK
10	sujanagar	Bera Upazila Health Complex, Pabna	20	2.5	2	Mat	2	Load Bearing Brick	Column, Beam & Slab is Heair crack .	No file	Not Possible	Renovated	OK

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	atgharia	Atgharia Upazila Health Complex, Pabna	0	1	N/A	Septic Tank	200	No	0	N/A	Yes	NA	OK
2	bera	Bera Upazila Health Complex, Pabna	0	1	Not Aplicable	Septic Tank	200	No	0	Not Aplicable	Needed	Not Aplicable	ok
3	bhangura	Bhangura Upazila Health complex	0	1	No	Septic Tank		No		Poor Drainage Facility exist	RCC drain required	Existing pond in the campus	
4	chatmohar	Chatmohar Upazila Health complex	0	1	NA	Septic Tank		No		Poor Drainage Facility exist	RCC drain required	Existing pond in the campus	
5	faridpur	Faridpur Upazila Health complex		2	No	Septic Tank		No		Poor Drainage Facility exist	RCC drain required	Existing pond in the campus	
6	santhia	Santhia Upazila Health Complex, Pabna	0	1	NA	Septic Tank	200	No	0	NA	Yes	NA	OK
7	sujanagar	Sujanagar Upazila Health Complex, Pabna	0	1	NA	Septic Tank	200	No	0	NA	Yes	NA	ok

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	atgharia	Atgharia Upazila Health Complex, Pabna	0	2357	0	0	30	10	No	Yes	ok
2	bera	Bera Upazila Health Complex, Pabna	0	2440	0	0	30	12	Yes	Yes	ok
3	bhangura	Bhangura Upazila Health complex		2050	2050		15	RCC, HBB road	Yes	Yes	
4	chatmohar	Chatmohar Upazila Health complex		2083	2083		16	RCC, HBB, Kutcha road	Yes	Yes	
5	faridpur	Faridpur Upazila Health complex		2145	2145		13	RCC, Pucca Road	Yes	Yes	
6	santhia	Santhia Upazila Health Complex, Pabna	0	2268	0	0	30	12	No	Yes	OK
7	sujanagar	Santhia Upazila Health Complex, Pabna	0	2550	0	0	40	12	No	Yes	OK

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	atgharia	Atgharia Upazila Health Complex, Pabna	UCH Building	1	2	2	1500	3000	Not Aplicable	No file	No file	ok
2	bera	Bera Upazila Health Complex, Pabna	UCH Building	1	2	2	1500	3000	Not Aplicable	No file	No file	ok
3	chatmohar	Chatmohar Upazila Health complex	4th class quarter	2	1974	2			dilapidated	No file	No file	
4	chatmohar	Chatmohar Upazila Health complex	Nurse's Quarter	2	1974	2			dilapidated	No file	No file	
5	chatmohar	Chatmohar Upazila Health complex	Doctor's quarter	2	1974	2			dilapidated	No file	No file	
6	faridpur	Faridpur Upazila Health complex	4th class quarter	1	1982	2			dilapidated	No file	No file	
7	faridpur	Faridpur Upazila Health complex	3rd class quarter	2	1982	2			dilapidated	No file	No file	
8	faridpur	Faridpur Upazila Health complex	Nurse dormitory	1	1982	1			dilapidated	No file	No file	
9	faridpur	Faridpur Upazila Health complex	Nurse's Quarter	1	1982	2			dilapidated	No file	No file	
10	faridpur	Faridpur Upazila Health complex	Doctor's quarter	2	1982	2			dilapidated	No file	No file	
11	santhia	Santhia Upazila Health Complex, Pabna	UCH Building	1	2	2	1500	3000	Not Aplicable	No file	No file	ok
12	sujanagar	Sujanagar Upazila Health Complex, Pabna	UCH Building	1	2	2	1500	3000	Not Aplicable	No file	No file	ok

District Name: Panchagarh

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	atoari	Upazila Health Complex Atoari, Panchagarh	1 xlsx	
2	boda	Uapzila Health Complex Boda, Panchagarh	1 xlsx	
3	debiganj	Upazila Health Complex Debiganj,Panchagarh	1 xlsx	
4	tetulia	Uapzila Health Complex Tetulia, Panchagarh	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	atoari	Upazila Health Complex,Atoari Panchagarh	1980		Yes	50	1 dwg, 1 pdf	No file	3 pdfs	1 pdf		GF=7629.48 FF=6844.5	1 pdf	No file	1 jpg		
2	atoari	Upazila Health Complex Atoari, Panchagarh	2014	HED	Yes	50	1 dwg, 1 pdf	No file	2 pdfs	1 pdf	8771.48	GF=6490.00 FF=6490.00	1 pdf	No file	2 jpgs		
3	boda	Uapzila Health Complex Boda, Panchagarh	2014	HED	Yes	50	1 dwg, 1 pdf	No file	2 pdfs	2 pdfs		GF=6490.00 FF=6490.00	1 pdf	2 pdfs	2 jpgs		
4	boda	Upazila Health Complex Boda,panchagarh	1981		Yes	50	1 dwg, 1 pdf	No file	3 pdfs	2 pdfs		GF=7629.48 FF=6844.5	1 pdf	2 pdfs	3 jpgs		
5	debiganj	Upazila Health Complex Debiganj,Panchagarh	2012	HED	Yes	50	1 dwg, 1 pdf	No file	2 pdfs	1 pdf	8576.8	GF=6490.00 FF=6490.00	1 pdf	1 pdf	4 jpgs		
6	debiganj	Upazila Health Complex Debiganj,Panchagarh	1981		Yes	50	1 dwg, 1 pdf	No file	3 pdfs	1 pdf	10658.85	GF=7629.48 FF=6844.5	1 pdf	1 pdf	9 jpgs		
7	tetulia	Uapzila Health Complex Tetulia, Panchagarh	1980		Yes	50	1 dwg, 1 pdf	No file	3 pdfs	2 pdfs		GF=7629.48 FF=6844.5	1 pdf	2 pdfs	5 jpgs		
8	tetulia	Uapzila Health Complex Tetulia, Panchagarh	2013	HED	Yes	50	1 dwg, 1 pdf	No file	2 pdfs	2 pdfs		GF=6490.00 FF=6490.00	1 pdf	2 pdfs	5 jpgs		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	atoari	Upazila Health Complex,Atoari Panchagarh	22	2	2	Footing	4	RCC	Average	No file	Possible	no	
2	atoari	Upazila Health Complex,Atoari Panchagarh	22	1	2	Footing	0	RCC	The Building is very old and dilapidated	No file	Not Possible	no	
3	boda	Uapzila Health Complex Boda, Panchagarh	22	0.67	2	Footing		RCC	The Building is very old dilapidated	No file	Not Possible		
4	boda	Uapzila Health Complex Boda, Panchagarh	22	1.67	2	Footing	4	RCC		No file	Possible	no	
5	debiganj	Uapzila Health Complex Debiganj, Panchagarh	22	2	2	Footing	4	RCC	Average	No file	Possible	no	
6	debiganj	Upazila Health Complex Debiganj,Panchagarh	22	2	2	Footing		RCC	The Building is very old dilapidated	No file	Not Possible		

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
7	tetulia	Upazila Health Complex Tetulia, Panchagarh	22	1.5	2	Footing		RCC	The Building is very old dilapidated	No file	Not Possible		
8	tetulia	Upazila Health Complex Tetulia, Panchagarh	22	2	2	Footing	4	RCC		No file	Possible	no	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	atoari	Upazila Health Complex Atoari, Panchagarh		1	no	Septic Tank	853	No		Surface drain made of brick masonry	RCC surface drain	Road side drain of municipality.	
2	atoari	Upazila Health Complex Atoari,Panchagarh		1	no	Septic Tank	1706	No		Surface drain made of brick masonry	RCC surface drain	Road side drain of municipality.	
3	boda	Upazila Health Complex Boda, Panchagarh				Septic Tank	853	No		Surface drain made of brick masonry	RCC surface drain	Road side drain of municipality.	
4	boda	Upazila Health Complex Boda,panchagarh		1	no	Septic Tank	853	No		Surface drain made of brick masonry	RCC surface drain	Road side drain of municipality.	
5	debiganj	Upazila Health Complex Debiganj,Panchagarh			no	Septic Tank	853	No		Surface drain made of brick masonry	RCC surface drain	Road side drain of municipality.	
6	debiganj	Upazila Health Complex Debiganj,Panchagarh		1	no	Septic Tank	1706	No		Surface drain made of brick masonry	RCC surface drain	Road side drain of municipality.	
7	tetulia	Upazila Health Complex Tetulia, Panchagarh				Septic Tank	853	No		Surface drain made of brick masonry	RCC surface drain	Road side drain of municipality.	
8	tetulia	Upazila Health Complex Tetulia, Panchagarh		1	no	Septic Tank	1707	No		Surface drain made of brick masonry	RCC surface drain	Road side drain of municipality.	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	atoari	Upazila Health Complex Atoari, Panchagarh		1900			22	RCC	Yes	Yes	
2	atoari	Upazila Health Complex Atoari, Panchagarh			800		22	RCC	Yes	Yes	
3	boda	Upazila Health Complex Boda, Panchagarh		2553.24			28	RCC	Yes	Yes	
4	boda	Upazila Health Complex Boda, Panchagarh					28	RCC	Yes	Yes	
5	debiganj	Upazila Health Complex Debiganj,Panchagarh			1100		12	RCC AND CC	Yes	Yes	
6	debiganj	Upazila Health Complex Debiganj,Panchagarh		2200			12	RCC AND CC	Yes	Yes	

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
7	tetulia	Uapzila Health Complex Tetulia, Panchagarh			1000		16	RCC	Yes	Yes	
8	tetulia	Uapzila Health Complex Tetulia, Panchagarh		2043			16	RCC	Yes	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	atoari	Atwari Upazila Health Complex, Panchagarh	0	0	0	8	7	বিদ্যমান অন্তত ০৫টি এসি মেরামত প্রয়োজন	শুধুমাত্র কিছু ফায়ার এক্সটিংগুশার বিদ্যমান আছে। এছাড়া ফায়ার কোনো প্রটেকশন নাই। ফায়ার ডিটেকশন নাই।	2	1	০২টি ১০ হর্স পাওয়ার সাবমার্সিবল পাম্প স্ট্যান্ড বাই হিসেবে প্রয়োজন। এছাড়া আরো ৬টি সেন্টিফিউগাল পাম্প প্রয়োজন।	Not Present	
2	boda	Boda Upazila Health Complex, Panchagarh	0	0	0	8	10	বিদ্যমান অন্তত ০৬টি এসি মেরামত প্রয়োজন	শুধুমাত্র কিছু ফায়ার এক্সটিংগুশার বিদ্যমান আছে। এছাড়া ফায়ার কোনো প্রটেকশন নাই। ফায়ার ডিটেকশন নাই।	1	5	০১টি ১০ হর্স পাওয়ার সাবমার্সিবল পাম্প স্ট্যান্ড বাই হিসেবে প্রয়োজন। এছাড়া আরো ৩টি সেন্টিফিউগাল পাম্প প্রয়োজন।	Not Present	
3	debiganj	Debiganj Upazila Health Complex, Panchagarh	0	0	0	16	6	বিদ্যমান অন্তত ০২টি এসি মেরামত প্রয়োজন	শুধুমাত্র কিছু ফায়ার এক্সটিংগুশার বিদ্যমান আছে। এছাড়া ফায়ার কোনো প্রটেকশন নাই। ফায়ার ডিটেকশন নাই।	5.5	3	০১টি ১০ হর্স পাওয়ার সাবমার্সিবল পাম্প স্ট্যান্ড বাই হিসেবে প্রয়োজন। এছাড়া আরো ২টি সেন্টিফিউগাল পাম্প প্রয়োজন।	Not Present	
4	tetulia	Tetulia Upazila Health Complex, Panchagarh	0	0	0	5	8	বিদ্যমান অন্তত ০৪টি এসি মেরামত প্রয়োজন	শুধুমাত্র কিছু ফায়ার এক্সটিংগুশার বিদ্যমান আছে। এছাড়া ফায়ার কোনো প্রটেকশন নাই। ফায়ার ডিটেকশন নাই।	7.5	8	০১টি ১০ হর্স পাওয়ার সাবমার্সিবল পাম্প স্ট্যান্ড বাই হিসেবে প্রয়োজন। এছাড়া বিদ্যমান সেন্টিফিউগাল পাম্প সমূহ অনেক পুরাতন হওয়ায় বেশিরভাগ অকেজো থাকে। তাই নতুন করে আরো অন্তত ৫টি ২ হর্স পাওয়ারের নতুন সেন্টিফিউগাল পাম্প প্রয়োজন।	Not Present	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	atoari	Atwari Upazila Health Complex, Panchagarh	REB	Yes	70	100	150	All components technically under size and very old condition.	0	1	0	0	65 METER Aluminium D-12 Cable As HT Cable & LT Service Cable Size is NYY 16sqmm Cable 40 meter		
2	boda	Boda Upazila Health Complex, Panchagarh	REB	Yes	80	100	150	All components technically under size and very old condition.	0	1	0	0	55 METER Aluminium D-12 Cable As HT Cable & LT Service Cable Size is NYY 16sqmm Cable 35 meter		
3	debiganj	Debiganj Upazila Health Complex, Panchagarh	REB	No	80	100	250		0	1	0	0			
4	tetulia	Tetulia Upazila Health Complex, Panchagarh	NESCO	Yes	110	100	150	All components technically under size and very old condition.	0	1	0	0	45 METER Aluminium D-12 Cable As HT Cable & LT Service Cable Size is NYY 25sqmm Cable 30 meter		

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	atoari	Atwari Upazila Health Complex, Panchagarh	No	0	0	0	No	No	No	No	No	0	ক্যাম্পাসে বিদ্যমান ভবনসমূহে বৈদ্যুতিক ওয়্যারিং লাইন সংস্কার ও নষ্ট বৈদ্যুতিক ফিটিংস ফিক্সার সমূহ পরিবর্তন করা জরুরী	
2	boda	Boda Upazila Health Complex, Panchagarh	Yes	0	50	বিদ্যমান মেডিক্যাল গ্যাস সিস্টেম পুরোপুরি ফাংশনাল নাই। সংস্কার করা প্রয়োজন আছে।	No	No	No	No	No	0	ক্যাম্পাসে বিদ্যমান ভবনসমূহে বৈদ্যুতিক ওয়্যারিং লাইন সংস্কার ও নষ্ট বৈদ্যুতিক ফিটিংস ফিক্সার সমূহ পরিবর্তন করা জরুরী	
3	debiganj	Tetulia Upazila Health Complex, Panchagarh	Yes			বিদ্যমান মেডিক্যাল গ্যাস সিস্টেম ফাংশনাল নাই। সংস্কার করা প্রয়োজন আছে।	No	No	No	No	No	0	ক্যাম্পাসে বিদ্যমান ভবনসমূহে বৈদ্যুতিক ওয়্যারিং লাইন সংস্কার ও নষ্ট বৈদ্যুতিক ফিটিংস ফিক্সার সমূহ পরিবর্তন করা জরুরী	
4	tetulia	Tetulia Upazila Health Complex, Panchagarh	No	0	0	0	No	No	No	No	No	0	ক্যাম্পাসে বিদ্যমান ভবনসমূহে বৈদ্যুতিক ওয়্যারিং লাইন সংস্কার ও নষ্ট বৈদ্যুতিক ফিটিংস ফিক্সার সমূহ পরিবর্তন করা জরুরী	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	atoari	Upazila Health Complex Atoari, Panchagarh	2 std Nurses Domitory	1		1	1232.67		The Building is being used	1 pdf	1 jpg	
2	atoari	Upazila Health Complex Atoari, Panchagarh	2 std 4th class employer's Qtr	1		2	1489.24	2600	The Building is being used	1 pdf	1 jpg	
3	atoari	Upazila Health Complex Atoari, Panchagarh	3 std 4th class employer's Qtr	2		2	1370.66		Abandoned	1 pdf	No file	
4	atoari	Upazila Health Complex Atoari, Panchagarh	2 storied nurses qtr	1	2014	2		4000	The Building is being used	1 pdf	1 jpg	
5	atoari	Upazila Health Complex Atoari, Panchagarh	Doctor's Quarter	1	2014	2		7500	The Building is being used	1 pdf	1 jpg	
6	boda	Uapzila Health Complex Boda, Panchagarh	2 std jamuna qtr	1		2	1500		Abandoned	1 pdf	No file	
7	boda	Uapzila Health Complex Boda, Panchagarh	2 std meghna qtr	1		2	1400		Abandoned	1 pdf	No file	
8	boda	Uapzila Health Complex Boda, Panchagarh	1 storied nurses Dormitory	1		1	1140	1140	Abandoned	1 pdf	1 jpg	
9	boda	Uapzila Health Complex Boda, Panchagarh	3storied medical officer's qtr building	1	2014	2	2800		The Building is not being used	1 pdf	1 jpg	
10	boda	Uapzila Health Complex Boda, Panchagarh	2nd class Officer's Qtr	1	2014	3	1766.24	6000	The Building is being used	1 pdf	1 jpg	
11	boda	Uapzila Health Complex Boda, Panchagarh	Doctor's Quarter	1	2014	3	3076	7500	The Building is being used	1 pdf	1 jpg	
12	boda	Upazila Health Complex Boda,panchagarh	3rd class employer's Qtr	1	2014	3	1359.27	3900	The Building is being used	1 pdf	1 jpg	
13	debiganj	Upazila Health Complex Debiganj,Panchagarh	2 std Doctor's Quarter	1		2	2414.4		The Building is being used	1 pdf	1 jpg	
14	debiganj	Upazila Health Complex Debiganj,Panchagarh	2 std Doctor's Quarter	1	2014	2	2829.75	5000	The Building is being used	1 pdf	1 jpg	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
15	debiganj	Upazila Health Complex Debiganj,Panchagarh	2 std Nurses qtr	1	2014	2	2093.27	4000	The Building is not being used	1 pdf	1 jpg	
16	debiganj	Upazila Health Complex Debiganj,Panchagarh	1 std Employer's Qtr	1		1	1584.21		Abandoned	1 pdf	3 jpgs	
17	debiganj	Upazila Health Complex Debiganj,Panchagarh	2 std kortoya employer's Qtr	1		2	1316.84		The Building is not being used	1 pdf	2 jpgs	
18	debiganj	Upazila Health Complex Debiganj,Panchagarh	2 std tista Employer's qtr	1		2	1316.84		The Building is not being used	1 pdf	1 jpg	
19	debiganj	Upazila Health Complex Debiganj,Panchagarh	3 storied Chaitali Qtr	1		3	1316.84		The Building is not being used	1 pdf	1 jpg	
20	debiganj	Upazila Health Complex Debiganj,Panchagarh	3 std 3rd class employer's Qtr	1	2014	3	1495.59	3900	The Building is being used	1 pdf	1 jpg	
21	tetulia	Uapzila Health Complex Tetulia, Panchagarh	3 std 4th class Employer's Qtr	1		3	1450		Abandoned	1 pdf	No file	
22	tetulia	Uapzila Health Complex Tetulia, Panchagarh	3 std 3rd class Emplyer.s qtr	2		3	1800		Abandoned	1 pdf	No file	
23	tetulia	Uapzila Health Complex Tetulia, Panchagarh	1 std Nurses Dormitory	1		1	1102		Abandoned	1 pdf	No file	
24	tetulia	Uapzila Health Complex Tetulia, Panchagarh	2 std old Doctor.s Qtr	1		2	2800		Abandoned	1 pdf	No file	
25	tetulia	Uapzila Health Complex Tetulia, Panchagarh	3rd class employer's Qtr	1	2013	3		3900	The Building is being used	1 pdf	1 jpg	
26	tetulia	Uapzila Health Complex Tetulia, Panchagarh	2nd class Officer's Qtr	1	2013	3		6000	The Building is being used	1 pdf	1 jpg	
27	tetulia	Uapzila Health Complex Tetulia, Panchagarh	Doctor's Quarter	1	2013	4		7500	The Building is being used	1 pdf	1 jpg	

District Name: Patuakhali

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	bauphal	50 Bedded Upazila Health Complex, Bauphal	1 xlsx	na
2	dashmina	50 Bedded Upazila Health Complex, Dashmina	1 xlsx	na
3	dumki	31 Bedded Upazila Health Complex, Dumki.	1 xlsx	na
4	galachipa	50 Bedded Upazila Health Complex, Galachipa.	1 xlsx	na
5	kalapara	50 Bedded Upazila Health Complex, Kalapara.	1 xlsx	na
6	mirzaganj	50 Bedded Upazila Health Complex Mirzaganj, Patuakhali.	1 xlsx	N/A
7	rangabali	50 Bedded Upazila Health Complex, Rangabali.	1 xlsx	The new 50 bed hospital is under construction. Earlier there was no hospital in this Upazila.

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	bauphal	50 Bedded Upazila Health Complex, Bauphal	2007	HED	6.98 acre	50	2 dwgs	No file	No file	No file	16560	GF-16560.00, 1st.F-14362.00, 2nd.F-5619.00, 3rd.F-5619	2 dwgs	No file	6 jpegs	2 ft	na
2	dashmina	50 Bedded Upazila Health Complex, Dashmina	2011	HED	5.95 acre	50	1 dwg	No file	1 jpeg	No file	21173	GF-21173.00 sft, 1st.F-11288.00 sft	1 dwg	No file	4 jpegs	2 ft	na
3	dumki	31 Bedded Upazila Health Complex, Dumki.	1984	PWD	4.27 acre	50	1 dwg	No file	No file	No file	21173	GF-21173.00 sft, 1st.F-11288.00 sft	1 dwg	No file	7 jpegs	2 ft	na
4	galachipa	50 Bedded Upazila Health Complex, Galachipa.	2005	HED	6.15 acre	50	1 dwg	No file	No file	No file	14362	GF-14362.00, 1st.F-14362.00, 2nd.F-5619.00	1 dwg	No file	3 jpegs	3 ft	na
5	kalapara	50 Bedded Upazila Health Complex, Kalapara.	2010	HED	5.90 acre	50	1 dwg	No file	No file	No file	21173	GF-21173.00 sft, 1st.F-11288.00 sft	1 dwg	No file	4 jpegs	2 ft	na
6	mirzaganj	50 Bedded Upazila Health Complex, Mirzaganj.	1980	HED	4 acre	50	1 dwg	No file	No file	No file	6710	6360	1 dwg	No file	No file	N/a	No
7	rangabali	50 Bedded Upazila Health Complex, Rangabali.	202	HED	5.44 acre	50	1 dwg	No file	No file	No file	3	0	1 dwg	No file	8 jpegs	3 ft	na

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	bauphal	50 Bedded Upazila Health Complex, Bauphal	11	2	4	Deep	4	RCC	well	2 jpegs	info not available	na	na

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
2	dashmina	50 Bedded Upazila Health Complex, Dashmina	11	2	2	Deep	4	RCC	Good	2 jpegs	Possible	Regular	na
3	dumki	31 Bedded Upazila Health Complex, Dumki.	11	2	2	Footing	2	RCC	Since the building was built a long time ago, no upward extension can be done	2 jpegs	Not Possible	na	na
4	galachipa	50 Bedded Upazila Health Complex, Galachipa.	11	2	3	Deep	4	RCC	Since the building was built a long time ago, no upward extension can be done	5 jpegs	Possible	na	na
5	kalapara	50 Bedded Upazila Health Complex, Kalapara.	11	2	2	Footing	4	RCC	Since the building was built a long time ago, no upward extension can be done	5 jpegs	Not Possible	na	na
6	mirzaganj	50 Bedded Upazila Health Complex, Mirzaganj.	12	3	4	Deep	4	RCC	Good	No file	Not Possible	N/A	N/A
7	rangabali	50 Bedded Upazila Health Complex, Rangabali.	12	3	3	Deep	4	RCC	well	4 jpegs	Possible	na	na

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	bauphal	50 Bedded Upazila Health Complex, Bauphal	0	1	Pond	Others	0	No	0	Surface Drain	Rcc Master Drain	Govt. land	na
2	dashmina	50 Bedded Upazila Health Complex, Dashmina	0	1	Pond	Others	0	No	0	Surface Drain	Rcc Master Drain	Govt. land	na
3	dumki	31 Bedded Upazila Health Complex, Dumki.	0	1	no	Septic Tank	0	No	0	Surface Drain	Rcc Master Drain	Govt. land	na
4	galachipa	50 Bedded Upazila Health Complex, Galachipa.	10000	1	pond	Septic Tank	0	No	0	Surface Drain	Rcc Master Drain	Govt. land	na
5	kalapara	50 Bedded Upazila Health Complex, Kalapara.	0	1	no	Septic Tank	0	No	0	Surface Drain	Rcc Master Drain	Govt. land	na
6	mirzaganj	50 Bedded Upazila Health Complex, Mirzaganj.	0	1	N/A	Septic Tank		Yes	0	Surface Drain	Rcc Master Drain	Govt Land to Shimonto River	
7	rangabali	50 Bedded Upazila Health Complex, Rangabali.	30000	1	0	Others	0	No	0	0	0	0	0

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	bauphal	50 Bedded Upazila Health Complex, Bauphal	210	1861	160	330	20	Rcc	Yes	Yes	na

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
2	dashmina	50 Bedded Upazila Health Complex, Dashmina	301	2613	313	87	16	Rcc, Carpeting, 12 rft wide	Yes	Yes	na
3	dumki	31 Bedded Upazila Health Complex, Dumki.	285	1360	357	113	12	12	No	Yes	na
4	galachipa	50 Bedded Upazila Health Complex, Galachipa.	250	1384	256	319	16	12	Yes	Yes	na
5	kalapara	50 Bedded Upazila Health Complex, Kalapara.	490	561	351	284	16	12	No	Yes	na
6	mirzaganj	50 Bedded Upazila Health Complex, Mirzaganj.	225	300	280	239.98	16	12	Yes	Yes	No
7	rangabali	50 Bedded Upazila Health Complex, Rangabali.	225	300	280	2238	16	12	Yes	Yes	na

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	bauphal	50 Bedded Upazila Health Complex, Bauphal	0	0	Stair, Ramp	8	22	Ceiling Fan	no	1	1	Submersible pump with Deep tube well	Not Present	na
2	dashmina	50 Bedded Upazila Health Complex, Dashmina	0	0	Stair, Ramp	2	16	Ceiling Fan	no	1	1	Submersible pump with Deep tube well	Others	na
3	dumki	31 Bedded Upazila Health Complex, Dumki.	0	0	0	4	24	Ceiling Fan	no	1	0	Submersible pump with Deep tube well	Not Present	na
4	galachipa	50 Bedded Upazila Health Complex, Galachipa.	0	0	0	8	30	Ceiling Fan	no	1	1	Submersible pump with Deep tube well	Others	na
5	kalapara	50 Bedded Upazila Health Complex, Kalapara.	0	0	0	4	22	Ceiling Fan	no	1	0	Submersible pump with Deep tube well	Not Present	na
6	mirzaganj	50 Bedded Upazila Health Complex, Mirzaganj.	0	0	Use Link Corridor in lieu of Lift	4	10	Use Ceiling Fan	at present several number of fire extinguisher	2	1	Submersible pump with deep tubewell	Not Present	no
7	rangabali	50 Bedded Upazila Health Complex, Rangabali.	0	0	0	0	0	0	0	0	0	0	Not Present	na

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	bauphal	50 Bedded Upazila Health Complex, Bauphal	REB	Yes	220	250	30	LT	10	30	0	1	10rm, HT Length-92 rft	4rm, Length-197 rft	NA
2	dashmina	50 Bedded Upazila Health Complex, Dashmina	REB	Yes	100	150	50	LT	0	30	0	0	10rm, HT Length-107 rft	4rm, Length-121 rft	NA
3	dumki	31 Bedded Upazila Health Complex, Dumki.	REB	Yes	100	100	0	LT	0	30	0	0	10rm, HT Length-37 rft	4rm, Length-417 rft	NA
4	galachipa	50 Bedded Upazila Health Complex, Galachipa.	REB	Yes	150	150	0	LT	0	30	0	0	10rm, HT Length-107 rft	4rm, Length-227 rft	NA
5	kalapara	50 Bedded Upazila Health Complex, Kalapara.	REB	Yes	100	100	0	LT	0	30	0	0	10rm, HT Length-67 rft	4rm, Length-220 rft	NA
6	mirzaganj	50 Bedded Upazila Health Complex, Mirzaganj.	REB	Yes	100	100	0	LT	0	30	0	0	10rm, HT Length-67 rft	4rm, Length-161 rft	N/A
7	rangabali	50 Bedded Upazila Health Complex, Rangabali.	REB	No	0	0	0	LT	0	0	0	0	0	0	0

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	bauphal	50 Bedded Upazila Health Complex, Bauphal	No	0	0	oxygen cylinder	Yes	No	No	No	Yes	1	NA	NA
2	dashmina	50 Bedded Upazila Health Complex, Dashmina	No	0	0	oxygen cylinder	Yes	No	No	No	No	1	NA	NA
3	dumki	31 Bedded Upazila Health Complex, Dumki.	No	0	0	oxygen cylinder	Yes	No	No	No	No	1	NA	NA
4	galachipa	50 Bedded Upazila Health Complex, Galachipa.	No	0	0	oxygen cylinder	Yes	No	No	No	No	1	NA	NA
5	kalapara	50 Bedded Upazila Health Complex, Kalapara.	No	0	0	oxygen cylinder	Yes	No	No	No	No	1	NA	NA
6	mirzaganj	50 Bedded Upazila Health Complex, Mirzaganj.	No	0	0	oxygen cylinder	Yes	No	No	No	No	1	0	na
7	rangabali	50 Bedded Upazila Health Complex,	No	0	0	0	No	No	No	No	No	0	0	0

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
		Rangabali.												

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	bauphal	50 Bedded Upazila Health Complex, Bauphal	NA	na	1993	0	0	0	Repair and renovation are not eligible	4 jpegs	7 jpegs	na
2	dashmina	50 Bedded Upazila Health Complex, Dashmina	Pump House	1	1984	1	240	240	Repair and renovation are not eligible	No file	No file	na
3	dashmina	50 Bedded Upazila Health Complex, Dashmina	Oxygen room	1	1984	1	242	242	Repair and renovation are not eligible	No file	No file	na
4	dashmina	50 Bedded Upazila Health Complex, Dashmina	0	0	2017	0	0	0	Repair and renovation are not eligible	3 jpegs	5 jpegs	na
5	dashmina	50 Bedded Upazila Health Complex, Dashmina	NA	na	2017	0	0	0	well	4 jpegs	4 jpegs	na
6	dumki	31 Bedded Upazila Health Complex, Dumki.	NA	na	2015	0	0	0	well	3 jpegs	4 jpegs	na
7	galachipa	50 Bedded Upazila Health Complex, Galachipa.	NA	na	1994	0	0	0	0	5 jpegs	5 jpegs	na
8	kalapara	50 Bedded Upazila Health Complex, Kalapara.	NA	13	1994	2	0	0	0	2 jpegs	7 jpegs	na
9	mirzaganj	50 Bedded Upazila Health Complex, Mirzaganj.	Upazila Model Mosque	1	2023	3	11500	20000	Structure works Done as well as Finishing Works on going	No file	No file	na
10	rangabali	50 Bedded Upazila Health Complex, Rangabali.	0	0	2025	0	0	0	0	1 jpeg	6 jpegs	na

District Name: Pirojpur

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	bhandaria	bhandaria upazila health complex	No file	Number of Beds of Existing Hospital Building=50,average OPD=350,ICU,CCU Facility available
2	indurkani	Indurkani upazila health complex	No file	Number of Beds of Existing Hospital Building=50,average OPD=300,icu ccu facility not available
3	kawkhali	kawkhali upazila health complex	No file	Number of Beds of Existing Hospital Building:31,Average OPD=350+,ICU,CCU Facility not availabe
4	mathbaria	Mathbaria upazila health complex	No file	Number of Beds of Existing Hospital Building=50,average OPD=300
5	nazirpur	nazirpur upazila health complex	No file	Number of Beds of Existing Hospital Building=50,average OPD=350+,icu ccu facility not available
6	nesarabad	nesarabad upazila health complex	No file	Number of Beds of Existing Hospital Building=19,average OPD=250-300,,ICU,CCU Facility not availabe

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	bhandaria	bhandaria upazila health complex	2006	HED	no	50	1 pdf	2 jpegs	No file	No file	19707.26	19707.26	1 pdf	No file	7 jpegs	.5 meter	Number of Beds of Existing Hospital Building=50,average OPD=350
2	indurkani	Indurkani upazila health complex	2022	HED	50%	50	1 pdf	No file	No file	No file	5638	5638	1 pdf	No file	9 jpegs	.5 meter up	old building=2005,new building=2022
3	kawkhali	kawkhali upazila health complex	2022	HED	50%	31	1 pdf	2 jpegs	No file	No file	6292	6292	1 pdf	No file	6 jpegs	.5 meter up	old building=1973-74,new building=2022
4	mathbaria	Mathbaria upazila health complex	2023	HED	25%	50	1 pdf	No file	No file	No file	16700	16700	4 pdfs	No file	8 jpegs, 1 mp4	.5 meter	3 storied old building=2008,6 storied new building -under construction
5	nazirpur	nazirpur upazila health complex	2025	HED	25%	50	1 pdf	1 jpeg	No file	No file	8670.94	8670.94	1 pdf	No file	10 jpegs	.5 meter up	3 storied old building=2012
6	nesarabad	nesarabad upazila health complex	2010	HED	25%	19	1 pdf	2 jpegs	No file	4 jpegs	6598	6598	1 pdf	No file	6 jpegs	.00 down	3 storid new hospital building=2010

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	bhandaria	bhandaria upazila health complex	43	1.6	4	Deep	6	RCC	good	No file	Possible	2017	nurse quarter,doctor quarter,3rd class & 4th class quarter,driver room,oxygen room,family planning building,garage,kitchen,store
2	indurkani	Indurkani upazila health complex	50	2	5	Deep	5	RCC	good	No file	Not Possible	no	4 storied old building =2005,5 storied new building=2022

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
3	kawkhali	kawkhali upazila health complex	30	1.5	3	Deep	4	RCC	good	No file	Not Possible	no	most of the buildings were damaged
4	mathbaria	Mathbaria upazila health complex	30	1.5	3	Deep	4	RCC	good	No file	Possible	yes	nurse quarter,doctor quarter,3rd class & 4th class quarter,driver room,oxygen room,family planning building,garage,kitchen,store
5	nazirpur	nazirpur upazila health complex	20	2	2	Deep	5	RCC	good	No file	Not Possible	no	3 storied old building=2012,2 storied new building=2025
6	nesarabad	nesarabad upazila health complex	32	1	3	Deep	4	RCC	good	No file	Possible	yes,2022	most of the buildings were damaged

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	bhandaria	bhandaria upazila health complex	0	1	yes	Septic Tank	1000	No	0	no	no	no	
2	indurkani	Indurkani upazila health complex	10000	1	no	Septic Tank	100	No	0	yes	yes	no	
3	kawkhali	kawkhali upazila health complex	50	1			400	No	0	no	no	no	
4	mathbaria	Mathbaria upazila health complex	0	0	no	Septic Tank	500	No	0	no	no	no	
5	nazirpur	nazirpur upazila health complex	10000	1	no	Septic Tank	1200	No	0	yes	yes	yes	
6	nesarabad	nesarabad upazila health complex	200	1	no		0	No	0	no	no	no	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	bhandaria	bhandaria upazila health complex		630.96		15.71	10	N/A	Yes	No	nurse quarter,doctor quarter,3rd class & 4th class quarter,driver room,oxygen room,family planning building,garage,kitchen,store
2	indurkani	Indurkani upazila health complex					15	N/A	Yes	No	most of the quarter building were damaged.
3	kawkhali	kawkhali upazila health complex		45.43				N/A	No	No	most of the quarter building were damaged.
4	mathbaria	Mathbaria upazila health complex		247			30	N/A	No	Yes	doctor quarter,nurse quarter,3rd and 4th class staff quarter,opd buildind
5	nazirpur	nazirpur upazila health complex					20	N/A	Yes	No	most of the quarter building were damaged.
6	nesarabad	nesarabad upazila health complex					20	N/A	No	No	most of the quarter building were damaged.

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	bhandaria	bhandaria upazila health complex	0	0		3	10		no	2	1		Not Present	no
2	indurkani	Indurkani upazila health complex	0	0		6	8		no	2	2		Not Present	no
3	kawkhali	kawkhali upazila health complex	0	0	0	4	12		no	2	2		Not Present	no
4	mathbaria	Mathbaria upazila health complex	0	0	no	6	8		no	2	2		Not Present	no
5	nazirpur	nazirpur upazila health complex	0	0	0	6	10		no	2	2		Not Present	no
6	nesarabad	nesarabad upazila health complex	0	0	0	6	8		no	2	2		Not Present	no

District Name: Rajbari

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	baliakandi	Baliakandi upazilla health complex	1 xlsx	ok
2	goalandaghat	Goalando Upazilla Complex	2 xlsxs	ok
3	kalukhali	kalukhali upazilla health complex	No file	ok
4	pangsha	Pangsha upazilla health complex	No file	ok

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	baliakandi	Baliakandi upazilla health complex	1968	PWD	5.04 acre	50	1 pdf	No file	No file	No file	49379.38	18195	No file	No file	No file	N/A	ok
2	goalandaghat	Goalondo upazilla health complex	1977	PWD	6.84 acre	50	No file	No file	No file	No file	36000	18000	No file	No file	No file	N/A	ok
3	kalukhali	kalukhali upazilla health complex	2018	HED	3.3753 acre	50	1 pdf	No file	No file	No file	11000	42000	No file	No file	No file	N/A	ok
4	pangsha	Pangsha upazilla health complex	1983	PWD	4.607 acre	40	1 pdf	No file	No file	No file	22000	44000	No file	No file	No file	N/A	ok

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	baliakandi	Baliakandi upazilla health complex	32.99	2.5	3	Footing	3	Load Bearing Brick	vulnerable	No file	Not Possible		ok
2	goalandaghat	Goalando Upazilla Complex	22	2.5	2	Footing	2	Load Bearing Brick	vulnerable	No file	Not Possible	N/A	
3	kalukhali	kalukhali upazilla health complex	44	3	4	Deep	4	RCC	good	No file	Not Possible	need renovation	ok
4	pangsha	Pangsha upazilla health complex	22	2.5	2	Footing	2	Load Bearing Brick	vulnerable	No file	Not Possible	need renovation	ok

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	baliakandi	Baliakandi upazilla health complex	32000	1	no	Septic Tank	0	No	0	vulnerable	vulnerable	Baliakandi pourasova	ok

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
2	goalandaghat	Goalando Upazilla Complex	32000	1	no	Septic Tank	0	No	0	vulnerable	esstential	goyalondo pourasova	ok
3	kalukhali	kalukhali upazilla health complex	40000	1	0	Septic Tank	0	No	0	good	no need	kalukhali pourasova	ok
4	pangsha	Pangsha upazilla health complex	32000	1	no	Septic Tank	0	No	0	vulnerable	vulnerable	pangsha pourasova	ok

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	baliakandi	Baliakandi upazilla health complex					20	12	Yes	Yes	ok
2	goalandaghat	Goalando Upazilla Complex	2003	0	2100	1800	40	12	Yes	Yes	ok
3	kalukhali	kalukhali upazilla health complex					12	10	Yes	Yes	ok
4	pangsha	Pangsha upazilla health complex	0	0	0	0	18	10	Yes	Yes	ok

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional Info (Capacity, Demand etc)
1	baliakandi	Baliakandi upazilla health complex	0	0		12	26		Fire extinguisher	10			Not Present	
2	goalandaghat	Goalando Upazilla Complex	0			12	25		Fire extinguisher	17	0		Not Present	
3	pangsha	Pangsha upazilla health complex	0	0		16	20		Fire extinguisher	10			Not Present	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	baliakandi	Baliakandi upazilla health complex	PDB	Yes	100					100					
2	goalandaghat	Goalando Upazilla Complex	PDB	Yes	100	250			10	100	0	1			

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
3	pangsha	Pangsha upazilla health complex	PDB	Yes						100					

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	baliakandi	Baliakandi upazilla health complex	No				Yes	No	No	No	No			
2	baliakandi	Baliakandi upazilla health complex	No				Yes	No	No	No	No			
3	goalandaghat	Goaland Upazilla Complex					Yes	No	No	No	No	0		
4	pangsha	Pangsha upazilla health complex	No				Yes	No	No	No	No			

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	baliakandi	Baliakandi upazilla health complex	Doctors ,nurse and staff quraters	10		0	0	0	Need renovation	No file	No file	ok
2	goalandaghat	Goaland Upazilla Complex	Doctors , nurse and staff quraters	11						No file	No file	
3	kalukhali	kalukhali upazilla health complex	Doctors ,nurse and staff quraters	5	2018	4	0	0	Need renovation	No file	No file	ok
4	pangsha	Pangsha upazilla health complex	Doctors ,nurse and staff quraters	10			0	0	Need renovation	No file	No file	ok

District Name: Rajshahi

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	bagmara	50 Beded UHC, Bagmara	1 xlsx	
2	durgapur	50 Beded UHC, Durgapur	1 xlsx	
3	godagari	50 Beded UHC, Godagari	1 xlsx	
4	mohanpur	50 Beded UHC, Mohanpur	1 xlsx	
5	puthia	50 Beded UHC, Puthia	1 xlsx	
6	tanore	50 Beded UHC, Tanore	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (If any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	bagmara	50 Beded UHC, Bagmara	1983	Other		50	1 dwg, 4 pdfs	1 pdf	4 jpegs	1 dwg	17735	30610	1 pdf	No file	3 jpegs	N/A	
2	durgapur	50 Beded UHC, Durgapur	1982	Other		50	1 dwg, 4 pdfs	3 pdfs	2 pdfs	No file	6874	20622	1 dwg	No file	9 jpegs		one old Building 2 storied Brick structure Plinth area 13774 sft, Total floor area 26163(construction year 1982)sft, New Building Cons. year 2015
3	godagari	50 Beded UHC, Godagari	1983	Other		50	1 dwg, 1 pdf	3 pdfs	1 pdf	No file	9448	29546	1 dwg	No file	3 jpegs		New building Cons. year 2025. one another Building 2 storied RCC structure (3 storied foundation) Plinth area 6285 sft, Total floor area 12560 sft(construction year 2011))sft. Constructed by HED
4	mohanpur	50 Beded UHC, Mohanpur	1983	Other		50	1 dwg, 3 pdfs	1 pdf	4 jpegs	1 dwg	14333	35796	1 pdf	No file	3 jpegs	N/A	
5	paba	Upazilla Health Complex, Paba, Rajshahi.	1974	PWD		31	1 dwg	1 pdf	No file	No file	9154.7	9154.7	No file	No file	1 jpeg		
6	puthia	50 Beded UHC, Puthia	1982	Other		50	1 dwg, 4 pdfs	3 pdfs	1 pdf	1 dwg	5869	15385	1 dwg	No file	4 jpegs		one old Building 2 storied Brick structure Plinth area 13774 sft, Total floor area 26163(construction year 1982)sft, New building Cons. year 2015
7	tanore	50 Beded UHC, Tanore	1983	Other		50	1 dwg, 3 pdfs	1 pdf	2 pdfs	1 dwg	1773.65	5320.95	1 pdf	No file	2 jpegs	N/A	

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	bagha	Bagha Upazilla Health Complex	22	1.5	2	Footing		Load Bearing Brick		No file			
2	bagmara	50 Beded UHC, Bagmara	22	2	2	Footing	6	RCC	Well condition. For vertical extension details study needed	No file	info not available	n/a	one old Building 3 storied Brick structure and one new building
3	charghat	Charghat Upozila Health Complex	33	2	3	Deep		RCC		No file	info not available		
4	durgapur	50 Beded UHC, Durgapur	33	1.5	3	Footing	6	RCC	Well condition. For vertical extension details study needed	No file	info not available	n/a	one old Building 2 storied Brick structure Plinth area 12218 sft, Total floor area 24436sft (Construction year 1984)
5	godagari	50 Beded UHC, Godagari	33	2	3	Footing	6	RCC	Well condition. For vertical extension details study needed	No file	info not available	n/a	Old Building height 20 ft. EGL to Pl= 2ft
6	mohanpur	50 Beded UHC, Mohanpur	33	2	3	Footing	6	RCC	Well condition. For vertical extension details study needed	No file	info not available	n/a	one old Building 2 storied Brick structure and one new building
7	paba	Upazilla Health Complex, Paba, Rajshahi.	22	1.5	2	Footing	2	Load Bearing Brick	Not Good	No file	Not Possible		
8	puthia	50 Beded UHC, Puthia	33	2	3	Footing	6	RCC	Well condition. For vertical extension details study needed	No file	info not available	n/a	one old Building 2 storied Brick structure Plinth area 13774 sft, Total floor area 26163(construction year 1982)sft
9	tanore	50 Beded UHC, Tanore	33	2.5	3	Footing	6	RCC	Well condition. For vertical extension details study needed	No file	info not available	n/a	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	bagha	Bagha Upazilla Health Complex	0	1		Septic Tank		No				service not available	
2	bagmara	50 Beded UHC, Bagmara	0	2		Septic Tank		No	2	Internal drain			
3	charghat	Charghat Upozila Health Complex	0	2		Septic Tank		No				Service not available	
4	durgapur	50 Beded UHC, Durgapur	0	1		Septic Tank		No	0	Internal drain		Have a pond and municipality drain	
5	godagari	50 Beded UHC, Godagari	25000	1		Septic Tank		No	0	Internal drain		Have a pond	
6	mohanpur	50 Beded UHC, Mohanpur	0	1		Septic Tank		No	1	Internal drain			
7	paba	Upazilla Health Complex, Paba, Rajshahi.	0	2		Septic Tank		No	0			Service Not Available	
8	puthia	50 Beded UHC, Puthia	0	1		Septic Tank		No	0	Internal drain		Have a pond outside the area	
9	tanore	50 Beded UHC, Tanore	0	1		Septic Tank		No	0	Internal drain		Have a pond	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	bagha	Bagha Upazilla Health Complex					18	Rigid pavement. Bituminous carpeting	Yes	Yes	
2	bagmara	50 Beded UHC, Bagmara	0	2178	0	0	12	RCC Road	Yes	No	
3	charchat	Charchat Upozila Health Complex				400	32	Rigid pavement.	Yes	Yes	
4	durgapur	50 Beded UHC, Durgapur	0	1333	0	0	20	RCC Road	Yes	No	
5	godagari	50 Beded UHC, Godagari	0	2612	0	0	14	RCC Road	Yes	No	
6	mohanpur	50 Beded UHC, Mohanpur	0	2434	0	0	30	RCC Road	Yes	No	
7	paba	Upazilla Health Complex, Paba, Rajshahi.	0	1578.91	459.57	0	18	R.C.C (with brick chips)	Yes	Yes	
8	puthia	50 Beded UHC, Puthia	0	2787	0	575	20	RCC Road	Yes	No	
9	tanore	50 Beded UHC, Tanore	0	2028.5	0	0	24	RCC Road	Yes	No	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	bagmara	50 Beded UHC, Bagmara	0	0	NA	24		NA	0	4	0	NA	Not Present	NA
2	durgapur	50 Beded UHC, Durgapur	0	0	NA	10		NA	0	2	0	NA	Not Present	NA
3	godagari	50 Beded UHC, Premtoli, Godagari	0	0	NA	20		NA	0	2	0	NA	Not Present	NA
4	mohanpur	50 Beded UHC, Mohonpur	0	0	NA	12		NA	0	5	0	NA	Not Present	NA
5	puthia	50 Beded UHC, Puthia	0	0	NA	10		NA	0	2	0	NA	Not Present	NA
6	tanore	50 Beded UHC, Tanore	0	0	NA	48		NA	0	12	0	NA	Not Present	NA

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	bagmara	50 Beded UHC, Bagmara	REB	Yes	0	0	0	MDB	0	150	0	0	25 RM NYY 150 meter,	WAPS 800 meter	

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
2	durgapur	50 Beded UHC, Durgapur	REB	Yes	0	40	400	MDB	0	150	0	0	25 RM NYY 150 meter,	WAPS 800 meter	
3	godagari	50 Beded UHC, Premtoli, Godagari	NESCO	Yes	150	150	400	LT HT PFI MDB	60	100	0	0	40 meter, 35 RM HT; 35 RM Armored 70 meter,	WAPS 800 meter	
4	mohanpur	50 Beded UHC, Mohonpur	REB	Yes	200	0	400	MDB	0	150	0	0	25 RM NYY 150 meter,	WAPS 800 meter	
5	puthia	50 Beded UHC, Puthia	REB	Yes	40	40	400	MDB	0	150	0	0	25 RM NYY 150 meter,	WAPS 800 meter	
6	tanore	50 Beded UHC, Tanore	NESCO	Yes	200	250	50	LT HT PFI MDB	25	100	0	0	40 meter,50 RM HT; 25 RM NYY 200 meter,	WAPS 800 meter, 25 RM NYY 300 meter,	

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	bagmara	50 Beded UHC, Bagmara	No	0	0		Yes	No	No	No	Yes			
2	durgapur	50 Beded UHC, Durgapur	No	0	0		Yes	No	No	No	Yes			
3	godagari	50 Beded UHC, Premtoli, Godagari	No	0	0		Yes	No	No	Yes	Yes			
4	mohanpur	50 Beded UHC, Mohonpur	No	0	0		Yes	No	No	No	Yes			
5	puthia	50 Beded UHC, Puthia	No	0	0		Yes	No	No	No	Yes	0	-	
6	tanore	50 Beded UHC, Tanore	No	0	0		Yes	No	No	Yes	Yes			

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	bagha	Bagha Upazilla Health Complex	Quarter			4	2275	9100	Useable	No file	No file	
2	bagha	Bagha Upazilla Health Complex	Quarter			4	2330	9320	Useable	No file	No file	
3	bagha	Bagha Upazilla Health Complex	Garage			1	750	750	Use as Garage	No file	No file	
4	bagha	Bagha Upazilla Health Complex	Pump House			1	690	690	Service running	No file	No file	
5	bagha	Bagha Upazilla Health Complex	Quarter			2	1180	2360	Dilapidated Building	No file	No file	
6	bagha	Bagha Upazilla Health Complex	Quarter			2	1650	3300	Useable	No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
7	bagha	Bagha Upazilla Health Complex	UHFPO Quarter			1	1000	1000	abandoned	No file	No file	
8	bagha	Bagha Upazilla Health Complex	Doctor's Quarter			4	1450	5800	use as doctor's	No file	No file	
9	bagha	Bagha Upazilla Health Complex	Medical cum ward			2	3250	6500	Service running	No file	No file	
10	bagha	Bagha Upazilla Health Complex	Outdoor unit			3	7200	21600	Service running	No file	No file	
11	charghat	Charghat Upazilla Health Complex	Staff Quarter's			1	3610	3610	abandoned	No file	No file	
12	charghat	Charghat Upazilla Health Complex	TB & Leprosy Hospital			1	800	800	Service running	No file	No file	
13	charghat	Charghat Upazilla Health Complex	RTC Hostel Building			2	2000	4000	Few cracks on Beam Column wall and Roof slab	No file	No file	
14	charghat	Charghat Upazilla Health Complex	Nurse's Quarter			3	1550	4650	Use as nurse's quarter	No file	No file	
15	charghat	Charghat Upazilla Health Complex	Nurse's Quarter			3	1550	4650	Use as nurse's quater	No file	No file	
16	charghat	Charghat Upazilla Health Complex	Doctor's Quarter			2	2250	4500	Use As Doctor's Quarter	No file	No file	
17	charghat	Charghat Upazilla Health Complex	Staff Quarter			1	620	620	dilapidated Condition	No file	No file	
18	charghat	Charghat Upazilla Health Complex	RMO Quarter			1	1200	1200	Abandoned	No file	No file	
19	charghat	Charghat Upazilla Health Complex	UHFPO Quarter			1	1200	1200	Abandoned	No file	No file	
20	charghat	Charghat Upazilla Health Complex	Outdoor Unit			3	2000	6000	Few Cracks on Beam, Column and Roof slab	No file	No file	
21	durgapur	50 Beded UHC, Durgapur	4th Class Quarter		1982	3	1400	4200	need to repair	No file	1 jpeg	Brick Structure
22	durgapur	50 Beded UHC, Durgapur	3rd Class Quarter		1982	2	1800	3600	need to repair	No file	1 jpeg	Brick Structure
23	durgapur	50 Beded UHC, Durgapur	2nd Class Quarter		1982	2	2200	4400	need to repair	No file	1 jpeg	Brick Structure
24	durgapur	50 Beded UHC, Durgapur	Nurse's Dormitory		1982	1	800	800	need to repair	No file	No file	Brick Structure
25	durgapur	50 Beded UHC, Durgapur	Nurse's Quarter		1982	2	2200	4400	need to repair	No file	1 jpeg	Brick Structure
26	durgapur	50 Beded UHC, Durgapur	Doctor's Quarter		1982	3	2800	6850	need to repair	No file	1 jpeg	Brick Structure
27	durgapur	50 Beded UHC, Durgapur	Old hospital building		1982	2	12218	24436	well condition	1 pdf	5 jpegs	Brick Structure
28	godagari	50 Beded UHC, Godagari	3rd Class Quarter 5		1983	2	2825	4237	need to minor repair	No file	1 jpeg	
29	godagari	50 Beded UHC, Godagari	3rd Class Quarter 4		1983	1	1437	1437	well condition	No file	No file	Brick Structure
30	godagari	50 Beded UHC, Godagari	3rd Class Quarter 3		2011	2	1864	3728	well condition	No file	1 jpeg	
31	godagari	50 Beded UHC, Godagari	3rd Class Quarter 2		2011	2	1578	3156	well condition	No file	1 jpeg	
32	godagari	50 Beded UHC, Godagari	3rd Class Quarter-1		2011	2	1294	2588	well condition	No file	1 jpeg	
33	godagari	50 Beded UHC, Godagari	Pump House		2011	1	254	254	well condition	No file	1 jpeg	
34	godagari	50 Beded UHC, Godagari	TB Clinic		2011	1	1390	1390	well condition	No file	1 jpeg	
35	godagari	50 Beded UHC, Godagari	Store		2011	1	2358	2358	well condition	No file	1 jpeg	
36	godagari	50 Beded UHC, Godagari	Dormitory		2011	1	1412	1412	well condition	No file	1 jpeg	
37	godagari	50 Beded UHC, Godagari	Old hospital building		2011	2	6285	12570	well condition	No file	6 jpegs	RCC structure

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
38	godagari	50 Beded UHC, Tanore	Garage		2011	1	624	624	well condition	No file	1 jpeg	
39	paba	Upazilla Health Complex, Paba, Rajshahi.	Main Hospital Building (OPD)		2011	3	10526.32	31578.96	Good	No file	No file	
40	paba	Upazilla Health Complex, Paba, Rajshahi.	Doctor quarter Building		2011	3	1021.21	3063.63	Good	No file	No file	
41	paba	Upazilla Health Complex, Paba, Rajshahi.	Dormitory Building (For Doctor)		2011	2	2251.98	4583.96	Good	No file	No file	
42	paba	Upazilla Health Complex, Paba, Rajshahi.	Staff Quarter Building (For 3rd & 4th Class) 3 Nos Bldg.	3	1974	2	2957.11	14559.66	Good	No file	No file	
43	paba	Upazilla Health Complex, Paba, Rajshahi.	Dormitory Building (For Nurse)		1974	3	2957.11	8871.33	Good	No file	No file	
44	puthia	50 Beded UHC, Puthia	garage		1984	1	496	496	well condition	No file	1 jpeg	Brick Structure
45	puthia	50 Beded UHC, Puthia	Male Doctor's Dormitory		1984	2	2136	4272	need to minor repair	No file	1 jpeg	Brick Structure
46	puthia	50 Beded UHC, Puthia	4th Class Quarter- 2		1984	3	1364	4092	need to minor repair	No file	1 jpeg	Brick Structure
47	puthia	50 Beded UHC, Puthia	4th Class Quarter 1		1984	3	1254	3762	need to minor repair	No file	1 jpeg	Brick Structure
48	puthia	50 Beded UHC, Puthia	3rd Class Quarter 2		1982	2	1254	2508	need to repair	No file	1 jpeg	
49	puthia	50 Beded UHC, Puthia	3rd Class Quarter 1		1982	2	1753	5259	need to repair	No file	1 jpeg	Brick Structure
50	puthia	50 Beded UHC, Puthia	Doctor's Quarter 2		1982	2	2238	4476	need to repair	No file	1 jpeg	Brick Structure
51	puthia	50 Beded UHC, Puthia	Doctor's Quarter 1		1982	3	2131	6393	need to repair	No file	1 jpeg	Brick Structure
52	puthia	50 Beded UHC, Puthia	Female Dormitory		1982	2	2853	4279	need to repair	No file	1 jpeg	Brick Structure
53	puthia	50 Beded UHC, Puthia	Old hospital building		1982	2	13773	26162	well condition	1 pdf	9 jpegs	Brick Structure
54	tanore	50 Beded UHC, Tanore	Building 3		1983	2	1500	1700	Damaged	No file	1 jpeg	
55	tanore	50 Beded UHC, Tanore	Building 2		1983	2	2000	2000	Damaged	No file	1 jpeg	
56	tanore	50 Beded UHC, Tanore	Building 1		1983	2	3750	7500	Damaged	No file	1 jpeg	
57	tanore	50 Beded UHC, Tanore	3rd Class Quarter		2014	2	3200	6400	well condition	No file	1 jpeg	
58	tanore	50 Beded UHC, Tanore	2nd Class Quarter		2014	2	1450	2900	well condition	No file	1 jpeg	
59	tanore	50 Beded UHC, Tanore	1st Class Quarter		2014	2	3000	6000	well condition	No file	1 jpeg	

District Name: Rangamati

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	baghaichhari	Baghaichhari Health Complex	1 xlsx	ok
2	juraichhari	Juraichhari Health Complex	1 xlsx	ok
3	kaptai	Kaptai Upazila Health Complex	1 xlsx	ok
4	kawkhali	Kawkhali Upazila Health Complex	1 xlsx	ok
5	langadu	Langadu Upazila Health Complex	1 xlsx	ok
6	naniarchar	Naniarchar Upazila Health Complex	1 xlsx	ok

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	baghaichhari	Baghaichhari Health Complex	1964	PWD	available	31	No file	No file	No file	No file	6200	Ground Floor 6200 sft, 1st floor 6200 sft	No file	No file	5 jpegs	never flooded	
2	juraichhari	Juraichhari Health Complex	2025	HED	available	31	No file	No file	No file	No file	8400	Ground Floor 8400 sft, 1st floor 8400 sft, 2nd floor 8400 sft, 3rd floor 8400 sft	No file	No file	4 jpegs	never flooded	
3	kaptai	Kaptai Upazila Health Complex	2018	HED	3.5 acre land	50	No file	No file	No file	No file	6000	Ground Floor 6000 sft, 1st floor 6000 sft, 2nd floor 6000 sft, 3rd floor 6000 sft	No file	No file	No file	never flooded	
4	kawkhali	Kawkhali Upazila Health Complex	2022	HED	yes	50	1 pdf	No file	1 pdf	1 pdf	11000	Ground floor 9000, 1st Floor 8500, 2nd floor 8500	1 pdf	No file	3 jpegs	Never Flooded	
5	langadu	Langadu Upazila Health Complex	2016	HED	yes	50	No file	No file	No file	No file	22625	Ground floor 12650, 1st Floor 12650, 2nd floor 9975, 3rd floor 9975	No file	No file	No file	Never Flooded	
6	naniarchar	Naniarchar Upazila Health Complex	1982	PWD	yes	31	No file	No file	No file	No file	3120	Ground floor 3120	No file	No file	No file	Never Flooded	

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	baghaichhari	Baghaichhari Upazila Health Complex	24	2	2	Footing	2	Load Bearing Brick	Load bearing structure, repair needed	No file	Not Possible		
2	juraichhari	Juraichhari Health Complex	44	2	4	Footing	4	RCC	building is under construction	No file	Not Possible	building is under construction	

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
3	kaptai	Kaptai Upazila Health Complex	44	3	4	Footing	4	RCC	good condition	No file	Not Possible		
4	kawkhali	Kawkhali Upazila Health Complex	33	3	3	Footing	5	RCC	Good condition, no visible cracks are noticed	No file	Possible		
5	langadu	Langadu Upazila Health Complex	40	2	4	Footing	5	RCC	4 storied Building, New Good condition, no visible cracks are noticed. 2 storied old building is in poor condition	No file	info not available	data was not found	
6	naniarchar	Naniarchar Upazila Health Complex	12	2	1	Footing	1	Load Bearing Brick	almost damaged building	No file	Not Possible	data was not found	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	baghaichhari	Baghaichari Upazila Health Complex	0	2	no additional water supply facilities	Septic Tank		No	0	surface drain of bricks 300mm	required	80 ft from hospital building	
2	juraichhari	Juraichari Health Complex	10000	2	no additional water supply facilities	Septic Tank		No	0	drain construction is going on	required	200 ft from hospital building	
3	kaptai	kaptai Upazila Health Complex	10000	1	no additional water supply facilities	Septic Tank		No	0	surface drain 300 mm, master drain 600 mm	required	120 ft from hospital building	
4	kawkhali	Kawkhali Upazila Health Complex	10000	1	1 shallow tube well, no additional water supply facility	Septic Tank	2400	No	0	surface drain 300mm , master drain 600mm , total length 1000 rft	required	800 feet away from main hospital building	
5	langadu	Langadu Upazila Health Complex	0	1	no additional water supply facility	Septic Tank	100	No	0	not up the mark	Drainage facilities are required for discharging rain water	400 feet away from main hospital building	
6	naniarchar	Naniarchar Upazila Health Complex	0	2	no additional water supply facility	STP	10	No	0	not up the mark	Drainage facilities are required for wastewater and for discharging rain water	Just a dustbin 150 feet away from main hospital building	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	baghaichhari	Baghaichari Upazila Health Complex	1250	250	350	1100	18	HBB road 6 ft	No	Yes	
2	juraichhari	Juraichari Health Complex	0	0		1100	18	6 ft width CC HBB road of 220 ft, Mud road 800 ft	No	Yes	
3	kaptai	kaptai Upazila Health Complex	0	600	0	1100	10	6 ft width CC RCC/CC road of 220 ft	No	Yes	
4	kawkhali	Kawkhali Upazila Health Complex	0	1928	0	1200	10	8 ft width, 850 ft long RCC/CC road, good condition	Yes	Yes	
5	langadu	Langadu Upazila Health Complex	330	1100	400	300	12	8 feet width, 480 feet length, CC Road	No	Yes	
6	naniarchar	Naniarchar Upazila Health Complex	0	0	600	900	12	6 feet width, 100 feet length CC Road, 270 feet	No	Yes	

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
								earth road			

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional Info (Capacity, Demand etc)
1	baghaichhari	বাঘাইছড়ি উপজেলা স্বাস্থ্য কমপ্লেক্স	0	0		14	10		There are 5 fire extinguishers	2	0		Autoclave	
2	barkal	বরকল উপজেলা স্বাস্থ্য কমপ্লেক্স	0	0		0	24		0	1	1	Existing pumps need to be replaced.	Autoclave	Not is use.
3	belaichhari	বিলাইছড়ি উপজেলা স্বাস্থ্য কমপ্লেক্স	0	0		14	10		There are 5 fire extinguishers	1	0	Existing pump needs to be replaced and more pumps are required.	Autoclave	Not is use.
4	juraichhari	জুরাছড়ি উপজেলা স্বাস্থ্য কমপ্লেক্স	0	0		0	30	Tin shed structure of 10 bed Upazila Health Complex has been demolished. New building for 50 bed Upazila Health Complex is being constructed by HED.	0	1	0		Autoclave	Not is use.
5	kaptai	কাপ্তাই উপজেলা স্বাস্থ্য কমপ্লেক্স	0	0		0	24		There are 30 fire extinguishers	5.5	7.5		Autoclave	Not is use.
6	kawkhali	কাউখালী উপজেলা স্বাস্থ্য কমপ্লেক্স	0	0		9	15		There are 25 fire extinguishers	3	0	Existing pumps need to be replaced.	Autoclave	40 KW Autoclave
7	langadu	লংগদু উপজেলা স্বাস্থ্য কমপ্লেক্স	0	0		21	4		There are 30 fire extinguishers	3	0	Existing pumps need to be replaced.	Autoclave	40 KW Autoclave
8	naniarchar	নানিয়ারচর উপজেলা স্বাস্থ্য কমপ্লেক্স	0	0		0	24		There are 8 fire extinguishers	0.5	0	Existing pump needs to be replaced and more pumps are required.	Autoclave	55KW Autoclave (Not in use)
9	rajasthali	রাজস্থলী উপজেলা স্বাস্থ্য কমপ্লেক্স	0	0		12	12		There are 8 fire extinguishers	2.5	0	Existing pumps need to be replaced.	Autoclave	Not is use.

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	baghaichhari	বাঘাইছড়ি উপজেলা স্বাস্থ্য কমপ্লেক্স	PDB			0		No Sub-station is available	10		0	0	16 RM NYY Cable, L= 10m		
2	barkal	বরকল উপজেলা স্বাস্থ্য কমপ্লেক্স	PDB			0		No Sub-station is available	2.5		0	0	16 RM NYY Cable, L= 50m		
3	belaichhari	বিলাইছড়ি উপজেলা স্বাস্থ্য কমপ্লেক্স	PDB			100		All the componens are available	10		0	0	3*70 HT Cable, 80m	4*95 NYY, from transformer to MDB; L= 200 m	

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
4	juraichhari	জুরাছড়ি উপজেলা স্বাস্থ্য কমপ্লেক্স	PDB			0		No Sub-station is available	0		0	0			Tin shed structure of 10 bed Upazila Health Complex has been demolished. New building for 50 bed Upazila Health Complex is being constructed by HED.
5	kaptai	কাপ্তাই উপজেলা স্বাস্থ্য কমপ্লেক্স	PDB		100	300		All the componenrs are available	20		0	0	3*95 HT Cable, 60m	4*150 NYY, from transformer to MDB; L= 100 m	Condition of wires is not up to the mark
6	kawkhali	কাউখালী উপজেলা স্বাস্থ্য কমপ্লেক্স	PDB		100	150		All the componenrs are available	62.5		0	0	3*70 HT Cable, 50m	4*120 NYY, from transformer to MDB; L= 300 m	Condition of wires is not up to the mark
7	langadu	লংগদু উপজেলা স্বাস্থ্য কমপ্লেক্স	PDB		100	150		All the componenrs are available	62.5		0	0	3*70 HT Cable, 50m	4*120 NYY, from transformer to MDB; L= 150 m	Condition of wires is not up to the mark
8	naniarchar	নানিয়ারচর উপজেলা স্বাস্থ্য কমপ্লেক্স	PDB			0		No Sub-station is available	10		0	0	16 RM NYY Cable, L= 50m		The generator is unserviceable
9	rajasthali	রাজস্থলী উপজেলা স্বাস্থ্য কমপ্লেক্স	PDB		75	100		All the componenrs are available	40		0	0	3*70 HT Cable, 50m	4*95 NYY, from transformer to MDB; L= 100 m	Condition of wires is not up to the mark

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	baghaichhari	বাঘাইছড়ি উপজেলা স্বাস্থ্য কমপ্লেক্স	No			Oxygen cylinders are used	Yes	No	No	No	Yes	0	Networking/Internet System is required	
2	barkal	বরকল উপজেলা স্বাস্থ্য কমপ্লেক্স	No			Oxygen cylinders are used	Yes	No	No	No	Yes	0	Networking/Internet System is required	
3	belaichhari	বিলাইছড়ি উপজেলা স্বাস্থ্য কমপ্লেক্স	No			Oxygen cylinders are used	Yes	No	No	No	Yes	0	Networking/Internet System is required	
4	juraichhari	জুরাছড়ি উপজেলা স্বাস্থ্য কমপ্লেক্স	No			Oxygen cylinders are used	Yes	No	No	No	No	0	Networking/Internet System is required	Tin shed structure of 10 bed Upazila Health Complex has been demolished. New building for 50 bed Upazila Health Complex is being constructed by HED.
5	kaptai	কাপ্তাই উপজেলা স্বাস্থ্য কমপ্লেক্স	No			Oxygen cylinders are used	Yes	No	No	No	Yes	0	Networking/Internet System is required	
6	kawkhali	কাউখালী উপজেলা স্বাস্থ্য কমপ্লেক্স	No			Oxygen cylinders are used	Yes	No	No	No	Yes	0	Networking/Internet System is required	
7	langadu	লংগদু উপজেলা স্বাস্থ্য কমপ্লেক্স	No			Oxygen cylinders are used	Yes	No	No	No	Yes	0	Networking/Internet System is required	
8	naniarchar	নানিয়ারচর উপজেলা স্বাস্থ্য কমপ্লেক্স	No			Oxygen cylinders are used	Yes	No	No	No	Yes	0	Networking/Internet System is required	

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
9	rajasthali	রাজস্থলী উপজেলা স্বাস্থ্য কমপ্লেক্স	No			Oxygen cylinders are used	Yes	No	No	No	Yes	0	Networking/Internet System is required	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	kawkhali	Kawkhali Upazila Health Complex	Staff Quarter	1	2020	2	1800	3500	Good condition	No file	No file	

District Name: Rangpur

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	gangachara	Upazila Health Complex Gangacara , Rangpur	1 xlsx	
2	pirganj	Upazila health Complex Pirganj	2 xlsxs	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	badarganj	Badarganj Upazila Health Complex	1982	PWD	Yes	50	1 dwg	No file	No file	1 dwg	7993	Old Building GF=7993, 1st Floor=7993 & New Building GF=7215 1st= 7215, 2nd=7215	No file	No file	10 jpegs	NA	
2	gangachara	Upazila Health Complex Gangacara , Rangpur	1973	PWD	Yes	20	1 dwg	No file	No file	No file		950	No file	No file	10 jpegs	no high flood occures in recent recent years	
3	kaunia	Kawnia Upazila Health Complex, Rangpur	1984	PWD	Yes	50	1 dwg	No file	1 pdf	1 pdf	8762	Old Building GF=8762, 1st Floor=8762 New Building GF=7099, 1st Floor=7816, 2nd Floor=7099	No file	No file	10 jpegs	NA	
4	mithapukur	Upazila Health Complex, Mithapukur	1974	PWD	Yes	50	1 dwg	No file	No file	No file			No file	No file	8 jpegs	There is no risk of flooding.	
5	pirgachha	Upazila Health Complex, Pirgachha, Rangpur	1978	PWD	Yes	50	1 dwg	No file	No file	No file	11000	9000	No file	No file	7 jpegs		
6	pirganj	Upazila Health Complex Gangacara , Rangpur	1974	PWD	Yes	50	1 dwg	No file	No file	No file	9000		No file	No file	No file	no high flood occures in recent recent years	১ টি ২ তলা ভবন যেটি ১৯৭৪ সালে গণপূর্ত কর্তৃক নির্মিত। আরেকটি ৩ তলা ভবন যেটি ২০০৪ সালে HED কর্তৃক নির্মিত
7	taraganj	Taraganj Upazila Health Complex	1992	HED	Yes	50	1 dwg	No file	No file	1 dwg	11200	11000	1 dwg	No file	10 jpgs	NA	

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	badarganj	Badarganj Upazila Health Complex	35	2	3	Footing	3	RCC	Good	No file	info not available	NA	New Building (2010)
2	badarganj	Badarganj Upazila Health Complex	25	1.5	2	Footing	2	RCC	Not Good	No file	Not Possible	NA	Old Building (1982)
3	gangachara	Upazila Health Complex Gangacara , Rangpur	25	2	2	Footing	2	Load Bearing Brick	Building is constructed 1974 , Present condition is vulnerable	No file	Not Possible		

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
4	kaunia	Kawnia Upazila Health Complex, Rangpur	25	1.5	2	Footing	2	RCC	Bad Condition	No file	Not Possible	N/A	
5	pirgachha	Upazila Health Complex, Pirgachha, Rangpur	20	2	2	Footing	2	RCC		No file			
6	pirganj	Upazila Health Complex Gangacara , Rangpur	30	2	3	Footing		RCC		No file	Not Possible		
7	taraganj	Taraganj Upazila Health Complex	23	1.5	2	Deep	2	Load Bearing Brick	Not Good	No file	Not Possible	NA	Building (1992)

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	badarganj	Badarganj Upazila Health Complex	0	1	N/A	Septic Tank	0	No	0	Surface Drain	Main Drain	Rangpur Sadar	
2	gangachara	Upazila Health Complex Gangacara , Rangpur	10000	1		Septic Tank		No		There is a Pourasava Drain Outside the boundary wall			
3	kaunia	Kownia Upazila Health Complex, Rangpur	0	1		Septic Tank		No		Surface drain	Main Drainage System	Rangpur Sadar	
4	pirgachha	Upazila Health Complex, Pirgachha, Rangpur		1		Septic Tank		No					
5	pirganj	Upazila Health Complex Gangacara , Rangpur		2		Septic Tank		No					
6	taraganj	Taraganj Upazila Health Complex	0	1	N/A	Septic Tank	0	No	0	No	No	Rangpur Sadar	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	badarganj	Badarganj Upazila Health Complex	0	1869	0	1869	15	All shown in uploaded picture and digital survey	Yes	Yes	
2	gangachara	Upazila Health Complex Gangacara , Rangpur		8		2	30	Internal road connectivity seems weel whown in picture& Digital survey	Yes	No	
3	kaunia	Kawnia Upazila Health Complex, Rangpur	0	2100	0	2100	18	Internal road connectivity system shown in picture& Digital survey.	Yes	Yes	
4	pirgachha	Upazila Health Complex, Pirgachha, Rangpur	10	8			18		No	Yes	
5	pirganj	Upazila Health Complex Gangacara , Rangpur		10							
6	taraganj	Taraganj Upazila Health Complex	0	1725	0	1725	30	All shown in uploaded picture and digital survey	Yes	Yes	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	kaunia	Kawnia Upazila Health Complex, Rangpur	Family Planning Building	N/A	0	2	1693	3386	Average	No file	No file	
2	kaunia	Kawnia Upazila Health Complex, Rangpur	Doctors Quarter	N/A	2010	2	1884	3768	Good	No file	No file	
3	kaunia	Kawnia Upazila Health Complex, Rangpur	Doctors Dormitory	N/A	1985	1	1264	1264	Abandoned	No file	No file	
4	kaunia	Kawnia Upazila Health Complex, Rangpur	Doctors Quarter	N/A	2011	2	2395	4790	Good	No file	No file	
5	kaunia	Kawnia Upazila Health Complex, Rangpur	Nurses Dormitory	N/A	2010	2	2778	5556	Good	No file	No file	
6	kaunia	Kawnia Upazila Health Complex, Rangpur	Pump House	N/A	1982	1	505	505	Not Good	No file	No file	
7	kaunia	Kawnia Upazila Health Complex, Rangpur	Doctors Quarter	N/A	0	1	1363	1363	Not Good	No file	No file	
8	kaunia	Kawnia Upazila Health Complex, Rangpur	Nurses Quarter	N/A	1982	3	1368	4104	Abandoned	No file	No file	
9	kaunia	Kawnia Upazila Health Complex, Rangpur	Nurses Quarter	N/A	1982	2	1544	3088	Abandoned	No file	No file	
10	kaunia	Kawnia Upazila Health Complex, Rangpur	Doctors Quarter	N/A	2010	3	1190	3570	Not Good	No file	No file	
11	pirgachha	Upazila Health Complex, Pirgachha, Rangpur	OPD Cum OT Complex	2	2011	2	8000	7000		No file	No file	

District Name: Satkhira

Medical Service Related Information

Sl. No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	assasuni	Assasuni UHC	1 xlsx	Ok
2	debhata	Upazila Health Complex, Debhata, Satkhira	1 xlsx	OK
3	kalaroa	50 Beded UHC,Kalaroa	1 xlsx	OK
4	kaliganj	Kaliganj UHC	1 xlsx	OK
5	tala	UHC,Tala	1 xlsx	OK

District Name: Shariatpur

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	bhedarganj	Upazila Health Complex Bhedarganj	1 xlsx	ok
2	damudya	Upazila Health Complex Damuddya	1 xlsx	ok
3	gosairhat	Upazila Health Complex Goshairhat	1 xlsx	ok
4	naria	Upazila Health Complex Naria	1 xlsx	ok
5	zanjira	Upazila Health Complex Zanjira	1 xlsx	ok

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	bhedarganj	Upazila Health Complex Bhedarganj	1980	PWD	yes	50	1 dwg	3 jpegs	No file	No file	9615	9615	No file	No file	2 jpegs	NA	ok
2	damudya	Upazila Health Complex Damuddya	1980	PWD	yes	50	1 dwg	No file	No file	No file	9262	9262	No file	No file	2 jpegs, 1 mp4	NA	ok
3	gosairhat	Upazila Health Complex Goshairhat	1980	PWD	yes	50	1 dwg	No file	No file	No file			No file	No file	6 jpegs	NA	ok
4	naria	Upazila Health Complex Naria	2013	HED	yes	50	1 dwg	No file	No file	No file	12180	12180	No file	No file	4 jpegs	NA	ok
5	zanjira	Upazila Health Complex Zanjira	1980	PWD	yes	50	1 dwg	No file	No file	No file			No file	No file	No file	NA	ok

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	bhedarganj	Upazila Health Complex Bhedarganj	21	2.5	2	Footing	2	Load Bearing Brick	Not Good enough for load bearing capacity.	No file	Not Possible	No	ok
2	damudya	Upazila Health Complex Damuddya	20	2.5	2	Footing	2	Load Bearing Brick	Not Good enough for load bearing capacity.	No file	Not Possible	No	ok
3	gosairhat	Upazila Health Complex Goshairhat	44	2.5	4	Deep	5	RCC	Good enough for load bearing capacity.	No file	Possible	No	ok
4	naria	Upazila Health Complex Naria	44	2.5	4	Deep	5	RCC	Good enough for load bearing capacity.	No file	Possible	No	ok

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	bhedarganj	Upazila Health Complex Bhedarganj	0	1	no	Septic Tank	1200	No	0	no	Open drain needed	no	ok
2	damudya	Upazila Health Complex Damuddya	0	1	no	Septic Tank	1200	No	0	no	Open drain needed	no	ok
3	gosairhat	Upazila Health Complex Goshairhat	0	1	no	Septic Tank	1400	No	0	no	Open drain needed	no	ok
4	naria	Upazila Health Complex Naria	0	1	no	Septic Tank	1500	No	0	yes	no	no	ok

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	bhedarganj	Upazila Health Complex Bhedarganj		2000		300	16	12	Yes	No	ok
2	damudya	Upazila Health Complex Damuddya		2000		200	16	24	Yes	No	ok
3	gosairhat	Upazila Health Complex Goshairhat		1900		200	16	16	Yes	No	ok
4	naria	Upazila Health Complex Naria		2077		0	16	15	Yes	No	ok

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	bhedarganj	Upazila Health Complex Bhedarganj.	0	0	0	16	12	2 Nos Unserviceable.	Nill	7.5	5.5	Nill	Not Present	Nill
2	damudya	Upazila Health Complex Damudya.	0	0	0	10	10	3 Nos Unserviceable.	Nill	5.5	3.5	Nill	Not Present	Nill
3	gosairhat	Upazila Health Complex Gosairhat	0	0	0	16	10	2 Nos Unserviceable.	Nill	5.5	5.5	Nill	Not Present	Nill
4	naria	Upazila Health Complex Naria	0	0	0	20	10	1 Nos Unserviceable.	Nill	7.5	3.5	Nill	Not Present	Nill
5	zanjira	Upazila Health Complex Zanjira	0	0	0	16	16	3 Nos Unserviceable.	Nill	11	4	Nill	Not Present	Nill

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	bhedarganj	Upazila Health Complex Bhedorganj.	REB	Yes	100	150	100	HT(No), LT(OK), PFI (OK)	50	100	5	0	HT Cable=70sqmm (Length=35m),LT Cable=95sqmm (length=15m).	LT To MDB=70 sqmm (Length=35m)MDB to FDB-16sqmmm (length=105m)	NA
2	damudya	Upazila Health Complex Damudya.	REB	Yes	105	150	100	HT(No), LT(OK), PFI (OK)	50	100	4.5	0	HT Cable=70sqmm (Length=38m),LT Cable=95sqmm (length=525m).	LT To MDB=70 sqmm (Length=32m)MDB to FDB-16sqmmm (length=110m)	NA
3	gosairhat	Upazila Health Complex Gosairhat	REB	Yes	100	150	100	HT(No), LT(OK), PFI (OK)	50	100	5	0	HT Cable=70sqmm (Length=35m),LT Cable=95sqmm (length=15m).	LT To MDB=70 sqmm (Length=35m)MDB to FDB-16sqmmm (length=105m)	NA
4	naria	Upazila Health Complex Naria	REB	Yes	105	150	100	HT(OK), LT(OK), PFI (OK)	50	100	5	0	HT Cable=70sqmm (Length=50m),LT Cable=95sqmm (length=20m).	LT To MDB=70 sqmm (Length=40m)MDB to FDB-16sqmmm (length=110m)	NA
5	zanjira	Upazila Health Complex Zanjira	REB	Yes	110	150	100	HT(No), LT(OK), PFI (OK)	50	100	4.5	0	HT Cable=70sqmm (Length=35m),LT Cable=95sqmm (length=15m).	LT To MDB=70 sqmm (Length=30m)MDB to FDB-16sqmmm (length=100m)	NA

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	bhedarganj	Upazila Health Complex Bhedorganj.	No	0	0	NA	Yes	No	Yes	No	No	1	NA	NA
2	damudya	Upazila Health Complex Damudya.	No	0	0	NA	Yes	No	Yes	No	No	1	NA	NA
3	gosairhat	Upazila Health Complex Gosairhat	No	0	0	NA	Yes	No	Yes	No	No	1	NA	NA
4	naria	Upazila Health Complex Naria	No	0	0	NA	Yes	No	Yes	Yes	Yes	1	NA	NA
5	zanjira	Upazila Health Complex Zanjira	No	0	0	NA	Yes	No	Yes	No	No	1	NA	NA

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	bhedarganj	Upazila Health Complex Bhedarganj	50 bedded Upazila Health Complex Bhedarganj	8	1980	2	9615	19230	Not Good	1 pdf	1 jpeg	ok
2	damudya	Upazila Health Complex Damuddya	50 bedded Upazila Health Complex Damuddya	5	1980	2	9262	18524	Not Good	1 pdf	1 mp4	ok
3	naria	Upazila Health Complex Naria	50 bedded Upazila Health Complex Naria	8	2023	4	12180	48720	Good	No file	4 jpegs	ok

District Name: Sherpur

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	nakla	50 Beded Upazila Health Complex	1 xlsx	
2	nalitabari	50 Beded Upazila Health Complex	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	jhenaigati	50 Beded Upazila Health Complex	1970	PWD	Yeas	31	1 dwg, 1 pdf	No file	4 pdfs	No file	9711	GF=9711 sft, 1st Floor=9711 sft	No file	No file	2 jpegs		
2	jhenaigati	50 Beded Upazila Health Complex	2018	HED	Yeas	19	1 dwg	No file	No file	No file	7463	GF=7463.87 sft, 1st Floor=7463.87 sft, 2nd Floor=6463.87 sft,	No file	No file	2 jpegs		
3	nakla	50 Beded Upazila Health Complex	2007	HED	yes	19	1 dwg	1 pdf	5 pdfs	1 pdf, 1 png	7290	GF=7290 sft, 1st Floor=7290 sft, 2nd Floor=7290 sft,	1 dwg	No file	1 jpg		
4	nakla	50 Beded Upazila Health Complex	1978	PWD	yes	31	1 dwg	1 pdf	4 pdfs	1 pdf, 1 png	6392	GF Floor=6393 Sft, 1st Floor=3950 sft	1 dwg	No file	2 jpgs		
5	nalitabari	50 Beded Upazila Health Complex	2012	HED	yes	19	1 dwg	No file	No file	1 jpg, 1 pdf	7400	GF Floor=7400 Sft 1st Floor=7400 sft	1 dwg	No file	2 jpgs		
6	nalitabari	50 Beded Upazila Health Complex	1982	PWD	yes	31	1 dwg	No file	No file	1 jpg, 1 pdf	9332	GF=9332 sft, 1st Floor=9332 sft	1 dwg	No file	2 jpgs		
7	sreebardi	50 Beded Upazila Health Complex	2009	HED	Yes	19	1 dwg, 1 pdf	No file	3 pdfs	No file	6834	GF=6834 sft, 1st Floor=6834 sft, 2nd Floor=5834 sft,	No file	No file	1 jpeg		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	jhenaigati	50 Beded Upazila Health Complex	36	2.75	3	Footing	5	RCC	কাঠামোগত অবস্থা প্রতিবেদন (3 তলা নতুন ভবন) 2018 সালে নির্মিত এই 3 তলা ভবনটির প্রাথমিক পরিদর্শনে বেশ কিছু ত্রুটি পরিলক্ষিত হয়েছে। ভবনের বিভিন্ন অংশে প্লাস্টারে ব্যাপক ডাম্প (আর্দ্রতা) দেখা গেছে এবং রং নষ্ট হয়ে গেছে। উল্লেখযোগ্য বিষয় হলো, ভবনের দেয়ালের বিভিন্ন স্থানে ফাটল (ক্র্যাক) দৃশ্যমান রয়েছে। ভবনের সার্বিক রক্ষণাবেক্ষণের অংশ হিসেবে বর্তমানে তে প্রয়োজনীয় প্লাস্টার মেরামত ও পুনরায় রং করনসহ আনুষঙ্গিক মেরামতের আবশ্যকতা রয়েছে।	No file	info not available		

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
2	nakla	50 Beded Upazila Health Complex	33	1.67	3	Footing	3	RCC	কাঠামোগত অবস্থা প্রতিবেদন (তিন তলা ভবন) ২০০৭ সালে নির্মিত এই তিন তলা ভবনটির প্রাথমিক পরিদর্শনে বেশ কিছু ত্রুটি পরিলক্ষিত হয়েছে। ভবনের বিভিন্ন অংশে প্লাস্টারে ব্যাপক ডাম্প (আর্দ্রতা) দেখা গেছে এবং রং নষ্ট হয়ে গেছে। তবে, ছাদের কংক্রিট খসে রড বেরিয়ে পড়ার মতো কোনো গুরুতর কাঠামোগত ক্ষতি এই ভবনে নেই। উল্লেখযোগ্য বিষয় হলো, ভবনের দেয়ালের বিভিন্ন স্থানে ফটিল (ক্র্যাক) দৃশ্যমান রয়েছে। ভবনের বর্তমান এই সার্বিক অবস্থা পরবর্তী প্রয়োজনীয় ব্যবস্থা ও সিদ্ধান্ত গ্রহণের জন্য উর্ধ্বতন কর্তৃপক্ষের নিকট উপস্থাপন করা হলো।	No file	info not available		
3	nakla	50 Beded Upazila Health Complex	22	1.5	2	Footing	2	Load Bearing Brick	কাঠামোগত অবস্থা প্রতিবেদন ১৯৭৮ সালে নির্মিত এই হাসপাতাল ভবনটির (সামনে দোতলা, পেছনে একতলা) বেশ কিছু কাঠামোগত ত্রুটি দৃশ্যমান। প্রাথমিক পরিদর্শনে ভবনের বিভিন্ন অংশে ব্যাপক ডাম্প, পানিজানিত ক্ষতি এবং প্লাস্টার খসে পড়ার প্রমাণ পাওয়া গেছে। বিশেষ করে, ছাদের কিছু অংশে কংক্রিট খসে পড়ে ভেতরের রড (rebar) বেরিয়ে গেছে। বর্তমান এই কাঠামোগত এবং আর্দ্রতাজনিত ক্ষতির বিবরণী উর্ধ্বতন কর্তৃপক্ষের পরবর্তী পর্যালোচনার জন্য উপস্থাপন করা হলো, যাতে তারা এ বিষয়ে যথাযথ সিদ্ধান্ত গ্রহণ করতে পারেন।	No file	Not Possible		
4	nalitabari	50 Beded Upazila Health Complex	22	1.5	2	Footing		RCC	কাঠামোগত অবস্থা প্রতিবেদন (২ তলা নতুন ভবন) ২০১২ সালে নির্মিত এই ২ তলা ভবনটির প্রাথমিক পরিদর্শনে বেশ কিছু ত্রুটি পরিলক্ষিত হয়েছে। ভবনের বিভিন্ন অংশে প্লাস্টারে ব্যাপক ডাম্প (আর্দ্রতা) দেখা গেছে এবং রং নষ্ট হয়ে গেছে। উল্লেখযোগ্য বিষয় হলো, ভবনের দেয়ালের বিভিন্ন স্থানে ফটিল (ক্র্যাক) দৃশ্যমান রয়েছে। ভবনের সার্বিক রক্ষণাবেক্ষণের অংশ হিসেবে বর্তমানে তে প্রয়োজনীয় প্লাস্টার মেরামত ও পুনরায় রং করনসহ আনুষঙ্গিক মেরামতের আবশ্যকতা রয়েছে।	No file	info not available		
5	nalitabari	50 Beded Upazila Health Complex	22	1	2	Footing	2	Load Bearing Brick	কাঠামোগত অবস্থা প্রতিবেদন (দুই তলা পুরাতন বিল্ডিং) ১৯৮২ সালে নির্মিত এই হাসপাতাল ভবনটি দুইতলা বিশিষ্ট। ভবনটির বেশ কিছু কাঠামোগত ত্রুটি দৃশ্যমান। প্রাথমিক পরিদর্শনে ভবনের বিভিন্ন অংশে ব্যাপক ডাম্প, পানিজানিত ক্ষতি এবং প্লাস্টার খসে পড়া, বিভিন্ন ধরনের ক্র্যাক পাওয়া গেছে। ভবনের সার্বিক রক্ষণাবেক্ষণের অংশ হিসেবে বর্তমানে তে প্রয়োজনীয় প্লাস্টার মেরামত ও পুনরায় রং করনসহ আনুষঙ্গিক মেরামতের আবশ্যকতা রয়েছে।	No file	Not Possible		
6	sreebardi	50 Beded Upazila Health Complex	36	2.3	3	Footing	5	RCC	কাঠামোগত অবস্থা প্রতিবেদন (৩ তলা নতুন ভবন) 2009 সালে নির্মিত এই 3 তলা ভবনটির প্রাথমিক পরিদর্শনে বেশ কিছু ত্রুটি পরিলক্ষিত হয়েছে। ভবনের বিভিন্ন অংশে প্লাস্টারে ব্যাপক ডাম্প (আর্দ্রতা) দেখা গেছে এবং রং নষ্ট হয়ে গেছে। উল্লেখযোগ্য বিষয় হলো, ভবনের দেয়ালের বিভিন্ন স্থানে ফটিল (ক্র্যাক) দৃশ্যমান রয়েছে। ভবনের সার্বিক রক্ষণাবেক্ষণের অংশ হিসেবে বর্তমানে তে প্রয়োজনীয় প্লাস্টার মেরামত ও পুনরায় রং করনসহ আনুষঙ্গিক মেরামতের আবশ্যকতা রয়েছে।	No file	info not available		

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	jhenagati	50 Beded Upazila Health Complex	3500	1		Septic Tank		No		ভবনের পেছনের অংশে পানি নিষ্কাশনের নিমিত্তে একটি ক্ষুদ্র পরিসরের ড্রেনেজ ব্যবস্থা রয়েছে।	5.667 একর বিস্তীর্ণ এই হাসপাতাল ক্যাম্পাসের সার্বিক পরিবেশ সুরক্ষা ও কার্যকর পানি নিষ্কাশনের নিমিত্তে একটি টেকসই এবং উচ্চমান সম্পন্ন ড্রেনেজ প্রয়োজনীয়তা রয়েছে।		
2	nakla	50 Beded Upazila Health Complex	0	1	N/A	Septic Tank	3500	No	0	ভবনের পেছনের অংশে পানি নিষ্কাশনের নিমিত্তে একটি ক্ষুদ্র পরিসরের ড্রেনেজ ব্যবস্থা রয়েছে।	৩.০৫ একর বিস্তীর্ণ এই হাসপাতাল ক্যাম্পাসের সার্বিক পরিবেশ সুরক্ষা ও কার্যকর পানি নিষ্কাশনের নিমিত্তে একটি টেকসই এবং উচ্চমান সম্পন্ন ড্রেনেজ নেটওয়ার্কের প্রয়োজনীয়তা রয়েছে।		
3	nalitabari	50 Beded Upazila Health Complex	0	1	N/A	Septic Tank	3500	No	0	ভবনের পেছনের অংশে পানি নিষ্কাশনের নিমিত্তে একটি ক্ষুদ্র পরিসরের ড্রেনেজ ব্যবস্থা রয়েছে। তবে সেগুলো অচল অবস্থা হয়ে রয়েছে।	৬.২৫ একর বিস্তীর্ণ এই হাসপাতাল ক্যাম্পাসের সার্বিক পরিবেশ সুরক্ষা ও কার্যকর পানি নিষ্কাশনের নিমিত্তে একটি টেকসই এবং উচ্চমান সম্পন্ন ড্রেনেজ নেটওয়ার্কের প্রয়োজনীয়তা রয়েছে।		
4	sreebardi	50 Beded Upazila Health Complex	3500	1		Septic Tank				ভবনের পেছনের অংশে পানি নিষ্কাশনের নিমিত্তে একটি ক্ষুদ্র পরিসরের ড্রেনেজ ব্যবস্থা রয়েছে।	3.031 একর বিস্তীর্ণ এই হাসপাতাল ক্যাম্পাসের সার্বিক পরিবেশ সুরক্ষা ও কার্যকর পানি নিষ্কাশনের নিমিত্তে একটি টেকসই এবং উচ্চমান সম্পন্ন ড্রেনেজ নেটওয়ার্কের প্রয়োজনীয়তা রয়েছে।		

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	nakla	50 Beded Upazila Health Complex		1820		680	33.5	হাসপাতাল চত্বরের অভ্যন্তরীণ যাতায়াত ব্যবস্থার জন্য সর্বমোট প্রায় ৫১০ ফুট দৈর্ঘ্যের রাস্তা রয়েছে। উক্ত রাস্তার ৩১০ ফুট অংশের প্রস্থ ১১ ফুট এবং অবশিষ্টাংশ, অর্থাৎ প্রায় ২০০ ফুট রাস্তার প্রস্থ ৬.৫ ফুট।	No	Yes	
2	nalitabari	50 Beded Upazila Health Complex		2065		690	32	হাসপাতাল চত্বরের অভ্যন্তরীণ যাতায়াত ব্যবস্থার জন্য সর্বমোট প্রায় ৭০০ ফুট দৈর্ঘ্যের রাস্তা রয়েছে। উক্ত রাস্তার ৪৫০ ফুট অংশের প্রস্থ ১২ ফুট এবং অবশিষ্টাংশ, অর্থাৎ প্রায় ২৫০ ফুট রাস্তার প্রস্থ ৮ ফুট।	No	Yes	
3	sreebardi	50 Beded Upazila Health Complex		1540			12	হাসপাতাল চত্বরের অভ্যন্তরীণ যাতায়াত ব্যবস্থার জন্য সর্বমোট প্রায় 988 ফুট দৈর্ঘ্যের রাস্তা রয়েছে। উক্ত রাস্তার 788 ফুট অংশের প্রস্থ 10 ফুট এবং অবশিষ্টাংশ প্রস্থ 9 ফুট।	Yes	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	jhenagati	50 Beded Upazila Health Complex	0	0	0	12	12		3 Nos ABC Fire Extinguisher	17.5	0	10 HP Submersible Pump Demand	Not Present	Need
2	nakla	50 Beded Upazila Health Complex	0	0	0	7	6	0	5 Nos ABC Extinguisher	10	0	10 HP Submersible Pump Demand	Not Present	need
3	nalitabari	50 Beded Upazila Health Complex	0	0	0	6	16	0	4 Nos ABC Extinguisher	10	0	5 HP Pump Demand	Not Present	need
4	sreebardi	50 Beded Upazila Health Complex	0	0	0	8	8	0	4 Nos ABC Extinguisher	9.75	0	10 HP Submersible Pump Demand & 1 HP Pump Repair	Not Present	need

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	jhenagati	50 Bed Upazila Health Complex	PDB	Yes	100	100	0	NOT Applying (Pole Mountain Transformer)	0	80	0	0	HT ACSR Cable 100 Mtr and 245 Mtr LT Dog Cable	1C-4x16 RM 80 MTR. NYY Service Cable	
2	nakla	50 Bed Upazila Health Complex	PDB	Yes	100	100	0	NOT Applying (Pole Mountain)	0	100	0	0	HT ACSR Cable 20 Mtr and 190 MTR LT Dog Cable	1C-4x25 RM 75 MTR. NYY Service Cable	
3	nalitabari	50 Bed Upazila Health Complex	PDB	Yes	150	150	0	NOT Applying (Pole Mountain)	0	100	0	0	HT ACSR Cable 40 Mtr and 280 MTR LT Dog Cable	1C-4X25 RM 60 MTR. NYY Service Cable	
4	sreebardi	50 Bed Upazila Health Complex	PDB	Yes	100	100	0	NOT Applying (Pole Mountain)	0	100	0	0	HT ACSR Cable 50 Mtr and 250 MTR LT Dog Cable	25 RM 60 MTR. NYY Service Cable	

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	jhenagati	50 Bed Upazila Health Complex	Yes	120	25	Need	Yes	No	Yes	No	Yes	0		
2	nakla	50 Bed Upazila Health Complex	Yes	120	28	Need	Yes	No	Yes	No	Yes	0		
3	nalitabari	50 Bed Upazila Health Complex	Yes	120	28	Need	Yes	No	Yes	No	Yes	0		
4	sreebardi	50 Bed Upazila Health Complex	Yes	120	28	NA	Yes	No	No	No	Yes	0		

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	nakla	50 Beded Upazila Health Complex	3 Storied Building Nurses Quarters		2007	3	1800	5400	নার্স কোয়ার্টার (তিন তলা): ক্যাম্পাসের অভ্যন্তরে ১৮০০ বর্গফুট প্লিন্থ এরিয়া বিশিষ্ট একটি তিন তলা নার্স কোয়ার্টার রয়েছে, যা বর্তমানে নার্সদের আবাসস্থল হিসেবে ব্যবহৃত হচ্ছে। ভবনটি সম্পূর্ণ সচল ও ব্যবহারযোগ্য থাকলেও, এর বিভিন্ন অংশে প্লাস্টার ও রঙের কাজ ক্ষতিগ্রস্ত হয়েছে। ভবনটির সার্বিক রক্ষণাবেক্ষণের অংশ হিসেবে বর্তমানে এতে প্রয়োজনীয় প্লাস্টার মেরামত ও পুনরায় রং করার আবশ্যকতা রয়েছে।"	No file	1 jpg	
2	nakla	50 Beded Upazila Health Complex	3 Storied Building Doctor Quarters		2007	3	1500	4500	ডক্টরস কোয়ার্টার (তিন তলা): ক্যাম্পাসের অভ্যন্তরে ১৫০০ বর্গফুট প্লিন্থ এরিয়া বিশিষ্ট একটি তিন তলা ডক্টরস কোয়ার্টার রয়েছে, যা বর্তমানে চিকিৎসকদের আবাসস্থল হিসেবে ব্যবহৃত হচ্ছে। ভবনটি সম্পূর্ণ সচল ও ব্যবহারযোগ্য থাকলেও, এর বিভিন্ন অংশে প্লাস্টার ও রঙের কাজ ক্ষতিগ্রস্ত হয়েছে। ভবনটির সার্বিক রক্ষণাবেক্ষণের অংশ হিসেবে বর্তমানে এতে প্রয়োজনীয় প্লাস্টার মেরামত ও পুনরায় রং করার আবশ্যকতা রয়েছে।"	No file	1 jpg	
3	nakla	50 Beded Upazila Health Complex	1 Storied Nurse dormitory		1978	1	1470	1470	নার্স ডরমিটরি (একতলা): ১৯৭৮ সালে নির্মিত এই একতলা ডরমিটরি ভবনটি বর্তমানে অব্যবহৃত অবস্থায় রয়েছে। দীর্ঘদিনের পুরোনো এই ভবনটি ভবিষ্যতে পুনরায় ব্যবহার করা নিরাপদ হবে কিনা, সে বিষয়ে বর্তমানে কোনো সুনির্দিষ্ট তথ্য বা উপাত্ত নেই। এছাড়া, কেবল খালি চোখে ভবনের বাহ্যিক ও সার্বিক অবস্থা পর্যবেক্ষণ করে এর কাঠামোগত সক্ষমতা বা ব্যবহারযোগ্যতার বিষয়ে কোনো চূড়ান্ত মতামত প্রদান করা সম্ভব নয়।"	No file	1 jpg	
4	nakla	50 Beded Upazila Health Complex	2 Storied Doctor Quarters		2007	2	2322	4644	ডক্টরস কোয়ার্টার (দোতলা): ক্যাম্পাসের অভ্যন্তরে ২৩২২ বর্গফুট প্লিন্থ এরিয়া বিশিষ্ট একটি দোতলা ডক্টরস কোয়ার্টার রয়েছে, যা বর্তমানে চিকিৎসকদের আবাসস্থল হিসেবে ব্যবহৃত হচ্ছে। ভবনটি সম্পূর্ণ সচল ও ব্যবহারযোগ্য থাকলেও, এর বিভিন্ন অংশে প্লাস্টার ও রঙের কাজ ক্ষতিগ্রস্ত হয়েছে। ভবনটির সার্বিক রক্ষণাবেক্ষণের অংশ হিসেবে বর্তমানে এতে প্রয়োজনীয় প্লাস্টার মেরামত ও পুনরায় রং করার আবশ্যকতা রয়েছে।"	No file	1 jpg	
5	nalitabari	50 Beded Upazila Health Complex	2 Storied Building Consultant Quarter		2012	2	2260	4520	কনসালটেন্ট কোয়ার্টার (দুই তলা): ক্যাম্পাসের অভ্যন্তরে ২২৬০ বর্গফুট প্লিন্থ এরিয়া বিশিষ্ট একটি দুই তলা কনসালটেন্ট কোয়ার্টার রয়েছে, ভবনটি ২০১২ সালে নির্মিত। যা বর্তমানে চিকিৎসকদের আবাসস্থল হিসেবে ব্যবহৃত হচ্ছে। ভবনটি সম্পূর্ণ সচল ও ব্যবহারযোগ্য থাকলেও, এর বিভিন্ন অংশে প্লাস্টার ও রঙের কাজ ক্ষতিগ্রস্ত হয়েছে। ভবনটির সার্বিক রক্ষণাবেক্ষণের অংশ হিসেবে বর্তমানে এতে প্রয়োজনীয় প্লাস্টার মেরামত ও পুনরায় রং করণসহ আনুষঙ্গিক মেরামত করার আবশ্যকতা রয়েছে।"	No file	1 jpg	
6	nalitabari	50 Beded Upazila Health Complex	2 Storied Building Quarter		1982	2	2730	5460	ডরমিটরি (দুতলা): ১৯৮২ সালে নির্মিত ২৭৩০ স্কয়ার ফিটের এই দুই তলা ডরমিটরি ভবনটি বর্তমানে সীমিত পরিসরে ব্যবহৃত হচ্ছে। তবে ভবনটির বাহ্যিক অবস্থা দেখে মনে হচ্ছে তারা ঝুঁকি নিয়েই ভবনটিতে বসবাস করছে। দীর্ঘদিনের পুরোনো এই ভবনটি ভবিষ্যতে পুনরায় পুরোদমে ব্যবহার করা নিরাপদ হবে কিনা, সে বিষয়ে বর্তমানে কোনো সুনির্দিষ্ট তথ্য বা উপাত্ত নেই। এছাড়া, কেবল খালি চোখে ভবনের বাহ্যিক ও সার্বিক অবস্থা পর্যবেক্ষণ করে এর কাঠামোগত সক্ষমতা বা ব্যবহারযোগ্যতার বিষয়ে কোনো চূড়ান্ত মতামত প্রদান করা সম্ভব নয়।"	No file	1 jpg	
7	nalitabari	50 Beded Upazila Health Complex	2 Storied Building		1982	2	1100	2200	ডরমিটরি (দুতলা): ১৯৮২ সালে নির্মিত ১১০০ স্কয়ার ফিটের এই দুই তলা ডরমিটরি ভবনটি বর্তমানে অব্যবহৃত অবস্থায় রয়েছে। দীর্ঘদিনের পুরোনো এই ভবনটি ভবিষ্যতে পুনরায় ব্যবহার করা নিরাপদ হবে কিনা, সে বিষয়ে বর্তমানে কোনো সুনির্দিষ্ট তথ্য বা উপাত্ত নেই। এছাড়া, কেবল খালি চোখে ভবনের বাহ্যিক ও সার্বিক অবস্থা পর্যবেক্ষণ করে এর কাঠামোগত সক্ষমতা বা ব্যবহারযোগ্যতার বিষয়ে কোনো চূড়ান্ত মতামত প্রদান করা সম্ভব নয়।"	No file	1 jpg	
8	nalitabari	50 Beded Upazila Health Complex	3 Storied Building Quarter		1982	3	2800	8400	ডক্টরস কোয়ার্টার (তিন তলা): ক্যাম্পাসের অভ্যন্তরে 2800 বর্গফুট প্লিন্থ এরিয়া বিশিষ্ট একটি তিন তলা ডক্টরস কোয়ার্টার রয়েছে, ভবনটি ১৯৮২ সালে নির্মিত। যা বর্তমানে চিকিৎসকদের আবাসস্থল হিসেবে ব্যবহৃত হচ্ছে। ভবনটি সম্পূর্ণ সচল ও ব্যবহারযোগ্য থাকলেও, এর বিভিন্ন অংশে প্লাস্টার ও রঙের কাজ ক্ষতিগ্রস্ত হয়েছে। ভবনটির সার্বিক রক্ষণাবেক্ষণের অংশ হিসেবে বর্তমানে এতে প্রয়োজনীয় প্লাস্টার মেরামত ও পুনরায় রং করণসহ আনুষঙ্গিক মেরামত করার আবশ্যকতা রয়েছে।"	No file	1 jpg	

District Name: Sirajganj

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	kamarkhanda	50 Bed Upozilla Health Complex, Kamarkhanda, Sirajganj	1 xlsx	
2	shahjadpur	50 Bed Upozilla Health Complex, Shahjadpur, Sirajganj	1 xlsx	
3	tarash	50 Bed Upozilla Health Complex, Tarash, Sirajganj	1 xlsx	
4	ullahpara	50 Bed Upozilla Health Complex, Ullapara, Sirajganj	1 xlsx	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	kamarkhanda	50 Bed Upozilla Health Complex, Kamarkhanda, Sirajganj	1981	PWD	Available	50	1 dwg	No file	No file	1 jpeg	16219	Two storied new building 7438, two storied old building 8781	No file	No file	3 jpegs		Old building two storied constructed in 1981 by PWD, new building three storied constructed in 2023 by HED
2	rayganj	50 Bed Upozilla Health Complex, Raiganj, Sirajganj	1996	HED	Available	50	1 dwg	1 pdf	No file	No file	1530	Two storied old hospital 7905, two storied old hospital annex 2362, three storied new building 7438	No file	No file	No file		
3	shahjadpur	50 Bed Upozilla Health Complex, Shahjadpur, Sirajganj	1961	PWD	Available	50	1 dwg	2 jpegs	No file	4 jpegs	17704	Two storied old hospital 7905, two storied old hospital annex 2362, three storied new building 7438	No file	No file	4 jpegs		
4	tarash	50 Bed Upozilla Health Complex, Tarash, Sirajganj	1987	PWD	Available	50	1 dwg	1 pdf	No file	5 jpegs	20846	Two storied old hospital 13408, Three storied new building 7438	No file	No file	4 jpegs		Old building two storied constructed in 1987 by PWD, new building three storied constructed in 2015 by HED
5	ullahpara	50 Bed Upozilla Health Complex, Ullapara, Sirajganj	1961	PWD	Available	50	1 dwg	No file	No file	No file	15360	Two storied old hospital 7922, Four storied new building 7438	No file	No file	3 jpegs, 1 jpg		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	kamarkhanda	50 Bed Upozilla Health Complex, Kamarkhanda, Sirajganj	22	2.5	2	Footing	4	RCC	New building, in service, good condition	1 jpeg	Possible		In service since 2023

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
2	kamarkhanda	50 Bed Upozilla Health Complex, Kamarkhanda, Sirajganj	22	2.5	2	Footing	2	RCC	Good	2 jpegs	Not Possible		Old building. In service, Very good condition, recently repaired
3	shahjadpur	50 Bed Upozilla Health Complex, Shahjadpur, Sirajganj	22	2	2	Footing	2	RCC	Very old building. Constructed around 60s. Spalling from slab is very prominent, prone to injury.	5 jpegs	Not Possible		All wards (male and female), OT, UHFPO room, medical officer room, statistics room in this building.
4	shahjadpur	50 Bed Upozilla Health Complex, Shahjadpur, Sirajganj	33	2	3	Deep	5	RCC	Good	3 jpegs	Possible		
5	tarash	50 Bed Upozilla Health Complex, Tarash, Sirajganj	22	2.5	2	Footing	2	RCC	Good	1 jpeg	Not Possible		
6	tarash	50 Bed Upozilla Health Complex, Tarash, Sirajganj	33	2.5	3	Deep	4	RCC	Good	3 jpegs	Possible		
7	ullahpara	50 Bed Upozilla Health Complex, Ullapara, Sirajganj	22	2	2	Footing	2	RCC	Old building but in good condition.	No file	Not Possible		
8	ullahpara	50 Bed Upozilla Health Complex, Ullapara, Sirajganj	44	2	4	Deep	5	RCC	Good	6 jpegs	Possible		New building in operation since 2016

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	kamarkhanda	50 Bed Upozilla Health Complex, Kamarkhanda, Sirajganj	0	2	no	Septic Tank	0	No	0	Surface drain for individual building	Master drain required	Dustbin within UHC campus	No STP or medical waste disposal facility
2	shahjadpur	50 Bed Upozilla Health Complex, Shahjadpur, Sirajganj	0	2	NA	Septic Tank		No	0	Surface drain for individual building. No central or master drain available	Master drain and fallout required	Surrounding water body and dustbin within hospital campus	No medical waste disposal system available
3	tarash	50 Bed Upozilla Health Complex, Tarash, Sirajganj	0	2	no	Septic Tank	0	No	0	Surface drain for individual building	Master drain required	Dustbin within UHC campus	No STP or medical waste disposal facility
4	ullahpara	50 Bed Upozilla Health Complex, Ullapara, Sirajganj	0	2	NA	Septic Tank	0	No	0	Surface drain for individual building. No central or master drain available	Master drain and fallout required	Surrounding water body and dustbin within hospital campus	No medical waste disposal system available

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	kamarkhanda	50 Bed Upozilla Health Complex, Kamarkhanda, Sirajganj					20	RCC	Yes	No	
2	shahjadpur	50 Bed Upozilla Health Complex, Shahjadpur, Sirajganj					15	RCC	Yes	No	
3	tarash	50 Bed Upozilla Health Complex, Tarash, Sirajganj					20	RCC	Yes	No	

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
4	ullahpara	50 Bed Upozilla Health Complex, Ullapara, Sirajganj					20	RCC	Yes	No	There is a big pond adjacent to new hospital building

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	kamarkhanda	50 Bed Upozilla Health Complex, Kamarkhanda, Sirajganj	0	0	No lift core available	12	30	Split type	Fire extinguisher	2	0		Not Present	
2	shahjadpur	50 Bed Upozilla Health Complex, Shahjadpur, Sirajganj	0	0	No lift core in new building	34	30	Split type AC, no central system	Very few fire extinguiser	10	0	Two pumps for two 4"bDTW are in operational	Not Present	
3	tarash	50 Bed Upozilla Health Complex, Tarash, Sirajganj	0	0	No lift core available	12	30	Split type	Fire extinguisher	1	0		Not Present	
4	ullahpara	50 Bed Upozilla Health Complex, Ullapara, Sirajganj	0	0	No lift core in new building	28	24	Split type AC, no central system	Very few fire extinguiser	10	0	Two pumps for two 4" DTW are in operational	Not Present	

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	kamarkhanda	50 Bed Upozilla Health Complex, Kamarkhanda, Sirajganj	REB	Yes	100	150	50	In service	46	0	0	0			
2	shahjadpur	50 Bed Upozilla Health Complex, Shahjadpur, Sirajganj	REB	Yes	100	150	50	Active	0	30	0	0			
3	tarash	50 Bed Upozilla Health Complex, Tarash, Sirajganj	REB	Yes	100	150	50	In service	20	20	0	0			
4	ullahpara	50 Bed Upozilla Health Complex, Ullapara, Sirajganj	REB	Yes	100	150	50	Active	0	30	0	0			

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	kamarkhanda	50 Bed Upozilla Health Complex, Kamarkhanda, Sirajganj	No	0	0	One room to store medical gas cylinders	Yes	No	Yes	No	Yes	0	PABX, CCTV, network system, solar system etc.	

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
2	shahjadpur	50 Bed Upozilla Health Complex, Shahjadpur, Sirajganj	No	0	0	Medical gas room is seen, but without generation capacity. No central system, only cylinder available	Yes	No	Yes	Yes	Yes	1	CCTV, network system is very limited. 32 nos CCTV and network system required.	
3	tarash	50 Bed Upozilla Health Complex, Tarash, Sirajganj	No	0	0	One room to store medical gas cylinders	Yes	No	Yes	No	Yes	1	PABX, CCTV, network system, solar system etc.	
4	ullahpara	50 Bed Upozilla Health Complex, Ullapara, Sirajganj	No	0	0	Medical gas room is seen, but without generation capacity. No central system, only cylinder available	Yes	No	Yes	Yes	Yes	1	CCTV, network system is very limited. 32 nos CCTV and network system required.	

District Name: Sunamganj

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	bishwamandarpur	Bishwamandapur Upazila Health Complex	1 xlsx	ok
2	chhatak	Chhatak Upazilla Health Complex	1 xlsx	ok
3	derai	Derai Upazila Health Complex	1 xlsx	ok
4	dharampasha	Dharampasha Upazilla Health Complex	1 xlsx	ok
5	dowarabazar	Dowarabazar Upazila Health Complex	1 xlsx	ok
6	jagannathpur	Jagannathpur Upazilla Health Complex	1 xlsx	ok
7	jamalganj	Jamalganj Upazila Health Complex	1 xlsx	ok
8	madhyanagar	Madhyanagar Upazila Health Complex(newly proposed)	No file	newly proposed project
9	shanthiganj	Shanthiganj Upazila Health Complex	1 xlsx	ok
10	sullah	Sullah Upazila Health Complex	1 xlsx	ok
11	tahirpur	Tahitpur Upazilla Health Complex	1 xlsx	ok

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	bishwamandarpur	Bishwamandapur Upazila Health Complex (Old Building)	1998	HED	available	50	1 dwg	No file	No file	No file	14756	GF 14756, FF 14756	No file	No file	No file	4 ft	
2	bishwamandarpur	Bishwamandapur Upazila Health Complex (new Building))	1998	HED	available	50	1 dwg	No file	No file	No file	7664	GF 7664, FF 7664, SF 7664,	No file	No file	No file	4 ft	
3	chhatak	Chhatak Upazila Health Complex (Old Building)	1983	HED	available	50	1 dwg	No file	No file	No file	14213	GF 14213, FF 14213	No file	No file	No file	4 ft	
4	chhatak	Chhatak Upazilla Health Complex (new Building)	1983	HED	available	50	1 dwg	No file	No file	No file	7352	GF 7352, FF 7352, SF 7352, TF 7352	No file	No file	No file	4 ft	
5	derai	Derai Upazila Health Complex (new building)	1983	HED		50	1 dwg	No file	No file	No file			No file	No file	No file	4 ft	
6	derai	Derai Upazila Health Complex (Old Building)	1983	HED		50	1 dwg	No file	No file	No file			No file	No file	No file	4 ft	
7	dharampasha	Dharampasha Upazila Health Complex (Old Building)	1979	HED	available	50	No file	No file	No file	No file			No file	No file	No file		
8	dharampasha	Dharampasha Upazilla Health Complex (new building)	1979	HED		50	No file	No file	No file	No file			No file	No file	No file	1 ft	
9	dowarabazar	Dowarabazar Upazila Health Complex (new	1999	HED		50	1 dwg	No file	No file	No file			No file	No file	No file	4 ft	

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
		building)															
10	dowarabazar	Dowarabazar Upazila Health Complex (Old Building)	1999	HED	available	50	1 dwg	No file	No file	No file			No file	No file	No file	4 ft	
11	jagannathpur	Jagannathpur Upazila Health Complex (Old Building)	1964	Other		50	1 dwg	No file	No file	No file			No file	No file	No file	2 ft	
12	jagannathpur	Jagannathpur Upazilla Health Complex (new building)	1964	HED		50	1 dwg	No file	No file	No file			No file	No file	No file	2 ft	
13	jamalganj	Jamalganj Upazila Health Complex (new building)	1986	HED	available	50	1 dwg	No file	No file	No file			No file	No file	No file	4 ft	
14	jamalganj	Jamalganj Upazila Health Complex (Old Building)	1986	HED	available	50	1 dwg	No file	No file	No file			No file	No file	No file	4 ft	
15	madhyanagar	Madhynagar Upazila Health Complex(new proposed)	2026	PWD	already selected land for acqusition(proposed)	101	No file	No file	No file	No file			No file	No file	No file	4 ft	newly proposed project
16	shanthiganj	Shanthiganj Upazila Health Complex	2021	HED	available	50	1 dwg	No file	No file	No file	11158	GF 11158, FF 11158, SF 11158, TF 11158 FF 11158	No file	No file	10 jpegs	4 ft	
17	sullah	Sullah Upazila Health Complex (new building)	1984	HED		50	1 dwg	No file	No file	No file			No file	No file	No file	4 ft	
18	sullah	Sullah Upazila Health Complex (Old Building)	1984	HED		50	1 dwg	No file	No file	No file			No file	No file	No file	4 ft	
19	tahirpur	Tahirpur Upazila Health Complex (Old Building)	1978	HED	available	50	1 dwg	No file	No file	No file			No file	No file	No file	4 ft	
20	tahirpur	Tahitpur Upazilla Health Complex (new building)	1978	HED		50	1 dwg	No file	No file	No file			No file	No file	No file	4 ft	

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	bishwamandarpur	Bishwamandapur Upazila Health Complex								No file			
2	bishwamandarpur	Bishwamandapur Upazila Health Complex (Old Building)								No file			
3	chhatak	Chhatak Upazila Health Complex (New Blding)	40	2.5	4	Deep		RCC		No file			
4	chhatak	Chhatak Upazila Health Complex (Old Building)	20.5	1.5	2	Footing		Load Bearing Brick		No file	Not Possible		

Sl No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
5	derai	Derai Upazila Health Complex								No file			
6	derai	Derai Upazila Health Complex (Old Building)								No file			
7	dharampasha	Dharampasha Upazila Health Complex								No file			
8	dharampasha	Dharampasha Upazilla Health Complex (Old Building)								No file			
9	dowarabazar	Dowarabazar Upazila Health Complex								No file			
10	dowarabazar	Dowarabazar Upazila Health Complex (Old Building)								No file			
11	jagannathpur	Jagannathpur Upazila Health Complex								No file			
12	jagannathpur	Jagannathpur Upazila Health Complex (Old Building)								No file			
13	jamalganj	Jamalganj Upazila Health Complex								No file			
14	jamalganj	Jamalganj Upazila Health Complex (Old Building)								No file			
15	madhyanagar	Madhyanagar Upazila Health Complex								No file			
16	shanthiganj	Shanthiganj Upazila Health Complex	50	4	5	Deep		RCC		No file			
17	sullah	Sullah Upazila Health Complex								No file			
18	sullah	Sullah Upazila Health Complex (Old Building)								No file			
19	tahirpur	Tahirpur Upazila Health Complex								No file			
20	tahirpur	Tahitpur Upazilla Health Complex (Old Building)								No file			

Water Supply and Sanitation

[illegible]

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
6	jagannathpur	Jagannathpur Upazila Health Complex											
7	jamalganj	Jamalganj Upazila Health Complex											
8	madhyanagar	Madhyanagar Upazila Health Complex											
9	shanthiganj	Shanthiganj Upazila Health Complex	0	1	no	Septic Tank	0	No			Required master drain ,internal connecting drain	Waste & Water Dispose by nearest Municipality, Open low land like pond and haor	
10	sullah	Sullah Upazila Health Complex											
11	tahirpur	Tahirpur Upazila Health Complex											

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	bishwamandarpur	Bishwamandapur Upazila Health Complex									
2	chhatak	Chhatak Upazila Health Complex									
3	derai	Derai Upazila Health Complex									
4	dharampasha	Dharampasha Upazila Health Complex									
5	dowarabazar	Dowarabazar Upazila Health Complex									
6	jagannathpur	Jagannathpur Upazila Health Complex									
7	jamalganj	Jamalganj Upazila Health Complex									
8	madhyanagar	Madhyanagar Upazila Health Complex									
9	shanthiganj	Shanthiganj Upazila Health Complex					20		Yes	No	
10	sullah	Sullah Upazila Health Complex									
11	tahirpur	Tahirpur Upazila Health Complex									

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
1	bishwamandarpur	Bishwamandapur Upazila Health Complex	0	0	0	10	18		Not present	7.5	0	Required submersible and Centrifugal Pump	Not Present	Demand
2	chhatak	Chhatak Upazila Health Complex	0	0	0	6.5	20		NA	3	0	Required submersible and Centrifugal Pump	Not Present	
3	derai	Derai Upazila Health Complex	0	0	0	4	30		Not present	7	0	Required submersible and Centrifugal Pump	Not Present	Demand
4	dharampasha	Dharampasha Upazila Health Complex	0	0	0	10	20		No	7	0	Required submersible and Centrifugal Pump	Not Present	Demand
5	dowarabazar	Dowarabazar Upazila Health Complex	0	0	0	10	15		0	5.5	0	Required submersible and centrifugal pump	Not Present	Na
6	jagannathpur	Jagannathpur Upazila Health Complex	0	0	0	15	15		NA	7.5	0	Required submersible and Centrifugal Pump	Not Present	
7	jamalganj	Jamalganj Upazila Health Complex	0	0	0	8	20		Not present	1	0	Required submersible and Centrifugal Pump	Not Present	Demand
8	madhyanagar	0	0	0										
9	shanthiganj	Shanthiganj Upazila Health Complex	0	0	0	20	25		NA	4	0	Required submersible and Centrifugal Pump	Not Present	
10	sullah	Sullah Upazila Health Complex	0	0	n/a	8.5	15	n/a	n/a	5.5	0	Demand	Not Present	n/a
11	tahirpur	Tahirpur Upazila Health Complex	0	0	0	12	20		Not present	2	0	Required submersible and Centrifugal Pump	Not Present	Demand

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	bishwamandarpur	Bishwamandapur Upazila Health Complex	REB	Yes	135	150	15	good	40	0	0	0	HT 3x70 sqm Lenth 30 meter, Transformer to LT= 1C-4x70 rm=10m, LT to PFI= 1C-3x50 rm, (Approx)	FDB= 1C-4x10 Sqmm (Approx)	Situation of Generator (dilapidated)
2	chhatak	Chhatak Upazila Health Complex	PDB	Yes	150	250	100	operational	6.6	50	0	0	HT cable 4x70 sqm, length 35 Meter	Substation to Overhead Line 4x50 sqm length 20 meter, Overhead Line to MDB 25 sqm, length 60 meter FDB 10 RM Length 15 meter	সাবস্টেশনটি দীর্ঘদিনের পুরাতন ও জরাজীর্ণ।
3	derai	Derai Upazila Health Complex	PDB	Yes	60	0	0	0	0	50	0	0	Every building individually connection by PDB.	FDB= 1C-4x10 Sqmm	50 KVA Generator (Damaged)=01 No and need substation
4	dharampasha	Dharampasha Upazila Health Complex	REB	Yes	120	150	30	dilapidated	10	60	0	0	LT- 1C-4x35 Sqmm =150 mtr	FDB1= 1C-4x10 Sqmm=5m,FDB2= 1C-4x10 Sqmm=10m	transformer (pole mounted),
5	dowarabazar	Dowarabazar Upazila Health Complex		Yes	135	150	15	operational	60	0	2	0	HT 3x70 sqm Length 40 meter	Substation to Overhead Line 4x50 sqm length 25 meter, Overhead line to MDB 4x35 sqm length 60 Meter, FDB 10 RM Length 10 meter	

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
6	jagannathpur	Jagannathpur Upazila Health Complex	PDB	Yes	150	200	50	Pole Mounted Substation (Operational)	50	0	0		LT 4x35sqm Length 25 meter	Overhead Line to MDB 4x25 sqm length 40 Meter, FDB 10 RM Length 15 meter	
7	jamalganj	Jamalganj Upazila Health Complex	REB	Yes	120	0	0	N/A	0	50	0	0	Every building individually connection by REB.	FDB= 1C-4x10 Sqmm	Need Substation and Generator
8	madhyanagar	Madhyanagar Upazila Health Complex													
9	shanthiganj	Shanthiganj Upazila Health Complex	REB	Yes	135	150	15	operational	50	0	0	0	HT 3x95 sqm Length 25 meter	Substation to Overhead Line 4x70 sqm length 80meter,MDB 4x16 sqm length 25 Meter,FDB 10 RM Length 10 meter	
10	sullah	Sullah Upazila Health Complex	PDB	Yes	125	150	25	operational	50				HT 3x70 sqm Lenth 25 meter	Substation to Overhead Line 4x50 sqm length 40 meter, Overhead Line to MDB 4x35 sqm length 50 Meter,FDB 10 RM Length 10 meter	Solar System useless
11	tahirpur	Tahirpur Upazila Health Complex	REB	Yes	130	150	20	dilapidated	0	50	0	0	HT 3x70 sqm Lenth 25 meter, LT-1C-4x70 Sqmm=08m	Sub-station to Building MDB= 1C-4x35 Sqmm=50m	150 KVA Transformer (Damaged)

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	bishwamandarpur	Bishwamandapur Upazila Health Complex	No	0	0	0	Yes	No	No		Yes	0	Required PABX System, Neon Poly sign,CCTV system,computer networks, Sound and PA System, Medical Gas for Proposed 101 Bed UHC	CCTV and Security Light insufficient. About 20 oxygen gas outlets can be seen on the ground but are useless.
2	chhatak	Chhatak Upazila Health Complex	No	0	0	0	Yes	No	No	No	No		Required PABX System, Neon Poly sign,CCTV system,computer networks, Sound and PA System, Medical Gas for Proposed 101 Bed UHC	Security Light insufficient
3	derai	Derai Upazila Health Complex	No	0	0	0	Yes	No	No	No	No	0	Required PABX System, Neon Poly sign,CCTV system,computer networks, Sound and PA System, Medical Gas for Proposed 101 Bed UHC.	Security Compound light condition not good & quantity not enough
4	dharampasha	Dharampasha Upazila Health Complex	No	0	0	Demand	Yes	No	No	No	No	0	Required PABX System, Neon Poly sign,CCTV system,computer networks, Sound and PA System, Medical Gas for Proposed 101 Bed UHC	Security Light insufficient. About 20 oxygen gas outlets can be seen on the ground but are useless.
5	dowarabazar	Dowarabazar Upazila Health Complex	No	0	0	0	Yes	No	No	No	Yes	0	Required PABX System, Neon Poly sign,CCTV system,computer networks, Sound and PA System, Medical Gas for Proposed 101 Bed UHC	CCTV and Security Light insufficient
6	jagannathpur	Jagannathpur Upazila Health Complex	No	0	0	0	No	No	No	No	Yes	0	Required PABX System, Neon Poly sign,CCTV system,computer networks, Sound and PA System, Medical Gas for Proposed 101 Bed UHC	CCTV Insufficient

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
7	jamalganj	Jamalganj Upazila Health Complex	No	0	0	Demand	Yes	No	No	No	No	0	Required PABX System, Neon Poly sign,CCTV system,computer networks, Sound and PA System for Proposed 101 Bed UHC	
8	madhyanagar	Madhyanagar Upazila Health Complex	No	0	0	no	No						Required PABX System, Neon Poly sign,CCTV system,computer networks, Sound and PA System, Medical Gas for Proposed 101 Bed UHC	
9	shanthiganj	Shanthiganj Upazila Health Complex	No				Yes	No	No	No	Yes	0	Required PABX System, Neo poly Sign, computer networks, Sound and PA System for Proposed 101 Bed UHC	CCTV and Security Light insufficient,
10	sullah	Sullah Upazila Health Complex	No	0	0		Yes	No	No	No	No	0	Required PABX System, Neon Poly sign,CCTV system,computer networks, Sound and PA System, Medical Gas for Proposed 101 Bed UHC	Compound and Security Light not sufficient
11	tahirpur	Tahirpur Upazila Health Complex	No	0	0	no	Yes	No		No	Yes	0	Required PABX System, Neon Poly sign,CCTV system,computer networks, Sound and PA System, Medical Gas for Proposed 101 Bed UHC	CCTV and Security Light insufficient

District Name: Sylhet

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	balaganj	50 bedded Upazila Health Complex at Balaganj.	No file	
2	beanibazar	50 bedded Upazila Health Complex, Beanibazar.	No file	
3	bishwanath	50 bedded upazila health complex at Bishwanath	No file	
4	companiganj	50 bedded upazila hospital at Companiganj, Sylhet	No file	
5	fenchuganj	50 bedded upazila health complex at Fenchuganj.	No file	
6	golapganj	Upazila health complex	No file	
7	gowainghat	50 bedded Upazila Hospital at Gowainghat , Sylhet	No file	
8	jaintiapur	50 bedded upazila hospital at Jaintiapur, Sylhet	No file	
9	kanaighat	50 bedded Upazila Health Complex, Kanaighat.	No file	
10	osmani nagar	50 bedded upazila health complex at Osmani nagar.	No file	
11	south_surma	50 bedded upazila health complex at South Surma.	No file	
12	zakiganj	50 bedded Upazila Health Complex, Zakiganj.	No file	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	balaganj	50 bedded Upazila Health complex at balaganj	1968	PWD	Available	50	1 dwg	1 pdf	No file	No file	6000	6000 approximately	No file	No file	8 jpgs		
2	beanibazar	upazila health complex	1982		available	50	No file	No file	1 jpg	1 pdf	12139	31203	No file	No file	6 movs	not affected by flood.	
3	bishwanath	50 bedded upazila health complex at Bishwanath	2018	HED	Availabile	50	1 dwg	1 pdf	No file	No file			No file	No file	No file		
4	companiganj	19 bedded 6 storied Hospital Building at Companiganj, Sylhet	2022	HED	Available	19	1 dwg	2 pdfs	1 dwg	No file	5215	GF to 4F- each floor 5215 sft	No file	No file	3 jpegs	PL+2ft flash flood inundation at 18 June 2022	Soil test was for Companiganj Model mosque around 500-600 feet away. water soaking and moss growth at many parts, under utilized (currently only GF and 1F under usage), There is a 1 storied link corridor to old building, Column strength not sufficient as per rebound hammer test (avg. 26 MPa)
5	companiganj	31 bedded upazila hospital at Companiganj, Sylhet	1997	PWD	Available	31	1 dwg	1 pdf	1 dwg	1 dwg	14953	GF 14953 SFT, 1F 8902 sft	No file	No file	8 jpegs	PL+2ft flash flood inundation at 18 June 2022	Soil test was for Companiganj Model mosque around 500-600 feet away.Old building vertical Extension not possible, There is a big pond that needs to be filled partially for new construction. There ia a one storied connecting corridor to new 6 storied building implemented by HED at 2022

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
6	fenchuganj	50 bedded upazila health complex at Fenchuganj.	1984	PWD	yes	50	1 dwg	1 pdf	No file	No file	440000	11000	No file	No file	1 jpeg	Effected Flood 2022	
7	golapganj	Upazila health complex	1982		available	50	No file	1 pdf	1 jpg	1 pdf	12139	31203	No file	No file	1 mov	not affected by flood.	
8	gowainghat	31 Bedded Upazila Hospital at Gowainghat, Sylhet	1978	PWD	Available	31	1 dwg	1 pdf	No file	No file	10000	GF 14953 SFT, 1F 8902 sft	No file	No file	9 jpegs	PL+4 feet at 18 June 2022	load bearing structure, store shortage, adjacent road level high so inundation even at light rain, needs campus filling and new road (in that case many old buildings PL will be at below sub-road level), conference hall missing, Outside wall 10 inch, partition wall 5"
9	jaintiapur	19 bedded 3 storied hospital building	2013	HED	Available	19	No file	1 pdf	No file	No file	5000	GF 5000 SFT (approx), 1F 5000 sft(approx), 2F 2500 sft (approx)	No file	1 pdf	8 jpegs	PL+1 feet at 18 june 2022	Visible cracks, visible water soaking and moss growth.
10	jaintiapur	31 bedded Upazila Hospital Building, Jaintiapur, Sylhet	1985	PWD	Available	31	No file	1 pdf	No file	No file	15000	GF 10000, 1F 8900	No file	1 pdf	7 jpegs	No inundation till date	Old building vertical Extension not possible. There is a 2 storied connecting corridor to 3 storied newly constructed building (2010).
11	kanaighat	upazila health complex	1982		available	50	2 pdfs	1 pdf	1 pdf	2 pdfs	12212	32597	No file	No file	1 jpeg	FGL+4'	
12	osmani nagar	50 bedded Upazila Health complex at Osmaninagar	2023	HED	Available	50	No file	1 pdf	No file	No file	6000	6000 approximately	No file	No file	2 jpegs		
13	south_surma	50 bedded upazila health complex at South Surma	2013	HED	yes	50	1 dwg	1 pdf	No file	No file	38000	9500	No file	No file	2 jpegs	N/A	
14	zakiganj	upazila health complex	1982		available	50	No file	1 pdf	No file	2 pdfs	12212	32597	No file	No file	2 jpegs	FGL+2'	

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	balaganj	50 bedded Upazila Health complex at balaganj	70	3	7	Deep	7	RCC	Standard	No file	Not Possible	Not yet.because its newly constructed building	A new building need to extend upto 101 bed
2	beanibazar	upazila health complex	38	2	3	Deep	5	RCC	old building portion is vernarable. New building structural condition is good.	No file	Possible	n/a	regular maintenance required.
3	bishwanath	50 bedded upazila health complex at Bishwanath	30	2.5	3		5	RCC	Moderate	No file	Possible		Vertical etension of 2 stories is possible, but that may not cover the additional 50 bed.
4	companiganj	19 bedded 6 storied Hospital Building at Companiganj, Sylhet	80	3	6	Deep	6	RCC	visible cracks, water ingress and moss accumulation	No file	Not Possible		There is one lift, 3rd to 5th floor is unused

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
5	companionanj	31 bedded Upazila Hospital Building, Jaintiapur, Sylhet	32	1	2	Footing	2	RCC	Visible cracks and ingress of water from roof.	No file	Not Possible		Inundation during flash flood at 2022
6	fenchuganj	50 bedded upazila health complex at South Fenchuganj.	40	2.5	4	Footing	4	RCC	Below Standard	No file	Not Possible	Before 10 years Some renovation Completed	
7	golapganj	Upazila health complex, golapganj	38	1.5	3		5	RCC	moderate	No file	Possible	N/A	
8	gowainghat	19 bedded 3 storied hospital building	34	3	3	Deep		RCC	Water ingress at many places	No file	info not available		around 1 ft inundation at 2022
9	gowainghat	31 Bedded Upazila Hospital at Gowainghat, Sylhet	30	1	2	Footing	2	Load Bearing Brick	visible cracks, water ingress and moss accumulation	No file	Not Possible		Built 1978
10	jaintiapur	19 bedded 3 storied hospital building	36	2	3	Deep		RCC	Visible cracks and ingress of water from roof.	No file	info not available		
11	jaintiapur	31 bedded Upazila Hospital Building, Jaintiapur, Sylhet	32	1	2	Footing	2	RCC	Visible cracks and ingress of water from roof.	No file	Not Possible		
12	jaintiapur	31 bedded Upazila Hospital Building, Jaintiapur, Sylhet	32	1	2	Footing	2	RCC	Visible cracks and ingress of water from roof.	No file	Not Possible		
13	kanaighat	upazila health complex	38	1.5	3	Deep	5	RCC	moderate	No file	Possible	N/A	
14	osmani nagar	50 bedded Upazila Health complex at Osmaninagar	40	2.5	4	Deep	5	RCC	Standard	No file	Not Possible	Not applicable,because its newly constructed	1-story vertical extension possible but it will not enough to extend 101 bed
15	south surma	50 bedded upazila health complex at South Surma.	40	2.5	4	Footing	4	RCC	Below Standard	No file	Not Possible	N/A	
16	zakiganj	upazila health complex	38	1.5	3	Deep	5	RCC	below standard	No file	Possible	N/A	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	balaganj	50 bedded Upazila Health complex at balaganj	0	2	0	Septic Tank	2472	No	0	Surface Drainage system	Construction of new master drain Master drain and connect to River	Not applicable	Water supply System need reset and repair,Need a new Water reservoir
2	beanibazar	upazila health complex	0	1	1 shallow tubewell	Septic Tank	2500	No	0	surface drain system	master drain and connection to main drain is required.		
3	bishwanath	50 bedded upazila health complex at Bishwanath		1	1 shallow tubewell	Septic Tank		No	0	surface draining system	Master drain and a culvert in nearby road to carry the water towards the low land.	No specific disposal site.Water suppose to move to low lands.	
4	fenchuganj	50 bedded upazila health complex at Fenchuganj.	0	0	1 Shallow Tubwel	Septic Tank	750	No	0	Not Sufficient	380 Rm	Low Land Area	
5	fenchuganj	50 bedded upazila health complex at Fenchuganj.	0	1	1 Shallow Tubwel		720	No	0	Not Sufficient	430 Rm Needed	yes	

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
6	golapganj	Upazila health complex, golapganj	0	1	1 shallow tubewell	Septic Tank	2500	No	0	surface draining system	Master drain and a culvert in nearby road to carry the water towards the low land.	No specific disposal site. Water suppose to move to low lands.	
7	kanaighat	upazila health complex	0	2		Septic Tank	3000	No	0	surface drain available. A connection with municipal drain is required.	Master drain required.	Nearby drain available. Connection required.	
8	osmani nagar	50 bedded Upazila Health complex at Osmaninagar	0	1	Shallow tube well-01	Septic Tank	13596	No	0	Surface Drainage system	Need some extension and addition	Not applicable	Need a Reservoir and need some renovation in water supply system
9	south surma	50 bedded upazila health complex at South Surma	0	0	1 Shallow Tubwel	Septic Tank	750	No	0	Not Sufficient	430 Rm Needed	Low Land Area	
10	zakiganj	upazila health complex	0	1	1 shallow	Septic Tank	2700	No	0	surface drain available.	Master drain required.		

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	balaganj	50 bedded Upazila Health complex at balaganj	0	550			12	Need to expand, extend, renovate internal Road, existing roads are narrow and not usable	Yes	Yes	
2	beanibazar	upazila health complex	10		350		24	below standard	Yes	No	
3	bishwanath	50 bedded upazila health complex at Bishwanath					12	10 ft wide road. some portion required repairing works.	Yes	Yes	
4	fenchuganj	50 bedded upazila health complex at Fenchuganj.	0	680	400	360	60	20 ft Rcc Road	No	Yes	
5	golapganj	Upazila health complex, golapganj	10		400		24	10 ft wide road. some portion required repairing works.	Yes	No	
6	kanaighat	upazila health complex		4.5		2.5	25.83	moderate	Yes	Yes	
7	osmani nagar	50 bedded Upazila Health complex at Osmaninagar	1200	800	0	0	20	Newly constructed and in well condition	No	No	
8	south surma	50 bedded upazila health complex at South Surma	0	920	0	600	40	20 ft Rcc Road	No	Yes	
9	zakiganj	upazila health complex		5		2.5	25.83	moderate	Yes	Yes	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (if any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional Info (Capacity, Demand etc)
1	balaganj	Balaganj Upazila Health Complex Sylhet	1	0	Not Usable Most of the Time	4	6		NO Fire Detection System. Only Contains some Fire Extinguisher	3	0	Need Additional Pump Motor	Not Present	

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional info (Capacity, Demand etc)
2	beanibazar	Beanibazar Upazila Health Complex	0	0		10	6		NO Fire Detection System. Only Contains some Fire Extinguisher	3	0		Not Present	
3	bishwanath	Bishwanath Upazila Health Complex	0	0		10	6		NO Fire Detection System. Only Contains some Fire Extinguisher	3	0		Not Present	
4	companiganj	Osmaninagar Upazila Health Complex	0	0		8	4		NO Fire Detection System. Only Contains some Fire Extinguisher	3	0		Not Present	
5	fenchuganj	Fenchuganj Upazila Health Complex	0	0		10	6		NO Fire Detection System. Only Contains some Fire Extinguisher	2	0		Not Present	
6	golapganj	Golapganj Upazila Health Complex	0	0		0	10		NO Fire Detection System. Only Contains some Fire Extinguisher	3	0		Not Present	
7	gowainghat	Upazila Health Complex, Gowainghat	0	0		0	6		NO Fire Detection System. Only Contains some Fire Extinguisher	2	0		Not Present	
8	jaintiapur	Jaintapur Upazila Health Complex	0	0		0	8		NO Fire Detection System. Only Contains some Fire Extinguisher	2	0		Not Present	
9	kanaighat	Upazila Health Complex Kanaighat	0	0		12	6		NO Fire Detection System. Only Contains some Fire Extinguisher	3	0		Not Present	
10	osmani_nagar	Osmaninagar Upazila Health Complex	0	0		8	4		NO Fire Detection System. Only Contains some Fire Extinguisher	6	0		Not Present	
11	south_surma	Upazila Health Complex, South Surma	0	0		20	4		NO Fire Detection System. Only Contains some Fire Extinguisher	6	0		Not Present	
12	zakiganj	Upazila Health Complex,Zakiganj	0	0		0	20	N/A	NO Fire Detection System. Only Contains some Fire Extinguisher	3			Not Present	Need Medical Waste Management Sestem

External Electrification

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 KVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of out going connection)	Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
1	balaganj	Balaganj Upazila Health Complex Sylhet	REB	Yes	150	150	0		30	0	0	1			
2	beanibazar	Beanibazar Upazila Health Complex	REB	Yes	100	100	0		0	30	0	1			
3	bishwanath	Bishwanath Upazila Health Complex	REB	Yes	150	150	0		30	0	0	1			
4	companiganj	Companiganj Upazilla Health Complex	REB	Yes	100	100	0		30	0	0	1			
5	fenchuganj	Fenchuganj Upazila Health Complex	REB	Yes	100	100	0		30	0	0				

SL No	Upazilla	Name of the Hospital	Connection Provider	Can Provider Provide Apprx 1250 kVA Load?	Existing Actual Usage of Power or Load (kVA)	Present Total KVA Capacity of Substation	Reusable KVA of substation	Situation of Substation Components (LT HT PFI MDB etc)	Existing Total KVA Capacity of Generator	Additional Requirement of Generator (KVA)	Present Usable Capacity of on grid solar (kWp)	Present Capacity of Ring Main Unit (number of outgoing connection)	Detailed Description of incoming Service Cable (RM, Type and Length of HT or LT)	Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc)	Remarks (Provide any additional information here)
6	golapganj	Golapganj Upazila Health Complex	REB	Yes	100	100	0		0	30	0	1			
7	gowainghat	Upazila Health Complex, Gowainghat	REB	Yes	50	150	0		25	0	0	1			
8	jaintiapur	Jaintapur Upazila Health Complex	REB	Yes	50	50	0	Pole Mounted Transformer currently Exists	30	0	0	1	25 RM service cable (NYY)		
9	kanaighat	Upazila Health Complex Kanaighat	REB	Yes	100	100	0	Pole Mounted Transformer currently Exists	0	30	2	1			
10	osmani_nagar	Osmaninagar Upazila Health Complex	REB	Yes	150	150	0		30	0	2	1			
11	south_surma	Upazila Health Complex, South Surma	REB	Yes	150	150	0		30	30	0	1			
12	zakiganj	Upazila Health Complex,Zakiganj	REB	Yes	100	100	0		30	0	0	1			

Ancillary EM Items

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
1	balaganj	Balaganj Upazila Health Complex Sylhet	No	0	0		Yes	No	No	No	Yes	1	Update of CCTV, PABX, New Active Neon Signboard , Adequate Compound Lights will be required	
2	beanibazar	Beanibazar Upazila Health Complex	No	0	0		Yes	No	No	No	Yes	0	New CCTV, PABX, Neon Signboard , Adequate Compound Lights will be required	
3	bishwanath	Bishwanath Upazila Health Complex	No	0	0		Yes	No	No	No	No	0	New CCTV, PABX, Neon Signboard , Adequate Compound Lights will be required	
4	companiganj	Companigonj Upazilla Health Complex	No	0	0		Yes	No	No	No	Yes	0	New CCTV, PABX, Neon Signboard , Adequate Compound Lights will be required	
5	fenchuganj	Fenchuganj Upazila Health Complex	No	0	0		Yes	No	No	No	Yes	1	New CCTV, PABX, Adequate Compound Lights will be required	
6	golapganj	Golapganj Upazila Health Complex	No	0			No	No	No		No	0	New CCTV, PABX, Neon Signboard , Adequate Compound Lights will be required	
7	gowainghat	gowainghat upazila health complex	No	0	0		Yes	No	No	No		1	Update of CCTV, PABX, Adequate Compound Lights will be	
8	jaintiapur	Jaintapur Upazila Health Complex	No	0	0		Yes	No	No	No		1	Update of CCTV, PABX, Internet system , Adequate Compound Lights are required	
9	kanaighat	Upazila Health Complex Kanaighat	No	0	0		Yes	No	No	No	No	0	New CCTV, PABX, Active Neon Signboard , Adequate Compound	

SL No	Upazilla	Name of the Hospital	Presence of Medical Gas System	Capacity of Medical Gas Plant if any (LPM)	Number of bed having Medical Gas Facility if any (nos)	Medical Gas Related Additional Info (describe)	Presence of Compound and Security Light	Presence of Sound and PA System	Presence of computer networks	Presence of PABX System	Presence of CCTV system	Number of Neon Poly sign board	Requirement of any ancillary items (Describe in detail)	Remarks (For any Additional Information)
													Lights will be required	
10	osmani nagar	Osmaninagar Upazila Health Complex	No	0	0		Yes	No	No	No	No	0	Security and compounds lights are not adequate	
11	south_surma	Upazila Health Complex, South Surma	No	0	0		Yes	No	No	No	No	0	New CCTV, PABX, Neon Signboard , Adequate Compound Lights will be required	
12	zakiganj	Upazila Health Complex,Zakiganj	No	0	0	0	Yes	No	No	No	No	0	New CCTV, PABX, Neon Signboard , Adequate Compound Lights will be required	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	beanibazar	upazila health complex	Pump house		1982	1	250.25	250.25	below standard	1 pdf	No file	
2	beanibazar	upazila health complex	Garage		1982	1	900	900	below standard	1 pdf	No file	
3	beanibazar	upazila health complex	Sub-Station & Genaretor		1982	1	638	638	below standard	1 pdf	No file	
4	beanibazar	upazila health complex	Dr. Quarter's (4-Unit)		1982	2	2482.6	4965.2	below standard	1 pdf	No file	
5	beanibazar	upazila health complex	Staff Quarter (3-unit)		1982	2	1321.1	2123.67	below standard	1 pdf	No file	
6	beanibazar	upazila health complex	Staff Quarter		1982	1	2772	2772	below standard	1 pdf	No file	
7	beanibazar	upazila health complex	Staff Quarter (6-unit)		1982	3	1340.14	4020.42	below standard	1 pdf	No file	
8	beanibazar	upazila health complex	Staff Quarter (4-unit)		1982	2	1320.1	2640.2	below standard	1 pdf	No file	
9	beanibazar	upazila health complex	Interni hostel		2000	1	1954	1954	below standard	1 pdf	No file	
10	beanibazar	upazila health complex	Mosque		2000	1	678.29	678.29	below standard	1 pdf	No file	
11	beanibazar	upazila health complex	Oxigen building		2018	1	264	264	below standard	1 pdf	No file	
12	beanibazar	upazila health complex	UH FPO & RMO Quarter-02		1982	1	1530.42	1530.42	below standard	1 pdf	No file	
13	beanibazar	upazila health complex	UH FPO & RMO Quarter-01		1982	1	1529.42	1529.42	below standard	1 pdf	No file	
14	beanibazar	upazila health complex	Nurse Quarter		1982	1	1276.27	1276.27	below standard	1 pdf	No file	
15	beanibazar	upazila health complex	Nurse Dormitory		1982	1	1276.27	1276.27	below standard	1 pdf	No file	
16	beanibazar	upazila health complex	Dr. Quarter's (3-Unit)		1982	2	2739.63	4029.55	below standard	1 pdf	No file	
17	beanibazar	upazila health complex	Medicine Store		1982	1	929.47	929.47	below standard	1 pdf	No file	
18	beanibazar	upazila health complex	New hospital building		2018	3	6925	20775	average	1 pdf	No file	
19	beanibazar	upazila health complex	Family planning		1982	2	2714.65	5429.3	below standard	1 pdf	No file	
20	beanibazar	upazila health complex	Old hospital building		1982	2	5214.37	10428.74	below standard	1 pdf	No file	
21	golapganj	upazila health complex, golapganj	3 storied staff quarter			3	1500	4500	repair and maintenance required	No file	No file	
22	golapganj	upazila health complex, golapganj	3 storied new hospital building			3	5000	15000	area assume	No file	No file	
23	golapganj	upazila health complex, golapganj	2storied old hospital building			2	5000	10000	area assume	No file	No file	
24	golapganj	upazila health complex, golapganj	4 storied nurse's quarter			4	1500	6000	repair and maintenance required	No file	No file	
25	golapganj	upazila health complex, golapganj	Generator/Substation			1	225	225	repair and maintenance required	No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
26	golapganj	upazila health complex, golapganj	1 storied store room for family planning			1	964	964	repair and maintenance required	No file	No file	
27	golapganj	upazila health complex, golapganj	1 storied nurse dormitory			1	675	675	repair and maintenance required	No file	No file	
28	golapganj	upazila health complex, golapganj	semi paka garrage			1	506	506	repair and maintenance required	No file	No file	
29	golapganj	upazila health complex, golapganj	2 storied officers quarter			2	1250	2500	repair and maintenance required	No file	No file	
30	golapganj	upazila health complex, golapganj	2 storied doctors quarter			2	2300	4600	repair and maintenance required	No file	No file	
31	golapganj	upazila health complex, golapganj	2 storied staff quarter			2	2500	3750	repair and maintenance required	No file	No file	
32	golapganj	upazila health complex, golapganj	2 storied staff quarter			2	1500	3000	repair and maintenance required	No file	No file	
33	golapganj	upazila health complex, golapganj	2 storied staff quarter			2	1900	3800	repair and maintenance required	No file	No file	
34	kanaighat	upazila health complex	Oxigen building		2018	1	264	264	below standard	1 pdf	1 jpeg	
35	kanaighat	upazila health complex	Pump house		1982	1	250.25	250.25	below standard	1 pdf	1 jpeg	
36	kanaighat	upazila health complex	Nurse Dormitory		2018	5	988	4940	below standard	1 pdf	1 jpeg	
37	kanaighat	upazila health complex	Mosque		2008	2	680	1360	below standard	1 pdf	1 jpeg	
38	kanaighat	upazila health complex	Staff Quarter (3rd. Class)		2018	2	988	1976	below standard	1 pdf	1 jpeg	
39	kanaighat	upazila health complex	Dr. Dormitory		2018	5	1143.53	5717.65	below standard	1 pdf	1 jpeg	
40	kanaighat	upazila health complex	UH FPO & RMO Quarter		2018	2	1529.42	3058.84	moderate	1 pdf	1 jpeg	
41	kanaighat	upazila health complex	Garage & Driver Room		2018	2	561	1122	below standard	1 pdf	1 jpeg	
42	kanaighat	upazila health complex	Waste menagement		1982	1	400	400	below standard	1 pdf	1 jpeg	
43	kanaighat	upazila health complex	Sub-Station & Genaretor		1982	1	638	638	below standard	1 pdf	1 jpeg	
44	kanaighat	upazila health complex	Staff Quarter (4th. Class)		1982	2	1320.1	2640.2	below standard	1 pdf	1 jpeg	
45	kanaighat	upazila health complex	Staff Quarter (3rd. Class)		1982	4	1340.14	5360.56	below standard	1 pdf	1 jpeg	
46	kanaighat	upazila health complex	Nurse Dormitory		1982	1	1263.64	1263.64	below standard	1 pdf	1 jpeg	
47	kanaighat	upazila health complex	Dr. Quarter's (5-Unit)		1982	3	2731.89	6909.41	below standard	1 pdf	1 jpeg	
48	kanaighat	upazila health complex	Medicine Store		1982	1	929.47	929.47	below standard	1 pdf	1 jpg	
49	kanaighat	upazila health complex	New hospital building		2018	3	8171.97	24515.91	below standard	1 pdf	1 jpeg	
50	kanaighat	upazila health complex	Family planning		1982	2	2714.65	5429.3	below standard	1 pdf	1 jpeg	
51	kanaighat	upazila health complex	Old hospital building		1982	2	5214	10428	below standard	1 pdf	1 jpeg	
52	osmani nagar	50 bedded Upazila Health complex at Osmaninagar	Sub-Station building with Pre cast pile Foundation	1	2023	1			Good	No file	No file	
53	osmani nagar	50 bedded Upazila Health complex at Osmaninagar	Garage cum driver Quarter(accommodation for two ambulance) with pre cast pile Foundation	1	2023	1			Good	No file	No file	
54	osmani nagar	50 bedded Upazila Health complex at Osmaninagar	5-Storied class-2 & 3 staff dormitory with 5-storied pre cast pile Foundation	1	2023	5				No file	No file	
55	osmani nagar	50 bedded Upazila Health complex at Osmaninagar	5-Storied Nursing Dormitory with 5-storied pre cast pile Foundation	1	2023	5			Good	No file	No file	
56	osmani nagar	50 bedded Upazila Health complex at Osmaninagar	3-Storied 800 sft Nurse Quarter with 5-storied pre cast pile Foundation	1	2023	3	800	2400	Good	No file	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
57	osmani nagar	50 bedded Upazila Health complex at Osmaninagar	5-Storied Consultant & Medical Officer's Dormitory with 5-storied pre cast pile Foundation	1	2023	5			Good	No file	No file	
58	osmani nagar	50 bedded Upazila Health complex at Osmaninagar	4-Storied 1000 sft Quarter with 5-storied pre cast pile Foundation	1	2023	4	1000	4000	Good	No file	No file	
59	osmani nagar	50 bedded Upazila Health complex at Osmaninagar	4-Storied1250 sft Quarter with 5-storied pre cast pile Foundation	1	2023	4	1250	5000	Good	No file	No file	
60	osmani nagar	50 bedded Upazila Health complex at Osmaninagar	1-Storied 1500 sft Quarter 5-storied pre cast pile Foundation	1	2023	1	1500	1500	Good	No file	No file	
61	zakiganj	upazila health complex	Public toilet		2023	1	477.75		moderate	1 pdf	1 jpeg	
62	zakiganj	upazila health complex	Mosque		2000	1	678.29		below standard	1 pdf	1 jpeg	
63	zakiganj	upazila health complex	Interni hostel		2000	1	2568.4		below standard	1 pdf	1 jpeg	
64	zakiganj	upazila health complex	Dr. Dormitory		2018	3	1977.18		moderate	1 pdf	1 jpeg	
65	zakiganj	upazila health complex	Garage-02		1982	1	604.7		below standard	1 pdf	1 jpeg	
66	zakiganj	upazila health complex	Garage-01		2008	1	678.29		below standard	1 pdf	1 jpeg	
67	zakiganj	upazila health complex	Waste menagement		1982	1	400		below standard	1 pdf	1 jpeg	
68	zakiganj	upazila health complex	Sub-Station & Genaretor		1982	1	250.25		below standard	1 pdf	1 jpeg	
69	zakiganj	upazila health complex	Staff Quarter (4th. Class)		1982	2	1320.1		below standard	1 pdf	1 jpeg	
70	zakiganj	upazila health complex	Staff Quarter (3rd. Class)		1982	4	1340.14		below standard	1 pdf	1 jpeg	
71	zakiganj	upazila health complex	Nurse Dormitory		1982	1	1263.64		below standard	1 pdf	1 jpeg	
72	zakiganj	upazila health complex	Dr. Quarter's (5-Unit)		1982	3	2731.89	6909.41	below standard	1 pdf	1 jpeg	
73	zakiganj	upazila health complex	Medicine Store		1982	1	929.47		below standard	1 pdf	1 jpeg	
74	zakiganj	upazila health complex	New hospital building		2018	3	8171.97		moderate	1 pdf	1 jpeg	
75	zakiganj	upazila health complex	Family planning		1982	1	2588.01		below standard	1 pdf	1 jpeg	
76	zakiganj	upazila health complex	Old hospital building		1982	2	4040.73		below standard	1 pdf	1 jpeg	

District Name: Tangail

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	basail	বাসাইল উপজেলা স্বাস্থ্য কমপ্লেক্স	No file	
2	bhuapur	ভূঞাপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	1 xlsx	
3	delduar	দেলদুয়ার উপজেলা স্বাস্থ্য কমপ্লেক্স	No file	ok
4	delduar	দেলদুয়ার উপজেলা স্বাস্থ্য কমপ্লেক্স	No file	ok
5	gopalpur	গোপালপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	1 xlsx	
6	nagarpur	নাগরপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	No file	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	basail	বাসাইল উপজেলা স্বাস্থ্য কমপ্লেক্স	1977	HED	NA	31	1 pdf	No file	2 pdfs	No file	12816	GF=12816, FF=2044	No file	No file	1 jpg		Court has a stay order on under construction building (extended hospital, residential building)
2	bhuapur	ভূঞাপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	1985	HED		50	1 pdf	No file	2 jpegs	No file	6448	GF=6448, FF=6448	No file	No file	2 jpegs		
3	bhuapur	ভূঞাপুর উপজেলা স্বাস্থ্য কমপ্লেক্স(OPD building)	2005	HED		0	1 pdf	No file	2 jpegs	No file	6800	GF=6800, FF=6500, 2nd floor=6500	No file	No file	1 jpg		
4	delduar	দেলদুয়ার উপজেলা স্বাস্থ্য কমপ্লেক্স	2017	HED		19	1 dwg, 1 pdf	No file	3 pdfs	No file	7466.45	GF-7466.45, 1ST F-7466.45, 2ND F-7466.45,3RD F-7466.45	No file	No file	1 jpg		
5	delduar	দেলদুয়ার উপজেলা স্বাস্থ্য কমপ্লেক্স	1984	HED	YES	31	1 dwg, 1 pdf	No file	2 pdfs	No file	10959.21	GF-7466.45, 1ST F-7466.45, 2ND F-7466.45	No file	No file	2 jpegs		
6	dhanbari	ধনবাড়ী উপজেলা স্বাস্থ্য কমপ্লেক্স	2015	HED		50	1 dwg	No file	1 jpg	No file	10768.86	G.F=10768.86,F.F=10768.86	No file	No file	1 jpg		
7	ghatail	ঘাটাইল উপজেলা স্বাস্থ্য কমপ্লেক্স	2005	HED		19	1 dwg	No file	2 jpegs	No file	6800	GF=6800, FF=6500, 2nd floor=6500	No file	No file	2 jpegs		
8	ghatail	ঘাটাইল উপজেলা স্বাস্থ্য কমপ্লেক্স	1965	HED		31	1 dwg	No file	No file	No file	5485	GF=5485, FF=5485	No file	No file	1 jpg		
9	gopalpur	গোপালপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	2010	HED		19	1 pdf	No file	1 jpeg	No file	6800	GF=6800, FF=6500	No file	No file	1 jpeg		
10	gopalpur	গোপালপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	1976	HED		31	1 pdf	No file	No file	No file	6448	GF=6448, FF=6448	No file	No file	1 jpeg		
11	kalihati	কালীহাতি উপজেলা স্বাস্থ্য কমপ্লেক্স	2014	HED	YES	19	1 dwg, 1 pdf	No file	4 pdfs	No file	8290	GF-8290, 1ST F-8290, 2ND F-8290,3RD F-2030	No file	No file	1 jpg		
12	kalihati	কালীহাতি উপজেলা স্বাস্থ্য কমপ্লেক্স	1973	HED	YES	31	1 dwg, 1 pdf	No file	1 pdf	No file	10760	G.F=10760,F.F=10760	No file	No file	1 jpg		

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
13	madhupur	মধুপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	1974	HED	YES	50	1 dwg	No file	2 pdfs	No file	33066	GF-33066, 1ST F-33066	No file	No file	2 jpgs		
14	madhupur	মধুপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	2019	HED		50	1 dwg	No file	4 pdfs	No file	11564	GF-11564.057, 1ST F-10991.117, 2ND F-10991.117,3RD F-10991.117	No file	No file	1 mp4		
15	mirzapur	মির্জাপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	1996	HED	no	31	1 dwg, 1 pdf	No file	1 pdf	1 pdf	14888.73	GF-14888.73 and 1st Floor 10400.00	No file	No file	1 jpg		
16	nagarpur	নাগরপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	2014	HED	YES	19	1 dwg, 1 pdf	No file	1 jpg	No file	8300	G.F= 8300,F.F=8300	No file	No file	No file		
17	nagarpur	নাগরপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	1972	HED		19	1 dwg, 1 pdf	No file	1 jpeg, 1 jpg	No file	6800	G.F= 6800,F.F=6800	No file	No file	1 jpeg		
18	sakhipur	সখিপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	1977	HED		31	1 pdf	No file	2 pdfs	No file	7945	GF=7945, FF= 8191	No file	No file	1 jpg		
19	sakhipur	সখিপুর উপজেলা স্বাস্থ্য কমপ্লেক্স(বহির্বিভাগ)	2004	HED		19	1 pdf	No file	2 jpegs	No file	6800	GF=6800, FF=6500, 2nd floor=6500	No file	No file	1 jpg		

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	basail	বাসাইল উপজেলা স্বাস্থ্য কমপ্লেক্স	21	0.83	2	Footing	2	Load Bearing Brick	বিভিন্ন অংশে স্লাব থেকে কনক্রিট ভেঙে মরিচাধরা রড বের হয়েছে, কলাম বিম এ ফাটল ছিল, রিপেয়ার করা হয়েছে।	No file	Not Possible		
2	bhuapur	ভূঞাপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	21	1.83	2	Footing	3	Load Bearing Brick	1. Old building condition is poor,	No file	Not Possible		
3	bhuapur	ভূঞাপুর উপজেলা স্বাস্থ্য কমপ্লেক্স(OPD building)	31.5	2.5	3	Footing	3	RCC	Good enough	No file	Not Possible		
4	delduar	দেলদুয়ার উপজেলা স্বাস্থ্য কমপ্লেক্স	30.5	2.5	3	Footing		RCC	good	No file	info not available		
5	delduar	দেলদুয়ার উপজেলা স্বাস্থ্য কমপ্লেক্স	21	1	2	Footing		RCC	poor enough	No file	Not Possible	unknown	
6	dhanbari	ধনবাড়ী উপজেলা স্বাস্থ্য কমপ্লেক্স	44	2.25	4	Footing		RCC		No file	Possible		
7	ghatail	ঘাটাইল উপজেলা স্বাস্থ্য কমপ্লেক্স	31.5	2	3	Footing	3	RCC	Good enough	No file	Not Possible		
8	ghatail	ঘাটাইল উপজেলা স্বাস্থ্য কমপ্লেক্স	20	0.16	2	Footing	3	Load Bearing Brick	1. Old building condition is poor	No file	Not Possible		
9	gopalpur	গোপালপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	22	2.5	2	Footing	3	RCC	Good enough	No file	Possible		
10	gopalpur	গোপালপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	22	1.5	2	Footing	2	Load Bearing Brick	building condition is poor	No file	Not Possible		

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
11	kalihati	কালীহাতি উপজেলা স্বাস্থ্য কমপ্লেক্স	44	2	4	Deep		RCC	Moderate	No file	Possible		
12	kalihati	কালীহাতি উপজেলা স্বাস্থ্য কমপ্লেক্স	22	0.5	2	Footing	2	Load Bearing Brick	poor	No file	Not Possible		
13	madhupur	মধুপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	22	0.5	2	Footing		Load Bearing Brick		No file	info not available		
14	madhupur	মধুপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	44	2.5	4	Deep	6	RCC	good	No file	Possible		
15	mirzapur	মির্জাপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	23	2	2	Footing	3	RCC	Moderate	No file	Not Possible	Unknown	
16	nagarpur	নাগরপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	21	1	2	Footing		RCC		No file	Not Possible		
17	nagarpur	নাগরপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	31.5	2.5	3	Footing		RCC	good	No file	info not available		
18	sakhipur	সখিপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	21	1.5	2	Footing	2	Load Bearing Brick	বিভিন্ন অংশে স্লাব থেকে কনক্রিট ভেঙে মরিচাধরা রুড বের হয়েছে, কলাম বিম এ ফাটল ছিল, রিপেয়ার করা হয়েছে।	No file	Not Possible		
19	sakhipur	সখিপুর উপজেলা স্বাস্থ্য কমপ্লেক্স(বহির্বিভাগ)	31.5	2.5	3	Footing	3	RCC	Structural condition os good enough	No file	Not Possible		

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	basail	বাসাইল উপজেলা স্বাস্থ্য কমপ্লেক্স	0	1	no	Septic Tank		No		No drainage system, exist natural drainage process	Master drain is requiref	One pond is exist outside of the campus	
2	bhuapur	ভূঞাপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	0	1	no	Septic Tank	1500	No		Surface drain exist	Master drain is requiref	One pond is exist outside of the campus	
3	delduar	দেলদুয়ার উপজেলা স্বাস্থ্য কমপ্লেক্স	0	1		Septic Tank	2800	No	0	Surface		ditch	
4	dhanbari	ধনবাড়ী উপজেলা স্বাস্থ্য কমপ্লেক্স	0	1	NO	Septic Tank	2100	No		Surface Drain		ditch	
5	ghatail	ঘাটাইল উপজেলা স্বাস্থ্য কমপ্লেক্স	0	1	no	Septic Tank	1700	No		Surface drain exist	Master drain is requiref	One pond is exist outside of the campus	
6	gopalpur	গোপালপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	0	1		Septic Tank	5540	No		Surface drain and master drain exist		one pond is exist outside of the campus	
7	kalihati	কালীহাতি উপজেলা স্বাস্থ্য কমপ্লেক্স	0	1	NO	Septic Tank	1500	No		Surface Drain	NEEDED	ditch	
8	madhupur	মধুপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	0	1	NO	Septic Tank	2450	No		Surface Drain	NEEDED	ditch	
9	mirzapur	মির্জাপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	1050	1		Septic Tank	4862	No		Surface Drain and Master Drain Existing		One Pond is Existing Outside Of the Campus	
10	nagarpur	নাগরপুর উপজেলা স্বাস্থ্য কমপ্লেক্স		1	no	Septic Tank	3000	No	0	Surface Drain		ditch	

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
11	sakhipur	সখিপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	0	1		Septic Tank	3696	No		Surface drain exist	Master drain is required	One pond is exist outside of the campus	

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	basail	বাসাইল উপজেলা স্বাস্থ্য কমপ্লেক্স	0	0	860	2100	16.5	কিছু আরসিসি রাস্তা, কিছু বিটুমিনাস রাস্তা	Yes	Yes	
2	bhuapur	ভূঞাপুর উপজেলা স্বাস্থ্য কমপ্লেক্স				0	24.5	RCC road, poor condition	Yes	Yes	
3	delduar	দেলদুয়ার উপজেলা স্বাস্থ্য কমপ্লেক্স	0	1800		1200	18	Road condition is poor	Yes	No	
4	dhanbari	ধনবাড়ী উপজেলা স্বাস্থ্য কমপ্লেক্স					40	RCC road, good condition	Yes	No	
5	ghatail	ঘাটাইল উপজেলা স্বাস্থ্য কমপ্লেক্স					38	RCC road, poor condition	Yes	Yes	
6	gopalpur	গোপালপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	350			1800	16	Road condition is poor	Yes	No	
7	kalihati	কালীহাতি উপজেলা স্বাস্থ্য কমপ্লেক্স		2280	1400		12	bituminous road, Moderate condition	Yes	Yes	
8	madhupur	মধুপুর উপজেলা স্বাস্থ্য কমপ্লেক্স		1973	1400		30	RCC road, poor condition	Yes		
9	mirzapur	মির্জাপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	274	586	352		18	Road Condition is Poor	Yes	No	
10	nagarpur	নাগরপুর উপজেলা স্বাস্থ্য কমপ্লেক্স		2114.6			20	CC road, poor condition	Yes	No	
11	sakhipur	সখিপুর উপজেলা স্বাস্থ্য কমপ্লেক্স		2100			25	বিটুমিনাস রাস্তা	No	Yes	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	basail	বাসাইল উপজেলা স্বাস্থ্য কমপ্লেক্স	class IV QT		1977	2	1458	2916	সিলিং খসে পড়েছে, ভবন স্যাতস্যাতে, বিম কলামে ফাটল রয়েছে	No file	No file	
2	basail	বাসাইল উপজেলা স্বাস্থ্য কমপ্লেক্স	Nurse quarter		1977	1	2046	2046	Dilapidated	No file	No file	
3	basail	বাসাইল উপজেলা স্বাস্থ্য কমপ্লেক্স	Doctors quarter		1977	2	3762	7524	সিলিং খসে পড়েছে, ভবন স্যাতস্যাতে, বিম কলামে ফাটল রয়েছে	No file	No file	
4	basail	বাসাইল উপজেলা স্বাস্থ্য কমপ্লেক্স	৩য় শ্রেণি কোয়ার্টার		1977	2	3035	6070	সিলিং খসে পড়েছে, ভবন স্যাতস্যাতে, বিম কলামে ফাটল	No file	2 jpgs	
5	bhuapur	ভূঞাপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	600 sft standard class III QT		1985	2	600	1200	সিলিং খসে পড়েছে, ভবন স্যাতস্যাতে, বিম কলামে হালকা ফাটল	1 jpg	No file	
6	bhuapur	ভূঞাপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	800 sft standard class II		1985	2	800	1600	সিলিং খসে পড়েছে, ভবন স্যাতস্যাতে, বিম কলামে হালকা ফাটল	1 jpg	No file	
7	bhuapur	ভূঞাপুর উপজেলা স্বাস্থ্য কমপ্লেক্স	1000sft Officers QT		1985	2	1000	2000	সিলিং খসে পড়েছে, ভবন স্যাতস্যাতে, বিম কলামে ফাটল	1 jpg	No file	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
8	gopalpur	গোপালপুর উপজেলা সাহ্য কমপ্লেক্স	Class III quarter 2		1976	2	1370	2740	Dilapidated	No file	1 jpeg	
9	gopalpur	গোপালপুর উপজেলা সাহ্য কমপ্লেক্স	Class III quarter 1		1976	2	1370	2740	সিলিং খসে পড়েছে, ভবন স্যাতস্যাতে, বিম কলামে ফাটল	No file	1 jpeg	
10	gopalpur	গোপালপুর উপজেলা সাহ্য কমপ্লেক্স	Nurse Dormitory		1976	1	2031	2031	সিলিং খসে পড়েছে, ভবন স্যাতস্যাতে, বিম কলামে ফাটল	No file	No file	
11	gopalpur	গোপালপুর উপজেলা সাহ্য কমপ্লেক্স	Class IV quarter 1		1976	2	1370	2740	Dilapidated	No file	1 jpeg	
12	gopalpur	গোপালপুর উপজেলা সাহ্য কমপ্লেক্স	Class IV quarter		1976	2	1520	3040	সিলিং খসে পড়েছে, ভবন স্যাতস্যাতে, বিম কলামে ফাটল	No file	No file	
13	gopalpur	গোপালপুর উপজেলা সাহ্য কমপ্লেক্স	Class III quarter		2010	2	1890	3780	Building condition is good enough	No file	1 jpeg	
14	gopalpur	গোপালপুর উপজেলা সাহ্য কমপ্লেক্স	Doctors quarter 1		2010	2	2400	4800	সিলিং খসে পড়েছে, ভবন স্যাতস্যাতে, বিম কলামে ফাটল	No file	1 jpeg	
15	gopalpur	গোপালপুর উপজেলা সাহ্য কমপ্লেক্স	Doctors quarter		1976	2	2550	5100	সিলিং খসে পড়েছে, ভবন স্যাতস্যাতে, বিম কলামে ফাটল	No file	No file	
16	sakhipur	সখিপুর উপজেলা সাহ্য কমপ্লেক্স	৪র্থ শ্রেণি কোয়ার্টার		1977	2	1280	2560	Dilapidated	No file	No file	
17	sakhipur	সখিপুর উপজেলা সাহ্য কমপ্লেক্স	নার্স কোয়ার্টার		1977	2	1589	3160	সিলিং খসে পড়েছে, ভবন স্যাতস্যাতে, বিম কলামে ফাটল	No file	No file	
18	sakhipur	সখিপুর উপজেলা সাহ্য কমপ্লেক্স	৩য় শ্রেণি কোয়ার্টার		1977	1	2070	2070	সিলিং খসে পড়েছে, ভবন স্যাতস্যাতে, বিম কলামে ফাটল রয়েছে	No file	No file	
19	sakhipur	সখিপুর উপজেলা সাহ্য কমপ্লেক্স	Officers QT		1977	2	2688	5337	সিলিং খসে পড়েছে, ভবন স্যাতস্যাতে, বিম কলামে ফাটল রয়েছে	No file	No file	

District Name: Thakurgaon

Medical Service Related Information

SL No	Upazilla	Name of the Hospital	Filled up Form	Remarks
1	baliadangi	upazilla health complex , Baliadangi.	No file	
2	haripur	Haripur Upazilla Health Complex	No file	
3	ranisankail	Ranisankail Upazilla Health Complex	No file	

General Information

SL No	Upazilla	Name of the Hospital	Year of Establishment	Construction agency	Availability of Additional Land	Number of Beds of Existing Hospital Building	Digital Survey Map (CAD and PDF)	Soil Test Report (click i button for detail)	As Built Arc Drawing of Existing Hospital Building (Floor Plans)	Layout of Hospital (At least Hand Drawn)	Plinth Area of Existing Hospital Bldg (sqft)	Floor Area (sft by each floor)	Master Plan of Campus (Demarking Visually Vulnerable Buildings)	Attach Land Records (if any)	Visual Evidence of the area (Image or video)	Flood Level Information	Remarks (Additional Information)
1	baliadangi	Baliadangi Upazilla Health Complex	1978	HED	Available	50	2 dwgs, 2 pdfs	No file	No file	No file	15988	Ground Floor=15988sft, 1st Floor= 15988sft	No file	No file	1 jpeg	NA	
2	haripur	Haripur Upazilla Health Complex	1985	HED	Available	50	1 dwg	No file	No file	No file	20592	GF=20592, FF=20592	No file	No file	1 jpeg	NA	
3	ranisankail	Ranisankail Upazilla Health Complex	1984	HED	Available	50	2 dwgs, 1 pdf	No file	No file	No file	19461	GF=19461, FF=14018, 2nd Floor= 4639	No file	No file	1 jpeg	NA	

Civil Related

SL No	Upazilla	Name of the Hospital	Building Height (PL to Top in ft)	PL Height (EGL to PL in ft)	Existing Floor Number	Foundation Type	Foundation Capacity (floor number)	Structure Type	Structural Condition of Main Hospital Bldg (Describe)	Structural Assessment Report	Vertical Extension (possible or not-possible)	Previous Renovation History	Remarks (Additional Information)
1	baliadangi	Baliadangi Upazilla Health Complex	21	0.83	2	Footing		RCC		No file	info not available	NA	
2	baliadangi	Baliadangi Upazilla Health Complex	21	0.83	2	Footing		Load Bearing Brick		No file	info not available	NA	
3	haripur	Haripur Upazilla Health Complex	20	2	2	Footing		RCC	Good	No file	info not available	NA	
4	ranisankail	Ranisankail Upazilla Health Complex	33	1	3	Footing		RCC		No file	info not available	NA	
5	ranisankail	Ranisankail Upazilla Health Complex	22	0.5	2	Footing		RCC		No file	info not available	NA	

Water Supply and Sanitation

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
1	baliadangi	Baliadangi Upazilla Health Complex		1	NA	Septic Tank		No					
2	haripur	Haripur Upazilla Health Complex	0	1		Septic Tank		No		Yes			
3	ranisankail	Ranisankail Upazilla Health		1		Septic Tank		No					

SL No	Upazilla	Name of the Hospital	Capacity of Existing UGWR (gal)	Number of Deep Tubewell	Additional Water Supply Facility (Describe)	Sewage or Waste Management Facility	Capacity of Sewerage or waste management (cft)	Presence of Rainwater Harvesting Facility	Capacity of Rain Water Harvesting (gal)	Existing Drainage Facility (Describe)	Required Drainage Facility (Describe)	Nearest Waste & Water Disposal Location (Describe)	Remarks (Any other issues will be Described here)
		Complex											

Ancillary Civil Items

SL No	Upazilla	Name of the Hospital	Existing boundary wall with retaining wall (ft)	Existing boundary wall without retaining wall (ft)	Additionally Required boundary wall with retaining wall (ft)	Additionally Required boundary wall without retaining wall (ft)	Width of The Main Road (Municipality or City Corp) In front of Hospital (ft)	Internal Road Scenario (Describe)	Existence of Link Corridor	Requirement of Site Improvement	Remarks (additional information)
1	baliadangi	Baliadangi Upazilla Health Complex		2081			18.83	RCC Road	Yes	No	
2	haripur	Haripur Upazilla Health Complex		2284.99			23	RCC	Yes	No	
3	ranisankail	Ranisankail Upazilla Health Complex		1938			18.5	RCC Road	Yes	No	

Electromechanical Items

SL No	Upazilla	Name of the Hospital	Present Number of Lift	Number of Usable Lift (if present)	Lift Related Additional Info (If any)	Present AC Capacity (Ton)	Additional AC Requirement (Ton)	AC Related Additional Info (If any)	Present Situation of Fire Detection and Protection System	Present Total HP of Submersible Pump	Present Total HP of Centrifugal Pump	Pump Related Additional Info (Demand, Repair need etc)	Medical Waste Management System	Medical Waste Related Additional Info (Capacity, Demand etc)
1	baliadangi	Baliadangi Upazilla Health Complex								4			Not Present	

Other Buildings

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
1	baliadangi	Baliadangi Upazilla Health Complex	3rd-class staff quarters (New)	1	2006	3	1438	4314		No file	1 jpeg	
2	baliadangi	Baliadangi Upazilla Health Complex	2nd-class staff quarters	1	2006	2	1804	3608		No file	1 jpeg	
3	baliadangi	Baliadangi Upazilla Health Complex	Nurses Quarter	1	1979	1	1376	1376		No file	1 jpeg	
4	baliadangi	Baliadangi Upazilla Health Complex	3rd-class staff quarters (Old)	1	1979	2	1372	2744		No file	1 jpeg	
5	baliadangi	Baliadangi Upazilla Health Complex	Nurses dormitory	1	1979	1	1235	1235		No file	1 jpeg	
6	baliadangi	Baliadangi Upazilla Health Complex	Old Doctor quarters	1	1978	3	2786	7121		No file	1 jpeg	
7	baliadangi	Baliadangi Upazilla Health Complex	New Doctor quarters	1	2011	2	2281	4562		No file	1 jpeg	
8	baliadangi	Baliadangi Upazilla Health Complex	4th-class staff quarters		1978	2	1099	2198		No file	1 jpeg	
9	haripur	Haripur Upazilla Health Complex	Garage	1	1990	1	422	421.99	bad	No file	1 jpeg	
10	haripur	Haripur Upazilla Health Complex	nurse dormitory	1	1990	1	533	533	bad	No file	1 jpeg	
11	haripur	Haripur Upazilla Health Complex	doctor dormitory	1	1990	2	1924	3848	good	No file	1 jpeg	

SL No	Upazilla	Name of the Hospital	Building Name	Building No (if any)	Year of Construction	Number of Floors	Plinth Area (sqft)	Total Floor Area (sqft)	Current Condition (Describe)	Floor Plan (if any)	Visual Evidence (Image and Video)	Remarks (Additional Information)
12	haripur	Haripur Upazilla Health Complex	1st class doctor quarter	1	1990	3	2475	7424.99	good	No file	1 jpeg	
13	haripur	Haripur Upazilla Health Complex	4th class quarter	1	2000	4	1303	5211.99	good	No file	1 jpeg	
14	haripur	Haripur Upazilla Health Complex	3rd class quarter	1	2006	2	1947	3894	good	No file	1 jpeg	
15	haripur	Haripur Upazilla Health Complex	3rd class quarter	1	1990	2	1022	2044	good	No file	1 jpeg	
16	haripur	Haripur Upazilla Health Complex	3rd class quarter	1	1990	2	1022	2044	good	No file	1 jpeg	
17	haripur	Haripur Upazilla Health Complex	nurses quater	1	2006	3	2538	5076	good	No file	1 jpeg	
18	ranisankail	Ranisankail Upazilla Health Complex	3rd-class staff quarters 2	1	1984	2	1445	2890		No file	1 jpeg	
19	ranisankail	Ranisankail Upazilla Health Complex	3rd-class staff quarters 1	1	1984	2	1457	2914		No file	1 jpeg	
20	ranisankail	Ranisankail Upazilla Health Complex	Doctor quarters 3	1	1984	2	950	1900		No file	1 jpeg	
21	ranisankail	Ranisankail Upazilla Health Complex	Doctor quarters 2	1	1984	2	946	1892		No file	1 jpeg	
22	ranisankail	Ranisankail Upazilla Health Complex	Doctor quarters 1	1	2006	2	2543	5086		No file	1 jpeg	