

## Office: Division - Bagerhat PWD Division

### Medical Service Related Information

| SL No | District Name | Name of the Hospital                          | Upazilla   | Filled up Form | Remarks |
|-------|---------------|-----------------------------------------------|------------|----------------|---------|
| 1     | Bagerhat      | 50 Bed Fakirhat Upazila Health Complex        | fakirhat   | 1 xlsx         |         |
| 2     | Bagerhat      | 50 Bed Mollahat Upazila Health Complex        | mollahat   | 1 xlsx         |         |
| 3     | Bagerhat      | Chitalmari Upazilla Health Complex            | chitalmari | 1 xlsx         |         |
| 4     | Bagerhat      | kachua Upazilla Health Complex                | kachua     | 1 xlsx         |         |
| 5     | Bagerhat      | Mongla Upazila Health Complex, Bagerhat.      | mongla     | 1 xlsx         |         |
| 6     | Bagerhat      | Morelgonj Upazila Health Complex              | morelgonj  | No file        |         |
| 7     | Bagerhat      | Rampal Upazila Health Complex, Bagerhat.      | rampal     | No file        |         |
| 8     | Bagerhat      | Sharonkhola Upazila Health Complex, Bagerhat. | sarankhola | 1 xlsx         |         |

### General Information

| SL No | District Name | Name of the Hospital                   | Upazilla   | Year of Establishment | Construction agency | Availability of Additional Land        | Number of Beds of Existing Hospital Building | Digital Survey Map (CAD and PDF) | Soil Test Report (click i button for detail) | As Built Arc Drawing of Existing Hospital Building (Floor Plans) | Layout of Hospital (At least Hand Drawn) | Plinth Area of Existing Hospital Bldg (sqft) | Floor Area (sft by each floor) | Master Plan of Campus (Demarking Visually Vulnerable Buildings) | Attach Land Records (if any) | Visual Evidence of the area (Image or video) | Flood Level Information | Remarks (Additional Information ) |
|-------|---------------|----------------------------------------|------------|-----------------------|---------------------|----------------------------------------|----------------------------------------------|----------------------------------|----------------------------------------------|------------------------------------------------------------------|------------------------------------------|----------------------------------------------|--------------------------------|-----------------------------------------------------------------|------------------------------|----------------------------------------------|-------------------------|-----------------------------------|
| 1     | Bagerhat      | 50 Bed Fakirhat Upazila Health Complex | fakirhat   | 2012                  | HED                 | Available                              | 50                                           | 1 dwg                            | No file                                      | 1 pdf                                                            | 1 pdf                                    | 8601                                         | 8601, 8256,6390                | 1 dwg                                                           | No file                      | 3 jpegs                                      | H.F=G.L+1               | Land Area:7.23 acre               |
| 2     | Bagerhat      | 50 Bed Mollahat Upazila Health Complex | mollahat   | 2012                  | HED                 | Available                              | 50                                           | 1 dwg                            | No file                                      | 1 pdf                                                            | 1 pdf                                    | 8601                                         | 8601, 8256,6390                | 1 dwg                                                           | No file                      | 3 jpegs                                      | H.F=G.L+2               | Land Area: 4.05 acre              |
| 3     | Bagerhat      | Chitalmari Upazilla Health Complex     | chitalmari | 2012                  | HED                 | 21630 sft area ( if pond is filled up) | 31                                           | 1 dwg                            | No file                                      | 1 pdf                                                            | 1 pdf                                    | 8601                                         | 8601.8256, 4110                | 1 dwg                                                           | No file                      | 4 jpegs                                      | H.F+1'                  |                                   |
| 4     | Bagerhat      | kachua Upazilla Health Complex         | kachua     | 2005                  | HED                 | Available                              | 19                                           | 1 dwg                            | No file                                      | 1 pdf                                                            | 1 pdf                                    | 8601                                         | 8601, 8256                     | 1 dwg                                                           | No file                      | 1 jpeg                                       | 3' above                |                                   |



| SL No | District Name | Name of the Hospital                   | Upazilla   | Building Height (PL to Top in ft) | PL Height (EGL to PL in ft) | Existing Floor Number | Foundation Type | Foundation Capacity (floor number) | Structure Type | Structural Condition of Main Hospital Bldg (Describe)                                                                                                              | Structural Assessment Report | Vertical Extension (possible or not-possible) | Previous Renovation History                                                                        | Remarks (Additional Information)                                                                                                     |
|-------|---------------|----------------------------------------|------------|-----------------------------------|-----------------------------|-----------------------|-----------------|------------------------------------|----------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|-----------------------------------------------|----------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|
| 2     | Bagerhat      | 50 Bed Mollahat Upazila Health Complex | mollahat   | 30                                | 2.5                         | 3                     | Deep            | 4                                  | RCC            | Coloum Size =21"836" ,21"*18",21*13" Span =18'                                                                                                                     | No file                      | Not Possible                                  |                                                                                                    | *সেতু ভেঙে গেছে। সেতুটি পুনরুদ্ধার করা হয়েছে।<br>submersible *সেতুটি ভেঙে গেছে।<br>*সেতুটি ভেঙে গেছে। সেতুটি পুনরুদ্ধার করা হয়েছে। |
| 3     | Bagerhat      | Chitalmari Upazilla Health Complex     | chitalmari | 30                                | 1.5                         | 3                     | Footing         | 3                                  | RCC            | Structural condition of main hospital building is at a moderate level. Structural defects have become visible in some areas of the building's column, beam & slab. | No file                      | Not Possible                                  | Regular civil ( plaster, paint sanitary work) & electrical maintenance works have been undertaken. |                                                                                                                                      |

| SL No | District Name | Name of the Hospital           | Upazilla | Building Height (PL to Top in ft) | PL Height (EGL to PL in ft) | Existing Floor Number | Foundation Type | Foundation Capacity (floor number) | Structure Type | Structural Condition of Main Hospital Bldg (Describe) | Structural Assessment Report | Vertical Extension (possible or not-possible) | Previous Renovation History | Remarks (Additional Information)                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
|-------|---------------|--------------------------------|----------|-----------------------------------|-----------------------------|-----------------------|-----------------|------------------------------------|----------------|-------------------------------------------------------|------------------------------|-----------------------------------------------|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 4     | Bagerhat      | kachua Upazilla Health Complex | kachua   | 22                                | 1.66                        | 2                     | Footing         | 3                                  | RCC            |                                                       | No file                      | Not Possible                                  |                             | In 1980, the facility had a total of 31 beds. Over time, due to natural causes, this number gradually decreased. Several beds became unusable because of deterioration, and some were rendered non-functional. As a result, the facility could no longer maintain the original capacity of 31 beds. In 2005, an additional 19 beds were added. These newly added beds were also incorporated into the national database. Among the 50 beds listed in the national database, 19 were newly added, while the remaining 31 had gradually become unusable over the years due to natural causes. Among the 19 newly added beds, 3 were designated for female patients. These 3 beds were included in the national database in alignment with the government's initiative to ensure dedicated facilities for women. Necessary government support and facilities were also allocated for these beds. |

| SL No | District Name | Name of the Hospital                          | Upazilla   | Building Height (PL to Top in ft) | PL Height (EGL to PL in ft) | Existing Floor Number | Foundation Type | Foundation Capacity (floor number) | Structure Type | Structural Condition of Main Hospital Bldg (Describe) | Structural Assessment Report | Vertical Extension (possible or not-possible) | Previous Renovation History | Remarks (Additional Information)          |
|-------|---------------|-----------------------------------------------|------------|-----------------------------------|-----------------------------|-----------------------|-----------------|------------------------------------|----------------|-------------------------------------------------------|------------------------------|-----------------------------------------------|-----------------------------|-------------------------------------------|
| 5     | Bagerhat      | Mongla Upazila Health Complex, Bagerhat.      | mongla     | 42                                | 2.5                         | 3                     | Footing         | 3                                  | RCC            | Good/New                                              | No file                      | Not Possible                                  | NA                          | ১১ টি টাক্সি ইন্টারলক্কিং সিস্টেম রয়েছে। |
| 6     | Bagerhat      | Morelgonj Upazila Health Complex              | morrelganj | 42                                | 2.5                         | 3                     | Footing         | 3                                  | RCC            | Good                                                  | No file                      | Not Possible                                  | NA                          |                                           |
| 7     | Bagerhat      | Rampal Upazila Health Complex, Bagerhat.      | rampal     | 42                                | 2.5                         | 3                     | Footing         | 6                                  | RCC            | Good                                                  | No file                      | Possible                                      | NA                          | 31 টি টাক্সি ইন্টারলক্কিং সিস্টেম রয়েছে। |
| 8     | Bagerhat      | Sharonkhola Upazila Health Complex, Bagerhat. | sarankhola | 42                                | 3                           | 3                     | Footing         | 3                                  | RCC            | Good/New                                              | No file                      | Not Possible                                  | NA                          | ১১ টি টাক্সি ইন্টারলক্কিং সিস্টেম রয়েছে। |

### Water Supply and Sanitation

| SL No | District Name | Name of the Hospital                   | Upazilla   | Capacity of Existing UGWR (gal) | Number of Deep Tubewell | Additional Water Supply Facility (Describe)                                                          | Sewage or Waste Management Facility | Capacity of Sewerage or waste management (cft) | Presence of Rainwater Harvesting Facility | Capacity of Rain Water Harvesting (gal) | Existing Drainage Facility (Describe)                                                                                                                                    | Required Drainage Facility (Describe)                                                 | Nearest Waste & Water Disposal Location (Describe)                    | Remarks (Any other issues will be Described here)                       |
|-------|---------------|----------------------------------------|------------|---------------------------------|-------------------------|------------------------------------------------------------------------------------------------------|-------------------------------------|------------------------------------------------|-------------------------------------------|-----------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|-----------------------------------------------------------------------|-------------------------------------------------------------------------|
| 1     | Bagerhat      | 50 Bed Fakirhat Upazila Health Complex | fakirhat   | 0                               | 1                       |                                                                                                      | Septic Tank                         |                                                | No                                        | 0                                       | around only main building                                                                                                                                                | Required forTotal project area                                                        |                                                                       | 1. Water supply system improvement<br><br>2.Waste management facilities |
| 2     | Bagerhat      | 50 Bed Mollahat Upazila Health Complex | mollahat   | 0                               | 1                       |                                                                                                      | Septic Tank                         | 0                                              | No                                        | 0                                       | around only main building                                                                                                                                                | Required forTotal project area                                                        |                                                                       |                                                                         |
| 3     | Bagerhat      | Chitalmari Upazilla Health Complex     | chitalmari | 30000                           | 1                       | pond                                                                                                 | Septic Tank                         |                                                | No                                        |                                         | Apron is provided around the building and surface drain is available along the boundary. This appear to be adequate for proper drainage of rainwater and surface runoff. |                                                                                       | At a abandoned area situated approximately 40 feet from the building. |                                                                         |
| 4     | Bagerhat      | kachua Upazilla Health Complex         | kachua     | 0                               | 0                       | Water is taken from the campus pond, purified through a filter system, and then used in the hospital | Septic Tank                         | 10000                                          | No                                        | 0                                       | The surface drain is dilapidated and does not provide proper drainage. Due to the inability to drain rainwater, waterlogging occurs                                      | The construction of both the surface drain and the master drain is urgently required. |                                                                       |                                                                         |



| SL No | District Name | Name of the Hospital                          | Upazilla   | Existing boundary wall with retaining wall (ft) | Existing boundary wall without retaining wall (ft) | Additionally Required boundary wall with retaining wall (ft) | Additionally Required boundary wall without retaining wall (ft) | Width of The Main Road (Municipality or City Corp) In front of Hospital (ft) | Internal Road Scenario (Describe) | Existence of Link Corridor | Requirement of Site Improvement | Remarks (additional information) |
|-------|---------------|-----------------------------------------------|------------|-------------------------------------------------|----------------------------------------------------|--------------------------------------------------------------|-----------------------------------------------------------------|------------------------------------------------------------------------------|-----------------------------------|----------------------------|---------------------------------|----------------------------------|
| 8     | Bagerhat      | Sharonkhola Upazila Health Complex, Bagerhat. | sarankhola | 1850                                            | 0                                                  | 315                                                          | 1535                                                            | 12                                                                           | poor                              | Yes                        | Yes                             |                                  |

### Electromechanical Items

| SL No | District Name | Name of the Hospital                          | Upazilla   | Present Number of Lift | Number of Usable Lift (if present) | Lift Related Additional Info (If any) | Present AC Capacity (Ton) | Additional AC Requirement (Ton) | AC Related Additional Info (If any) | Present Situation of Fire Detection and Protection System  | Present Total HP of Submersible Pump | Present Total HP of Centrifugal Pump | Pump Related Additional Info (Demand, Repair need etc)                   | Medical Waste Management System | Medical Waste Related Additional info (Capacity, Demand etc) |
|-------|---------------|-----------------------------------------------|------------|------------------------|------------------------------------|---------------------------------------|---------------------------|---------------------------------|-------------------------------------|------------------------------------------------------------|--------------------------------------|--------------------------------------|--------------------------------------------------------------------------|---------------------------------|--------------------------------------------------------------|
| 1     | Bagerhat      | Chitalmari Upazila Health complex             | chitalmari | 0                      | 0                                  | 0                                     | 10                        | 20                              |                                     | no                                                         | 0                                    | 1                                    | 1 nos 10 hp and 2 nos 2 hp Centifugal pum motor required                 | Not Present                     | no                                                           |
| 2     | Bagerhat      | Kachua Upazila Health complex                 | kachua     | 0                      | 0                                  |                                       | 8                         | 20                              |                                     | no                                                         | 0                                    | 4                                    | 2 nos 10 hp and 2 nos 1 hp Centifugal pum motor required                 | Not Present                     |                                                              |
| 3     | Bagerhat      | Mongla Upazila Health Complex, Bagerhat.      | mongla     | 0                      | 0                                  |                                       | 30                        | 100                             | Repair & Maintenance Needed         | 15 Nos Fire Extinguisher is Available & 40 Nos is Required | 0                                    | 2                                    | 2 HP Centrifugal Or JET Pump - 2 Nos is Required                         | Incinerator Type                | 1 No Incineration Type Needed                                |
| 4     | Bagerhat      | Morelgonj Upazila Health Complex              | morrelganj | 0                      | 0                                  |                                       | 9.5                       | 20                              |                                     | no                                                         |                                      | 7.5                                  | 1 nos 10 hp and 2 nos 2 hp Centifugal pum motor required                 | Not Present                     |                                                              |
| 5     | Bagerhat      | Rampal Upazila Health Complex, Bagerhat.      | rampal     | 0                      | 0                                  | Lift Core Available                   | 30                        | 30                              | Repair & Maintenance Needed         | 0                                                          | 2                                    | 0                                    | Needed , 2 HP Submersible - 2 Nos, 2 HP Centrifugal Or JET Pump - 2 Nos. | Not Present                     | 1 No Incineration Type Needed                                |
| 6     | Bagerhat      | Sharonkhola Upazila Health Complex, Bagerhat. | sarankhola | 0                      | 0                                  |                                       |                           |                                 |                                     |                                                            |                                      |                                      |                                                                          |                                 |                                                              |

### External Electrification

| SL No | District Name | Name of the Hospital                          | Upazilla   | Connection Provider | Can Provider Provide Apprx 1250 kVA Load? | Existing Actual Usage of Power or Load (kVA) | Present Total KVA Capacity of Substation | Reusable KVA of substation | Situation of Substation Components (LT HT PFI MDB etc)    | Existing Total KVA Capacity of Generator | Additional Requirement of Generator (KVA) | Present Usable Capacity of on grid solar (kWp) | Present Capacity of Ring Main Unit (number of out going connection) | Detailed Description of Incoming Service Cable (RM, Type and Length of HT or LT) | Detailed Description of Service Cable (RM and Length for FDB, MDB, ELT, NLT etc) | Remarks (Provide any additional information here) |
|-------|---------------|-----------------------------------------------|------------|---------------------|-------------------------------------------|----------------------------------------------|------------------------------------------|----------------------------|-----------------------------------------------------------|------------------------------------------|-------------------------------------------|------------------------------------------------|---------------------------------------------------------------------|----------------------------------------------------------------------------------|----------------------------------------------------------------------------------|---------------------------------------------------|
| 1     | Bagerhat      | Chitalmari Upazila Health complex             | chitalmari | REB                 | Yes                                       |                                              | 0                                        |                            | no                                                        | 10                                       | 50                                        |                                                |                                                                     | 15rm wap ,20 meter,                                                              | Dilapidated                                                                      | Dilapidated and almos wasted                      |
| 2     | Bagerhat      | Kachua Upazila Health complex                 | kachua     | REB                 | Yes                                       | 0                                            |                                          |                            | no                                                        | 10                                       | 50                                        |                                                |                                                                     | 25rm wap ,15 meter,                                                              | Dilapidated                                                                      | Dilapidated and almos wasted                      |
| 3     | Bagerhat      | Mongla Upazila Health Complex, Bagerhat.      | mongla     | WZPDCL              | Yes                                       | 70                                           | 150                                      | 300                        | Not in Good Situation, Maintenance and Service is Needed. | 10                                       | 15                                        | 2                                              | 0                                                                   | HT Cable - 3C X 50 Sqmm, LT Cable - 4 X 25 sqmm, 25 meter(Approximate)           | Concealed Wiring                                                                 | Dilapidated and almost wasted                     |
| 4     | Bagerhat      | Morelganj Upazila Health Complex              | morrelganj | REB                 | Yes                                       |                                              | 0                                        | 0                          | no                                                        | 10                                       | 50                                        |                                                | 0                                                                   | 20rm wap ,12 meter,                                                              | Dilapidated                                                                      | Dilapidated and almos wasted                      |
| 5     | Bagerhat      | Rampal Upazila Health Complex, Bagerhat.      | rampal     | REB                 | Yes                                       | 70                                           | 150                                      | 300                        | Good                                                      | 5.5                                      | 20                                        | 0                                              | 0                                                                   | HT Cable - 3C X 50 Sqmm, LT Cable - 4 X 25 sqmm, 25 meter(Approximate)           | Concealed Wiring                                                                 |                                                   |
| 6     | Bagerhat      | Sharonkhola Upazila Health Complex, Bagerhat. | sarankhola |                     |                                           |                                              |                                          |                            |                                                           |                                          |                                           |                                                |                                                                     |                                                                                  |                                                                                  |                                                   |

### Ancillary EM Items

| SL No | District Name | Name of the Hospital              | Upazilla   | Presence of Medical Gas System | Capacity of Medical Gas Plant if any (LPM) | Number of bed having Medical Gas Facility if any (nos) | Medical Gas Related Additional Info (describe) | Presence of Compound and Security Light | Presence of Sound and PA System | Presence of computer networks | Presence of PABX System | Presence of CCTV system | Number of Neon Poly sign board | Requirement of any ancillary items (Describe in detail) | Remarks (For any Additional Information) |
|-------|---------------|-----------------------------------|------------|--------------------------------|--------------------------------------------|--------------------------------------------------------|------------------------------------------------|-----------------------------------------|---------------------------------|-------------------------------|-------------------------|-------------------------|--------------------------------|---------------------------------------------------------|------------------------------------------|
| 1     | Bagerhat      | Chitalmari Upazila Health complex | chitalmari | No                             |                                            | 16                                                     | There is only oxygen supply for 16 beds        | No                                      | No                              | No                            | No                      | Yes                     | 1                              |                                                         |                                          |
| 2     | Bagerhat      | Kachua Upazila Health complex     | kachua     | No                             |                                            | 10                                                     | There is only oxygen supply for 10 beds        | No                                      | No                              | No                            | No                      | Yes                     | 1                              |                                                         |                                          |



| SL No | District Name | Name of the Hospital                          | Upazilla   | Presence of Medical Gas System | Capacity of Medical Gas Plant if any (LPM) | Number of bed having Medical Gas Facility if any (nos) | Medical Gas Related Additional Info (describe) | Presence of Compound and Security Light | Presence of Sound and PA System | Presence of computer networks | Presence of PABX System | Presence of CCTV system | Number of Neon Poly sign board | Requirement of any ancillary items (Describe in detail)                                                                             | Remarks (For any Additional Information) |
|-------|---------------|-----------------------------------------------|------------|--------------------------------|--------------------------------------------|--------------------------------------------------------|------------------------------------------------|-----------------------------------------|---------------------------------|-------------------------------|-------------------------|-------------------------|--------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------|
| 3     | Bagerhat      | Mongla Upazila Health Complex, Bagerhat.      | mongla     | Yes                            | 0                                          | 10                                                     | 10 Nos Oxygen Cylinder is Available Only       | Yes                                     | Yes                             | Yes                           | No                      |                         | 1                              | Needed a Full Functional Incineration Type Medical Gas Plant, Addressable Sound System, PABX System and 3 Nos 16 Chanel CCTV System |                                          |
| 4     | Bagerhat      | Morelgonj Upazila Health Complex              | morrelganj | No                             |                                            | 0                                                      |                                                | No                                      | No                              | No                            | No                      | Yes                     | 2                              |                                                                                                                                     |                                          |
| 5     | Bagerhat      | Rampal Upazila Health Complex, Bagerhat.      | rampal     | Yes                            | 0                                          | 30                                                     | 30 Nos Oxygen Cylinder is Available Only       | Yes                                     | Yes                             | Yes                           | No                      | Yes                     | 1                              | Needed a Full Functional Incineration Type Medical Gas Plant, Addressable Sound System, PABX System and 3 Nos 16 Chanel CCTV System |                                          |
| 6     | Bagerhat      | Sharonkhola Upazila Health Complex, Bagerhat. | sarankhola |                                |                                            |                                                        |                                                |                                         |                                 |                               |                         |                         |                                |                                                                                                                                     |                                          |

### Other Buildings

| SL No | District Name | Name of the Hospital                   | Upazilla   | Building Name  | Building No (if any) | Year of Construction | Number of Floors | Plinth Area (sqft) | Total Floor Area (sqft) | Current Condition (Describe)                                                                                            | Floor Plan (if any) | Visual Evidence (Image and Video) | Remarks (Additional Information)   |
|-------|---------------|----------------------------------------|------------|----------------|----------------------|----------------------|------------------|--------------------|-------------------------|-------------------------------------------------------------------------------------------------------------------------|---------------------|-----------------------------------|------------------------------------|
| 1     | Bagerhat      | 50 Bed Fakirhat Upazila Health Complex | fakirhat   | OPD Block      |                      | 1965                 | 2                | 7012.46            | 11732.46                |                                                                                                                         | No file             | No file                           | Old damaged unserviceable Building |
| 2     | Bagerhat      | 50 Bed Mollahat Upazila Health Complex | mollahat   | OPD Block      |                      | 1965                 | 2                | 7012.46            | 11732.46                | Old damaged unserviceable Building                                                                                      | 1 pdf               | No file                           |                                    |
| 3     | Bagerhat      | Chitalmari Upazilla Health Complex     | chitalmari | admin building | 1                    | 1998                 | 2                | 11240              | 22480                   | minar cracks were visible in some portions of the walls. Overall, the current condition of the building is satisfactory | No file             | 1 mp4                             |                                    |
| 4     | Bagerhat      | kachua Upazilla Health Complex         | kachua     | UHFPO          |                      | 1985                 | 1                | 1242               | 1242                    |                                                                                                                         | No file             | No file                           |                                    |

| SL No | District Name | Name of the Hospital                     | Upazilla   | Building Name     | Building No (if any) | Year of Construction | Number of Floors | Plinth Area (sqft) | Total Floor Area (sqft) | Current Condition (Describe) | Floor Plan (if any) | Visual Evidence (Image and Video) | Remarks (Additional Information) |
|-------|---------------|------------------------------------------|------------|-------------------|----------------------|----------------------|------------------|--------------------|-------------------------|------------------------------|---------------------|-----------------------------------|----------------------------------|
| 5     | Bagerhat      | kachua Upazilla Health Complex           | kachua     | 4TH CLASS QUARTER |                      | 1984                 | 1                | 4312               | 4312                    |                              | No file             | No file                           |                                  |
| 6     | Bagerhat      | kachua Upazilla Health Complex           | kachua     | 3RD CLASS QUARTER |                      | 1983                 | 2                | 2905               | 5810                    |                              | No file             | No file                           |                                  |
| 7     | Bagerhat      | kachua Upazilla Health Complex           | kachua     | NURSE QUARTER     |                      | 1982                 | 1                | 1550               | 1550                    |                              | No file             | No file                           |                                  |
| 8     | Bagerhat      | kachua Upazilla Health Complex           | kachua     | DOCTORS QUARTER 2 |                      | 1981                 | 1                | 1947               | 1947                    |                              | No file             | No file                           |                                  |
| 9     | Bagerhat      | kachua Upazilla Health Complex           | kachua     | DOCTORS QUARTER   |                      | 1980                 | 1                | 1947               | 1947                    |                              | No file             | No file                           |                                  |
| 10    | Bagerhat      | kachua Upazilla Health Complex           | kachua     | HALL ROOM         |                      | 2005                 | 1                | 1104               | 1                       |                              | No file             | No file                           |                                  |
| 11    | Bagerhat      | kachua Upazilla Health Complex           | kachua     | Oxyzen Room       |                      | 2005                 | 1                | 264                | 264                     |                              | No file             | No file                           |                                  |
| 12    | Bagerhat      | Mongla Upazila Health Complex, Bagerhat. | mongla     | Mosque            |                      | 2010                 | 1                | 5600               |                         |                              | No file             | 1 jpeg                            |                                  |
| 13    | Bagerhat      | Mongla Upazila Health Complex, Bagerhat. | mongla     | Staff Quarter     |                      | 1998                 | 1                | 2500               | 2500                    | Use                          | No file             | 1 jpeg                            |                                  |
| 14    | Bagerhat      | Mongla Upazila Health Complex, Bagerhat. | mongla     | Nurses Quarter    |                      | 1998                 | 2                | 2700               | 5400                    | Condemned                    | No file             | 1 jpeg                            |                                  |
| 15    | Bagerhat      | Mongla Upazila Health Complex, Bagerhat. | mongla     | Dormitory         |                      | 2010                 | 2                | 1000               | 2000                    | Use                          | No file             | 1 jpeg                            |                                  |
| 16    | Bagerhat      | Mongla Upazila Health Complex, Bagerhat. | mongla     | Nurses Quarter    |                      | 1998                 | 2                | 1200               | 4800                    | Condemned                    | No file             | 1 jpeg                            | ১১১১ ১১১১ ১১১১ ১১১১              |
| 17    | Bagerhat      | Mongla Upazila Health Complex, Bagerhat. | mongla     | Nurses Quarter    |                      | 1998                 | 2                | 1600               | 6400                    | Use                          | No file             | 1 jpeg                            |                                  |
| 18    | Bagerhat      | Mongla Upazila Health Complex, Bagerhat. | mongla     | Doctors Quarter   |                      | 1998                 | 2                | 3000               | 6000                    | Running                      | No file             | 1 jpeg                            |                                  |
| 19    | Bagerhat      | Mongla Upazila Health Complex, Bagerhat. | morrelganj | Staff Quarter     |                      | 1962                 | 1                | 2000               | 2000                    | Condemned                    | No file             | 1 jpeg                            |                                  |
| 20    | Bagerhat      | Morelgonj Upazila Health Complex         | morrelganj | Dormitory         |                      |                      | 2                | 1150               | 2300                    | Running/Repair (on going)    | No file             | 1 jpeg                            |                                  |
| 21    | Bagerhat      | Morelgonj Upazila Health Complex         | morrelganj | Staff Quarter     |                      |                      | 2                | 1600               | 6400                    | Unuse                        | No file             | No file                           |                                  |
| 22    | Bagerhat      | Morelgonj Upazila Health Complex         | morrelganj | Staff Quarter     |                      |                      | 2                | 1700               | 3400                    | Unuse                        | No file             | 1 jpeg                            |                                  |
| 23    | Bagerhat      | Morelgonj Upazila Health Complex         | morrelganj | Doctors Quarter   |                      | 2020                 | 2                | 2200               | 4400                    | Running                      | No file             | 1 jpeg                            |                                  |

| SL No | District Name | Name of the Hospital                          | Upazilla   | Building Name   | Building No (if any) | Year of Construction | Number of Floors | Plinth Area (sqft) | Total Floor Area (sqft) | Current Condition (Describe) | Floor Plan (if any) | Visual Evidence (Image and Video) | Remarks (Additional Information) |
|-------|---------------|-----------------------------------------------|------------|-----------------|----------------------|----------------------|------------------|--------------------|-------------------------|------------------------------|---------------------|-----------------------------------|----------------------------------|
| 24    | Bagerhat      | Sharonkhola Upazila Health Complex, Bagerhat. | sarankhola | Mosque          |                      |                      | 1                |                    |                         |                              | No file             | 1 jpeg                            |                                  |
| 25    | Bagerhat      | Sharonkhola Upazila Health Complex, Bagerhat. | sarankhola | Staff Quarter   |                      | 1976                 | 1                |                    |                         | Condemned                    | No file             | 1 jpeg                            |                                  |
| 26    | Bagerhat      | Sharonkhola Upazila Health Complex, Bagerhat. | sarankhola | Staff Quarter   |                      | 1976                 |                  | 2800               | 5600                    | Running                      | No file             | 1 jpeg                            |                                  |
| 27    | Bagerhat      | Sharonkhola Upazila Health Complex, Bagerhat. | sarankhola | Auditorium      |                      | 2001                 | 2                | 1350               | 2700                    | Running                      | No file             | 1 jpeg                            |                                  |
| 28    | Bagerhat      | Sharonkhola Upazila Health Complex, Bagerhat. | sarankhola | Nurses Quarter  |                      | 1976                 | 2                | 2600               | 5200                    | Running                      | No file             | 1 jpeg                            |                                  |
| 29    | Bagerhat      | Sharonkhola Upazila Health Complex, Bagerhat. | sarankhola | Nurses Quarter  |                      | 2001                 | 2                | 1300               | 2600                    | Running                      | No file             | 1 jpeg                            |                                  |
| 30    | Bagerhat      | Sharonkhola Upazila Health Complex, Bagerhat. | sarankhola | Doctors Quarter |                      | 2001                 | 2                | 3600               | 7200                    | Running                      | No file             | 1 jpeg                            |                                  |