

314

315



justnicecleancars

Just Nice House - Millers Road - Warwick - CV34 5AE
Tel: 01926 836 900 Email: sales@justnicecleancars.co.uk Website: www.justnicecleancars.co.uk
VAT No. 992 0343 17 Company Reg No. 7251788



SERVICED VEHICLE

Make Vauxhall
Model Astra 1.6 CDTi ecoFLEX Design
Sports Tourer 5dr Diesel Manual
Registration MT15ZUA
Chassis No W0LPD8E63F8064153
Engine No A2151325GWRX0360LVM
Mileage 87507
Registered 24/07/2015

SERVICE PROFORMA

Service No 23511
Date 05/03/2024
Order No
Telephone 07910887587
Email

Your Ref HODGSONO

Next Service Due By

or

MIs

Brief Service Description

POL: Interim Service Includes up to 4 Ltrs of Oil - Specialist or additional oil will incur extra cost

LABOUR WORK CARRIED OUT

	Hours Charged	Total	VAT Rate
Interim Service	0.60	43.50	20.00%
LABOUR TOTAL:			43.50

PARTS

Description	Qty	Price	Total	VAT Rate
Sump Plug Washer	1	1.30	1.30	20.00%
Oil Filter	1	12.15	12.15	20.00%
PARTS TOTAL:			13.45	

OILS / LUBRICANTS

Description	Qty	Price	Total	VAT Rate
Anti Freeze - Caflon OAT Coolant	0.1	8.49	.85	20.00%
POLYGARD ARTIC SCREEN WASH	2	.15	.30	20.00%
(Yellow) EXOPRO 5W30 C2 C3 SN/CF BMWLL04 GM D2	5	9.58	47.90	20.00%
OILS / LUBRICANTS TOTAL:			49.05	

EXTRAS

Description	Qty	Total	VAT Rate
Consumables & Environmental Charge (Including waste oil & parts disposal)	1	5.00	20.00%
EXTRAS TOTAL:		5.00	

I agree for all work and parts required for the above repairs at your retail charge. All repairs
taken on a cash basis unless prior arrangements for credit have been approved. I have
accept your terms and conditions. Nothing herein is designed to nor will it affect, a
ers statutory rights. All goods shall remain the property of Just Nice Clean Cars Ltd until paid
Credit card payments are accepted up to a maximum of £200.00.
PLEASE NOTE ANY SUSPENSION WORK CARRIED OUT MAY REQUIRE WHEEL
ALIGNMENT TO BE DONE - THIS MAY NOT BE APPARENT ON THE DAY OF FITMENT - WE
CAN OFFER FRONT WHEEL ALIGNMENT IF REQUIRED***

Sub Total	£111.00
MOT: Standard	0.00
Retest	0.00
+ VAT Due	22.20

Invoice Total	£133.20
---------------	---------

Total Deposits	0.00
----------------	------

Total Due	£133.20
-----------	---------

VAT Analysis
VAT @ 20% on 111.00 = 22.20

Company Reg. No. 7251788

VAT No. 992 0343 17

Date..... Signature.....

Get Clean Cars

Interim Service

DETAIL

VEHICLE DETAIL

VHC NO

4405

bury- Hodgson

Make Vauxhall

Date 2024-03-05

Model Astra

Service Advisor

M 07910887587

Registration MT15ZUA

MOT Due 14/06/2024

W

Chassis No W0LPD8E63F8064153

Inspected By Ben Smith

Mileage 87507

VHC Type Interim Service

Comments / Recommendations		Net	VAT	Total
Preliminary checks				
G	Check body condition and report defects			
G	Steering wheel and gear knob protector applied			
Parts included				
G	Engine oil			
G	Oil filter			
Top-ups included				
G	Windscreen washer fluid	2.0 litres		
G	Coolant / Anti-freeze	None required		
G	Tyre inflation			
Vehicle Interior				
G	Check instruments, gauges, warning lights			
G	Check horn			
A	Check windscreen wipers and washer operation	Off side washer jet poor spray pattern advise replacement		
Vehicle Exterior				
G	Check exterior lights and lamps			
Under the Bonnet				
G	Check anti-freeze/coolant strength & condition	-31		
G	Visual engine check			
Under the Vehicle				
G	Full tyre inspection			
Final Checks				
G	Video sent of any issues found			
G	Run engine and check oil level			
G	Reset oil change indicator (if available)			
Total		0.00	0.00	0.00

e Clean Cars

Interim Service

DETAIL

VEHICLE DETAIL

VHC NO

4405

erbury- Hodgson

Make Vauxhall

Date 2024-03-05

Model Astra

Service Advisor

M 07910887587

Registration MT15ZUA

MOT Due 14/06/2024

W

Chassis No W0LPD8E63F8064153

Inspected By Ben Smith

Mileage 87507

VHC Type Interim Service

Tyres		Tread (mm)			Manufacturer	Size	Comments/Recommendations
A	N/S Front	3.3	3.7	3.0			
G	N/S Rear	5.3	5.4	4.8			
G	O/S Front	3.4	4.0	3.3			
G	O/S Rear	5.3	5.2	5.1			
G	Spare		7.0			Steel spare	Unused

Brakes	Drums	Pads	Discs	Comments/Recommendations
		mm Remaining	mm Remaining	
N/S Front	N			
N/S Rear	N			
O/S Front	N			
O/S Rear	N			

Photos

Customer Signature

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.