



AA Certified Garage



justnicecleancars

Just Nice House - Millers Road - Warwick - CV34 5AE
Tel: 01926 836 900 Email: sales@justnicecleancars.co.uk Website: www.justnicecleancars.co.uk
VAT No. 992 0343 17 Company Reg No. 7251788



INVOICE TO
Mr Oliver Yerbury- Hodgson

SERVICED VEHICLE
Make **Vauxhall**
Model **Astra 1.6 CDTi ecoFLEX Design Sports Tourer 5dr Diesel Manual**
Registration **MT15ZUA**
Chassis No **W0LPD8E63F8064153**
Engine No **A2151325GWRX0360LVM**
Mileage **95716**
Registered **24/07/2015**

SERVICE PROFORMA
Service No **25955**
Date **27/09/2024**
Order No
Telephone **07803514949**
Email

Your Ref **HODGSONO**

Next Service Due By **26/09/2025** or **20000 Mls** Service Advisor **Simon Mould**

Brief Service Description

(IC) Full Service Includes up to 4 Ltrs of Oil - Specialist or additional oil will incur extra cost

LABOUR WORK CARRIED OUT

	Hours Charged	Total	VAT Rate
Carry out full service	1.10	80.66	20.00%
LABOUR TOTAL:			80.66

PARTS

Description	Qty	Price	Total	VAT Rate
Sump Plug Washer	1	1.10	1.10	20.00%
Air Filter	1	12.20	12.20	20.00%
Oil Filter	1	10.85	10.85	20.00%
PARTS TOTAL:			24.15	

OILS / LUBRICANTS

Description	Qty	Price	Total	VAT Rate
(YELLOW) Q8 Formula Special RN 5W-30	5	9.75	48.75	20.00%
OILS / LUBRICANTS TOTAL:			48.75	

EXTRAS

Description	Qty	Total	VAT Rate
Consumables & Environmental Charge (Including parts and/or waste oil disposal but not including tyres)	1	5.00	20.00%
EXTRAS TOTAL:			5.00

to pay for all work and parts required for the above repairs at your retail charge. All repairs undertaken on a cash basis unless prior arrangements for credit have been approved. I have read and accept your terms and conditions. Nothing herein is designed to nor will it affect, a customer's statutory rights. All goods shall remain the property of Just Nice Clean Cars Ltd until paid in full.

*** PLEASE NOTE ANY SUSPENSION WORK CARRIED OUT MAY REQUIRE WHEEL ALIGNMENT - THIS MAY NOT BE APPARENT ON THE DAY OF FITMENT - WE OFFER WHEEL ALIGNMENT IF REQUIRED***

PLEASE HAVE YOUR WHEEL NUTS RETORQUED AFTER 50 MILES AFTER LEAVING THE PREMISES

Sub Total	£158.56
MOT: Standard	0.00
Retest	0.00
+ VAT Due	31.71

Invoice Total	£190.27
---------------	---------

Total Deposits	0.00
----------------	------

Total Due	£190.27
-----------	---------

VAT Analysis
VAT @ 20% on 158.56 = 31.71

Date..... Signature.....

Company Reg. No. 7251788

VAT No. 992 0343 17

Price Clean Cars

Full Service

DETAIL

VEHICLE DETAIL

VHC NO

5155

Yerbury- Hodgson

Make Vauxhall

Date 27/09/2024

H 07803514949

Model Astra

Service Advisor Simon Mould

M 07910887587

Registration MT15ZUA

MOT Due 14/06/2025

W

Chassis No W0LPD8E63F8064153

Inspected By Will Bush

Mileage 95716

VHC Type Full Service

Comments / Recommendations

Preliminary Checks

- A** Check body condition and report defects
- G** Steering wheel and gear knob protector applied

Parts Included

- G** Engine oil
- G** Oil Filter
- G** Air Filter

Top-ups Included

- G** Windscreen washer fluid
- G** Coolant / anti-freeze
- G** Brake Fluid
- N/A** Power Steering Fluid (if required)
- G** Tyre Inflation

Vehicle Interior

- R** Check instruments, gauges, warning lights Tpms fault- Service vehicle message on dash - Service Light has been reset but vehicle requires a full diagnostics test
- G** Check horn
- G** Check windscreen wipers and washer operation
- G** Check all interior lights
- G** Check clutch operation (manual only)
- G** Check all seatbelts

Vehicle Exterior

- G** Check exterior lights and lamps
- G** Check doors - operation & condition
- G** Check boot - operation & condition
- G** Check fuel cap - operation & condition
- G** Check mirrors - operation & condition
- G** Check key fob operation

Under the Bonnet

- A** Check battery - state of health & charge Good & recharge
- G** Check battery wiring
- G** Check alternator and starter motor
- G** Check anti-freeze/coolant level, strength & cond
- R** Check brake fluid level and moisture content 4% Moisture Content - Recommend Brake Fluid Change
- G** Check and grease bonnet catch
- G** Check brake pipes and hoses

Price Clean Cars

Full Service

DETAIL

VEHICLE DETAIL

VHC NO 5155
Date 27/09/2024
Service Advisor Simon Mould
MOT Due 14/06/2025
Inspected By Will Bush
VHC Type Full Service

Yerbury- Hodgson
H 07803514949
M 07910887587
W

Make Vauxhall
Model Astra
Registration MT15ZUA
Chassis No W0LPD8E63F8064153
Mileage 95716

Comments / Recommendations

N/A	Check power steering - operation and leaks
G	Check radiator and coolant hoses
G	Visual engine check

Under the Vehicle

G	Check steering, suspension linkages & ball joints	
A	Suspension - check shock absorbers, springs & all	Rear spring corroded
R	Full tyre inspection	Front tyres worn 2mm advise tracking
G	Check boot for spare wheel, condition/kit	
A	Visual brake inspection of discs & pads	Front and rear discs are lipped, front pads okay rear pads @ 2/3mm

Final Checks

G	Video sent of any issues found
G	Run engine and check oil level
G	Vehicle road test
G	Reset oil change indicator (if available)
G	Reset service indicator light
G	Complimentary Coronavirus neutraliser
G	Stamp service book (if available)

Tyres Tread (mm) Manufacturer Size Comments/Recommendations

A	N/S Front	2.0	3.0	2.0	Michelin	215/60R16 99v	
G	N/S Rear	5.0	5.0	5.0			
A	O/S Front	2.0	3.0	2.0	Michelin	205/60R16 99v	
G	O/S Rear	5.0	5.0	5.0			
G	Spare						

Brakes Drums Pads Discs Comments/Recommendations

			mm Remaining	mm Remaining	
N/S Front	N	G	7		
N/S Rear	N	A	3		
O/S Front	N	G	7		
O/S Rear	N	A	3		

Photos

Customer Signature

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.