



justnicecleancars

Just Nice House - Millers Road - Warwick - CV34 5AE
Tel. 01926 836 900 Email: sales@justnicecleancars.co.uk Website: www.justnicecleancars.co.uk
VAT No. 992 0343 17 Company Reg No. 7251788



INVOICE TO
Mr Oliver Yerbury- Hodgson

SERVICED VEHICLE
Make Vauxhall
Model Astra 1.6 CDTi ecoFLEX Design
Sports Tourer 5dr Diesel Manual
Registration MT15ZUA
Chassis No W0LPD8E63F8064153
Engine No A2151325GWRX0360LVM
Mileage 96457
Registered 24/07/2015

SERVICE INVOICE
Service No 26270
Invoice No 27361
Date 21/10/2024
Payment
Order No

Your Ref HODGSONO

Telephone 07910887587
Email oyerburyhodgson@gmail.com

Next Service Due By 26/09/2025 or 20000 MIs

Brief Service Description

Check tyre pressure sensors and change one or replace battery if possible before carrying out other 2 which also show dead batteries -
Check reversing sensors

LABOUR WORK CARRIED OUT

	Hours Charged	Price	Discount	Total	VAT Rate
Carried out diagnostic check of TPMS system - Found 3 of the 4 wheels TPMS sensors batteries had expired and the O/S/F was very low.	0.50	42.50	100.00%	0.00	20.00%
Video carried out to show customer faults and also advised of issue stated on service carried out 27/09/2024 TPMS faults on dashboard		0.00		0.00	20.00%
Replace TPMS sensor in O/S/F wheel	0.50	36.67	100.00%	0.00	20.00%
Rear parking sensor system checked found power going to the main unit so fault maybe in one of the sensors but unable to check on our diagnostic equipment due to it being an after market system so not part of the vehicles ECU		0.00		0.00	20.00%
We would recommend speaking with Angus who fits after market parking sensor as he will be in a better place to assist - ANGUS 07836 623912		0.01		0.01	20.00%

LABOUR TOTAL: 0.01

PARTS

Description	Qty	Price	Discount	Total	VAT Rate
TPMS MX-Sensor (Metal)	1	39.99	100.00%	0.00	20.00%

PARTS TOTAL: 0.00

pay for all work and parts required for the above repairs at your retail charge. All repairs taken on a cash basis unless prior arrangements for credit have been approved. I have and accept your terms and conditions. Nothing herein is designed to nor will it affect, a customers statutory rights. All goods shall remain the property of Just Nice Clean Cars Ltd until paid full. All work and parts are covered by a 12 month warranty.
** PLEASE NOTE ANY SUSPENSION WORK CARRIED OUT MAY REQUIRE WHEEL ALIGNMENT - THIS MAY NOT BE APPARENT ON THE DAY OF FITMENT - WE OFFER WHEEL ALIGNMENT IF REQUIRED**
PLEASE HAVE YOUR WHEEL NUTS RETORQUED AFTER 50 MILES AFTER LEAVING THE PREMISES

Sub Total	£0.01
MOT: Standard	0.00
Retest	0.00
+ VAT Due	0.00

Invoice Total	£0.01
---------------	-------

Total Payments	0.01
----------------	------

Total Due	£0.00
-----------	-------

VAT Analysis
VAT @ 20% on 0.01 = 0.00

Company Reg. No. 7251788

VAT No. 992 0343 17

Date..... Signature.....

2015 Vauxhall Vehicle Diagnostic Report

Vehicle Information

2015/Vauxhall/Astra-J/
VIN: WOLPD8E63F8064153

Odometer Reading: 96457miles
License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS906 Pro
Version: V3.00

Serial Number: VA3GMCV01589
Repair Order Number:
VA3GMCV0158920241021120337360

System Scanned(10)

System	Status/DTC
Engine control module	1
Electronic brake control module	0
Inflatable restraint sensing and diagnostic module	1
Instrument cluster	0
Power steering control module	0
Steering wheel angle sensor module	0
Body control module	7
HVAC control module	0
Multi-axis acceleration sensor module	0
Radio	0

DTC (9)

Engine control module (1 DTC)

DTC	Description	Status
P151B:00	Engine oil life exceeded - forced limited engine power	DTC history status : History Since DTC clear : Passed and failed Last test : Passed This ignition cycle : Passed MIL status : Not requested

Inflatable restraint sensing and diagnostic module (1 DTC)

DTC	Description	Status
-----	-------------	--------

U0184:00

Lost communication with radio - Malfunction

DTC history status :
History
DTC current status : Not
current

Body control module (7 DTCs)

DTC	Description	Status
C0750:03	Left front tire pressure sensor - Low voltage	DTC history status : History Since DTC clear : Passed and failed Last test : Passed This ignition cycle : Passed MIL status : Not requested
C0750:29	Left front tire pressure sensor - Too few pulses	DTC history status : History Since DTC clear : Passed and failed Last test : Failed current DTC This ignition cycle : Failed MIL status : Not requested
C0755:03	Right front tire pressure sensor - Low voltage	DTC history status : History Since DTC clear : Passed and failed Last test : Failed current DTC This ignition cycle : Failed MIL status : Not requested
C0760:03	Left rear tire pressure sensor - Low voltage	DTC history status : History Since DTC clear : Passed and failed Last test : Passed This ignition cycle : Passed MIL status : Not requested
C0760:29	Left rear tire pressure sensor - Too few pulses	DTC history status : History Since DTC clear : Passed and failed Last test : Failed current DTC This ignition cycle : Failed MIL status : Not requested
C0765:03	Right rear tire pressure sensor - Low voltage	DTC history status : History Since DTC clear : Passed and failed Last test : Passed This ignition cycle : Passed MIL status : Not requested

C0765:29

Right rear tire pressure sensor - Too few pulses

DTC history status :
History
Since DTC clear : Passed
and failed
Last test : Failed current
DTC
This ignition cycle : Failed
MIL status : Not requested

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.