**Report #** 06092018-00405 **Created** Sep 06 2018 04:28:01 PM

Start Mileage1End Mileage2Registration No.PL 4023Vehicle TypeBus

Report By Jake Doe

**Report Notes** 

| Bus Checklist                     | Status | Remarks |
|-----------------------------------|--------|---------|
| 1. Mirrors and Glass              | Good   |         |
| 2. Brakes                         | Good   |         |
| 3. Windscreen Wipers and Washers  | Good   |         |
| 4. Heating/Ventilation            | Good   |         |
| 5. Horn                           | Good   |         |
| 6. Excessive Engine Exhaust Smoke | Good   |         |
| 7. Steering                       | Good   |         |
| 8. Warning Lamps                  | Good   |         |
| 9. Lights and Indicators          | Good   |         |
| 10. First Aid Kit                 | Good   |         |
| 11. Wheelchair Accessibility      | Good   |         |
| 12. Fire Extinguisher             | Good   |         |
| 13. Doors and Exits               | Good   |         |
| 14. Body Interior                 | Good   |         |
| 15. Emergency Exit Hammer         | Good   |         |
| 16. Tyre and Wheel Fixing         | Good   |         |
| 17. Fuel, Oil and Waste Leaks     | Good   |         |
| 18. Numberplate                   | Good   |         |
| 19. Body Exterior                 | Good   |         |

Jake Doe

Signature over printed name