Start Mileage 1 End Mileage 2

Registration No.PL 4023Trailer No.PL 4023Report ByChok Doe

Report Notes

Driver Checklist	Status	Remarks
1. Front and Back Lamps	Defect	
2. Tire	Defect	
3. Side Mirror	Good	
4. Air Horn	Rechecked	
5. Break	Rechecked	
6. Steering Wheel	Good	
7. Exhaust	Rechecked	

Chok Doe

Signature over printed name