Report # Created Aug 23 2018 04:58:08 PM 23082018-00310

Start Mileage **End Mileage** Registration No. Trailer No. VM 1 VM 1 Report By

John Doe

Report Notes

Driver Checklist	Status	Remarks
1. Front and Back Lamps	Defect	
2. Tire	Good	
3. Side Mirror	Good	
4. Air Horn	Defect	
5. Break	Rechecked	
6. Steering Wheel	Good	
7. Exhaust	Good	

John Doe

Signature over printed name