Report #17082018-00237CreatedAug 17 2018 10:42:41 AMStart Mileage1End Mileage2Registration No.PL 4023Trailer No.PL 4023Report ByElfeim Zuark

Report Notes

Driver Checklist		Remarks
1. Lamps	✓	
2. Tire	✓	
3. Side Mirror	✓	
4. Horn	✓	
5. Break	✓	
6. Steering Wheel	✓	
7. Exhaust	~	



Elfeim Zuark

Signature over printed name