Report #17082018-00238CreatedAug 17 2018 10:45:35 AMStart Mileage1End Mileage2Registration No.PL 4023Trailer No.PL 4023Report ByElfeim Zuark

**Report Notes** 

Driver Checklist	Remarks
1. Lamps	✓
2. Tire	✓
3. Side Mirror	✓
4. Horn	✓
5. Break	✓
6. Steering Wheel	$\checkmark$
7. Exhaust	✓

Elfeim Zuark

Signature over printed name