

Report #

23082018-00304

Start Mileage

2

Registration No.

VM 1

Report By

John Doe

Created

Aug 23 2018 02:14:33 PM

End Mileage


3

Trailer No.

VM 1

Report Notes

Driver Checklist	Status	Remarks
1. Front and Back Lamps	Good	
2. Tire	Good	
3. Side Mirror	Good	
4. Air Horn	Good	
5. Break	Good	
6. Steering Wheel	Good	
7. Exhaust	Good	



John Doe

Signature over printed name