Report #
 05092018-00402
 Created
 Sep 05 2018 09:59:43 AM

 Start Mileage
 1
 End Mileage
 3

Registration No. PL 4023 Trailer No. PL 4023
Report By Jake Doe

**Report Notes** 

Driver Checklist	Status	Remarks
1. Front and Back Lamps	Rechecked	test1
2. Tire	Defect	test2
3. Side Mirror	Good	
4. Air Horn	Good	
5. Break	Rechecked	
6. Steering Wheel	Defect	
7. Exhaust	Rechecked	

Jake Doe

Signature over printed name