

Report #

22082018-00294

Start Mileage

1

Registration No.

VM 1

Report By

John Doe

Created

Aug 22 2018 03:27:25 PM

End Mileage

2

Trailer No.

VM 1

Report Notes

Driver Checklist	Status	Remarks
1. Front and Back Lamps	Good	
2. Tire	Rechecked	
3. Side Mirror	Good	
4. Air Horn	Rechecked	
5. Break	Defect	
6. Steering Wheel	Defect	
7. Exhaust	Rechecked	

John Doe

Signature over printed name