

Report #

Start Mileage

Registration No.

Report By

Report Notes

23082018-00309

2

PL 4023

John Doe

Created

End Mileage


Trailer No.

Aug 23 2018 04:45:49 PM

3

PL 4023

Driver Checklist	Status	Remarks
1. Front and Back Lamps	Defect	
2. Tire	Good	
3. Side Mirror	Good	
4. Air Horn	Good	
5. Break	Good	
6. Steering Wheel	Good	
7. Exhaust	Good	



John Doe

Signature over printed name