**Report #** 04092018-00397 **Created** Sep 04 2018 09:33:20 AM

Start Mileage 1 End Mileage

**Registration No.** PL 4023 **Trailer No.** PL 4023

Report By Jake Doe

**Report Notes** 

Driver Checklist	Status	Remarks
1. Front and Back Lamps	Rechecked	
2. Tire	Good	
3. Side Mirror	Good	
4. Air Horn	Good	
5. Break	Good	
6. Steering Wheel	Good	
7. Exhaust	Good	

Jake Doe

Signature over printed name