Start Mileage2End Mileage3Registration No.PL 4023Trailer No.PL 4023

Report By Chok Doe

Report Notes

Driver Checklist	Status	Remarks
1. Front and Back Lamps	Defect	
2. Tire	Defect	
3. Side Mirror	Good	
4. Air Horn	Rechecked	
5. Break	Good	
6. Steering Wheel	Rechecked	
7. Exhaust	Good	

Chok Doe

Signature over printed name