Report #
 22082018-00282
 Created
 Aug 22 2018 10:25:03 AM

 Start Mileage
 1
 End Mileage
 2

 Registration No.
 PL 4023
 Trailer No.
 PL 4023

**Report Notes** 

John Doe

Report By

Driver Checklist	Remarks
1. Front and Back Lamps	✓
2. Tire	✓
3. Side Mirror	✓
4. Air Horn	✓
5. Break	✓
6. Steering Wheel	✓
7. Exhaust	×



John Doe

Signature over printed name