

Report #	07092018-00413	Created
Start Mileage	1	End Mileage
Registration No.	AB 9218	Vehicle
Report By	Louigie Narvaez	
Report Notes		

Van Checklist	Status
1. All lights and indicators work correctly	Good
2. All lenses are present, clean and are the correct colour	Rechecked
3. Stop lamps come on when the service brake is applied and go out when released	Good
4. Marker lights are present and work	Good
5. ABS dashboard warning lamp	Good
6. Airbags (SRS) dashboard warning lamp works	Good
7. EPS dashboard warning lamp	Good
8. Full beam headlamp dashboard warning lamp	Rechecked
9. Parking brake dashboard warning lamp	Good
10. Horn	Good
11. Steering has no excessive play	Good
12. Wipers move continually when switched on	Good
13. Wiper blades are not so deteriorated that they don't clear the windscreen effectively when used with washers	Good
14. Washers point at the windscreen and are operational	Good
15. Washer fluid is topped up	Good
16. Mirrors and Glass	Defect
17. Seats are secure	Good
18. Seatbelts operate correctly and are free from cuts and damage	Good
19. Foot / Service brake works correctly and does not have any excessive travel	Good
20. Hand / Parking brake works correctly and does not have any excessive travel	Good
21. Battery is held securely in place by the correct means and not cables	Good
22. Tyres and Wheels: a minimum tread depth of 1.6mm	Good
23. Tyres and Wheels : sufficient inflation of each tyre	Good
24. Tyres and Wheels : no deep cuts in the sidewall	Good
25. Tyres and Wheels : no cord visible anywhere on the tyre	Good
26. Tyres and Wheels : no missing or insecure wheel-nuts	Good
27. Brake Fluid, Engine Coolant, Engine oil, Power Steering fluid, Windscreen washer fluid and Water levels are correct	Good
28. Fuel filler cap is securely fitted	Good
29. There are no brake fluid, power steering fluid and water leaks by looking for puddles on the ground	Good
30. With the engine on, check underneath the van for any fuel and oil leaks looking for puddles on the ground	Good
31. Exhaust doesn't emit excessive amount of smoke	Good
32. Tow bar is secure and any trailer is correctly and securely attached with all electrical connections working correctly	Good
33. Tail lift is secure and free from damage, functions correctly and the electrics are working correctly	Good
34. Bodywork and Doors: all doors shut properly and are secure when closed	Good
35. Bodywork and Doors: there are no sharp edges or damage	Good
36. Bodywork and Doors: no body panel are loose or in danger of falling off	Good
37. Load: any load is adequately secured	Good
38. Load: Van doors have an effective locking device	Good

Louigie Narvaez

Signature over printed name

