

Report #	18082018-00268	Created	Aug 18 2018 10:54:00 AM
Start Mileage	3	End Mileage	39
Registration No.	PL 4023	Trailer No.	PL 4023
Report By	Pie Doe		
Report Notes	test		

Driver Checklist		Remarks
1. Lamps	✗	
2. Tire	✓	
3. Side Mirror	✓	
4. Horn	✓	
5. Break	✗	
6. Steering Wheel	✓	
7. Exhaust	✓	



Pie Doe

Signature over printed name