

Report #

Start Mileage

Registration No.

Report By

Report Notes

23082018-00299

3

PL 4023

Chok Doe

Created

End Mileage


Trailer No.

Aug 23 2018 10:37:52 AM

6

PL 4023

Driver Checklist	Status	Remarks
1. Front and Back Lamps	Rechecked	
2. Tire	Good	
3. Side Mirror	Defect	
4. Air Horn	Defect	
5. Break	Good	
6. Steering Wheel	Good	
7. Exhaust	Good	



Chok Doe

Signature over printed name