

Report #

Start Mileage

Registration No.

Report By

Report Notes

23082018-00311

1

PL 4023

Chok Doe

Created

End Mileage


Trailer No.

Aug 23 2018 05:07:46 PM

3

PL 4023

Driver Checklist	Status	Remarks
1. Front and Back Lamps	Defect	
2. Tire	Defect	
3. Side Mirror	Defect	
4. Air Horn	Defect	
5. Break	Defect	
6. Steering Wheel	Defect	
7. Exhaust	Defect	



Chok Doe

Signature over printed name