Report # 05092018-00401 **Created** Sep 05 2018 09:45:01 AM

Start Mileage 1 End Mileage 2

Registration No. PL 4023 **Trailer No.** PL 4023

Report By Jake Doe

Report Notes

Driver Checklist	Status	Remarks
1. Front and Back Lamps	Rechecked	
2. Tire	Defect	
3. Side Mirror	Good	
4. Air Horn	Good	
5. Break	Good	
6. Steering Wheel	Good	
7. Exhaust	Good	

Jake Doe

Signature over printed name