

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT




LOAD ID: 44777				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes Phone: 954-397-1833		DESTINATION Lifted Trucks 401 NE Loop 820 Hurst, TX 76053 Contact: Lifted Trucks Phone: (817) 864-8795		
VIN 1FTFW1RG0PFA53769	Year / Make / Model 2023 Ford F-150	Type Pickup (4 doors)	Color	Odometer 53306
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed NO INSPECTION DAMAGE MARKINGS CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/Y3b3g3pK6WzV40JVG7oOJO3Le				
Notes: CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed on the weekends		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 27, 2026 / Denes Dombai 		Vehicle received in good condition except as noted above. Destination Signature / Jul 29, 2026 / Lifted Trucks		
Driver Signature / Jul 27, 2026 / Dmitry Tyushnyakov 		Driver Signature / Jul 29, 2026 / Dmitry Tyushnyakov		

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 44777				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes Phone: 954-397-1833		DESTINATION Lifted Trucks 401 NE Loop 820 Hurst, TX 76053 Contact: Lifted Trucks Phone: (817) 864-8795		
VIN 3C63R3SL8SG506676	Year / Make / Model 2025 Ram 3500	Type Pickup (4 doors)	Color	Odometer 5012
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed  NO INSPECTION DAMAGE MARKINGS CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/Y3b3g3pK6WzV40JVG7oOJO3Le				
Notes: CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed on the weekends		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 27, 2026 / Denes Dombai 		Vehicle received in good condition except as noted above. Destination Signature / Jul 29, 2026 / Lifted Trucks		
Driver Signature / Jul 27, 2026 / Dmitry Tyushnyakov 		Driver Signature / Jul 29, 2026 / Dmitry Tyushnyakov		