




DEALERS CHOICE AUTO TRANSPORT INC

2833 Exchange Court, Suite A
West Palm Beach, FL 33409
Phone: +15616865225
Email: team@dcat.com

BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 605170 - NI				
ORIGIN C & K Auto Imports - South 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes . Phone: 9543971833		DESTINATION CarTopia 46 265 US-46 Elmwood Park, NJ 07407 Contact: Sales Manager Phone: 2018347335		
VIN SAL1Z9F95SA462807	Year / Make / Model 2025 LAND ROVER Range Rover Sport	Type SUV	Color Obsidian Black Paint	Odometer
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed  CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/DKOlv3j4pDe0vvxbWLWG8RgL				
Notes:		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Aug 7, 2026 / Jordan 		Vehicle received in good condition except as noted above. Destination Signature / Aug 12, 2026 / Sales Manager		
Driver Signature / Aug 7, 2026 / Artem Maltsev 		Driver Signature / Aug 12, 2026 / Artem Maltsev		