


OLYMP TRANSPORT INC

2900 OAK RIDGE RD
SEDALIA, Missouri 65301
MC Number: 1691715
Phone: +12066368727
Email: dispatcholymp@gmail.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: VS926263				
ORIGIN C & K Auto Imports 1210 S Andrew AVE Pompano Beach, FL 33069 Contact: Manager Phone: 305.542.2496		DESTINATION Hendrick Lexus KC 6935 W Frontage Road Merriam, KS 66203 Contact: Manager on site Phone: 816.332.6461		
VIN 5TDAAAA64RS000507	Year / Make / Model 2024 Lexus TX 350	Type SUV	Color	Odometer
Inspection notes:				
- BR-Broken - CH-Chipped - CR-Cracked - D-Dented - F-Faded - FF-Foreign Fluid - FT-Flat Tire - G-Gouge - HD-Hail Damage - LC-Loose Contents - M-Missing - MD-Major Damage - MS-Multiple Scratches - O-Other - PC-Paint Chip - R-Rubbed - RU-Rust - S-Scratched - SC-Scuffed		 NO INSPECTION DAMAGE MARKINGS		
CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/Zm1wGbw3rarRakaOxkkV3ZmnM				
Notes:		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Aug 13, 2026 / Jordan 		Vehicle received in good condition except as noted above. Destination Signature / Aug 14, 2026 / Manager on site		
Driver Signature / Aug 13, 2026 / Anatolii Radchuk 		Driver Signature / Aug 14, 2026 / Anatolii Radchuk		