



DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 45187				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes Phone: 954-397-1833		DESTINATION Foreign Cars Italia of Greensboro 5603 Roanne Way A Greensboro, NC 27409 Contact: Foreign Cars Italia of Greensboro Phone: (336) 717-0147		
VIN SAL119E99SA425221	Year / Make / Model 2025 Land Rover Range Rover Sport	Type SUV	Color	Odometer
Inspection notes:				
- BR-Broken - CH-Chipped - CR-Cracked - D-Dented - F-Faded - FF-Foreign Fluid - FT-Flat Tire - G-Gouge - HD-Hail Damage - LC-Loose Contents - M-Missing - MD-Major Damage - MS-Multiple Scratches - O-Other - PC-Paint Chip - R-Rubbed - RU-Rust - S-Scratched - SC-Scuffed		 NO INSPECTION DAMAGE MARKINGS		
CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/aLRPXMp8RQdEK3kNd6k4kMoPK				
Notes: CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed on the weekends		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Aug 3, 2026 / Denes Dombai 		Vehicle received in good condition except as noted above. Destination Signature / Aug 4, 2026 / Foreign Cars Italia of Greensboro		
Driver Signature / Aug 3, 2026 / Ed Perez 		Driver Signature / Aug 4, 2026 / Ed Perez		