

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 43779				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes Phone: 954-397-1833		DESTINATION Cocoa Ford 1360 W King St Cocoa, FL 32922 Contact: Cocoa Ford Phone: (321) 471-3809		
VIN 3FA6P0G78HR369196	Year / Make / Model 2017 Ford Fusion	Type Sedan	Color	Odometer
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/vZ3Bakd7LbvKGvXnYrX7wOM3v				
Notes: CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed on the weekends		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 9, 2026 / Denes Dombai 		Vehicle received in good condition except as noted above. Destination Signature / Jul 9, 2026 / Cocoa Ford		
Driver Signature / Jul 9, 2026 / Davit Tsutsunava 		Driver Signature / Jul 9, 2026 / Davit Tsutsunava		

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 43779				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes Phone: 954-397-1833		DESTINATION Cocoa Ford 1360 W King St Cocoa, FL 32922 Contact: Cocoa Ford Phone: (321) 471-3809		
VIN 1GYS4CKJ9JR390608	Year / Make / Model 2018 Cadillac Escalade	Type SUV	Color	Odometer
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/vZ3Bakd7LbvKGvXnYrX7wOM3v				
Notes: CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed on the weekends		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 9, 2026 / Denes Dombai 		Vehicle received in good condition except as noted above. Destination Signature / Jul 9, 2026 / Cocoa Ford		
Driver Signature / Jul 9, 2026 / Davit Tsutsunava 		Driver Signature / Jul 9, 2026 / Davit Tsutsunava		