

AMERICAN ALEMAN PICKUP LLC



7161 SW 4TH ST

MIAMI, Florida 33144

Phone: +17867573309

Email: americanpickupllc@gmail.com

BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 80650				
ORIGIN Left Lane Exotics/Experience Wholesale S Andrews Ave Pompano Beach, FL 33069 Contact: Phone: 954-4492499		DESTINATION italian Imports Indy 4180 East 96th Street Indianapolis, IN 46240 Contact: Phone: 317-660-4160		
VIN 5J8YD4H56KL003261	Year / Make / Model 2019 Acura MDX	Type SUV	Color	Odometer 47184
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed		 NO INSPECTION DAMAGE MARKINGS		
CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/X3dX7EKWpxyEeMmXPYKjZkL8Q				
Notes:		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 22, 2026 / Jordan 		Vehicle received in good condition except as noted above. Destination Signature / Jul 23, 2026		
Driver Signature / Jul 22, 2026 / Yuniet Aleman 		Driver Signature / Jul 23, 2026 / Yuniet Aleman		

AMERICAN ALEMAN PICKUP LLC



7161 SW 4TH ST

MIAMI, Florida 33144

Phone: +17867573309

Email: americanpickupllc@gmail.com

BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 80650				
ORIGIN Left Lane Exotics/Experience Wholesale S Andrews Ave Pompano Beach, FL 33069 Contact: Phone: 954-4492499		DESTINATION italian Imports Indy 4180 East 96th Street Indianapolis, IN 46240 Contact: Phone: 317-660-4160		
VIN WBA5U7C06LFH18894	Year / Make / Model 2020 BMW 3-Series	Type Sedan	Color	Odometer 53795
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed		 NO INSPECTION DAMAGE MARKINGS		
CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/X3dX7EKWpxyEeMmXPYKjZkL8Q				
Notes:		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 22, 2026 / Jordan 		Vehicle received in good condition except as noted above. Destination Signature / Jul 23, 2026		
Driver Signature / Jul 22, 2026 / Yuniet Aleman 		Driver Signature / Jul 23, 2026 / Yuniet Aleman		