

Bill of Lading

Pickup Inspection: 08/19/2026

Load ID: 3f373cb2

Shipper: Don Williamson Nissan



Autosled, Inc
6010 Executive Blvd
Rockville, MD, 20852
240-880-2702

Vehicle

Year	2022
Make	Land Rover
Model	Range Rover
Type	SUV
Color	
VIN #	SALGS2SE4NA460527
Odometer	49466

Transporter

Company Name	MBL TRANSPORT LLC
Company Phone	+1 (786)-683-1247
Driver Name	MICHAEL BOBADILLA
Driver Phone	+1 (786)-683-1247
US DOT #	3683108

Origin

Experience Wholesale
1210 S Andrews Ave, Pompano Beach, FL 33069

Contact: Austin
Phone: +1 (904)-240-8674

Contact Printed Name

Austin

Contact Signature, 08/19/2026, 12:36 PM

Pending

Driver Signature

Pending

Destination

Burnout Garage
609 N Anderson Rd, Rock Hill, SC 29730

Contact: Manager
Phone: +1 (803)-366-1000

Contact Printed Name

Pending

Contact Signature

Driver Signature

Pending

Driver Notes

No notes provided by driver at pickup.

Pickup Photos



26.215256, -80.13821



26.215233, -80.13819




26.215256, -80.13821




26.215256, -80.13821



26.215256, -80.13821



26.215256, -80.13821





26.215256, -80.13821




26.215256, -80.13821




26.215256, -80.13821

Pickup Inspection




Front

1	No Damage
2	No Damage
3	No Damage
4	No Damage




Rear

1	No Damage
2	No Damage
3	No Damage
4	No Damage



Driver Side

1	No Damage
2	No Damage
3	No Damage
4	No Damage
5	No Damage
6	No Damage
7	No Damage
8	No Damage



Passenger Side

1	No Damage
2	No Damage
3	No Damage
4	No Damage
5	No Damage
6	No Damage
7	No Damage
8	No Damage

Additional Inspection Comments

No notes provided by driver at pickup.