

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com




LOAD ID: 46164				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Experience Wholesale Phone: 954-397-1833	DESTINATION CarTopia 897 US-22, Plainfield, NJ 07060 Contact: CarTopia Phone: (908) 364-9441			
VIN 1GYS4RKL2NR349036	Year / Make / Model 2022 Cadillac Escalade ESV	Type SUV	Color	Odometer 58928
Inspection notes:				
BR - Broken CH - Chipped CR - Cracked D - Dented F - Faded FF - Foreign Fluid FT - Flat Tire G - Gouge HD - Hail Damage LC - Loose Contents M - Missing MD - Major Damage MS - Multiple Scratches O - Other PC - Paint Chip R - Rubbed RU - Rust S - Scratched SC - Scuffed Damage marks on photos. Damage codes: ['S', 'S', 'S', 'PC', 'S', 'S', 'S', 'S', ...]				
CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/jdgGeWj7gqmv3748xOrbYNvJO				
Notes: CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed on the weekends		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Aug 19, 2026 / Jordan 		Vehicle received in good condition except as noted above. Destination Signature / Aug 24, 2026 / CarTopia		
Driver Signature / Aug 19, 2026 / Ivan Sosa 		Driver Signature / Aug 24, 2026 / Ivan Sosa		

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 46164				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Experience Wholesale Phone: 954-397-1833		DESTINATION CarTopia 897 US-22, Plainfield, NJ 07060 Contact: CarTopia Phone: (908) 364-9441		
VIN WAUENCF52KA067740	Year / Make / Model 2019 Audi A5 Sportback	Type Sedan	Color	Odometer 52632
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed		Damage marks on photos. Damage codes: ['S', 'D', 'S', 'S', 'CR', 'CR', 'CR', 'S', ... 		
CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/jdgGeWJ7gqmv3748xOrbYNvJO				
Notes: CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed on the weekends		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Aug 19, 2026 / Jordan 		Vehicle received in good condition except as noted above. Destination Signature / Aug 24, 2026 / CarTopia		
Driver Signature / Aug 19, 2026 / Ivan Sosa 		Driver Signature / Aug 24, 2026 / Ivan Sosa		