


AUTO BY ZACK INC

9120 SOUTHWEST FWY
Houston, Texas 77074
Phone: +18325886632
Email: frontdeskabz@gmail.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 0637				
ORIGIN 1210 SOUTH ANDREWS AVE Pompano Beach, FL 33069 Contact: Phone: 9544492499		DESTINATION ABZ MOTORS 9120 SOUTHWEST FWY Houston, TX 77074 Contact: KAGAN Phone: 8325886632		
VIN SALK19E98SA260637	Year / Make / Model 2025 Land Rover Range Rover	Type SUV	Color	Odometer
Inspection notes:				
- BR-Broken - CH-Chipped - CR-Cracked - D-Dented - F-Faded - FF-Foreign Fluid - FT-Flat Tire - G-Gouge - HD-Hail Damage - LC-Loose Contents - M-Missing - MD-Major Damage - MS-Multiple Scratches - O-Other - PC-Paint Chip - R-Rubbed - RU-Rust - S-Scratched - SC-Scuffed		 NO INSPECTION DAMAGE MARKINGS		
CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/0qj4GQv0bmRRawqNg0GeKoOzm				
Notes:		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Aug 18, 2026 / Jordan 		Vehicle received in good condition except as noted above. Destination Signature / Aug 21, 2026 / KAGAN		
Driver Signature / Aug 18, 2026 / Denis Shmytov 		Driver Signature / Aug 21, 2026 / Denis Shmytov		