

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT


LOAD ID: 43169				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Experience Wholesale Phone: 954-397-1833		DESTINATION Beaver Mazda 1865 Buford Hwy Cumming, GA 30041 Contact: Beaver Mazda Phone: (470) 873-9010		
VIN JM3KKDHD3R1162088	Year / Make / Model 2024 Mazda CX-90	Type SUV	Color	Odometer
Inspection notes:				
- BR-Broken - CH-Chipped - CR-Cracked - D-Dented - F-Faded - FF-Foreign Fluid - FT-Flat Tire - G-Gouge - HD-Hail Damage - LC-Loose Contents - M-Missing - MD-Major Damage - MS-Multiple Scratches - O-Other - PC-Paint Chip - R-Rubbed - RU-Rust - S-Scratched - SC-Scuffed		NO INSPECTION DAMAGE MARKINGS CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/jG3rYPMbMWZlQLdvXyZNXGG3a		
Notes: Closed on 4th of July! CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Clo...		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 1, 2026 / Denes Dombai 		Vehicle received in good condition except as noted above. Destination Signature / Jul 1, 2026 / Beaver Mazda		
Driver Signature / Jul 1, 2026 / Mouad Bekka 		Driver Signature / Jul 1, 2026 / Mouad Bekka		

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 43169				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Experience Wholesale Phone: 954-397-1833		DESTINATION Beaver Mazda 1865 Buford Hwy Cumming, GA 30041 Contact: Beaver Mazda Phone: (470) 873-9010		
VIN 3MVDMBBM8RM682796	Year / Make / Model 2024 Mazda CX-30	Type SUV	Color	Odometer
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed  CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/jG3rYPMbMWZlQLdvXyZNXGG3a				
Notes: Closed on 4th of July! CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Clo...		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 1, 2026 / Denes Dombai 		Vehicle received in good condition except as noted above. Destination Signature / Jul 1, 2026 / Beaver Mazda		
Driver Signature / Jul 1, 2026 / Mouad Bekka 		Driver Signature / Jul 1, 2026 / Mouad Bekka		

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT


LOAD ID: 43169				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Experience Wholesale Phone: 954-397-1833		DESTINATION Beaver Mazda 1865 Buford Hwy Cumming, GA 30041 Contact: Beaver Mazda Phone: (470) 873-9010		
VIN JM3KFBCL6R0511550	Year / Make / Model 2024 Mazda CX-5	Type SUV	Color	Odometer
Inspection notes:				
- BR-Broken - CH-Chipped - CR-Cracked - D-Dented - F-Faded - FF-Foreign Fluid - FT-Flat Tire - G-Gouge - HD-Hail Damage - LC-Loose Contents - M-Missing - MD-Major Damage - MS-Multiple Scratches - O-Other - PC-Paint Chip - R-Rubbed - RU-Rust - S-Scratched - SC-Scuffed		NO INSPECTION DAMAGE MARKINGS		
● CR Circles — pickup damages; ■ CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/jG3rYPMbMWZlQLdvXyZNXGG3a				
Notes: Closed on 4th of July! CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Clo...		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 1, 2026 / Denes Dombai 		Vehicle received in good condition except as noted above. Destination Signature / Jul 1, 2026 / Beaver Mazda		
Driver Signature / Jul 1, 2026 / Mouad Bekka 		Driver Signature / Jul 1, 2026 / Mouad Bekka		

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 43169				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Experience Wholesale Phone: 954-397-1833		DESTINATION Beaver Mazda 1865 Buford Hwy Cumming, GA 30041 Contact: Beaver Mazda Phone: (470) 873-9010		
VIN JM3KFBCL8R0531153	Year / Make / Model 2024 Mazda CX-5	Type SUV	Color	Odometer
Inspection notes:				
- BR-Broken - CH-Chipped - CR-Cracked - D-Dented - F-Faded - FF-Foreign Fluid - FT-Flat Tire - G-Gouge - HD-Hail Damage - LC-Loose Contents - M-Missing - MD-Major Damage - MS-Multiple Scratches - O-Other - PC-Paint Chip - R-Rubbed - RU-Rust - S-Scratched - SC-Scuffed		 NO INSPECTION DAMAGE MARKINGS		
CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/jG3rYPMbMWZlQLdvXyZNXGG3a				
Notes: Closed on 4th of July! CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Clo...		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 1, 2026 / Denes Dombai 		Vehicle received in good condition except as noted above. Destination Signature / Jul 1, 2026 / Beaver Mazda		
Driver Signature / Jul 1, 2026 / Mouad Bekka 		Driver Signature / Jul 1, 2026 / Mouad Bekka		