




DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 44987				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes Phone: 954-397-1833		DESTINATION Foreign Cars Italia Charlotte 416 Tyvola Rd Charlotte, NC 28217 Contact: Foreign Cars Italia Charlotte Phone: (704) 755-3233		
VIN SAL1L9E95SA467718	Year / Make / Model 2025 Land Rover Range Rover Sport	Type SUV	Color	Odometer
Inspection notes:				
- BR-Broken - CH-Chipped - CR-Cracked - D-Dented - F-Faded - FF-Foreign Fluid - FT-Flat Tire - G-Gouge - HD-Hail Damage - LC-Loose Contents - M-Missing - MD-Major Damage - MS-Multiple Scratches - O-Other - PC-Paint Chip - R-Rubbed - RU-Rust - S-Scratched - SC-Scuffed		 NO INSPECTION DAMAGE MARKINGS ● Circles — pickup damages; ■ Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/OQ37dWGV0oYGVp7DqRYy0P00b		
Notes: CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed on the weekends		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 29, 2026 / Denes Dombai 		Vehicle received in good condition except as noted above. Destination Signature / Jul 30, 2026 / Foreign Cars Italia Charlotte		
Driver Signature / Jul 29, 2026 / Igor Ognerubov 		Driver Signature / Jul 30, 2026 / Igor Ognerubov		