



DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 43384				
ORIGIN City Motor Group 186 Msgr. O'Brien Hwy Cambridge, MA 02141 Contact: City Motor Group Phone: 617-547-0692		DESTINATION Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes Phone: 954-397-1833		
VIN 5YJ3E1EAXPF656028	Year / Make / Model 2023 Tesla Model 3	Type Sedan	Color	Odometer 1
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed  CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/Y3NDOLi8DBEgbKowGxyonK8K8				
Notes:		Notes: Closed on July 3rd CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed ...		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 2, 2026 / Chaz Kary 		Vehicle received in good condition except as noted above. Destination Signature / Jul 6, 2026 / Jotdan 		
Driver Signature / Jul 2, 2026 / Melvin 		Driver Signature / Jul 6, 2026 / Melvin 		