

SHIP ME MY CAR


PO BOX 8

GRADYVILLE, PA 19039

Phone: (484) 352-8712

Email: ops@shipmemycar.com

BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 884352489				
ORIGIN EXPERIENCE WHOLESale 1210 s Andrews ave Pompano Beach, FL 33069 Contact: Austin Phone: 904-240-8674		DESTINATION MANHEIM IMPORTS ***NOT THE AUCTION*** 712 LANCASTER RD Manheim, PA 17545 Contact: JEFF LUDWIG Phone: 7176656611		
VIN SJAAT2ZV5PC024262	Year / Make / Model 2023 Bentley Bentayga	Type SUV	Color	Odometer 0
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed		 NO INSPECTION DAMAGE MARKINGS		
CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/wm8JbxKzJR33LoaB4Ijg4MJp				
Notes:		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 6, 2026 / Jordan 		Vehicle received in good condition except as noted above. Destination Signature / Jul 7, 2026 / JEFF LUDWIG		
Driver Signature / Jul 6, 2026 / Yevhen 		Driver Signature / Jul 7, 2026 / Yevhen		