

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT


LOAD ID: 43392				
ORIGIN EXPERIENCE WHOLESALE 1210 S ANDREWS AVE Pompano Beach, FL 33069 Contact: DANISH Phone: 954-397-1833		DESTINATION Beaver Toyota of Cumming 1875 Buford Hwy Cumming, GA 30041 Contact: Beaver Toyota of Cumming Phone: 470) 533-2060		
VIN 2T2BAMCA2RC066405	Year / Make / Model 2024 Lexus RX 350	Type SUV	Color	Odometer 999999
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/aZMerB7yKPZQbRm4XkdJOWeOK				
Notes: CALL DANISH TO SCHEDULE PICK UPS CLOSE AT 4:30 PM MON-FRI		Notes: Drivers - Make sure vehicles are not being dropped off in front of our collision center! They shoul...		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 6, 2026 / Denes Dombai 		Vehicle received in good condition except as noted above. Destination Signature / Jul 7, 2026 / Beaver Toyota of Cumming		
Driver Signature / Jul 6, 2026 / Ilia Savin (VLAD G) 		Driver Signature / Jul 7, 2026 / Ilia Savin (VLAD G)		

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 43392				
ORIGIN EXPERIENCE WHOLESALE 1210 S ANDREWS AVE Pompano Beach, FL 33069 Contact: DANISH Phone: 954-397-1833		DESTINATION Beaver Toyota of Cumming 1875 Buford Hwy Cumming, GA 30041 Contact: Beaver Toyota of Cumming Phone: 470) 533-2060		
VIN JTEVA5BR1S5030878	Year / Make / Model 2025 Toyota 4Runner	Type SUV	Color	Odometer 9999
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed  CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/aZMerB7yKPZQbRm4XkdJOWeOK				
Notes: CALL DANISH TO SCHEDULE PICK UPS CLOSE AT 4:30 PM MON-FRI		Notes: Drivers - Make sure vehicles are not being dropped off in front of our collision center! They shoul...		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 6, 2026 / Denes Dombai 		Vehicle received in good condition except as noted above. Destination Signature / Jul 7, 2026 / Beaver Toyota of Cumming		
Driver Signature / Jul 6, 2026 / Ilia Savin (VLAD G) 		Driver Signature / Jul 7, 2026 / Ilia Savin (VLAD G)		