


DEALERS CHOICE AUTO TRANSPORT INC

2833 Exchange Court, Suite A
West Palm Beach, FL 33409
Phone: +15616865225
Email: team@dcat.com

BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 602222 - EP				
ORIGIN 1930 Lafayette Rd Gladwyne, PA 19035 Contact: Mike Haber Phone: 2158703980		DESTINATION Left Lane Exotics 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes . Phone: 9543971833		
VIN SCBDGAZG0PC009023	Year / Make / Model 2023 BENTLEY Continental	Type Sedan	Color	Odometer 1841
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign Fluid FT-Flat Tire G-Gouge HD-Hail Damage LC-Loose Contents M-Missing MD-Major Damage MS-Multiple Scratches O-Other PC-Paint Chip R-Rubbed RU-Rust S-Scratched SC-Scuffed		NO INSPECTION DAMAGE MARKINGS  CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/ZLowD8ZN1qlgN7OrpwEol3O3Y		
Notes: Please call 24 hours prior to pickup and on day of pickup at least 2-3 hours		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 1, 2026 / melissa L Totoro 		Vehicle received in good condition except as noted above. Destination Signature / Jul 6, 2026 / Jordan 		
Driver Signature / Jul 1, 2026 / georgi farniev 		Driver Signature / Jul 6, 2026 / Gamlet Dzagoev 		