


DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 43528				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes Phone: 954-397-1833		DESTINATION Hennessy Cadillac 3377 Satellite Blvd Duluth, GA 30096 Contact: Hennessy Cadillac Phone: (833) 907-0852		
VIN 1GYS4HK90PR502630	Year / Make / Model 2023 Cadillac Escalade-V	Type SUV	Color	Odometer 31706
Inspection notes:				
- BR-Broken - CH-Chipped - CR-Cracked - D-Dented - F-Faded - FF-Foreign Fluid - FT-Flat Tire - G-Gouge - HD-Hail Damage - LC-Loose Contents - M-Missing - MD-Major Damage - MS-Multiple Scratches - O-Other - PC-Paint Chip - R-Rubbed - RU-Rust - S-Scratched - SC-Scuffed		 NO INSPECTION DAMAGE MARKINGS		
CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/xVOqvY8kKXJMOz60xBmYbbOpn				
Notes: CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed on the weekends		Notes:		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 6, 2026 / Denes Dombai 		Vehicle received in good condition except as noted above. Destination Signature / Jul 7, 2026 / Hennessy Cadillac		
Driver Signature / Jul 6, 2026 / Daniil Dmitriev 		Driver Signature / Jul 7, 2026 / Daniil Dmitriev		