

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT


LOAD ID: 43785				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes Phone: 954-397-1833		DESTINATION Rick Hendrick Chevrolet Atlanta 277 Satellite Blvd NW Duluth, GA 30096 Contact: Rick Hendrick Chevrolet Atlanta Phone: (678) 497-4598		
VIN 1FMCU0GN2RUA96816	Year / Make / Model 2024 Ford Escape	Type SUV	Color	Odometer 45967
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign F FT-Flat Tire G-Gouge HD-Hail Dam LC-Loose Co M-Missing MD-Major D: MS-Multiple O-Other PC-Paint Chi R-Rubbed RU-Rust S-Scratched SC-Scuffed CR Circles — pickup damages; CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/wE0yRJVPdmngoXG13groZN1ng				
Notes: CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed on the weekends		Notes: See Blake		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 9, 2026 / Todd K 		Vehicle received in good condition except as noted above. Destination Signature / Jul 10, 2026 / Rick Hendrick Chevrolet Atlanta		
Driver Signature / Jul 9, 2026 / Alexandr Solodovnik 		Driver Signature / Jul 10, 2026 / Alexandr Solodovnik		

DEALER DIRECT TRANSPORTATION LLC

39506 N Daisy Mountain Dr, STE 122
Anthem, Arizona 85086
Phone: +14808857561
Email: patrick@dealerdirecttransport.com



BILL OF LADING / VEHICLE INSPECTION REPORT

LOAD ID: 43785				
ORIGIN Experience Wholesale 1210 S Andrews Ave Pompano Beach, FL 33069 Contact: Denes Phone: 954-397-1833		DESTINATION Rick Hendrick Chevrolet Atlanta 277 Satellite Blvd NW Duluth, GA 30096 Contact: Rick Hendrick Chevrolet Atlanta Phone: (678) 497-4598		
VIN 5FNRL6H65SB062735	Year / Make / Model 2025 Honda Odyssey	Type Van	Color	Odometer 34922
Inspection notes:				
BR-Broken CH-Chipped CR-Cracked D-Dented F-Faded FF-Foreign F FT-Flat Tire G-Gouge HD-Hail Dam LC-Loose Co M-Missing MD-Major D: MS-Multiple O-Other PC-Paint Chi R-Rubbed RU-Rust S-Scratched SC-Scuffed  ● CR Circles — pickup damages; ■ CR Rounded rectangles — delivery damages; See inspection photos and details: https://bol.superdispatch.com/wE0yRJVPdmngoXG13groZN1ng				
Notes: CALL DANISH TO SCHEDULE PICK UPS OR DELIVERIES CLOSE AT 4:30 PM MON-FRI Closed on the weekends		Notes: See Blake		
I agree with the Driver's assessment of the condition of this vehicle. Origin Signature / Jul 9, 2026 / Todd K 		Vehicle received in good condition except as noted above. Destination Signature / Jul 10, 2026 / Rick Hendrick Chevrolet Atlanta		
Driver Signature / Jul 9, 2026 / Alexandr Solodovnik 		Driver Signature / Jul 10, 2026 / Alexandr Solodovnik		